

22/03/2017

ASS REC. BY:

REF:

CG/MSG17014159/TITB

Special Instruction:

SURVIVOR:

Tauhich

ASSIGNMENT (Office)

From (Person):

Elaine Ng

of

MSH

Estimated Cost:

Bill to:

Date/Time:

21072017 228pm

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SHA0971Y

at Workshop m/s

Ding Automotive

Insured:

SJV 4450Z

of

31 Corporation Road

Tel:

6131 6518

Policy No:

A78880267QMX

Sum Insured:

Claim No:

523864

Make of Veh:
(Client's Record)

Excess:

D.O.A.

20072017

CA / REV / REP. / REV 24 HRS WPI

Date/Time:

21072017 233pm

Person Contacted:

Lucas

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 971Y - CG/A7608624109/KDN

SJV 4450Z - X

QIA: 30032008

Tough

REF:

MS16

ASSIGNMENT

COE: 2018 April

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen

Consistent? Yes or No

Est. Repairs:

days Res. Yes or No

Lum Sum:

% 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction:

Veh No: SHA 9714 Yr Regn: 2010 April 15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Sonata

CC 1991

Colour: Yellow

A.C: Insured / Std / NI / NA

Sp. Reading: 248000

T.Radio: Insured / Std / NI / NA

Eng No:

C.No: KM HET 41V M9A 780 858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

Lc

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Triangle

Front

Rear

R.Bal:

6

mm

R.Bal:

6

mm

L.Bal:

6

mm

L.Bal:

6

mm

D.O.A:

D.O.I:

21/7/17 01700

Survey held at:

Diy Auto 31 Gopation Rd.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear up

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 23 NOV 2017

Date/Time: File Pass to?



Preli. Report



Final Report

23/11 Typist

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$

TP 2900

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

300

10

310



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17014159/T11b	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 21-07-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SVJ 4450Z		Veh. Inspected	SHA 971Y
Policy No.	A28880267QMX		Coverage (\$)	0.00
Claim No.	523864		Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)		Assign Date	21/07/2017
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/07/2017		Inspection Date	21/07/2017
Survey held at	31 CORPORATION RD			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2017		21 Jul 2017 14:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TAN LEE MENG, ID: S15105251								
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G								
Vehicle Reg. No.:	SHA0971Y	Date of Loss:	20/07/2017 16:00 - :59						
Claim Type:	TP / 523864	Policy/Cover Note No.:	A28880267QMX (Comprehensive) Coverage: 26/01/2017 - 25/01/2018						
Vehicle Reg. No. (Insured):	SJV4450Z	Policy No. (Claimant):							
		Excess:	S\$700.00						
Repairer:	Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/07/2017]								
Driver/Custodian (Insured):	LEE SIEW KUAN (), NRIC: S1501440G, Tel: +6594884835								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Report ID : 227C7PL32
DATE : 22.08.2017
TIME : 09:03:17

CityCab Pte Ltd
Vehicle NEW for Fleet Safety Division
AS AT 30.06.2017

USER ID : CTFNEX03
PAGE : 1

Co. Code : CAS
Licence Pl. No : SHA0971Y
Old Asset No : 10007280-0
Veh. Model : Hyundai Sonata
Reg. Date : 15.04.2010
Cap. Date : 15.04.2010
Accident. Date : 20.07.2017
Veh. Age : 087

Asset No	SA No	Bul. Dep. Mths	Per. Mth. Dep	Bal. Dep. Value	Asset Description 1	Cost	Op. Acc. Dep	Cur. Year Dep	Accum. Dep	Net Book Value	Scrap value/Estimated P&RF Refund
10007280	0	003	244.43	733.29	SHA0971Y HSN 15.04.2010 BASIC COST	22,000.00	19,799.10-	1,456.60-	21,255.70-	734.30	1.00
10007280	1	003	37.31	111.93	SHA0971Y HSN 15.04.2010 IMPORT DUTY	3,358.26	3,032.44-	223.88-	3,246.32-	111.94	0.00
10007280	2	003	74.63	223.89	SHA0971Y HSN 15.04.2010 ARF 100X0W\$16792	16,792.00	6,045.30-	447.80-	6,493.10-	10,298.90	10,075.00
10007280	3	003	190.41	571.23	SHA0971Y HSN 15.04.2010 COE 80%	17,137.00	15,423.30-	1,142.47-	16,565.77-	571.23	0.00
10007280	4	000	0.00	0.00	SHA0971Y HSN 15.04.2010 COE TOP UP	0.00	0.00	0.00	0.00	0.00	0.00
10007280	5	003	0.00	0.00	SHA0971Y HSN 15.04.2010 AIR CONDITIONER	0.00	0.00	0.00	0.00	0.00	0.00
10007280	6	003	0.00	0.00	SHA0971Y HSN 15.04.2010 PRINTER DIGITAX THERMAL	0.00	0.00	0.00	0.00	0.00	0.00
10007280	7	003	0.00	0.00	SHA0971Y HSN 15.04.2010 TAXIMETER DIGITAX FI	0.00	0.00	0.00	0.00	0.00	0.00
10007280	8	003	1.56	4.68	SHA0971Y HSN 15.04.2010 VEH REG FEE	140.00	126.00-	9.34-	135.34-	4.66	0.00
			548.34	1,645.02		59,427.26	44,416.14-	3,290.09-	47,706.23-	11,721.03	
COE			190.41	571.23	Vehicle : Without T/A & COE	42,290.26	28,992.84-	2,147.62-	31,140.46-	11,149.80	
Vehicle			357.93	1,073.79	Vehicle : Without T/A, With COE Taximeter	59,427.26	44,416.14-	3,290.09-	47,706.23-	11,721.03	
			548.34	1,645.02		0.00	0.00	0.00	0.00	0.00	

SLK6402J

TP Veh	SHA 971Y
Date of Reg	15/4/2010
DOA	20/7/2017

(I) Estimated Depreciation Value

\$

Unit Cost		22,000.00
Import Duty		2,518.80
Registration Fee	16792	140.00
PQP Paid		17,137.00
ARF Paid		16,792.00
Estimated Per Taxi Purchase Price		58,587.80
Estimated Per Taxi Purchase Price		58,587.80
Less		10,075.20
60% of ARF Paid		48,512.60
Estimated Full Lifespan Depreciation		48,512.60
Estimated Full Lifespan Depreciation		0.0938
Times Balance Life over (96 months)	9	4,548.06
Add 60% of ARF Paid		10,075.20
Estimated Depreciation Value		14,623.26

(Summary) Estimated Nett Value

Estimated Depreciation Value	14,623.26
Less Adjusted LTA Rebate	11,681.60
Estimated Net Value	2,941.66



SINGAPORE POLICE FORCE



T/20170720/2148

1 of 3

Report No. T/20170720/2148

Police Station Of Origin:
Tampines East NPP
263 Tampines Street 21 #01-138
SINGAPORE 520263
Tel No: 1800-7839999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/07/2017 20:52	Vide Report No.:	Station Diary No.: 23
--	------------------	--------------------------

Informant's Particulars

Name of Informant: ONG TECK KOON			Address: APT BLK 225A JURONG EAST STREET 21 #05-795 SINGAPORE 601225		
ID Type / ID No.: NRIC NO / S1215971D			Contact No.: Home/Office: Mobile: 96861531		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 61	Date of Birth: 26/04/1956	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 20/07/2017 16:00	Type of Location:
Location: STEVENS ROAD SCOTTS ROAD Toward Orchard (Junction)				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA971Y	Car					0
SJV4450Z	Car					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20170720/2148

Police Station Of Origin:
Tampines East NPP
263 Tampines Street 21 #01-138
SINGAPORE 520263
Tel No: 1800-7839999

2 of 3

Report No. T/20170720/2148

CONTINUATION OF REPORT

Driver			
Name	ONG TECK KOON	ID No.	S1215971D
Related Vehicle	SHA971Y (Car)	Contact No.	96861531
Hospital/Clinic	MEDILIFE CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	20/07/2017	Date Discharge	20/07/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On the above mentioned date time and location, while I was driving along lane 2 of a 3 lane road at the said junction. When the traffic started to turn green, I move off slowly and suddenly I felt an impact from the rear of my vehicle which caused my vehicle to spin forward. The impact caused a heavy dent and damages on my right rear side.

Afterwhich my vehicle was towed away and I was feeling unwell and went to see the mentioned clinic and was given a 3 days MC for suffering neck and back stiffness. I am also unsure if my onboard CCTV was working and I also never notice him approaching from behind.

Particulars of other driver:

Lee Siew Kuan
S1501440G
9488 4835



**SINGAPORE
POLICE FORCE**



T/20170720/2148

3 of 3

Report No. T/20170720/2148

Police Station Of Origin:
Tampines East NPP
263 Tampines Street 21 #01-138
SINGAPORE 520263
Tel No: 1800-7839999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G/ Staff Sgt WONG JIANYONG <i>Sgt Jitrich H</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 20/07/2017 20:52
Officer In Charge Of Case: TP / GIA /	Classification Of Case:
Contact No.: <i>2017</i>	
Authentication Stamp NP168	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/07/2017 09:25
Date Of Accident	20/07/2017 16:00
Exact Location Of Accident	ALONG STEVEN ROAD TOWARD ORCHARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA0971Y
Insured/Policyholder	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	199502839G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96861531
Alternative Phone No	OFFICE-96861531

Vehicle Particulars

Manufacturer	HYUNDAI
Model	SONATA-2.0 CRDI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category TAXI

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-15072702MFSH
Cover Note Number	

Driver

Name of Driver	ONG TECK KOON
NRIC No	S1215971D
Date Of Birth	26/04/1956
Occupation	OUTDOOR
Date Of Driving Pass	19/04/1977
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96861531
Fax Number	
Contact Number	OFFICE-96861531
Email Address	NOEMAIL



Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name TAMPINES EAST NPP
Police Station Address ROAD: 263 TAMPINES STREET 21 #01-138 , POSTCODE: 520263 ,
COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-7839999 - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATACHED POLICE REPORT STATEMENT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJV4450Z
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LEE SIEW KUAN
NRIC/Passport Number S1501440G
Contact Number 94884835
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number



Email Address

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: SHA971Y

B: SIV4450Z

Ding Automotive Pte Ltd

Blk 10 Sin Ming Industrial Est. Sector C, #01-20, Singapore 575645

Tel:6452 1208, Fax:6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

21/07/2017 15:40

JOB-NO: 50110176

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 3

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA0971Y

TRANS: AUTO

CHASSIS: KMHET41VMAA780858

MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDI

ENGINE: D4EAB944542

OWNER'S INSURER: FIRST CAPITAL INSURANCE LIMITED

JOB-CODE: TP

SA: Wong Siew Keong

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO REPAIR, REPLACE & REALIGN DAMAGE AREAS	1.00	1,500.00	0.00	1,500.00		Y	1000
2 TO STRAIGHTEN REAR CHASIS MEMBER RH	1.00	300.00	0.00	300.00		Y	1500 photo
3 TO REMOVE AND REFIT REAR BUMPER REVERSE SENSOR	1.00	60.00	0.00	60.00		Y	30
4 TO CHECK WIRING AND LIGHTING SYSTEM	1.00	60.00	0.00	60.00		Y	30
5 TO REMOVE AND REFIT REAR WINDSCREEN	1.00	200.00	0.00	200.00		Y	1200 photo
6 TO REMOVE AND REPLACE UNDERCARRIAGE NECESSARY PARTS	1.00	200.00	0.00	200.00		Y	1200 K photo
7 TO REMOVE AND REFIT REAR SEAT COMPENENT	1.00	100.00	0.00	100.00		Y	60
8 TOWING FEE	1.00	80.00	0.00	80.00		Y	60
9 TO SPRAY PAINT ON BOOTLID	1.00	250.00	0.00	250.00		Y	200
10 TO SPRAY PAINT ON END PANEL	1.00	250.00	0.00	250.00		Y	200
11 TO SPRAY PAINT ON REAR FENDER	1.00	250.00	0.00	250.00		Y	200
12 TO SPRAY PAINT ON SPARETYRE PANEL	1.00	250.00	0.00	250.00		Y	200
13 TO SPRAY PAINT ON RH DOOR	1.00	250.00	0.00	250.00		Y	200
14 TO SPRAY PAINT ON SPEAKER PANEL	1.00	250.00	0.00	250.00		Y	200
TOTAL:		4,000.00	0.00	4,000.00			2500

MATERIALS

1 REAR BUMPER	1.00	523.93	0.00	523.93	L	Y	de
2 REAR BUMPER REINFORCEMENT	1.00	462.30	0.00	462.30	L	Y	one
3 REAR BUMPER RETAINER RH	1.00	42.68	0.00	42.68	L	Y	ne
4 REAR BUMPER RETAINER LH	1.00	42.68	0.00	42.68	L	Y	x
5 REAR BUMPER BRACKET RH	1.00	79.75	0.00	79.75	L	Y	de
6 REAR BUMPER BRACKET LH	1.00	79.75	0.00	79.75	L	Y	x
7 REAR BUMPER SPONGE	1.00	113.52	0.00	113.52	L	Y	one
8 REAR BUMPER PROTECTOR RH	1.00	102.96	0.00	102.96	L	Y	de
9 REAR BUMPER PROTECTOR LH	1.00	102.96	0.00	102.96	L	Y	x
10 REAR BUMPER LOWER EXT	1.00	40.70	0.00	40.70	L	Y	x
11 REAR BUMPER LOWER COVER LH	1.00	38.83	0.00	38.83	L	Y	de
12 BOOTLID	1.00	1,139.00	0.00	1,139.00	L	Y	de
13 BOOTLID EMBLEM-LOGO	1.00	21.45	0.00	21.45	L	Y	ne
14 BOOTLID EMBLEM-HYUNDAI	1.00	20.13	0.00	20.13	L	Y	ne
15 BOOTLID EMBLEM-SONATA	1.00	40.92	0.00	40.92	L	Y	ne
16 BOOTLID EMBLEM-CRDI	1.00	18.70	0.00	18.70	L	Y	ne
17 BOOTLID LAMP RH	1.00	203.50	0.00	203.50	L	Y	cut

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
18 BOOTLID LAMP LH	1.00	203.50	0.00	203.50	L	Y	X nh
19 BOOTLID PLATE LAMP RH	1.00	49.50	0.00	49.50	L	Y	X nh
20 BOOTLID PLATE LAMP LH	1.00	49.50	0.00	49.50	L	Y	X nh
21 BOOTLID HINGE RH	1.00	140.80	0.00	140.80	L	Y	Rxo
22 BOOTLID HINGE LH	1.00	140.80	0.00	140.80	L	Y	ev
23 BOOTLID LOCK	1.00	109.45	0.00	109.45	L	Y	bb
24 BOOTLID LOCK CATCH	1.00	108.90	0.00	108.90	L	Y	X nh
25 BOOTLID INSULATOR	1.00	155.10	0.00	155.10	L	Y	X nh
26 BOOTLID RUBBER BEADING	1.00	91.30	0.00	91.30	L	Y	nr
27 BOOTLID DAMPER RH	1.00	104.50	0.00	104.50	L	Y	X nh
28 BOOTLID DAMPER LH	1.00	104.50	0.00	104.50	L	Y	X nh
29 END PANEL	1.00	323.29	0.00	323.29	L	Y	bt
30 END PANEL TOP GARNISH	1.00	42.02	0.00	42.02	L	Y	de
31 TAIL LAMP RH	1.00	323.40	0.00	323.40	L	Y	ow
32 TAIL LAMP LH	1.00	323.40	0.00	323.40	L	Y	X nh
33 TAIL LAMP INNER PANEL RH	1.00	267.30	0.00	267.30	L	Y	bt
34 TAIL LAMP INNER PANEL LH	1.00	267.30	0.00	267.30	L	Y	X nh
35 SPARETYRE PANEL	1.00	812.90	0.00	812.90	L	Y	X nh
36 SPARETYRE TOP BOARD	1.00	162.14	0.00	162.14	L	Y	X nh
37 SPARETYRE SIDE PANEL RH	1.00	179.30	0.00	179.30	L	Y	bt
38 SPARETYRE SIDE PANEL TRAY RH	1.00	17.60	0.00	17.60	L	Y	de
39 SPARETYRE TOOL HOLDER SPONGE	1.00	27.50	0.00	27.50	L	Y	X nh
40 REAR FENDER RH	1.00	1,598.30	0.00	1,598.30	L	Y	me
41 REAR FENDER INNER SHIELD RH	1.00	31.02	0.00	31.02	L	Y	de
42 REAR FENDER PILLAR INNER TRIM	1.00	191.62	0.00	191.62	L	Y	X nh
43 REAR WHEEL HOUSE PANEL RH	1.00	655.49	0.00	655.49	L	Y	Rx
44 REAR FENDER QTR GARNISH	1.00	27.60	0.00	27.60	L	Y	X nh
45 REAR MUD FLAP	1.00	16.50	0.00	16.50	L	Y	me
46 REAR WINDSCREEN MLDG	1.00	49.28	0.00	49.28	L	Y	me
47 REAR WINDSCREEN	1.00	833.69	0.00	833.69	L	Y	X nh
48 REAR SPEAKER PANEL	1.00	293.70	0.00	293.70	L	Y	Rx
49 REAR DOOR RH	1.00	1,128.28	0.00	1,128.28	L	Y	Rx
50 REAR SHOCK ABSORBER RH	1.00	182.38	0.00	182.38	L	Y	X nh
51 REAR SHOCK ABSORBER TOP MOUNTING	1.00	230.36	0.00	230.36	L	Y	X nh
52 REAR CHASIS RH	1.00	624.58	0.00	624.58	L	Y	Rx
53 REVERSE SENSOR	1.00	200.00	0.00	200.00	S	Y	me
54 REAR BUMPER RUBBER PAD PROTECTOR	1.00	120.00	0.00	120.00	S	Y	me
55 BOOTLID STICKER-CAB BOOKING 65521111	1.00	40.00	0.00	40.00	S	Y	me
56 BOOTLID STICKER-CITYCAB	1.00	40.00	0.00	40.00	S	Y	me
57 BOOTLID INSULATOR CLIP SET	1.00	35.00	0.00	35.00	S	Y	X nh
58 REAR NUMBER PLATE	1.00	35.00	0.00	35.00	S	Y	X nh
59 END PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	me
60 SPARETYRE INSULATOR PAD	1.00	280.00	0.00	280.00	S	Y	X nh
61 SPARETYRE PANEL SEALANT	1.00	50.00	0.00	50.00	S	Y	X nh
62 REAR WINDSCREEN SEALANT	1.00	50.00	0.00	50.00	S	Y	me
63 REAR WINDSCREEN TINTED	1.00	200.00	0.00	200.00	S	Y	X nh
64 REAR WINDSCREEN INNER SEAL	1.00	30.00	0.00	30.00	S	Y	me
65 REAR DOOR STICKER-65521111	1.00	40.00	0.00	40.00	S	Y	me
TOTAL:		14,110.56	0.00	14,110.56			
TOTAL PARTS & LABOUR:		18,110.56	0.00	18,110.56			

EXCESS/LOADING:\$\$ 0.00

No. Of Day: 8

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 21 / 7 / 17

Parts 4717.43.
 20% - 3773.94
 SN - 570
 Labor - 2500

G-STAR-WI-ET-001-02-Rev00

6843.94
 159 5450 * 8 days
 4159 2900

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

SURVEYED BY:

Tan Jiah

Lump sum

CONTACT NO:

97495711

FAX NO:

Resurvey after repair.

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

60100319

Wong Siew Keong

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

\$ to get taxi book value

\$ to check repair limit

sur@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jul 2017		21 Jul 2017 14:28 Edit Adj Rpt	S\$2,900.00 Edit Estimates	S\$2,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

TAN LEE MENG, ID: S15105251

Main Claimant:

CITYCAB PTE LTD, Co. Reg. No.: 199502839G

Vehicle Reg. No.:

SHA971Y

Date of Loss:

20/07/2017 16:00 - :59

Claim Type:

TP / 523864

Policy/Cover Note No.:

A28880267QMX (Comprehensive)
Coverage: 26/01/2017 - 25/01/2018

Vehicle Reg. No. (Insured):

SJV4450Z

Policy No. (Claimant):

Excess:

S\$700.00

Repairer:

Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD, 649825 Boon Lay - Tel: 96992878

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Imm.Advice due 22/07/2017]

Driver/Custodian (Insured):

LEE SIEW KUAN (), NRIC: S1501440G, Tel: +6594884835

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA971Y (523864)
[SJV4450Z]
TP
CITYCAB PTE LTD
Jul 20 2017 4:00PM
[TAN LEE MENG]
Ding Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		Use Viewer	
Assessment Reports						1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	21/07/17 14:23	Accident Statement From: SC - Reg. No: SJV4450Z, Claimant: TAN LEE MENG					Load HTM		
						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	23/11/17 10:21	General View					Load JPG	☒	
2	23/11/17 10:21	General View					Load JPG	☒	
3	23/11/17 10:21	General View					Load JPG	☒	
4	23/11/17 10:21	General View					Load JPG	☒	
5	23/11/17 10:21	General View					Load JPG	☒	
6	23/11/17 10:21	General View					Load JPG	☒	
7	23/11/17 10:21	General View					Load JPG	☒	
8	23/11/17 10:21	General View					Load JPG	☒	
9	23/11/17 10:21	General View					Load JPG	☒	
10	23/11/17 10:21	General View					Load JPG	☒	
11	23/11/17 10:21	General View					Load JPG	☒	
12	23/11/17 10:21	General View					Load JPG	☒	
13	23/11/17 10:21	General View					Load JPG	☒	
14	23/11/17 10:21	General View					Load JPG	☒	
15	23/11/17 10:21	General View					Load JPG	☒	
16	23/11/17 10:21	General View					Load JPG	☒	
17	23/11/17 10:21	General View					Load JPG	☒	
18	23/11/17 10:22	General View					Load JPG	☒	
19	23/11/17 10:22	General View					Load JPG	☒	
20	23/11/17 10:22	General View					Load JPG	☒	
21	23/11/17 10:22	General View					Load JPG	☒	
22	23/11/17 10:22	General View					Load JPG	☒	
23	23/11/17 10:22	General View					Load JPG	☒	
24	23/11/17 10:22	General View					Load JPG	☒	
25	23/11/17 10:22	General View					Load JPG	☒	
26	23/11/17 10:22	General View					Load JPG	☒	
27	23/11/17 10:22	General View					Load JPG	☒	
28	23/11/17 10:22	General View					Load JPG	☒	
29	23/11/17 10:22	General View					Load JPG	☒	
30	23/11/17 10:22	General View					Load JPG	☒	
31	23/11/17 10:22	General View					Load JPG	☒	
32	23/11/17 10:22	General View					Load JPG	☒	
33	23/11/17 10:22	General View					Load JPG	☒	
34	23/11/17 10:22	General View					Load JPG	☒	

35	23/11/17 10:22	General View		Load JPG	☒
36	23/11/17 10:22	General View		Load JPG	☒
37	23/11/17 10:22	General View		Load JPG	☒
38	23/11/17 10:22	General View		Load JPG	☒
39	23/11/17 10:22	General View		Load JPG	☒
40	23/11/17 10:22	General View		Load JPG	☒
41	23/11/17 10:22	General View		Load JPG	☒
42	23/11/17 10:22	General View		Load JPG	☒
43	23/11/17 10:22	General View		Load JPG	☒
44	23/11/17 10:22	General View		Load JPG	☒
45	23/11/17 10:22	General View		Load JPG	☒
46	23/11/17 10:22	General View		Load JPG	☒
47	23/11/17 10:22	General View		Load JPG	☒
48	23/11/17 10:22	General View		Load JPG	☒
49	23/11/17 10:22	General View		Load JPG	☒
50	23/11/17 10:22	General View		Load JPG	☒
51	23/11/17 10:23	Reinspection Photo		Load JPG	☒
52	23/11/17 10:23	Reinspection Photo		Load JPG	☒
53	23/11/17 10:23	Reinspection Photo		Load JPG	☒
54	23/11/17 10:23	Reinspection Photo		Load JPG	☒
55	23/11/17 10:23	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/07/17 14:23	PRI		Load PDF	
2	21/07/17 14:23	Survey Agreement Email		Load PDF	
3	21/07/17 14:23	TP GIA Report From: SC - Reg. No: S3V4450Z, Claimant: TAN LEE MENG		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17014159/T1TBE2
 Date: 23/11/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28880267QMX
Claimant Vehicle No :	SHA971Y	Insured Vehicle No :	SJV4450Z
Date of Loss:	20/07/2017	Nature of Claim:	TP
			Claim No: 523864

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA971Y		
Make & Model:	HYUNDAI SONATA NF, 2.0 2.0 CRDI AT ABS 2WD 4DR TURBO (A)	Engine No:	HIDDEN
Reg. Date:	15/04/2010 (Man. Year: 2010)	Chassis No:	KMHET41VMAA780858
Colour:	Yellow	Odometer:	248090 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Triangle 6 mm	Rear Left Side:	Triangle 6 mm
Front Right Side:	Triangle 6 mm	Rear Right Side:	Triangle 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,110.56	4,343.94	9,766.62	69.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	2,380.00	1,620.00	40.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,110.56	6,723.94	11,386.62	62.87
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	18,110.56	2,900.00	15,210.56	83.99
+ GST 7.00/7.00% (S\$)	1,267.74	203.00	1,064.74	83.99
Nett Amount (S\$)	19,378.30	3,103.00	16,275.30	83.99

INSPECTION

Date of Assignment:	21/07/2017	
Date Inspected:	21/07/2017	Inspected At:
		Ding Automotive Pte Ltd (HQ) 31 CORPORATION ROAD Singapore 649825
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD TAUFIKH

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REGISTRATION DATE UNABLE TO TRADE:DUE TO VEHICLE DE-REGISTER

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Nov 2017)

Parts: 143 HYUNDAI SONATA NF 2.0 2.0 CRDI AT ABS 2WD 4DR TURBO (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA971Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	523.93 F	*523.93 FL
2	1	*REAR BUMPER REINFORCEMENT	Cracked	462.30 F	*462.30 FL
3	1	*REAR BUMPER RETAINER RH	Necessary	42.68 F	*42.68 FL
4	1	*REAR BUMPER RETAINER LH	Not Necessary	42.68 F	*- FL
5	1	*REAR BUMPER BRACKET RH	Deformed	79.75 F	*79.75 FL
6	1	*REAR BUMPER BRACKET LH	Not Necessary	79.75 F	*- FL
7	1	*REAR BUMPER SPONGE	Cracked	113.52 F	*113.52 FL
8	1	*REAR BUMPER PROTECTOR RH	Deformed	102.96 F	*102.96 FL
9	1	*REAR BUMPER PROTECTOR LH	Not Necessary	102.96 F	*- FL
10	1	*REAR BUMPER LOWER EXT	Not Necessary	40.70 F	*- FL
11	1	*REAR BUMPER LOWER COVER LH	Deformed	38.83 F	*38.83 FL
12	1	*BOOTLID	Repair	1,139.00 F	*- FL
13	1	*BOOTLID EMBLEM-LOGO	Necessary	21.45 F	*21.45 FL
14	1	*BOOTLID EMBLEM-HYUNDAI	Necessary	20.13 F	*20.13 FL
15	1	*BOOTLID EMBLEM-SONATA	Necessary	40.92 F	*40.92 FL
16	1	*BOOTLID EMBLEM-CRDI	Necessary	18.70 F	*18.70 FL
17	1	*BOOTLID LAMP RH	Cut	203.50 F	*203.50 FL
18	1	*BOOTLID LAMP RH	Not Necessary	203.50 F	*- FL
19	1	*BOOTLID PLATE LAMP RH	Not Necessary	49.50 F	*- FL
20	1	*BOOTLID HINGE RH	Repair	140.80 F	*- FL
21	1	*BOOTLID HINGE LH	Repair	140.80 F	*- FL
22	1	*BOOTLID LOCK	Bent	109.45 F	*109.45 FL
23	1	*BOOTLID LOCK CATCH	Not Necessary	108.90 F	*- FL
24	1	*BOOTLID INSULATOR	Not Necessary	155.10 F	*- FL
25	1	*BOOTLID RUBBER BEADING	Twisted	91.30 F	*91.30 FL
26	1	*BOOTLID DAMPER RH	Not Necessary	104.50 F	*- FL
27	1	*BOOTLID DAMPER LH	Not Necessary	104.50 F	*- FL
28	1	*END PANEL	Bent	323.29 F	*323.29 FL
29	1	*END PANEL TOP GARNISH	Deformed	42.02 F	*42.02 FL
30	1	*TAIL LAMP RH	Cracked	323.40 F	*323.40 FL
31	1	*TAIL LAMP LH	Not Necessary	323.40 F	*- FL
32	1	*TAIL LAMP INNER PANEL RH	Bent	267.30 F	*267.30 FL
33	1	*TAIL LAMP INNER PANEL LH	Not Necessary	267.30 F	*- FL
34	1	*SPARE TYRE PANEL	Not Necessary	812.90 F	*- FL
35	1	*SPARE TYRE TOP BOARD	Not Necessary	162.14 F	*- FL
36	1	*SPARE TYRE SIDE PANEL RH	Bent	179.30 F	*179.30 FL
37	1	*SPARE TYRE SIDE PANEL TRAY RH	Deformed	17.60 F	*17.60 FL
38	1	*SPARE TYRE TOOL HOLDER SPONGE	Not Necessary	27.50 F	*- FL
39	1	*REAR FENDER RH	Buckled	1,598.30 F	*1,598.30 FL
40	1	*REAR FENDER INNER SHIELD RH	Torn	31.02 F	*31.02 FL
41	1	*REAR FENDER PILLAR INNER TRIM	Not Necessary	191.62 F	*- FL
42	1	*REAR WHEEL HOUSE PANEL RH	Repair	655.49 F	*- FL
43	1	*REAR FENDER QTR GARNISH	Not Necessary	27.60 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR MUD FLAP	Missing	16.50 F	*16.50 FL
45	1		*REAR WINDSCREEN MLDG	Necessary	49.28 F	*49.28 FL
46	1		*REAR WINDSCREEN	Not Necessary	833.69 F	*- FL
47	1		*REAR SPEAKER PANEL	Repair	293.70 F	*- FL
48	1		*REAR DOOR RH	Repair	1,128.28 F	*- FL
49	1		*REAR SHOCK ABSORBER RH	Not Necessary	182.38 F	*- FL
50	1		*REAR SHOCK ABSORBER TOP MOUNTING	Not Necessary	230.36 F	*- FL
51	1		*REAR CHASSIS RH	Repair	624.58 F	*- FL
52	1		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
53	1		*REAR BUMPER RUBBER PAD PROTECTOR	Necessary	120.00 FS	*120.00 FS
54	1		*BOOTLID STICKER - CAB BOOKING 65521111	Necessary	40.00 FS	*40.00 FS
55	1		*BOOTLID STICKER-CITYCAB	Necessary	40.00 FS	*40.00 FS
56	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	35.00 FS	*- FS
57	1		*REAR NUMBER PLATE	Not Necessary	35.00 FS	*- FS
58	1		*END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
59	1		*SPARE TYRE INSULATOR PAD	Not Necessary	280.00 FS	*- FS
60	1		*SPARE TYRE PANEL SEALANT	Not Necessary	50.00 FS	*- FS
61	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
62	1		*REAR WINDSCREEN TINTED	Not Necessary	200.00 FS	*- FS
63	1		*REAR WINDSCREEN INNER SEAL	Necessary	30.00 FS	*30.00 FS
64	1		*REAR DOOR STICKER-65521111	Necessary	40.00 FS	*40.00 FS
65	1		*BOOTLID PLATE LAMP LH	Not Necessary	49.50 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **14,110.56** **5,287.43**
 - List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 943.49

Total Parts (\$\$) **14,110.56** **4,343.94**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR, REPLACE & REALIGN DAMAGE AREAS	New	1,500.00	1,000.00
2	TO STRAIGHTEN REAR CHASSIS MEMBER RH	New	300.00	0.00
3	TO REMOVE AND REFIT REAR BUMPER REVERSE SENSOR	New	60.00	30.00
4	TO CHECK WIRING AND LIGHTING SYSTEM	New	60.00	30.00
5	TO REMOVE AND REFIT REAR WINDSCREEN	New	200.00	0.00
6	TO REMOVE AND REPLACE UNDERCARRIAGE NECESSARY PARTS	New	200.00	0.00
7	TO REMOVE AND REFIT REAR SEAT COMPENENT	New	100.00	60.00
8	TOWING FEE	New	80.00	60.00
9	TO SPRAY PAINT ON BOOTLID	New	250.00	200.00
10	TO SPRAY PAINT ON END PANEL	New	250.00	200.00
11	TO SPRAY PAINT ON REAR FENDER	New	250.00	200.00
12	TO SPRAY PAINT ON SPARE TYRE PANEL	New	250.00	200.00
13	TO SPRAY PAINT ON RH DOOR	New	250.00	200.00
14	TO SPRAY PAINT ON SPEAKER PANEL	New	250.00	200.00
Gross Labour Cost (S\$)			4,000.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >