

ASS. REC. BY:

REF: CS / TCU17014536 / Grb02

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): CWS Aung Yin Min of 7C1 Date/Time: 27/07/2017 2:35pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJU 866P Insured: SHB 2384Z

at Workshop m/s K Kim Hin Tel: 6452 7018

of 160 Sin Ming Drive # 03-20

Policy No: Claim No: D17007273MTSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 22/07/2017

CA / REV / REP. / REV 24 HRS Wp: 03-08-2017 @ 3pm H.O.D. Endorsement:

Date/Time: 27/07/2017 2:58pm Person Contacted: Shuman Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJU 866P - CA / MAX 16005953 / Tly63 Dep: 11-11-15
	SHB 2384Z - CA / ATG 09009063 / Wl Dep: 25/04/09
	Confirm LIS \$5750, 5 days
	Red: \$ 4694.10, 45%





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17014536/Grb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 27-07-2017	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHB 2384Z	Veh. Inspected	SJU 866P
Policy No.		Coverage (\$)	0.00
Claim No.	D17007273MFSH	Excess (\$)	0.00
Assign From	CWS (AUNG YIN MIN)	Assign Date	27/07/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	22/07/2017	Inspection Date	
Survey held at	160 SIN MING DRIVE #02-20		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	25-07-2017	<b>Our Ref No.</b> D17007273MFSH
<b>Accident Date</b>	22-07-2017	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHB2384Z	<b>Third Party Vehicle.</b> SJU866P
<b>Survey Location</b>	160 Sin Ming Drive #02-20SIN MING AUTOCITY	
<b>Contact Person.</b>	SANDRA	
<b>Contact No.</b>	64527018/ 96222116	<b>Fax No.</b> 0
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

## THIRD PARTY SURVEY REQUEST

<b>Cc : Workshop</b>	K. KIM HIN AUTO PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	AUNGYM	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/226143)  **PRI Documents**  **Close** 

**PRI Header Details**

<b>Claim No</b>	D17007273MFSH	<b>Policy No</b>	D-15072702MFSH	<b>Claimant S.No &amp; Name</b>	1 & K.
<b>Workshop Name</b>	K. KIM HIN AUTO PTE LTD (Contact Person : SANDRA)	<b>Survey Location &amp; Contact Details</b>	160 Sin Ming Drive #02-20SIN MING AUTOCIT <b>Mobile:</b> 96222116 , <b>Phone:</b> 64527018 , <b>Fax:</b> <b>EmailId:</b> SERVICE@KKIMHIN.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE:		
<b>Insured Name</b>	CITYCAB PTE LTD	<b>Insured Vehicle No</b>	SHB2384Z	<b>TP Vehicle No</b>	SJU866
<b>PRI Recieved Date</b>	25-07-2017 08:56:48 PM	<b>Surveyor Appointed Date</b>	27-07-2017 02:35:12 PM	<b>Surveyor Accept Date</b>	27-07-

**Survey Report Upload**

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	27-07-2017	<b>Upload Survey Report *:</b>	<input type="text"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

**Vehicle Particulars**

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

**Multiple Documents Upload**

File Name	Action
-----------	--------

**Surveyor Job Remarks**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 8808I

### Vehicle Details

Vehicle No.: SJU866P

Vehicle to be Exported: Yes

Intended De-registration Date: 24 Jul 2017

Vehicle Make: VOLVO

Vehicle Model: S60 2.4 T5 AUTO ABS AIRBAG

Primary Colour: Blue

Manufacturing Year: 2008

Engine No.: B5244T4320864

Chassis No.: YV1RS544992727213

Maximum Power Output: 191.0 kW (256 bhp)

Open Market Value: \$39,212.00

Original Registration Date: 28 Sep 2009

First Registration Date: 28 Sep 2009

Transfer Count: 1

Actual ARF Paid: \$39,212.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Sep 2019

PARF Rebate Amount: \$23,527.00

### Intended COE Rebate Details

COE Expiry Date: 27 Sep 2019

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$18,189.00

COE Rebate Amount: \$3,956.00

**Total Rebate Amount: \$27,483.00**

The information contained herein is correct as at 24 Jul 2017

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).

Please do not use the [Back](#) or [Forward](#) buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 16 Jul 2017 at 12:47 AM

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-18/19/20/21,  
 Sin Ming AutoCity, Singapore 575722  
 Tel: 6452 7018 Fax: 6458 3895  
 Email: service@kkimhin.com.sg

No. : 29032

Vehicle Insured : SHB 2384 Z  
 Accident Date : 22-Jul-2017

Date : 26-Jul-2017

Our Ref : 170526 (FIRST) / SHUMAN

PAGE : 1

NAZIR BIN HUSSIN (MR)  
 Singapore

ESTIMATED COST OF REPAIR FOR VOLVO S60 2.4 T5 AUTO ABS (2009) SJU866P

1 pc	o/s front door	X Repair		2,649.00	X
1 pc	o/s front door protector-top	-	MC	348.00	/
1 pc	o/s front door weatherstrip	X	NV	345.00	X
1 pc	o/s front door protector-lower	-	MC	243.00	/
1 pc	o/s rear door	-	Buc	2,410.00	/
1 pc	o/s rear door protector-top	-		348.00	/
1 pc	o/s rear door weatherstrip	-	MC	320.00	/
1 pc	o/s rear door protector-lower	-		243.00	/
1 pc	o/s rear sport rim 18"	-	Cut	1,752.00	/
1 pc	o/s rear wheel bearing	-	MC	491.00	/
				-----	
				9,149.00	6155
			Less 10% :	-914.90	5539.5
				-----	8,234.10

1 pc o/s rear tyre 18" - Cut. (-30%) 450.00 sn 315

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts. 400 540.00

To remove door's fittings 60 160.00

To putty and respray on affected portions. 800 900.00

To conduct front wheel alignment test. 60 80.00

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-18/19/20/21,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

Vehicle Insured : SHB 2384 Z  
Our Ref : 170526

Page : 2  
No. : 29032

Remove and press bearing.

1370

50 ~~40~~ 80.00

Total : S\$10,444.10  
=====

Singapore Dollars Ten Thousand Four Hundred and  
Forty Four and Cents Ten Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

5 Days.

lump sum repair

After repair photos.

Guo Qiang - 82880282

03/8/17.

7224.5

20%: 5750

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17014536/Grbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2384Z	Veh. Inspected	SJU 866P
Policy No.	D-15072702MFSH	Coverage (\$)	0.00
Claim No.	D17007273MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	27/07/2017
2. Vehicle Particulars & Condition			
Make & Model	VOLVO S60	c.c	2401
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	YV1RS544992727213	Colour	BLUE
Odometer	137666	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/40 R18	FIRESTONE	7 mm
L/H Front Tyre	235/40 R18	FIRESTONE	7 mm
R/H Rear Tyre	235/40 R18	FIRESTONE	7 mm
L/H Rear Tyre	235/40 R18	FIRESTONE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/07/2017	Inspection Date	03/08/2017
Survey held at	160 SIN MING DRIVE #02-20		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 866P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	O/S FRONT DOOR	TO REPAIR SEE LABOUR	2,649.00	-
1	O/S FRONT DOOR PROTECTOR-TOP	NECESSARY	348.00	348.00
1	O/S FRONT DOOR WEATHERSTRIP	NOT NECESSARY	345.00	-
1	O/S FRONT DOOR PROTECTOR-LOWER	NECESSARY	243.00	243.00
1	O/S REAR DOOR	BUCKLED	2,410.00	2,410.00
1	O/S REAR DOOR PROTECTOR-TOP	NECESSARY	348.00	348.00
1	O/S REAR DOOR WEATHERSTRIP	NECESSARY	320.00	320.00
1	O/S REAR DOOR PROTECTOR-LOWER	NECESSARY	243.00	243.00
1	O/S REAR SPORT RIM 18"	CUT	1,752.00	1,752.00
1	O/S REAR WHEEL BEARING	NECESSARY	491.00	491.00
	LESS 10% DISCOUNT		-914.90	-615.50
			<b>8,234.10</b>	<b>5,539.50</b>
<b>SPECIAL NETT ITEMS</b>				
1	O/S REAR TYRE 18" (70%)(SN)	CUT	450.00	315.00
			450.00	315.00
<b>LABOUR</b>				
	TO REMOVE,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF O/S FRONT DOOR.		540.00	400.00
	TO REMOVE DOOR'S FITTINGS.		160.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		900.00	800.00
	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.		80.00	60.00
	REMOVE AND PRESS BEARING.		80.00	50.00
	-		-	-
	-		-	-
	-		-	-
			<b>1,760.00</b>	<b>1,370.00</b>
<b>GRAND TOTAL</b>			<b>10,444.10</b>	<b>7,224.50</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,750.00
---	--	--	----------

Report Ref No. CS/FCI17014536/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.