

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1, Kaki Bukit Avenue 4 #01-01 Auto Eng. & Kaki Bukit Singapore 417002

MOBILE: 97291501 / Tel: 674 6750 / 771 / Fax: 674 6750 Email: liubro@com.com

Invoice/Ref No: GZ7619A170627

Estimate**Customer**

Name: India International Insurance Pte Ltd
 Address: Motor Claims Department
 64 Cecil Street #04-00 & #05-00
 IOB Building, Singapore 049711

Date: 28-07-17
 Vehicle No: GZ7619A
 Model/Make: Mitsubishi
 L300 HR M

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper	\$ 453.00	X
2	Bumper Side Lh	\$ 235.00	X
3	Bumper Side Bracket 02 pcs (@ \$98.00)	\$ 196.00	X
4	Bumper Reflector 02 pcs (@ \$146.00)	\$ 292.00	X
5	Tail Lamp Lh	\$ 220.00	SN X
6	"Corporate" Advertisement Sticker	\$ 250.00	SN X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc.	\$ 1,000.00	- 250
	To putty & spray painting & including touch up paint on accident affected areas	\$ 800.00	- 200
	To check all wiring & electrical component for proper function	\$ 50.00	-

Total Parts & Labour of estimate for damaged vehicle

\$ 3,496.00

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Acknt
 LKK
 take photo after rep in
 31/7/17
 P/P @ 450
 2 Jy.