

22/03/2012

ASS. REC. BY:

REF: CS / FCL17014748 / Dqbn2

Special Instruction:

Summary: Brian

**ASSIGNMENT (Office)**

From (Person): LWS May Chua of FCL Date/Time: 31/07/2017 5:30pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJA 8975K Insured: SH 6548E

at Workshop m/s Teamwork Tel: 6814 2475

of 53 Ubi Ave 1 #01-24

Policy No: Claim No: D17007405MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 28/07/2017  
(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time: 31/07/2017 3:18pm Person Contacted: Chris Vehicle: IN/OUT

| Date/Time | Action/Instruction (✓) Estimate               |
|-----------|-----------------------------------------------|
|           | SJA 8975K - NA / INC 17014565 / 114 28/07/17  |
|           | SH 6548E - CS / FCL16013648 / Avb3d1 28/07/16 |
|           |                                               |
|           |                                               |
|           |                                               |
|           |                                               |

SINGAPORE

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: \$10500

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: 85A 8975 K Yr Regn: 2007 / DecType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Airwave C.C. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading 175050 T/Radio: Insured / Std / NI / NAEng/No: L15A5155324C/No: G311204466Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/55 R15R: 11-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 28/07/2017 D.O.I. 31/07/2017Survey held at Teamwork Paya Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

FCI SH 6548 E

MV 10.5K

LTA 7.5K

HL 2.5K

14/12/17 Finan 2/5 21001 - with 2 days 2 hrs.  
(Red: 1105.97, 77%).

MV: \$10500, LTA: \$7527, NV: \$2973

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 2

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee:

Transportation:

2)

Add Fee:

☐ Site Insp (\$)

) S + RS. SI

☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

TOTAL

Report Format: TPLump Sum / I.B.I. (\$ 2100)

170

50

50+50

40

360

RECEIVED 14 DEC 2017



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17014748/Dgb

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 31-07-2017



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SH 6548E       | Veh. Inspected | SJA 8975K  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | D17007405MFSH  | Excess (\$)    | 0.00       |
| Assign From  | CWS (MAY CHUA) | Assign Date    | 31/07/2017 |

### 2. Vehicle Particulars & Condition

|              |        |              |
|--------------|--------|--------------|
| Make & Model | c.c    | 0            |
| Engine No.   | HIDDEN | Year of Reg. |
| Chassis No.  |        | Colour       |
| Odometer     | -      | Steering     |
| Brakes       |        | Modification |
| General      |        |              |

### 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

### 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

### 5. General Information

|                |                                                                           |                 |            |
|----------------|---------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 28/07/2017                                                                | Inspection Date | 31/07/2017 |
| Survey held at | TEAMWORK GARAGE PTE LTD<br>53 UBI AVENUE 1<br>#01-24<br>SINGAPORE 408934. |                 |            |

### 5a. Remarks

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

# First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

## MOTOR SURVEY ASSIGNMENT

|                           |                                                  |                                      |
|---------------------------|--------------------------------------------------|--------------------------------------|
| <b>Date</b>               | 31-07-2017                                       | <b>Our Ref No.</b> D17007405MFSH     |
| <b>Accident Date</b>      | 28-07-2017                                       | <b>Claim Type.</b> Third Party       |
| <b>Insured Vehicle</b>    | SH6548E                                          | <b>Third Party Vehicle.</b> SJA8975K |
| <b>Survey Location</b>    | BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL PARK |                                      |
| <b>Contact Person.</b>    | DARREN NG                                        |                                      |
| <b>Contact No.</b>        | 68442475/ 0                                      | <b>Fax No.</b> 68442474              |
| <b>Survey Type</b>        | WITHOUT PREJUDICE:                               |                                      |
| <b>Appointed Surveyor</b> | LKK AUTO CONSULTANTS PTE LTD                     |                                      |
| <b>Contact Person</b>     | NA                                               | <b>Fax No.</b> 68416315              |
| <b>Contact Number.</b>    | NA                                               |                                      |

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

### THIRD PARTY SURVEY REQUEST

|                          |                            |                                |
|--------------------------|----------------------------|--------------------------------|
| <b>Cc : Workshop</b>     | TEAMWORK GARAGE<br>PTE LTD | <b>Attention.</b> NIL          |
| <b>Cc : TP Solicitor</b> | NA                         | <b>TP Solicitor Fax No.</b> NA |
| <b>Officer Incharge</b>  | MAY CHUA                   |                                |

## IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/226328)



PRI Documents



Close



## PRI Header Details

|                          |                                                         |                                              |                                                                                                                                                             |                                 |         |
|--------------------------|---------------------------------------------------------|----------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|---------|
| <b>Claim No</b>          | D17007405MFSH                                           | <b>Policy No</b>                             | D-15072701MFSH                                                                                                                                              | <b>Claimant S.No &amp; Name</b> | 1 & TE/ |
| <b>Workshop Name</b>     | TEAMWORK GARAGE PTE LTD<br>(Contact Person : DARREN NG) | <b>Survey Location &amp; Contact Details</b> | BLK 53 UBI AVE 1 #01-24 PAYA UBI INDUSTRIAL<br><b>Mobile:</b> 0 , <b>Phone:</b> 68442475 , <b>Fax:</b> 6844247<br><b>EmailId:</b> CLAIMS@TEAMWORKGARAGE.COM |                                 |         |
| <b>Our Surveyor</b>      | LKK AUTO CONSULTANTS PTE LTD                            | <b>Instructions To Surveyor</b>              | WITHOUT PREJUDICE:                                                                                                                                          |                                 |         |
| <b>Insured Name</b>      | COMFORT TRANSPORTATION PTE LTD                          | <b>Insured Vehicle No</b>                    | SH6548E                                                                                                                                                     | <b>TP Vehicle No</b>            | SJA897  |
| <b>PRI Recieved Date</b> | 31-07-2017 06:12:57 PM                                  | <b>Surveyor Appointed Date</b>               | 31-07-2017 05:13:23 PM                                                                                                                                      | <b>Surveyor Accept Date</b>     | 31-07-  |

## Survey Report Upload

|                                    |                      |                             |            |                                |                      |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|----------------------|
| <b>Surveyor Inspection Date *:</b> | <input type="text"/> | <b>Surveyor Report Date</b> | 31-07-2017 | <b>Upload Survey Report *:</b> | <input type="text"/> |
|------------------------------------|----------------------|-----------------------------|------------|--------------------------------|----------------------|

## Vehicle Particulars

|                  |                                                 |                       |                                                  |                |                                     |
|------------------|-------------------------------------------------|-----------------------|--------------------------------------------------|----------------|-------------------------------------|
| <b>Make</b>      | <input type="text" value="Please Select Make"/> | <b>Model</b>          | <input type="text" value="Please Select Model"/> | <b>Year</b>    | <input type="text" value="Select"/> |
| <b>Chasis No</b> | <input type="text"/>                            | <b>Engine No</b>      | <input type="text"/>                             | <b>Mileage</b> | <input type="text"/>                |
| <b>Color</b>     | <input type="text"/>                            | <b>Cubic Capacity</b> | <input type="text"/>                             |                |                                     |

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|               |          |
|---------------|----------|
| Owner ID Type | Business |
| Owner ID      | 8297X    |

### Vehicle Details

|                               |                   |
|-------------------------------|-------------------|
| Vehicle No.                   | SJA8975K          |
| Vehicle to be Exported        | No                |
| Intended De-registration Date | 16 Oct 2017       |
| Vehicle Make                  | HONDA             |
| Vehicle Model                 | AIRWAVE 1.5M A    |
| Primary Colour                | Black             |
| Manufacturing Year            | 2007              |
| Engine No.                    | L15A5155324       |
| Chassis No.                   | GJ11204466        |
| Maximum Power Output          | 81.0 kW (108 bhp) |
| Open Market Value             | \$13,200.00       |
| Original Registration Date    | 26 Dec 2007       |
| First Registration Date       | 26 Dec 2007       |
| Transfer Count                | 1                 |
| Actual ARF Paid               | \$14,520.00       |

### Intended PARF Rebate Details

|                              |             |
|------------------------------|-------------|
| PARF Eligibility             | Yes         |
| PARF Eligibility Expiry Date | 25 Dec 2017 |
| PARF Rebate Amount           | \$7,260.00  |

### Intended COE Rebate Details

|                            |                          |
|----------------------------|--------------------------|
| COE Expiry Date            | 25 Dec 2017              |
| COE Category               | A - Car (1600cc & below) |
| COE Period(Years)          | 10                       |
| QP Paid                    | \$14,001.00              |
| COE Rebate Amount          | \$267.00                 |
| <b>Total Rebate Amount</b> | <b>\$7,527.00</b>        |

The information contained herein is correct as at 16 Oct 2017

OK



Please read through the Privacy Statement, Terms of Use, and Disclaimer.  
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

First Capital Insurance Ltd  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877

## 3RD PARTY CLAIM ESTIMATION

Vehicle number : SJA8975K  
 Make / Model : HONDA/AIRWAVE  
 Chassis number : GJ11204466  
 Accident date : 28 July 2017  
 Reference : 1707-44

Qty Particulars Unit Price - SGD \$

| PARTS REPLACEMENT - LIST ITEMS         |                                           |             |
|----------------------------------------|-------------------------------------------|-------------|
| 1                                      | FRONT BUMPER <i>Dental</i>                | 1255.90 ✓   |
| 2                                      | FRONT BUMPER RETAINER <i>svu</i>          | 150.80 x    |
| 1                                      | FRONT BUMPER LOWER GRILLE <i>HN</i>       | 232.10 x    |
| 1                                      | FRONT BUMPER REINFORCEMENT <i>HN</i>      | 330.22 x    |
| 2                                      | FRONT BUMPER COVER <i>HN</i>              | 310.20 x    |
| 1                                      | AIRCON CONDENSER <i>HN</i>                | 1082.00 x   |
| 1                                      | AIR RESONATOR <i>HN</i>                   | 213.50 x    |
| 1                                      | FRONT LH FENDER INNER SHIELD <i>svu</i>   | 149.21 x    |
| 1                                      | FRONT GRILLE <i>HN</i>                    | 401.30 x    |
| 1                                      | FRONT LH HEADLAMP <i>Wale</i>             | 868.30 ✓    |
| 1                                      | FRONT LH HEADLAMP BRACKET <i>crack</i>    | 65.30 ✓     |
| 1                                      | FRONT LH KNUCKLE ARM <i>HN</i>            | 590.40 x    |
| 1                                      | FRONT LH KNUCKLE BEARING <i>HN</i>        | 193.10 x    |
| 1                                      | FRONT LH LOWER ARM <i>HN</i>              | 410.60 x    |
| 1                                      | FRONT LH SHOCK ABSORBER <i>HN</i>         | 792.10 x    |
|                                        |                                           | 2189.50     |
|                                        |                                           | 1751.60     |
|                                        |                                           | 7045.03     |
|                                        |                                           | Less 20%    |
|                                        |                                           | 1409.06     |
|                                        |                                           | Subtotal    |
|                                        |                                           | 5635.97     |
|                                        |                                           | Balance C/F |
|                                        |                                           | 5635.97     |
| PARTS REPLACEMENT - SPECIAL NETT ITEMS |                                           |             |
|                                        |                                           | Balance B/F |
|                                        |                                           | 5635.97     |
| 1                                      | FRONT NUMBER PLATE <i>HN</i>              | 70.00 x     |
| 1 SET                                  | FRONT BUMPER CLIP <i>HN</i>               | 70.00 30/-  |
| 1 SET                                  | FRONT FENDER INNER SHIELD CLIP <i>svu</i> | 60.00 x     |
| 1                                      | RIM <i>HN</i>                             | 800.00 x    |
| 1                                      | BRAKE FULD <i>HN</i>                      | 60.00 x     |
|                                        |                                           | 30/-        |
|                                        |                                           | Subtotal    |
|                                        |                                           | 1060.00     |
|                                        |                                           | Balance C/F |
|                                        |                                           | 6695.97     |
| LABOUR AND MISCELLANEOUS CHARGES       |                                           |             |
|                                        |                                           | Balance B/F |
|                                        |                                           | 6695.97     |
| 1                                      | CHECK FRONT WIRING AND LIGHTNING SYSTEM   | 60.00 30/-  |

Vehicle number : SJA8975K

Make Model : HONDA/AIRWAVE

Reference : 1707-44

| S/No              | Particulars                               | Unit Price - SGD \$        |
|-------------------|-------------------------------------------|----------------------------|
| 2                 | REMOVE AND RENEW CONDENSER AND TOP UP GAS | 150.00 <del>RM</del>       |
| 3                 | CHECK FRONT WHEEL ALIGNMENT               | 150.00 <del>RM</del>       |
| 4                 | REMOVE AND REPLACE FRONT WHEEL ALIGNMENT  | 200.00 <del>RM</del>       |
| 5                 | PANEL BEATING ON AFFECTED AREAS           | <del>1000.00</del> 400/-   |
| 6                 | SPRAY PAINTING ON AFFECTED AREAS          | <del>800.00</del> 400/-    |
| 7                 | APPLY ANTI RUST ON AFFECTED AREAS         | <del>150.00</del> 40/-     |
| Subtotal          |                                           | 2510.00                    |
| Grand total       |                                           | <del>9205.97</del> 9206.02 |
| 31/07/2017 @ 1500 |                                           | 2651.60                    |
| Not Authorised    |                                           | 1/52100/-                  |
| 21/8/2017         |                                           |                            |
| 2 KIC Auto        |                                           |                            |
| 2 dg              |                                           |                            |
| Check MV          |                                           | Repair Unit.               |
| Check part        |                                           |                            |
| prices.           |                                           |                            |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer.

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                           |                            |            |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|----------------------------|------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                           | Ref : CS/FCI17014748/Dgbn2 |            |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                           | Date : 21-12-2017          |            |  |
|                                                                                                                                                                                        |                                                                           | Code : FCI2                |            |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                           |                            |            |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SH 6548E                                                                  | Veh. Inspected             | SJA 8975K  |                                                                                     |
| Policy No.                                                                                                                                                                             | D-15072701MFSH                                                            | Coverage (\$)              | 0.00       |                                                                                     |
| Claim No.                                                                                                                                                                              | D17007405MFSH                                                             | Excess (\$)                | 0.00       |                                                                                     |
| Assign From                                                                                                                                                                            | MAY CHUA                                                                  | Assign Date                | 31/07/2017 |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                           |                            |            |                                                                                     |
| Make & Model                                                                                                                                                                           | HONDA AIRWAVE                                                             | c.c                        | 1496       |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                    | Year of Reg.               | 2007       |                                                                                     |
| Chassis No.                                                                                                                                                                            | GJ11204466                                                                | Colour                     | BLACK      |                                                                                     |
| Odometer                                                                                                                                                                               | 175050                                                                    | Steering                   | IN ORDER   |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                  | Modification               | SPORTS RIM |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                      |                            |            |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                           |                            |            |                                                                                     |
|                                                                                                                                                                                        | Size                                                                      | Make                       | Balance    |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 195/55 R15                                                                | HANKOOK                    | 5 mm       |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 195/55 R15                                                                | HANKOOK                    | 5 mm       |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 195/55 R15                                                                | HANKOOK                    | 5 mm       |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 195/55 R15                                                                | HANKOOK                    | 5 mm       |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                           |                            |            |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.<br>DAMAGES SEE DETAILS.                                                                                                        |                                                                           |                            |            |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                           |                            |            |                                                                                     |
| Accident Date                                                                                                                                                                          | 28/07/2017                                                                | Inspection Date            | 31/07/2017 |                                                                                     |
| Survey held at                                                                                                                                                                         | TEAMWORK GARAGE PTE LTD<br>53 UBI AVENUE 1<br>#01-24<br>SINGAPORE 408934. |                            |            |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                           |                            |            |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                           |                            |            |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                           |                            |            |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                           | 2 Working Days             |            |                                                                                     |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJA 8975K

| Qty                         | Description of Parts                       | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                            |               |                           |                   |
| 1                           | FRONT BUMPER                               | DENTED        | 1,255.90                  | 1,255.90          |
| 2                           | FRONT BUMPER RETAINER                      | SERVICEABLE   | 150.80                    | -                 |
| 1                           | FRONT BUMPER LOWER GRILLE                  | NOT NECESSARY | 232.10                    | -                 |
| 1                           | FRONT BUMPER REINFORCEMENT                 | NOT NECESSARY | 330.22                    | -                 |
| 2                           | FRONT BUMPER COVER                         | NOT NECESSARY | 310.20                    | -                 |
| 1                           | AIRCON CONDENSER                           | NOT NECESSARY | 1,082.00                  | -                 |
| 1                           | AIR RESONATOR                              | NOT NECESSARY | 213.50                    | -                 |
| 1                           | FRONT LH FENDER INNER SHIELD               | SERVICEABLE   | 149.21                    | -                 |
| 1                           | FRONT GRILLE                               | NOT NECESSARY | 401.30                    | -                 |
| 1                           | FRONT LH HEADLAMP                          | CRACKED       | 868.30                    | 868.30            |
| 1                           | FRONT LH HEADLAMP BRACKET                  | CRACKED       | 65.30                     | 65.30             |
| 1                           | FRONT LH KNUCKLE ARM                       | NOT NECESSARY | 590.40                    | -                 |
| 1                           | FRONT LH KNUCKLE BEARING                   | NOT NECESSARY | 193.10                    | -                 |
| 1                           | FRONT LH LOWER ARM                         | NOT NECESSARY | 410.60                    | -                 |
| 1                           | FRONT LH SHOCK ABSORBER                    | NOT NECESSARY | 792.10                    | -                 |
|                             | LESS 20% DISCOUNT                          |               | -1,409.01                 | -437.90           |
|                             |                                            |               | 5,636.02                  | 1,751.60          |
| <b>SPECIAL NETT ITEMS</b>   |                                            |               |                           |                   |
| 1                           | FRONT NUMBER PLATE (SN)                    | NOT NECESSARY | 70.00                     | -                 |
| 1                           | SET FRONT BUMPER CLIP (SN)                 | NECESSARY     | 70.00                     | 30.00             |
| 1                           | SET FRONT FENDER INNER SHIELD CLIP (SN)    | SERVICEABLE   | 60.00                     | -                 |
| 1                           | RIM (SN)                                   | NOT NECESSARY | 800.00                    | -                 |
| 1                           | BRAKE FLUID (SN)                           | NOT NECESSARY | 60.00                     | -                 |
|                             |                                            |               | 1,060.00                  | 30.00             |
| <b>LABOUR</b>               |                                            |               |                           |                   |
|                             | CHECK FRONT WIRING AND LIGHTING SYSTEM.    |               | 60.00                     | 30.00             |
|                             | REMOVE AND RENEW CONDENSER AND TOP UP GAS. | NOT NECESSARY | 150.00                    | -                 |
|                             | CHECK FRONT WHEEL ALIGNMENT.               | NOT NECESSARY | 150.00                    | -                 |
|                             | REMOVE AND REPLACE FRONT WHEEL ALIGNMENT.  | NOT NECESSARY | 200.00                    | -                 |
|                             | PANEL BEATING ON AFFECTED AREAS.           |               | 1,000.00                  | 400.00            |

Report Ref No. CS/FCI17014748/Dgbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                     | Description of Parts               | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-------------------------------------------------------------------------|------------------------------------|-----------|---------------------------|-------------------|
|                                                                         | SPRAY PAINTING ON AFFECTED AREAS.  |           | 800.00                    | 400.00            |
|                                                                         | APPLY ANTI RUST ON AFFECTED AREAS. |           | 150.00                    | 40.00             |
|                                                                         |                                    |           | 2,510.00                  | 870.00            |
| GRAND TOTAL                                                             |                                    |           | 9,206.02                  | 2,651.60          |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |                                    |           |                           | 2,100.00          |

Report Ref No. CS/FCI17014748/Dgbn2

MARKET VALUE: \$10,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$7,527.00=NETT VALUE: \$2,973.00

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.