

12/03/2017

ASS. REC. BY:

REF:

CS/CT17015079/ST 69

Special Instruction:

SURVIVAL

ASSIGNMENT (Office)From (Person): Joel Cuh of CT1 Date/Time: 03/08/2017 932am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: STR 4201X Insured: SJJ 1248Aat Workshop m/s Trans Tempkars Tel: 63357874of 5 Ubi ClosePolicy No: DMHCSN 1670641600 Claim No: SNM 17 D04504C02/ 8

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 27/07/2017
(Client's Record)CA / REV / REP. / REV 24 HRS up

H.O.D. Endorsement: _____

Date/Time: 03/08/2017 11:15 am Person Contacted: Jess Vehicle IN/OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>STR 4201X - x</u>
	<u>SJJ 1248A - x</u>
	<u>Part by Part \$3,410.23 (Red: 30 49.92; 47%)</u>

0655c

Singer

Veh No: SG 4 4201 X Yr Regn: 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 C.C. 1476

Colour Red. A/C: Insured / Std / NI / NA

Sp. Reading 1492 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN 22A 814016 43

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 3 mm L/Bal. 3 mm

DOA 27/2/2017 D.O.I. 7/8/2017

Survey held at Trans Eurocars Ubi.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

☐: Prelim. Report
☒: Final Report

Days Of Repair: 3

Resurvey No. of Trip: | Survey Fee:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$) \$ + RS \$ SI☐ Interview (\$) Photos

Tech. Invs (\$) Others

☐ Weekend (\$_____)

TOTAL

Report Format :

Lump Sum / (B): (\$3410.23)

RECEIVED 2011 2010



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI17015029/b

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 03-08-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJJ 1248A	Veh. Inspected	SGY 4201X
Policy No.	DMHCSN1670641600	Coverage (\$)	0.00
Claim No.	SNM17D04504C02/8	Excess (\$)	0.00
Assign From	MERIMEN (JOEL GOH)	Assign Date	03/08/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

5. General Information

Accident Date 27/07/2017 Inspection Date

Survey held at TRANS EUROKARS PTE LTD
NO 5 UBI CLOSE
SINGAPORE 408605

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Aug 2017		03 Aug 2017 09:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: EMILYNE SIM POH AI									
Vehicle Reg. No.: SGY4201X									
Claim Type: TP / SNM17D04504C02/8									
Vehicle Reg. No. (Insured): SJJ1248A									
Date of Loss: 27/07/2017 00:00 - :59									
Policy/Cover Note No.: DMHCSN1670641600									
Policy No. (Claimant):									
Excess: S\$0.00									
Repairer: Trans Eurokars Pte Ltd () NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/08/2017]									
Adj Asg. Remarks: ESTIMATES AS ATTACHED. SELECTED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/07/2017 17:04
Date Of Accident	27/07/2017 14:45
Exact Location Of Accident	COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY4201X
Insured/Policyholder	
Name Of Registered Owner	EMILYNE SIM POH AI
NRIC No	S7000655C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97642280
Alternative Phone No	OTHERS-98890053

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100510908
Cover Note Number	

Driver

Name of Driver	D'SILVA CHARLES
NRIC No	S6812823D
Date Of Birth	04/05/1968
Occupation	INDOOR
Date Of Driving Pass	09/07/2007
Driving Experience	10 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98890053
Fax Number	
Contact Number	
EMail Address	PACIFICA68@HOTMAIL.COM

Address	BLK 144 LOR 2 TOA PAYOH #13-208
Postcode	310144
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	SUNNY
Road Surface	GOOD

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ1248A
Vehicle Make/Model/Colour	HONDA JAZZ
Details Of Properties	
Name of Driver	MOHAMMAD FAIROOZ BIN JUPRI
NRIC/Passport Number	S8323661B
Contact Number	96206255
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT, NO VISIBLE DAMAGE
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

CAME TO A COMPLETE STOP AT TRAFFIC LIGHT JUNCTION
AT COMMONWEALTH AVE WEST. LIGHTS WERE RED.
THE SAID VEHICLE SJJ 1248A BANG INTO THE
REAR OF MY CAR.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Irene Cher (Mazda)

From: Kenneth Lee <kennethlee123kc@yahoo.com>
Sent: Monday, August 7, 2017 2:00 PM
To: Mazda Service Booking
Subject: Re: Booking for vehicle servicing

To Mazda Service Centre

Dear Sir / Madam,

Re: Servicing for 110,000 km

I wish to make a booking to service my vehicle at Mazda (Ubi) Service Centre on 17 Aug 2017 at 9.00am with details as follows:

Nric no. S1502737A
Name: Kenneth Lee
Contact no. H/p. 96650480
Mileage (present) : 109,500 km

Vehicle no. SJK 8635 P
Model : Mazda 6
Registration year : 2008

Looking forward to your confirmation and advice regarding above mentioned booking of service.

B/rgds.

Kenneth Lee
(H/p. 96650480)



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
QUOTATION



CHINA TAIPING INSURANCE P/L		NAME : Ms Emilyne Sim Poh Ai	WIP : 24004
3 ANSON ROAD		ADDRESS : Blk 144 Lorong 2 Toa Payoh	EXCESS :
#16-00 SPRINGLEAF TOWER		#13-206	DATE: 29-Jul-17
SINGAPORE 079909		Singapore 310144	
ATTN. :	MOTOR CLAIMS	TEL : 97642280	
FAX :			

VEH NO :	SGY4201X	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6BN22A8H0164731	MILEAGE :	1490	TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L SDN	DATE REG.:	28-Jun-17	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO		QTY		REVISED	PRICES
1	REAR BUMPER ✓ m	1	MBHN1-50-221ABB	✓	\$ 1,074.80
2	RETAINER(LHS), REAR BUMPER x 7	1	MBHN1-50-2J1A		\$ 36.10
3	RETAINER(RHS), REAR BUMPER x	1	MBHN1-50-2H1A		\$ 36.10
4	BRACKET(LHS), REAR BUMPER x m	1	MBHN9-51-077B		\$ 45.60
5	BRACKET(RHS), REAR BUMPER x	1	MBHN9-51-067B		\$ 45.60
6	REFLECTOR(LHS) T m	1	MD350-51-5LDE		\$ 50.40
7	REFLECTOR(RHS) x m	1	MD350-51-5MOE		\$ 50.40
8	COVER(LHS), TOWING x m	1	MBHN1-50-EL1 BB		\$ 15.70
9	COVER(RHS), TOWING x m	1	MBHN1-50-EK1 BB		\$ 16.20
10	REAR REINFORCEMENT 7 DT	1	MB45A-50-260	✓	\$ 537.30
11	GROMMET, REAR BUMPER ✓ NEC	4	MBHN1-50-0Z1A	✓	\$ 10.00
12	GROMMET, REAR BUMPER ✓ NEC	1	M9991-00-501	✓	\$ 2.80
13	FASTENER, REAR BUMPER ✓ NEC	4	MB45A-56-146A	✓	\$ 11.20
14	RIVET, REAR BUMPER ✓ NEC	4	MBBM4-50-355	✓	\$ 16.80
15	BRACKET CENTER, REAR BUMPER x m	1	MKD53-50-251		\$ 5.10
16	GASKET(LHS), TAILLAMP ✓ NEC	1	MBHN1-51-163	✓	\$ 20.90
17	GASKET(RHS), TAILLAMP ✓ NEC	1	MBHN1-51-153	✓	\$ 20.90
18	FASTENER, TAILLAMP x m	2	MKD53-51-146B		\$ 7.80
19	GROMMET, TAILLAMP x m	2	MGJ6A-51-14Y		\$ 29.80
			TOTAL PARTS		\$ 2,033.50
			LESS 10%		\$ 203.35
			TOTAL PARTS COST		\$ 1,830.15

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	✓	\$ 1,800.00 630
---	--------------	---	---	--------------------



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
QUOTATION



CHINA TAIPING INSURANCE P/L		NAME :	Ms Emilyne Sim Poh Ai	WIP :	24004
3 ANSON ROAD		ADDRESS :	Blk 144 Lorong 2 Toa Payoh	EXCESS :	
#16-00 SPRINGLEAF TOWER			#13-206	DATE:	29-Jul-17
SINGAPORE 079909			Singapore 310144		
ATTN. :	MOTOR CLAIMS	TEL :	97642280		
FAX :					
VEH NO :	SGY4201X	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6BN22A8H0164731	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L SDN	DATE REG.:	28-Jun-17	POLICY NO. :	

NATURE OF WORKS

2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	✓	\$ 1,500.00 600
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	✓	\$ 530.00 315
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	✓	\$ 250.00 150
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	✓	\$ 350.00 180
6	MZ-BR-SUNDRI	SUNDRIES.	NETT ✓	\$ 100.00 10

TOTAL LABOUR	\$ -	\$ 4,630.00
TOTAL PARTS	\$ -	\$ 1,830.15
TOTAL	\$ -	\$ 6,460.15
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED

ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS

PRICE AS WELL AS LABOUR CHARGES.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days.

Sebastian. 7/6/2017.

- Part by part repair.

- Question Mark Item Photo.

- Photo before paint.

90036121 sebastianyeang@kkauto.com.

TRANS EUROKARS PTE LTD

 Authorised Signature



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIR



CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN.: MOTOR CLAIMS FAX:		NAME: Ms Emilyne Sim Poh Ai ADDRESS: Blk 144 Lorong 2 Toa Payoh #13-206 Singapore 310144 TEL: 97642280		WIP: 24004 EXCESS: DATE: 29-Jul-17		
VEH NO:	SGY4201X	DATE IN:		CONTACT PERSON:	JESS 6395 7874	
CHASSIS NO:	JM6BN22A8H0164731	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM	
MODEL:	MAZDA3 1.5L SDN	DATE REG.:	28-Jun-17	POLICY NO.:		
NATURE OF WORKS						
Parts Description						
NO	QTY			REVISED	PRICES	
1	REAR BUMPER	1	MBHN1-50-221ABB	\$ 1,074.80	\$ 1,074.80	
2	RETAINER(LHS), REAR BUMPER	1	MBHN1-50-2J1A		\$ 36.10	
3	RETAINER(RHS), REAR BUMPER	1	MBHN1-50-2H1A		\$ 36.10	
4	BRACKET(LHS), REAR BUMPER	1	MBHN9-51-077B		\$ 45.60	
5	BRACKET(RHS), REAR BUMPER	1	MBHN9-51-067B		\$ 45.60	
6	REFLECTOR(LHS)	1	MD350-51-5L0E		\$ 50.40	
7	REFLECTOR(RHS)	1	MD350-51-5M0E		\$ 50.40	
8	COVER(LHS), TOWING	1	MBHN1-50-EL1 BB		\$ 15.70	
9	COVER(RHS), TOWING	1	MBHN1-50-EK1 BB		\$ 16.20	
10	REAR REINFORCEMENT	1	MB45A-50-260	\$ 537.30	\$ 537.30	
11	GROMMET, REAR BUMPER	4	MBHN1-50-021A	\$ 10.00	\$ 10.00	
12	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80	\$ 2.80	
13	FASTENER, REAR BUMPER	4	MB45A-56-146A	\$ 11.20	\$ 11.20	
14	RIVET, REAR BUMPER	4	MBBM4-50-355	\$ 16.80	\$ 16.80	
15	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251		\$ 5.10	
16	GASKET(LHS), TAILLAMP	1	MBHN1-51-163	\$ 20.90	\$ 20.90	
17	GASKET(RHS), TAILLAMP	1	MBHN1-51-153	\$ 20.90	\$ 20.90	
18	FASTENER, TAILLAMP	2	MKD53-51-146B		\$ 7.80	
19	GROMMET, TAILLAMP	2	MGJ6A-51-14Y		\$ 29.80	
TOTAL PARTS				\$ 1,694.70	\$ 2,033.50	
LESS 10%				\$ 169.47	\$ 203.35	
TOTAL PARTS COST				\$ 1,525.23	\$ 1,830.15	
Labour Description						
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 630.00	\$ 1,800.00



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIR



CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN.: MOTOR CLAIMS FAX:		NAME : Ms Emilyne Sim Poh Ai ADDRESS : Blk 144 Lorong 2 Toa Payoh #13-206 Singapore 310144 TEL : 97642280		WIP : 24004 EXCESS : DATE: 29-Jul-17	
VEH NO :	SGY4201X	DATE IN :		CONTACT PERSON :	JESS 6395 7874
CHASSIS NO :	JM6BN22A8H0164731	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L SDN	DATE REG.:	28-Jun-17	POLICY NO. :	
NATURE OF WORKS					
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.			\$ 600.00 \$ 1,500.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.			\$ 315.00 \$ 630.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 150.00 \$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 180.00 \$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.			\$ 10.00 \$ 100.00
				TOTAL LABOUR	\$ 1,885.00 \$ 4,630.00
				TOTAL PARTS	\$ 1,525.23 \$ 1,830.15
				TOTAL	\$ 3,410.23 \$ 6,460.15
				LESS EXCESS	\$ - \$ -
				TOTAL AFTER EXCESS	\$ 3,410.23
				GST 7%	\$ 238.72 \$ -
				GRAND TOTAL	\$ 3,648.95 \$ -

REMARKS: SGY4201X

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Aug 2017		03 Aug 2017 09:37 Edit Adj Rpt	S\$3,410.23 Edit Estimates	S\$3,410.23 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, ID: -								
Main Claimant:	EMILYNE SIM POH AI								
Vehicle Reg. No.:	SGY4201X	Date of Loss:	27/07/2017 00:00 - :59						
Claim Type:	TP / SNM17D04504C02/B	Policy/Cover Note No.:	DMHCSN1670641600						
Vehicle Reg. No. (Insured):	SJJ1248A	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Trans Eurokars Pte Ltd () NO. 5 UBI CLOSE, SINGAPORE, 408605 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/08/2017]								
Adj Asg. Remarks:	ESTIMATES AS ATTACHED. SELECTED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGY4201X (SNM17D04504C02/8)
[SJJ1248A]
TP
EMILYNE SIM POH AI
Jul 27 2017 12:00AM
[-]
Trans Eurokars Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
2	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
3	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
4	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
5	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
6	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
7	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
8	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
9	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
10	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
11	26/03/18 14:39	General View	Load JPG	<input checked="" type="checkbox"/>	
12	26/03/18 14:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
13	26/03/18 14:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
14	26/03/18 14:40	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	03/08/17 09:39	ASSIGNMENT	Load PDF		
2	03/08/17 09:39	ESTIMATES AND TP GIA REPORT	Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; padding: 5px; margin-bottom: 10px;"> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div> </div> <div> Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small> </div>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117015029/UTBQ2

Date: 28/03/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSN1670641600

Claimant Vehicle
No: SGY4201XInsured Vehicle
No: SJJ1248A

Date of Loss: 27/07/2017

Nature of Claim: TP

Claim
No: SNM17D04504C02/8

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY4201X**

Make & Model: MAZDA 3, 1.5 L (A)

Engine No: P520456672

Reg. Date: 28/06/2017 (Man. Year: 2017)

Chassis No: JM6BN22A8H0164731

Colour: Red

Odometer: 1492 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,930.15	1,535.23	394.92	20.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,530.00	1,875.00	2,655.00	58.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,460.15	3,410.23	3,049.92	47.21
+ GST 7.00/7.00% (S\$)	452.21	238.72	213.49	47.21
Nett Amount (S\$)	6,912.36	3,648.95	3,263.41	47.21

INSPECTION

Date of Assignment: 03/08/2017

Date Inspected: 07/08/2017 Inspected At:

Trans Eurokars Pte Ltd
NO. 5 UBI CLOSE, SINGAPORE
Singapore 408605

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Mar 2018)	
Parts:	N/A	MAZDA 3 1.5 L (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGY4201X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,074.80 FL	*1,074.80 FL
2	1		*RETAINER (LHS),REAR BUMPER	Not Necessary	36.10 FL	*- FL
3	1		*RETAINER (RHS),REAR BUMPER	Not Necessary	36.10 FL	*- FL
4	1		*BRACKET (LHS),REAR BUMPER	Not Necessary	45.60 FL	*- FL
5	1		*BRACKET (RHS),REAR BUMPER	Not Necessary	45.60 FL	*- FL
6	1		*REFLECTOR (LHS)	Not Necessary	50.40 FL	*- FL
7	1		*REFLECTOR (RHS)	Not Necessary	50.40 FL	*- FL
8	1		*COVER (LHS),TOWING	Not Necessary	15.70 FL	*- FL
9	1		*COVER (RHS),TOWING	Not Necessary	16.20 FL	*- FL
10	1		*REAR REINFORCEMENT	Dented	537.30 FL	*537.30 FL
11	4		*GROMMET ,REAR BUMPER	Necessary	10.00 FL	*10.00 FL
12	1		*GROMMET ,REAR BUMPER	Necessary	2.80 FL	*2.80 FL
13	4		*FASTENER ,REAR BUMPER	Necessary	11.20 FL	*11.20 FL
14	4		*RIVET ,REAR BUMPER	Necessary	16.80 FL	*16.80 FL
15	1		*BRACKET CENTER ,REAR BUMPER	Not Necessary	5.10 FL	*- FL
16	1		*GASKET (LHS),TAILLAMP	Necessary	20.90 FL	*20.90 FL
17	1		*GASKET (RHS),TAILLAMP	Necessary	20.90 FL	*20.90 FL
18	2		*FASTENER ,TAILLAMP	Not Necessary	7.80 FL	*- FL
19	2		*GROMMET ,TAILLAMP	Not Necessary	29.80 FL	*- FL
20	1		*SUNDRIES	Necessary	100.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,133.50	1,704.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	203.35	169.47
Total Parts (\$\$)	1,930.15	1,535.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,800.00	630.00
2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT	New	1,500.00	600.00
3	TO TRANSFER REVERSE SENSORS	New	630.00	315.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROTER FUNCTIONING	New	250.00	150.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	180.00
Gross Labour Cost (\$\$)			4,530.00	1,875.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >