

08/11/13

AC 3. REC. BY: XPRREF: 03/A1617015082/Grb02

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Premium Auto

of _____

Insured: _____


Policy No: _____

Claims No: 951307477256Sum Insured: _____ Excess: 80

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$68K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SDW6776L Yr Regn: 30 Mar 2010Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 c.c. 1984Colour: Black A/C: Insured / Std / NI / NASp. Reading: 57261 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8T8-AA 051724Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/35 ZR19R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mmL/Bal. 6 mmD.O.A. _____ D.O.I. 03-08-17Survey held at W/S 10:30 AMDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction

SDW 6776LSent preli through menmen; seek mandate
mandate approved; inform authorise repair & assessconfirm \$12,726.64, 6 daysRed: \$7823.36, 387.

RECEIVED 13 MAR 2013

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 6Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Report Format: 00Lump Sum / I.B.I: (\$ 12,726.64)20010210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17015082/Grb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 04-08-2017



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SDW 6776L
Policy No. 2100201170-07000	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	03/08/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/06/2017	Inspection Date	03/08/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ahmad, Syaza

Date: 04 Aug 2017

Preliminary Advice

Vehicle No	: SDW6776L	Accident Date	: 01/06/2017
Make	: AUDI A5	Policy No.	:
Assignment Date	: 04/08/2017	Excess	: S\$0.00
Date of Inspection	: 03/08/2017	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,550.00
Revised Amount	:S\$	5,382.00
Check Items (Estimated)	:S\$	3,035.00
Total	:S\$	8,417.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	34,502.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,498.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 22 Jan 2018

Preliminary Advice

Vehicle No	: SDW6776L	Accident Date	: 01/06/2017
Make	: AUDI A5	Policy No.	:
Assignment Date	: 04/08/2017	Excess	: S\$0.00
Date of Inspection	: 03/08/2017	Est. Duration of Repair	: 8.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,550.00
Revised Amount	:S\$	12,726.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,726.64

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	34,502.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,498.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, September 16, 2017 3:05 PM
To: Guo Qiang (LKKAUTO); SUR; Janice Lee (LKKAUTO); Carrine Leong; Nora Khai
Subject: FINAL REVISION FOR SDW6776L - OD AIG - SURVEYED 3 AUG 17
Attachments: IMG-20170827-WA0014.jpg; IMG-20170827-WA0015.jpg; IMG_7979.JPG; IMG_7980.JPG; IMG_7981.JPG; IMG_7982.JPG; PA05532017 - SDW 6776 L - A5 SB 2.0 TFSI qu - Rear (liberty).xls

Hi Guo Qiang and all,

Revised estimate is attached.

Please confirm repair cost of \$12,726.64 @ 6 days of repairs exclude 1 Sunday.

B4 paint photos is attached.

Your early closure is well appreciated.

Best regards - jb

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 0410F

Vehicle Details

Vehicle No.: SDW6776L
Vehicle to be Exported: No
Intended De-registration Date: 04 Aug 2017
Vehicle Make: AUDI
Vehicle Model: A5 SPORTBACK 2.0 TFSI QU
Primary Colour: Grey
Manufacturing Year: 2010
Engine No.: CDN100117
Chassis No.: WAUZZZ8T8AA051724
Maximum Power Output: 155.0 kW (207 bhp)
Open Market Value: \$46,952.00
Original Registration Date: 30 Mar 2010
First Registration Date: 30 Mar 2010
Transfer Count: 0
Actual ARF Paid: \$46,952.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Mar 2020
PARF Rebate Amount: \$28,171.00

Intended COE Rebate Details

COE Expiry Date: 29 Mar 2020
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$24,229.00
COE Rebate Amount: \$6,331.00
Total Rebate Amount: \$34,502.00

The information contained herein is correct as at 04 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 30 Jul 2017 at 12:58 AM

Print Received Message

This mail is associated with :

***SDW6776L (9513074772SG)**

OD

Jun 1 2017 8:05PM

[LIM LI LI]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 07/08/2017 14:21 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$5382.00) - SDW6776L - Claim Handler: Loo, Tong Shing

Approved:5382.00:Re-inspection to be done for damage check and supplementary items / labour.

View Received Message

This mail is associated with :

***SDW6776L (9513074772SG)**

OD

Jun 1 2017 8:05PM

[LIM LI LI]

Premium Automobiles Pte Ltd

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 07/08/2017 14:05 PM.
To LKK_HQ
Subject SDW6776L / OD / 01/06/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$0.00

Thank you
Loo, Tong Shing

DOCUMENTS SUMMARY

There are no documents.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, August 07, 2017 4:49 PM
To: 'Claims'
Cc: SUR
Subject: RE: SDW 6776L

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SDW 6776L (excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Saturday, August 05, 2017 11:53 AM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: FW: SDW 6776L

Dear Janice,

Kindly expedite the process for repair authorization.

Thank you and Have a nice day ahead!

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



HOTLINE TEL: (65) 6419 3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100201170-07000

OWN DAMAGE EXCESS S\$400.00 (1)
WINDSCREEN EXCESS S\$100.00
(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes
SDW6776L

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

Lim Li Li

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

30 Mar 2017

4) DATE OF EXPIRY OF INSURANCE

29 Mar 2018

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *
SUBJECT TO AGE CONDITION :40 years old and above

- a) The Insured.
b) Any other person who is driving on the Insured's order or with his permission.
A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.
The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323)
APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)
2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)
4. Ethoz - 30 Bukit Batok Cres (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only
6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110)
8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)
10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY DBS BANK LTD
/ EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 9 Mar 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-200
PREMIUM LEASING - AP
281 ALEXANDRA ROAD
AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

SSPDAC

AIG Asia Pacific Insurance Pte. Ltd.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1720410F



Name

LIM LI LI

林莉莉

Race

CHINESE

Date of Birth

20-04-1965

Country of Birth

SINGAPORE

Sex

F



2373611



NRIC No. S1720410F



Blood Group

O+

Date of Issue

12-09-1994

83 PATERSON ROAD #10-05
SINGAPORE 238549

NRIC No: S1720410F

Date: 29/10/2012

No: 7148797

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0553/2017/JT
Date	:	6-Jun-17

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Lim Li Li
Address	:	83 Paterson Road #10-05 Singapore 238549
Telephone	:	HP +65 9666 1787
Type of Claim	:	Third Party Claims
Policy No.	:	
Vehicle No	:	SDW 6776 L
Model Code	:	Audi A5 SB 2.0 TFSI qu
Model / Year	:	Mar-10
Engine No	:	CDN 100117
Chassis No	:	WAUZZZ8T8AA051724
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	1-Jun-17
Place of Accident	:	Junc. of Grange Road & Orchard Link

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 6776 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	/ /
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	/ /
3	To renew rear windscreen glass.	S/N \$ 480.00	/ /
4	To remove all rear trunk fittings, trims, rear bumper and rear lid. Cut out and reweld rear outer, inner and lower panel. Renew rear lid. Transfer rear lid top spoiler and align rear lock carrier to position.	\$ 5,400.00	2800 3000
5	To respray rear bumper, rear lid, rear panelling, spare wheel tire housing and carry out joint sealer work.	\$ 3,000.00	1650 ✓
6	To carry out diagnostic checks.	S/N \$ 192.00	/ /
TOTAL LABOUR CHARGES		: \$ 9,632.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SDW 6776 L.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	REAR BUMPER / Re	\$ 1,550.00	1240.00
2	REAR BUMPER LOWER SPOILER - Lt	\$ 225.00	180.00
3	REAR BUMPER GUIDE - LHS/RHS X NN	\$ 88.00	X
4	REAR REINFORCEMENT BEAM R/BT	\$ 541.00	432.80
5	REINFORCEMENT BEAM BOLTS X NN	8 \$ 65.00	} X
6	REAR BUMPER HOLDER - LHS/RHS X NN	\$ 364.00	
7	PARKING AID SENSOR 1pc - DM	TBC	154.80
8	PARKING AID SENSOR WIRING SET X NN	\$ 446.00	X
9	REAR LID - BT	\$ 2,266.00	1812.80
10	REAR LID PACKING PIECE - MC	\$ 14.00	11.12
11	STRIKER PLATE X NN	\$ 114.00	} X
12	LID LOCK X NN	TBC	
13	REAR WEATHERSTRIP - Twi	\$ 257.00	205.60
14	REAR WINDSCREEN TOP MOULDING R/MC	\$ 272.00	217.20
15	REAR WINDSCREEN - MC	\$ 918.00	734.40
16	REAR CROSS PANEL - OUTER - BUC	\$ 448.00	358.40
17	REAR CROSS PANEL - INNER R/BUC	\$ 494.00	395.20
18	CROSS PANEL - LOWER X repair.	\$ 739.00	X
19	REAR PANEL TRIM - Re	\$ 149.00	119.20
20	REAR NUMBER PLATE X NN	S/N \$ 25.00	X
SUB-TOTAL PARTS		: \$ 8,975.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDW 6776 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR WINDSCREEN SEALENT	S/N \$ 200.00	200
22	ACRYLIC SEALER	S/N \$ 180.00	180
23	CAVITY WAX	S/N \$ 140.00	140
24	STONE CHIP	S/N \$ 180.00	180
25	SUNDRIES	S/N \$ 400.00	4.96
26	AUDI EMLEM	\$ 105.00	84
27	"A5" EMBLEM	\$ 81.00	64.72
28	"2.0" EMBLEM	\$ 81.00	64.72
29	"quattro" EMBLEM	\$ 81.00	64.72
TOTAL SPARE PARTS		: \$ 10,423.00	
TOTAL LABOUR CHARGES		: \$ 9,632.00	
GRAND TOTAL		: \$ 20,055.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

20209.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Eric Qian - 8288 0282
Surveyed Date : 03/8/17
Authorised Date :
Excess Cost : 68 Days.
Liability :
Remarks : Not Authorised.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0553/2017/JT
Date : 06-Jun-17

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Hi Guo Qiang - 6 days of repairs
exclude 1 Sundays - jb - ok - 16/9**

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Lim Li Li
Address : 83 Paterson Road
#10-05
Singapore 238549
Telephone : HP +65 9666 1787
Type of Claim : Third Party Claims
Policy No. :
Vehicle No : **SDW 6776 L**
Model Code : Audi A5 SB 2.0 TFSI qu
Model / Year : Mar-10
Engine No : CDN 100117
Chassis No : WAUZZZ8T8AA051724
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 01-Jun-17
Place of Accident : Junc. of Grange Road & Orchard Link

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SDW 6776 L

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00	\$ 280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	\$ 280.00
3	To renew rear windscreen glass.	S/N \$ 480.00	\$ 480.00
4	To remove all rear trunk fittings, trims, rear bumper and rear lid. Cut out and reweld rear outer, inner and lower panel. Renew rear lid. Transfer rear lid top spoiler and align rear lock carrier to position. (Checked item replaced - rear inner panel)	\$ 5,400.00	\$ 3,000.00
5	To respray rear bumper, rear lid, rear panelling, spare wheel tire housing and carry out joint sealer work.	\$ 3,000.00	\$ 1,650.00
6	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 9,632.00	\$ 5,882.00

MR. BOON CHIN
Block 512 Honggang Avenue 10
#06-60
Singapore 53-512
Ann. Nanan Lita Pey Cntr

Dear Sir/Madam,

ACCIDENT INVOLVING SDW 51521 AND SGE 1275C ON 09/01/2012

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDW 6776 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,550.00	\$ 1,240.00
2	REAR BUMPER LOWER SPOILER	\$ 225.00	\$ 180.00
3	REAR BUMPER GUIDE - LHS/RHS	\$ 88.00	
4	REAR REINFORCEMENT BEAM	\$ 541.00	\$ 432.80
5	REINFORCEMENT BEAM BOLTS	8 \$ 65.00	
6	REAR BUMPER HOLDER - LHS/RHS	\$ 364.00	
7	PARKING AID SENSOR	\$ 193.50	\$ 154.80
8	PARKING AID SENSOR WIRING SET	\$ 446.00	
9	REAR LID	\$ 2,266.00	\$ 1,812.80
10	REAR LID PACKING PIECE	\$ 14.00	\$ 11.12
11	STRIKER PLATE	\$ 114.00	
12	LID LOCK	TBC	
13	REAR WEATHERSTRIP	\$ 257.00	\$ 205.60
14	REAR WINDSCREEN TOP MOULDING	\$ 272.00	\$ 217.20
15	REAR WINDSCREEN	\$ 918.00	\$ 734.40
16	REAR CROSS PANEL - OUTER	\$ 448.00	\$ 358.40
17	REAR CROSS PANEL - INNER	\$ 494.00	\$ 395.20
18	CROSS PANEL - LOWER	\$ 739.00	
19	REAR PANEL TRIM	\$ 149.00	\$ 119.20
20	REAR NUMBER PLATE	S/N \$ 25.00	
SUB-TOTAL PARTS		\$ 9,168.50	\$ 5,861.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SDW 6776 L.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
			\$ 5,861.52
21	REAR WINDSCREEN SEALENT	S/N \$ 200.00	\$ 200.00
22	ACRYLIC SEALER	S/N \$ 180.00	\$ 180.00
23	CAVITY WAX	S/N \$ 140.00	\$ 140.00
24	STONE CHIP	S/N \$ 180.00	\$ 180.00
25	SUNDRIES	S/N \$ 400.00	\$ 4.96
26	AUDI EMLEM	\$ 105.00	\$ 84.00
27	"A5" EMBLEM	\$ 81.00	\$ 64.72
28	"2.0" EMBLEM	\$ 81.00	\$ 64.72
29	"quattro" EMBLEM	\$ 81.00	\$ 64.72
TOTAL SPARE PARTS		\$ 10,616.50	\$ 6,844.64
TOTAL LABOUR CHARGES		\$ 9,632.00	\$ 5,882.00
GRAND TOTAL		\$ 20,248.50	\$ 12,726.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SDW 6776 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0553/2017/MAS

13 March 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SDW 6776 L, Audi A5 SB 2.0 TFSI QU

With reference to the above-mentioned vehicle, no. **SDW 6776 L**, claimant, **Ms. Lim Li Li**, please find the related document per attached.

1. A copy of the Original invoice no. 85012243 – S\$13,617.50
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SDW 6776 L

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 1183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed
Main	08 Jun 2017		04 Aug 2017 10:43 Edit Adj Rpt	S\$12,726.64 Edit Estimates	S\$12,726.64 View Rpt	
						Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	LIM LI LI, ID: S1720410F, Tel: +6596661787, Email: NOEMAIL		
Vehicle Reg. No.:	SDW6776L	Date of Loss:	01/06/2017 20:00 - :59
Claim Type:	OD / 9513074772SG	Policy/Cover Note No.:	(Comprehensive)
		Excess:	S\$0.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 16/08/2017]		
Driver/Custodian:	LIM LI LI (52 / Female), NRIC: S1720410F, Tel: +6596661787		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (12/02/2018): Alert - Adj Mandate Approved (S\$12726.64) - SDW6776L - Claim Handler: Loo, Tong ...
- AIG_SG (23/01/2018): Alert - Adj Mandate Maintained - SDW6776L - Claim Handler: Loo, Tong Shing
- AIG_SG (07/08/2017): Alert - Adj Mandate Approved (S\$5382.00) - SDW6776L - Claim Handler: Loo, Tong S...
- AIG_SG (07/08/2017): SDW6776L / OD / 01/06/2017 / Coverage & Excess update
- AIG_SG (07/08/2017): SDW6776L / OD / 01/06/2017 / Coverage & Excess update

☐ **ALL ASSOCIATED TASKS**

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDW6776L (9513074772SG)
 OD
 Jun 1 2017 8:05PM
 [LIM LI LI]
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer	
										1 per page	☒
Assessment Reports										Thumbnail	Print
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)									Load HTM
1	04/08/17 15:06	Adjuster Immediate Advice									Load HTM
2	22/01/18 17:47	Adjuster Immediate Advice									
										3 per page	☒
Photos/Images										Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Load JPG
1	04/08/17 15:26	General View									Load JPG
2	04/08/17 15:26	General View									Load JPG
3	04/08/17 15:26	General View									Load JPG
4	04/08/17 15:26	General View									Load JPG
5	04/08/17 15:26	General View									Load JPG
6	04/08/17 15:26	General View									Load JPG
7	04/08/17 15:26	General View									Load JPG
8	04/08/17 15:26	General View									Load JPG
9	04/08/17 15:26	General View									Load JPG
10	04/08/17 15:26	General View									Load JPG
11	04/08/17 15:26	General View									Load JPG
12	04/08/17 15:26	General View									Load JPG
13	04/08/17 15:26	General View									Load JPG
14	04/08/17 15:26	General View									Load JPG
15	04/08/17 15:26	General View									Load JPG
16	04/08/17 15:26	General View									Load JPG
17	04/08/17 15:26	General View									Load JPG
18	04/08/17 15:26	General View									Load JPG
19	04/08/17 15:26	General View									Load JPG
20	04/08/17 15:26	General View									Load JPG
21	04/08/17 15:26	General View									Load JPG
22	04/08/17 15:26	General View									Load JPG
23	22/01/18 14:32	Reinspection Photo									Load JPG
24	22/01/18 14:32	Reinspection Photo									Load JPG
25	22/01/18 14:32	Reinspection Photo									Load JPG
26	22/01/18 14:32	Reinspection Photo									Load JPG
27	22/01/18 14:32	Reinspection Photo									Load JPG
28	22/01/18 14:32	Reinspection Photo									Load JPG
29	22/01/18 14:32	Reinspection Photo									Load JPG
30	22/01/18 14:32	Reinspection Photo									Load JPG
31	22/01/18 14:32	Reinspection Photo									Load JPG
32	22/01/18 14:32	Reinspection Photo									Load JPG
33	22/01/18 14:32	Reinspection Photo									Load JPG
34	22/01/18 14:32	Reinspection Photo									Load JPG
35	22/01/18 14:32	Reinspection Photo									Load JPG
36	22/01/18 14:32	Reinspection Photo									Load JPG
37	22/01/18 14:32	Reinspection Photo									Load JPG

38	22/01/18 14:32	Reinspection Photo	1	Load JPG	☒
39	22/01/18 14:32	Reinspection Photo	1	Load JPG	☒
			1 per page	☒	
Documentation				Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Load PDF	
1	04/08/17 15:25	Certificate of Insurance	1	Load PDF	
2	04/08/17 15:25	WORKSHOP EST	1	Load PDF	
3	04/08/17 15:25	Singapore Accident Statement	1	Load PDF	
4	04/08/17 15:25	Insureds NRIC	1	Load PDF	
5	07/08/17 09:16	DRIVING LICENSE	1	Load PDF	
6	10/02/18 16:36	SDW 6776L FINALISE ESTIMATE	1	Load PDF	
7	19/03/18 10:34	WORKSHOP INVOICE	1	Load PDF	
8	19/03/18 10:34	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

			View	Use Viewer	
			1 per page	☒	
Assessment Reports				Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1	Load HTM	
1	03/06/17 11:51	Accident Statement	1	Load JPG	☒
2	02/08/17 13:48	Addendum Sheet	1	Load HTM	
3	02/08/17 13:48	Accident Statement Addm. #1			
			3 per page	☒	
Photos/Images				Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1	Load JPG	☒
1	03/06/17 11:50	Accident Photo	1	Load JPG	☒
2	03/06/17 11:50	Accident Photo	1	Load JPG	☒
3	03/06/17 11:50	Accident Photo	1	Load JPG	☒
4	03/06/17 11:50	Accident Photo	1	Load JPG	☒
5	03/06/17 11:50	Accident Photo	1	Load JPG	☒
6	03/06/17 11:50	Accident Photo	1	Load JPG	☒
7	03/06/17 11:50	Accident Photo	1	Load JPG	☒
8	03/06/17 11:50	Accident Photo	1	Load JPG	☒
9	03/06/17 11:50	Accident Photo	1	Load JPG	☒
10	03/06/17 11:50	Accident Photo	1	Load JPG	☒
11	03/06/17 11:50	Accident Photo	1	Load JPG	☒
12	03/06/17 11:50	Accident Photo	1	Load JPG	☒
13	03/06/17 11:50	Accident Photo	1	Load JPG	☒
			1 per page	☒	
Documentation				Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	1	Load JPG	☒
1	03/06/17 11:51	Sketch Plan	1	Load JPG	☒
2	03/06/17 11:51	Sketch Plan #2			

Documents Checklist

Reset Save Print	
DOCUMENTS CHECKLIST	
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17015082/GRBN2
Date: 19/03/2018

REFERENCE

Insured/Claimant: LIM LI LI Policy No: OD Claim No: 9513074772SG
Date of Loss: 01/06/2017 Nature of Claim:

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDW6776L Engine No: CDN100117
Make & Model: AUDI A5, 2.0 TFSI MU (A) Chassis No: WAUZZZ8T8AA051724
Reg. Date: 30/03/2010 (Man. Year: 2010) Odometer: 57261 km
Colour: Black
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$68,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/35 ZR19 Rear Tyre Size: 245/35 ZR19
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,577.80	6,844.64	3,733.16	35.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,632.00	5,882.00	3,750.00	38.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,209.80	12,726.64	7,483.16	37.03
+ GST 7.00/7.00% (S\$)	1,414.69	890.86	523.83	37.03
Nett Amount (S\$)	21,624.49	13,617.50	8,006.99	37.03

INSPECTION

Date of Assignment: 04/08/2017
Date Inspected: 03/08/2017 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,550.00 FS	*1,240.00 FS
2	1		*REAR BUMPER LOWER SPOILER	Cut	225.00 FS	*180.00 FS
3	2		*REAR BUMPER GUIDE-LHS/RHS	Not Necessary	88.00 FS	*- FS
4	1		*REAR REINFORCEMENT BEAM	Bent	541.00 FS	*432.80 FS
5	8		*REINFORCEMENT BEAM BOLTS	Not Necessary	65.00 FS	*- FS
6	2		*REAR BUMPER HOLDER-LHS/RHS	Not Necessary	364.00 FS	*- FS
7	1		*PARKING AID SENSOR	Damaged	154.80 FS	*154.80 FS
8	1		*SET PARKING AID SENSOR WIRING	Not Necessary	446.00 FS	*- FS
9	1		*REAR LID	Bent	2,266.00 FS	*1,812.80 FS
10	1		*REAR LID PARKING PIECE	Necessary	14.00 FS	*11.12 FS
11	1		*STRIKER PLATE	Not Necessary	114.00 FS	*- FS
12	1		*LID LOCK (NPA)	Not Necessary	0.00 FS	*- FS
13	1		*REAR WEATHERSTRIP	Twisted	257.00 FS	*205.60 FS
14	1		*REAR WINDSCREEN TOP MOULDING	Necessary	272.00 FS	*217.20 FS
15	1		*REAR WINDSCREEN	Necessary	918.00 FS	*734.40 FS
16	1		*REAR CROSS PANEL-OUTER	Buckled	448.00 FS	*358.40 FS
17	1		*REAR CROSS PANEL-INNER	Buckled	494.00 FS	*395.20 FS
18	1		*CROSS PANEL-LOWER	Repair	739.00 FS	*- FS
19	1		*REAR PANEL TRIM	Deformed	149.00 FS	*119.20 FS
20	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
22	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
23	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
24	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
25	1		*SUNDRIES	Necessary	400.00 FS	*4.96 FS
26	1		*AUDI EMBLEM	Necessary	105.00 FS	*84.00 FS
27	1		*A5 EMBLEM	Necessary	81.00 FS	*64.72 FS
28	1		*2.0 EMBLEM	Necessary	81.00 FS	*64.72 FS
29	1		*QUATTRO EMBLEM	Necessary	81.00 FS	*64.72 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	10,577.80	6,844.64
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO RENEW REAR WINDSCREEN GLASS	New	480.00	480.00
4	TO REMOVE ALL REAR TRUNK FITTINGS,TRIMS,REAR BUMPER AND REAR LID.CUT OUT AND REWELD REAR OUTER,INNER AND LOWER PANEL.RENEW REAR LID.TRANSFER REAR LID TOP SPOILER AND ALIGN REAR LOCK CARRIER TO POSITION	New	5,400.00	3,000.00
5	TO RESPRAY REAR BUMPER,REAR LID,REAR PANELLING,SPARE WHEEL TIRE HOUSING AND CARRY OUT JOINT SEALER WORK	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			9,632.00	5,882.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >