

ASS. REC. BY:

REF:

CS/CT 17015385/DV0302

Special Instruction:

Surveyor

Bryan

ASSIGNMENT (Office)

From (Person):

Irene Ray

of

CTI

Date/Time:

8/8/2017

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 2469B

Insured:

SJA 374FK

at Workshop m/s

Teamwork

Tel:

6844 2415

of 53 Ubi Ave! #01-24

Policy No:

DMHCSN1681921600

Claim No:

SNM17D04581C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

3/8/2017

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 2469B -

SJA 374FK -

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No


Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKZ2469B Yr Regn: 2009 Jan
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Porsche Cayman Sport 3387
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 66159 T/Radio: Insured / Std / NI / NA
 Eng/No: 66802660
 C/No: WP0ZZZ98Z8U773733
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 265/35 R19
 R: — 11 —
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Michelin
 Front Rear
 R/Bal. S mm R/Bal. S mm
 L/Bal. S mm L/Bal. S mm
 D.O.A. 03/08/2017 D.O.I. 08/08/2017
 Survey held at Teamwork Page 401
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front 4 Rear
 The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

Chine Teiping S5A3747K

MV 90K

LIA 59.3K

HL 30K

RECEIVED 13 AUG 2019

13/08/19 Final 2/1 20000/- with 14 days of rev (Red 58, 264.40, 7490)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 13/8 - typistDays Of Repair: 14Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) \$ + RS. \$

) Photos

) Others

TOTAL

250

Report Format: MerimenLump Sum / I.B.I: (\$ 20,000p)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Aug 2017		08 Aug 2017 15:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	FIONA NEO WEE WEE, ID: S7617490C		
Vehicle Reg. No.:	SKZ2469B	Date of Loss:	03/08/2017 07:00 - :59
Claim Type:	TP / SNM17D04581C02	Policy/Cover Note No.:	DMHCSN1681921600
Vehicle Reg. No. (Insured):	SJA3747K	Policy No. (Claimant):	CN805828
		Excess:	S\$0.00
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/08/2017]		
Adj Asg. Remarks:	PLEASE ASSIST TO CONDUCT PRS AND REVERT WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7490C

Vehicle Details

Vehicle No.: SKZ2469B

Vehicle to be Exported: Yes

Intended De-registration
Date: 03 Aug 2017

Vehicle Make: PORSCHE

Vehicle Model: CAYMAN S SPORT

Primary Colour: Black

Manufacturing Year: 2008

Engine No.: 66802660

Chassis No.: WPOZZZ98Z8U773733

Maximum Power Output: 223.0 kW (299 bhp)

Open Market Value: \$104,082.00

Original Registration Date: 19 Jan 2009

First Registration Date: 19 Jan 2009

Transfer Count: 3

Actual ARF Paid: \$104,082.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 18 Jan 2019

PARF Rebate Amount: \$57,245.00

Intended COE Rebate Details

COE Expiry Date: 18 Jan 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$14,235.00

COE Rebate Amount: \$2,074.00

Total Rebate Amount: \$59,319.00

The information contained herein is correct as at 03 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 30 Jul 2017 at 12:58 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/08/2017 13:11
Date Of Accident	03/08/2017 07:40
Exact Location Of Accident	PIE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ2469B
Insured/Policyholder	
Name Of Registered Owner	FIONA NEO WEE WEE
NRIC No	S7617490C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98488890
Alternative Phone No	OFFICE-98488890

Vehicle Particulars

Manufacturer	PORSCHE
Model	CAYMAN SPORT

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN805828
Cover Note Number	

Driver

Name of Driver	FIONA NEO WEE WEE
NRIC No	S7617490C
Date Of Birth	07/06/1976
Occupation	OUTDOOR
Date Of Driving Pass	05/08/2002
Driving Experience	14 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98488890
Fax Number	
Contact Number	OFFICE-98488890
Email Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: CONTACT OWNER FOR VIDEO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJA3747K
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJX6866J

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

FIONA NEO WEE WEE

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKZ2469B

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

REFERENCE

[illegible]

Uninsured by Reporting Carrier
 Federal
 Progressive Automobile Plan
 841 3022A US Road 1 801-4546
 3300000 406310

Number Plate
 A - 9K2246RB
 B - 33A3744K
 C - 81x686W

Legend

 Vehicle Bike

Accident Sketch Plan

Describe Characteristics of the Account

My car was travelling along PIE towards Tuas, at the 4th lane. Vehicle in front of mine stopped, I also stopped my car completely, without any contact with the front vehicle. All of a sudden, I felt an impact from the rear portion of my car and the huge impact from my car rear caused my car to thrust forward and hit onto the front vehicle.

1

Declaration

We declare no competing financial interests in this work.

Revised: _____
 Printed: _____
 Date: _____

Figure 2. Zirconium is shown in red in the polyhedron / O^{2-} / H_2O / H^+

Witnessed by Reporting Officer
 [Signature]
 [Stamp]



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

China Taiping Insurance (Singapore) Pte Ltd

105 Cecil Street #19-00

The Octagon

Singapore 069534

Vehicle number	SKZ2469B
Make / Model	PORSCHE/CAYMAN
Chassis number	WPOZZZ98Z8U773733
Accident date	03 August 2017
Reference	1708-12

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS			
1	REAR BUMPER <i>Distorted</i>	4850.80	
2	REAR TAILLAMP <i>broken</i>	8741.20 ✓	
2	REAR BUMPER RETAINER <i>Svc</i>	3561.00 ✓	
1	REAR BUMPER REINFORCEMENT <i>Distorted</i>	870.80 X	
1	REAR BUMPER REINFORCEMENT CENTRE BRACKET <i>NW</i>	985.50 16678.00 ✓	
2	REAR BUMPER REINFORCEMENT SIDE BRACKET <i>1st</i>	622.50 X	
1	REAR BUMPER REINFORCEMENT HEAT SHIELD <i>NW</i>	376.10 874.30 ✓	
1	REAR END PANEL <i>Brk</i>	367.50 X	
1	REAR END PANEL TOP GARNISH <i>Svc</i>	2216.00 3387.00 ✓	
1	FLOOR COMPARTMENT PANEL <i>van</i>	702.00 X	
1	REAR BUMPER INNER BRACKET <i>NW</i>	3862.50 X	
1	REAR BUMPER TOP BRACKET <i>distorted 1st</i>	589.20 X	
4	REAR REVERSE SENSOR <i>Down</i>	302.50 410.40 ✓	
2	REAR REVERSE SENSOR WIRE <i>socket broken</i>	2190.00 ✓	1056.00
1	REAR NUMBER PLATE LAMP <i>broken</i>	2352.00 ✓	831.20
1	FRONT BUMPER <i>distorted</i>	162.00 ✓	
1	FRONT RH FOG LAMP COVER <i>distorted / missing broken</i>	8432.00 ✓	3550.00
2	FRONT BUMPER RETAINER <i>Svc</i>	387.00 ✓	
1	FRONT BUMPER REINFORCEMENT <i>Svc</i>	594.00 X	
1	FRONT NUMBER PLATE GARNISH <i>1st</i>	1137.00 X	
1	REAR EXHAUST ASSY <i>1st</i>	252.00 ✓	
1	HEAT SHIELD COVER - OUTER <i>1st</i>	25510.10 15900.00 ✓	5819.00
1	TAILLAMP BRACKET <i>1st</i>	612.00 ✓	
		550.00 ✓	
	Subtotal	73234.40	
	Balance C/F	73234.40	
PARTS REPLACEMENT - SPECIAL NETT ITEMS			
	Balance B/F	73234.40	
1	FRONT NUMBER PLATE <i>Crack</i>	80.00 351-	
1 SET	FRONT BUMPER CLIP <i>Nec</i>	70.00 301-	
1	REAR NUMBER PLATE <i>Crack</i>	80.00 351-	
1 SET	REAR BUMPER CLIP <i>Nec</i>	70.00 201-	
1	JOINT SEALANT <i>Nec</i>	150.00 401-	
	Subtotal	450.00	
	Balance C/F	73684.40	

<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	73684.40
1	CHECK FRONT , REAR LIGHTNING AND WIRING SYSTEM	80.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 150/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 80/-
5	DIAGNOIS CHECK AND CLEAR FAULT CODE	500.00 NH
6	PANEL BEATING ON AFFECTED AREAS	1800.00 1200/-
7	SPRAY PAINTING ON AFFECTED AREAS	1500.00 800/-
8	APPLY ANTI RUST ON AFFECTED AREAS	200.00 60/-
Subtotal		4580.00
Grand total		78264.40

2360.00

08/08/2017 @ 1500m
Not Antimal

2/8nm
yan

14 days.

25479.09
4/5 20000/-

LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT117015385/DVD3N2

Date: 13/08/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1681921600
Claimant Vehicle No :	SKZ2469B	Insured Vehicle No :	SJA3747K
Date of Loss:	03/08/2017	Nature of Claim:	TP
		Claim No:	SNM17D04581C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ2469B	Engine No:	66802660
Make & Model:	PORSCHE CAYMAN, 3.4 S Sport (A)	Chassis No:	WPOZZZ98Z8U773733
Reg. Date:	19/01/2009 (Man. Year: 2008)	Odometer:	66159 km
Colour:	Black		
Engine Capacity:	3387 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/35R19	Rear Tyre Size:	265/35R19
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	73,684.40	23,119.09	50,565.31	68.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	2,360.00	2,220.00	48.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	78,264.40	25,479.09	52,785.31	67.44
Approved Total (Overridden) (S\$)		20,000.00		
(S\$)	78,264.40	20,000.00	58,264.40	74.45
+ GST 7.00/7.00% (S\$)	5,478.51	1,400.00	4,078.51	74.45
Nett Amount (S\$)	83,742.91	21,400.00	62,342.91	74.45

INSPECTION

Date of Assignment:	08/08/2017	
Date Inspected:	08/08/2017	Inspected At:
		Teamwork Garage Pte Ltd (HQ)
		53 Ubi Ave 1 #01-24, Paya Ubi
		Industrial Park
		Singapore 408934

Estimated Period of Repair: 14.0 days

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2019)
Parts:	M1-COUPE	PORSCHE CAYMAN 3.4 S Sport (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ2469B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	8,741.20 F	*4,850.80 FL
2	2		*REAR TAILLAMP	Broken	3,561.00 F	*3,561.00 FL
3	2		*REAR BUMPER RETAINER	Serviceable	870.80 F	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Dented	16,678.00 F	*985.50 FL
5	1		*REAR BUMPER REINFORCEMENT CENTRE BRACKET	Not Necessary	622.50 F	*- FL
6	2		*REAR BUMPER REINFORCEMENT SIDE BRACKET	Bent	874.30 F	*375.10 FL
7	1		*REAR BUMPER REINFORCEMENT HEAT SHIELD	No such part	367.50 F	*- FL
8	1		*REAR END PANEL	Buckled	3,387.00 F	*2,216.00 FL
9	1		*REAR END PANEL TOP GARNISH	Serviceable	702.00 F	*- FL
10	1		*FLOOR COMPARTMENT PANEL	Repair	3,862.50 F	*- FL
11	1		*REAR BUMPER INNER BRACKET	Not Necessary	589.20 F	*- FL
12	1		*REAR BUMPER TOP BRACKET	Deformed/Bent	410.40 F	*302.50 FL
13	4		*REAR REVERSE SENSOR	Damaged	2,190.00 F	*1,056.00 FL
14	2		*REAR REVERSE SENSOR WIRE	Socket Broken	2,352.00 F	*831.20 FL
15	1		*REAR NUMBER PLATE LAMP	Broken	162.00 F	*162.00 FL
16	1		*FRONT BUMPER	Distorted	8,432.00 F	*3,550.00 FL
17	1		*FRONT RH FOG LAMP COVER	Deformed/Mounting Broken	387.00 F	*387.00 FL
18	2		*FRONT BUMPER RETAINER	Serviceable	594.00 F	*- FL
19	1		*FRONT BUMPER REINFORCEMENT	Serviceable	1,137.00 F	*- FL
20	1		*FRONT NUMBER PLATE GARNISH	Bent	252.00 F	*252.00 FL
21	1		*REAR EXHAUST ASSY	Bent	15,900.00 F	*5,819.00 FL
22	1		*HEAT SHIELD COVER-OUTER	Bent	612.00 F	*612.00 FL
23	1		*TAILLAMP BRACKET	Bent	550.00 F	*550.00 FL
24	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*35.00 FS
25	1		*SET FRONT BUMPER CLIP	Necessary	70.00 FS	*30.00 FS
26	1		*REAR NUMBER PLATE	Cracked	80.00 FS	*35.00 FS
27	1		*SET REAR BUMPER CLIP	Necessary	70.00 FS	*20.00 FS
28	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	73,684.40	25,670.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	2,551.01
Total Parts (\$\$)	73,684.40	23,119.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT,REAR LIGHTNING AND WIRING SYSTEM	New	80.00	30.00
2	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH	New	200.00	150.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
4	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	80.00
5	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	500.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	1,200.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	800.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (S\$)			4,580.00	2,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >