

ASS. REC BY:

REF:

REF: CS/PC1170015463/Gib02

Special Instruction:

SUNVALLEY

ASSIGNMENT (Office)

From (Person): Clyde (Joanney), of FCI Date/Time: 10/8/2017

Estimated Cost: _____ Bill to: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 1C 239LP Insured: SHA 3907P

at Workshop m/s Progressive Auto Pte Ltd Tel: 6844 4260

of No 1 Raki Bukit Ave 6 Authority #02-48/50

Policy No: _____ Claim No: 017007695 NIFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 7/8/2017
(Client's Record)

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 10/8 Person Contacted: Vehicle: IN/OUT

Date/Time	Action/Instruction () Estimate
	PC 2396P-X
	SHA 390FP-X
	25/9/18.
	Confirm \$8000 @ 10 days (Refinise with Wong by Guo Qiang)
	Red: \$9580.03, \$41.

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop mis Progressive Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$54K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS W/P

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC2396PYr Regn: 18 Ju/2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Hiacecc 2882Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 69684

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ITFST22P6000 14000Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195 R15R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 10-08-17Survey held at: W/S2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FrtThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/9 Finalized \$8000 with WWP.

RECEIVED 20 JUN 2018 pass back to handler

RECEIVED 25 SEP 2018

Date/Time, File Pass to?

☐

Preli. Report

1) typist☒

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 9Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

) S + RS Si

☐

Interview (\$

) Photos DSP☐

Tech. Invs (\$

) Others 2016/18☐

Weekend (\$

)

Report Format: TPLump Sum / 181 (\$ 8500)

TOTAL

451

7x15

1304105305076

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001675-9

MOTOR SURVEY ASSIGNMENT

Date	08-08-2017	Our Ref No.	D17007695MFSH
Accident Date	07-08-2017	Claim Type.	Third Party
Insured Vehicle	SHA3907P	Third Party Vehicle.	PC2396P
Survey Location	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48/50		
Contact Person.	BEREZA		
Contact No.	68444260/ 0	Fax No.	68444625
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTO PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	JOANNEY		

In - Guo Qiang

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/08/2017 09:45
Date Of Accident	07/08/2017 01:55
Exact Location Of Accident	ANG MO KIO AVE 6 TURNING LEFT ANG MO KIO AVENUE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC2396P
Insured/Policyholder	
Name Of Registered Owner	TAN TECK SENG
NRIC No	S1133543H
Email Address	EVOLUTION_126@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-82509236
Alternative Phone No	OTHERS-82509236

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5069592486-02
Cover Note Number	

Driver

Name of Driver	TAN WEI LIANG
NRIC No	S9145411D
Date Of Birth	06/12/1991
Occupation	INDOOR
Date Of Driving Pass	06/01/2014
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82509236
Fax Number	
Contact Number	OTHERS-82509236
Email Address	EVOLUTION_126@HOTMAIL.COM

Address	BLK 215 PETIR ROAD #03-437
Postcode	670215
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA3907P
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	ZAINAL ABIDIN BIN NORDIN
NRIC/Passport Number	S1149553B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Describe Circumstances of the Accident

On 07/03/17, time about 1.56am, I was travelling my vehicle DC 2396P along Ang Mo Kio Ave 6 turning left Ang Mo Kio Ave 8, Suddenly Vehicle B (SHA 3907P) hit on my vehicle front left portion, cause my vehicle very badly damage. Please see video footage.

Declaration

We declare the foregoing particulars are true in every respect.

TAN
Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

TAU
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Veh A : PC2396P
Veh B : SHA3907P

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: PC2396P

Claim Type: Third Party

Accident Date: 07-08-2017

TP Veh Reg No: SHA3907P

Estimate No: EST0000447

Date: 08 Aug 2017

Policy No: 5069592486-02

Veh Reg No: PC2396P

Make/Model: TOYOTA HIACE

Chassis No: JTFST22P00014000

Engine No: 1KD2200144

Reg. Date: 18-07-2012

Estimate Repair Cost to Vehicle No :PC2396P

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
PC2396P TOYOTA HIACE				
List Price				
1 Front Corner Panel LH	245.0000	1 PC	245.00	
2 Front Top Panel	900.0000	1 PC	900.00	
3 Front Top Panel Garnish LH	556.0000	1 PC	556.00	
4 Front Top Panel Garnish Clipse LH	5.9000	4 PC	23.60	
5 Front Grille	525.0000	1 PC	525.00	
6 Front Grille Moulding	319.0000	2 PC	638.00	
7 Front Grille Clip	5.5000	4 PC	22.00	
8 Front Head Lamp	825.0000	2 PC	1,650.00	
9 Front Head Lamp Lower Bracket LH	25.0000	1 PC	25.00	
10 Front Centre Beam	175.0000	1 PC	175.00	
11 Front Bumper	680.0000	1 PC	680.00	
12 Front Bumper Side Retainer	145.0000	2 PC	290.00	
13 Front Bumper Grille	290.0000	1 PC	290.00	
14 Front Bumper Reinforcement	386.0000	1 PC	386.00	
15 Front Bumper Fog Lamp	290.0000	1 PC	290.00	
16 Front Bumper Clips	5.5000	5 PC	27.50	
17 Front Bumper Towing Cover LH	20.0000	1 PC	20.00	
18 Front Step Panel LH	180.0000	1 PC	180.00	
19 Front Step Panel Garnish LH & RH	155.0000	1 PC	155.00	
20 Front Step Panel Garnish Clipse LH	5.9000	4 PC	23.60	
21 Front Door Pillar LH	425.0000	1 PC	425.00	
22 Front Door LH	1,795.0000	1 PC	1,795.00	
23 Front Door Lock LH	550.0000	1 PC	550.00	
24 Front Door Hinge Top LH	95.0000	1 PC	95.00	
25 Front Door Hinges Lower LH	95.0000	1 PC	95.00	
26 Front Door Check LH	155.0000	1 PC	155.00	
27 Front Door Rubber LH	220.0000	1 PC	220.00	
28 Front Door Glass Regulator LH	298.0000	1 PC	298.00	
29 Front Upper Arm LH	935.0000	1 PC	935.00	
30 Front Lower Arm LH	520.0000	1 PC	520.00	
31 Front Knuckle Arm LH	585.0000	1 PC	585.00	
32 Front Hub Bearing LH	288.0000	1 PC	288.00	
33 Front Shock Absorber LH	130.0000	1 PC	130.00	
			13,192.70	
		Less 25%	3,298.18	9,894.53

Special Net

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S: FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: PC2396P

Claim Type: Third Party

Accident Date: 07-08-2017

TP Veh Reg No: SHA3907P

Estimate No: EST0000447

Date: 08 Aug 2017

Policy No: 5069592486-02

Veh Reg No: PC2396P

Make/Model: TOYOTA HIACE

Chassis No: JTFST22P00014000

Engine No: 1KD2200144

Reg. Date: 18-07-2012

Estimate Repair Cost to Vehicle No :PC2396P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
34 Front Corner Panel Chrome Cover LH	120.0000	1 PCS	120.00	
35 Front Head Lamp Chrome Moulding LH	200.0000	1 PCS	200.00	
36 Front Bumper Chrome Cover (Fog Lamp) <i>Support</i>	150.0000	2 PC	300.00	
37 Front Door Sticker (Logo)	200.0000	1 SET	200.00	
38 Front Door LED light LH (Assy)	180.0000	1 PC	180.00	
39 Front Door Protector LH	450.0000	1 PC	450.00	
40 Front Tyre LH	320.0000	1 PC	320.00	
41 Front Spare Rim LH	950.0000	1 PC	950.00	
<i>42 Front Surge foy large cover - 98x2 A</i>			2,720.00	2,720.00
<i>43 Front door side mirror LH - 890 A</i>				
<i>44 Labour (4 hrs) side mirror chrome work - 120.00</i>				
42 Towing	50.0000	1 PC	50.00	
43 Panel Beating	1,200.0000	1 PC	1,200.00	
44 Check Wiring	60.0000	1 PC	60.00	
45 Rust Proofing	60.0000	1 PC	60.00	
46 To Remove & Replace Door Assy	80.0000	1 PC	80.00	
47 To Adjust Alignment	50.0000	1 PC	50.00	
48 To Remove & Replace Undercarriage	280.0000	1 PC	280.00	
49 Spray Painting	900.0000	1 PC	900.00	
			2,680.00	2,680.00
Total				S\$ 15,294.53

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND TWO HUNDRED NINETY FOUR AND CENTS FIFTY THREE ONLY

For PROGRESSIVE AUTO PTE LTD

AUTHORISED SIGNATURE

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 3543H

Vehicle Details

Vehicle No.: PC2396P

Vehicle to be Exported: No

Intended De-registration
Date: 11 Aug 2017

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE HIROOF AUTO 14 SEATER

Primary Colour: White

Manufacturing Year: 2012

Engine No.: 1KD2200144

Chassis No.: JTFST22P600014000

Maximum Power
Output: -

Open Market Value: \$37,122.00

Original Registration
Date: 18 Jul 2012

First Registration Date: 18 Jul 2012

Transfer Count: 1

Actual ARF Paid: \$1,857.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Jul 2022

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$57,589.00

COE Rebate Amount: \$28,407.00

Total Rebate Amount: \$28,407.00

The information contained herein is correct as at 11 Aug 2017

OK

Land Transport Authority

Please read through the [Privacy Statement](#), [Terms of Use](#) and [Disclaimer](#).
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 30 Jul 2017 at 12:58 AM

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST/200712509E RCB NO:200712509E

M/S: FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: PC2396P

Claim Type: Third Party

Accident Date: 07-08-2017

TP Veh Reg No: SHA3907P

Estimate No: EST0000447

Date: 08 Aug 2017

Policy No: 5069592486-02

Veh Reg No: PC2396P

Make/Model: TOYOTA HIACE

Chassis No: JTFST22P00014000

Engine No: 1KD2200144

Reg. Date: 18-07-2012

Estimate Repair Cost to Vehicle No :PC2396P

Description	U/Price	Quantity	List Price SS	Amount SS
PC2396P TOYOTA HIACE				
List Price				
1 Front Corner Panel LH X Repair Repair	245.0000	1 PC	245.00	X
2 Front Top Panel Repair X	900.0000	1 PC	900.00	X
3 Front Top Panel Garnish LH BR	556.0000	1 PC	556.00	
4 Front Top Panel Garnish Clip LH acc	5.9000	4 PC	23.60	
5 Front Grille cut	525.0000	1 PC	525.00	
6 Front Grille Moulding cut	319.0000	2 PC	638.00	
7 Front Grille Clip acc	5.5000	4 PC	22.00	
8 Front Head Lamp CHA	825.0000	2 PC	1,650.00	1550
9 Front Head Lamp Lower Bracket LH BR	25.0000	1 PC	25.00	
10 Front Centre Beam X Repair	175.0000	1 PC	175.00	X
11 Front Bumper cut	680.0000	1 PC	680.00	360
12 Front Bumper Side Retainer acc	145.0000	2 PC	290.00	
13 Front Bumper Grille cut	290.0000	1 PC	290.00	
14 Front Bumper Reinforcement BT	386.0000	1 PC	386.00	
15 Front Bumper Fog Lamp acc	290.0000	1 PC	290.00	
16 Front Bumper Clips acc	5.5000	5 PC	27.50	
17 Front Bumper Towing Cover LH mis	20.0000	1 PC	20.00	
18 Front Step Panel LH Repair X	180.0000	1 PC	180.00	X
19 Front Step Panel Garnish LH & RH BR	155.0000	1 PC	155.00	
20 Front Step Panel Garnish Clip LH acc	5.9000	4 PC	23.60	
21 Front Door Pillar LH Repair X	425.0000	1 PC	425.00	X
22 Front Door LH BT acc DM	1,795.0000	1 PC	1,795.00	1580.31
23 Front Door Lock LH acc	550.0000	1 PC	550.00	1240.00
24 Front Door Hinge Top LH acc	95.0000	1 PC	95.00	
25 Front Door Hinges Lower LH acc	95.0000	1 PC	95.00	
26 Front Door Check LH acc	155.0000	1 PC	155.00	
27 Front Door Rubber LH acc	220.0000	1 PC	220.00	
28 Front Door Glass Regulator LH acc	298.0000	1 PC	298.00	
29 Front Upper Arm LH X	935.0000	1 PC	935.00	X
30 Front Lower Arm LH X	520.0000	1 PC	520.00	X
31 Front Knuckle Arm LH X	585.0000	1 PC	585.00	X
32 Front Hub Bearing LH acc	288.0000	1 PC	288.00	
33 Front Shock Absorber LH X	130.0000	1 PC	130.00	X
34 Front Bumper Fog Lamp Cover mis	98.0000	2 PC	196.00	
35 Front Door Side Mirror acc CHA	890.0000	1 PC	890.00	654

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S: FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 6507 3848

FAX: 6507 3849

ATTN: Motor Claim Department

Your Ref No: PC2396P

Claim Type: Third Party

Accident Date: 07-08-2017

TP Veh Reg No: SHA3907P

Estimate No: EST0000447

Date: 08 Aug 2017

Policy No: 5069592486-02

Veh Reg No: PC2396P

Make/Model: TOYOTA HIACE

Chassis No: JTFST22P00014000

Engine No: 1KD2200144

Reg. Date: 18-07-2012

Estimate Repair Cost to Vehicle No :PC2396P

Description	U/Price	Quantity	List Price SS	Amount SS
			14,278.70	
		Less 25%	3,569.68	10,709.03
Special Net				
36 Front Corner Panel Chrome Cover LH	120.0000	1 PCS	120.00	50
37 Front Head Lamp Chrome Moulding LH	200.0000	1 PCS	200.00	50
38 Front Bumper Chrome Support (Fog Lamp)	150.0000	2 PC	300.00	60
39 Front Door Sticker (Logo)	200.0000	1 SET	200.00	80
40 Front Door LED light LH (Assy)	180.0000	1 PC	180.00	60
41 Front Door Protector LH	450.0000	1 PC	450.00	150
42 Front Tyre LH	320.0000	1 PC	320.00	X
43 Front Spare Rim LH	950.0000	1 PC	950.00	350
44 Door Side Mirror Chrome Cover	120.0000	1 PCS	120.00	40
45 Front Number Plate	100.0000	1 PC	100.00	40
			2,940.00	2,940.00
Labour				
46 Towing	50.0000	1 PC	50.00	-
47 Panel Beating	1,200.0000	1 PC	1,200.00	1000
48 Check Wiring	60.0000	1 PC	60.00	30
49 Rust Proofing	60.0000	1 PC	60.00	40
50 To Remove & Replace Door Assy	80.0000	1 PC	80.00	60
51 To Adjust Alignment	50.0000	1 PC	50.00	-
52 To Remove & Replace Undercarriage	280.0000	1 PC	280.00	80
53 Spray Painting	900.0000	1 PC	900.00	700
			2,680.00	2,680.00
			Total	SS 16,329.03

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND THREE HUNDRED TWENTY NINE AND CENTS THREE ONLY

10 Days.
umpsm repair
After paint photos.
Gu-Qi-q - 82880282
10/8/17

1 KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

For PROGRESSIVE AUTO PTE LTD

AUTHORISED SIGNATURE

Acknowledged by Repairer

Signature:

Date:

GST-200712509E RCH NO-200712509E

Reg. Date: 18-07-2012

AUTHORISED SIGNATURE

Janice Lee (LKKAUTO)

From: Progressive Auto <claims@progressiveauto.sg>
Sent: Tuesday, September 25, 2018 11:50 AM
To: Janice Lee (LKKAUTO)
Cc: Guo Qiang (LKKAUTO)
Subject: Re: PC 2396 P - AFTER REPAIR PHOTO LKK REF CS/FCI17015463/Grb

Without Prejudice

Your Ref: CS/FCI17015463/Grb
Our Ref: PC 2396 P

Dear OIC

With regards to the tele-conversation with Mr Wong earlier

Both party has agreed to the repair finalize cost \$8,000.00 without GST & 10 working days

Will submit LOD to First Capital by this Friday or Monday

Thank You

Best Regards
Bereza - On Behalf Of Wong (Forman)

Progressive Auto Pte Ltd
No.1 Kaki Bukit Ave 6
AutoBay #02-48/50
Singapore 417883
Tel: 6844 4620
Fax:6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant

or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

On Thu, Sep 6, 2018 at 10:10 AM Janice Lee (LKKAuto) <JaniceLee@lkkauto.com> wrote:

Dear Breza/ Mandy/ Wong,

Please see enclosed.

Kindly confirm L/S \$7,900 @ 9 Days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)

Sent: Wednesday, July 11, 2018 11:42 AM

To: Progressive Auto <claims@progressiveauto.sg>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: PC 2396 P - AFTER REPAIR PHOTO LKK REF CS/FCI17015463/Grb

Dear Bereza/ Mandy,

Please see enclosed.

Kindly confirm L/S \$7,400 @ 9 DAYS

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Progressive Auto [<mailto:claims@progressiveauto.sg>]

Sent: Friday, July 06, 2018 3:06 PM

To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: Re: PC 2396 P - AFTER REPAIR PHOTO LKK REF CS/FCI17015463/Grb

Without Prejudice

Dear OIC,

WRT the tele-conversation with Mr Wong on 18 July

Please advise us the status - Pending re-finalize repair cost

**** Accident Dated On 07/08/2017**

Thank You

Best Regards

Bereza

Progressive Auto Pte Ltd

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax:6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

On Wed, Jul 4, 2018 at 12:27 PM, Progressive Auto <claims@progressiveauto.sg> wrote:

Without Prejudice

Dear OIC,

Refer to our tele-conversation on 2 July 18

Please refer to attachment - **Repair finalize cost for the Q mark item which was not include**

We will agreed to the repair finalize cost at \$9700.00 exclude gst - 9 working days

Thank You

Best Regards

Bereza / Zali

Progressive Auto Pte Ltd

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax: 6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

On Fri, Jun 29, 2018 at 3:21 PM, Progressive Auto <claims@progressiveauto.sg> wrote:

Hi Janice,

Please hold this finalize amount , we need re-calculation.

Thank you.

Best Regards,

Mandy Sin

Progressive Auto Pte Ltd

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax:6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

On Thu, Jun 28, 2018 at 1:39 PM, Progressive Auto <claims@progressiveauto.sg> wrote:

Without Prejudice

Dear Janice,

Refer to your email below, Zali has agreed to the finalize repair cost as state in your email.

Kindly confirm L/S \$8500 @ 9 days

Will submit LOD to (First Capital Insurance Ltd)

Thank You

Best Regards

Bereza / Zali

Progressive Auto Pte Ltd

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax:6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been

maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

On Thu, Jun 28, 2018 at 12:53 PM, Janice Lee (LKKAuto) <JaniceLee@lkkauto.com> wrote:

Dear Mandy,

Kindly confirm L/S \$8500 @ 9 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Progressive Auto [<mailto:claims@progressiveauto.sg>]

Sent: Thursday, June 21, 2018 4:00 PM

To: SUR <sur@lkkauto.com>

Subject: Fwd: PC 2396 P - AFTER REPAIR PHOTO LKK REF CS/FCI17015463/Grb

Dear Xiao Zhang,

Hereby attached estimate for your perusal.

Kindly check and ask Guo Qiang Finalize.

Thank you.

Best Regards,

Mandy

Progressive Auto Pte Ltd

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax:6844 4625

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17015463/Grbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 25-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3907P	Veh. Inspected	PC 2396P
Policy No.		Coverage (\$)	0.00
Claim No.	D17007695MFSH	Excess (\$)	0.00
Assign From	JOANNEY	Assign Date	10/08/2017

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JTFST22P600014000	Colour	WHITE
Odometer	69684	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	TOYO	6 mm
L/H Front Tyre	195 R15	TOYO	6 mm
R/H Rear Tyre	195 R15	TOYO	6 mm
L/H Rear Tyre	195 R15	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/08/2017	Inspection Date	10/08/2017
Survey held at	NO 1 KAKI BUKIT AVE 6 AUTOBAY #02-48/50		
Repairer	PROGRESSIVE AUTOMOTIVE PTE LTD		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 2396P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT CORNER PANEL LH	TO REPAIR SEE LABOUR	245.00	-
1	FRONT TOP PANEL	TO REPAIR SEE LABOUR	900.00	-
1	FRONT TOP PANEL GARNISH LH	BROKEN	556.00	556.00
4	FRONT TOP PANEL GARNISH CLIPSE LH @\$5.90	NECESSARY	23.60	23.60
1	FRONT GRILLE	CRACKED	525.00	525.00
2	FRONT GRILLE MOULDING @\$319.00	CUT	638.00	638.00
4	FRONT GRILLE CLIP @\$5.50	NECESSARY	22.00	22.00
2	FRONT HEAD LAMP @\$825.00	CRACKED	1,650.00	1,550.00
1	FRONT HEAD LAMP LOWER BRACKET LH	BROKEN	25.00	25.00
1	FRONT CENTRE BEAM	TO REPAIR SEE LABOUR	175.00	-
1	FRONT BUMPER	CUT	680.00	560.00
2	FRONT BUMPER SIDE RETAINER @\$145.00	NECESSARY	290.00	290.00
1	FRONT BUMPER GRILLE	CUT	290.00	290.00
1	FRONT BUMPER REINFORCEMENT	BENT	386.00	386.00
1	FRONT BUMPER FOG LAMP	DISTORTED	290.00	290.00
5	FRONT BUMPER CLIPS @\$5.50	NECESSARY	27.50	27.50
1	FRONT BUMPER TOWING COVER LH	MISSING	20.00	20.00
1	FRONT STEP PANEL LH	TO REPAIR SEE LABOUR	180.00	-
1	FRONT STEP PANEL GARNISH LH & RH	BROKEN	155.00	155.00
4	FRONT STEP PANEL GARNISH CLIPSE LH @\$5.90	NECESSARY	23.60	23.60
1	FRONT DOOR PILLAR LH	TO REPAIR SEE LABOUR	425.00	-
1	FRONT DOOR LH	BENT	1,795.00	1,580.30
1	FRONT DOOR LOCK LH	DAMAGED	550.00	550.00
1	FRONT DOOR HINGE TOP LH	BENT	95.00	95.00
1	FRONT DOOR HINGES LOWER LH	BENT	95.00	95.00
1	FRONT DOOR CHECK LH	BENT	155.00	155.00
1	FRONT DOOR RUBBER LH	NECESSARY	220.00	220.00

Report Ref No. CS/FCI17015463/Grbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR GLASS REGULATOR LH	NOT NECESSARY	298.00	-
1	FRONT UPPER ARM LH	NOT NECESSARY	935.00	-
1	FRONT LOWER ARM LH	NOT NECESSARY	520.00	-
1	FRONT KNUCKLE ARM LH	NOT NECESSARY	585.00	-
1	FRONT HUB BEARING LH	NECESSARY	288.00	288.00
1	FRONT SHOCK ABSORBER LH	NOT NECESSARY	130.00	-
2	FRONT BUMPER FOG LAMP COVER @\$98.00	MISSING	196.00	196.00
1	FRONT DOOR SIDE MIRROR	CRACKED	890.00	654.00
1	FRONT CABLE SOCKET HANDLE LH (ADDITIONAL)	NOT NECESSARY	58.00	-
1	FRONT DOOR SIDE MIRROR (ADDITIONAL)	REPEATED	1,130.00	-
	LESS 25% DISCOUNT		-3,866.68	-2,303.75
			11,600.02	6,911.25
	SPECIAL NETT ITEMS			
1	FRONT CORNER PANEL CHROME COVER LH (SN)	CUT	120.00	50.00
1	FRONT HEAD LAMP CHROME MOULDING LH (SN)	CUT	200.00	50.00
2	FRONT BUMPER CHROME SUPPORT (FOG LAMP) @\$150.00 (SN)	CUT	300.00	60.00
1	SET FRONT DOOR STICKER (LOGO) (SN)	NECESSARY	200.00	80.00
1	FRONT DOOR LED LIGHT LH (ASSY) (SN)	NECESSARY	180.00	60.00
1	FRONT DOOR PROTECTOR LH (SN)	CUT	450.00	150.00
1	FRONT TYRE LH (SN)	NOT NECESSARY	320.00	-
1	FRONT SPARE RIM LH (SN)	BENT	950.00	350.00
1	DOOR SIDE MIRROR CHROME COVER (SN)	CUT	120.00	40.00
1	FRONT NUMBER PLATE (SN)	SCRATCHED	100.00	40.00
2	FRONT DOOR SOUND INSULATOR @\$180.00 (SN) (ADDITIONAL)	NECESSARY	360.00	200.00
			3,300.00	1,080.00
	LABOUR			
	TOWING.		50.00	50.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL LH, FRONT TOP PANEL, FRONT CENTRE BEAM, FRONT STEP PANEL LH AND FRONT DOOR PILLAR LH.		1,200.00	1,000.00
	CHECK WIRING.		60.00	30.00

Report Ref No. CS/FCI17015463/Grbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RUST PROOFING.		60.00	40.00
	TO REMOVE & REPLACE DOOR ASSY.		80.00	60.00
	TO ADJUST ALIGNMENT.		50.00	50.00
	TO REMOVE & REPLACE UNDERCARRIAGE.		280.00	80.00
	SPRAY PAINTING.		900.00	700.00
			2,680.00	2,010.00
GRAND TOTAL			17,580.02	10,001.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00

Report Ref No. CS/FCI17015463/Grbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.