

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
TEL: 6507 3848 FAX: 6507 3849
ATTN: Motor Claim Department
Your Ref No: PC2396P
Claim Type: Third Party
Accident Date: 07-08-2017
TP Veh Reg No: SHA3907P

Estimate No: EST0000464
Date: 24 Aug 2017
Policy No: 5069592486-02
Veh Reg No: PC2396P
Make/Model: TOYOTA HIACE
Chassis No: JTFST22P00014000
Engine No: 1KD2200144
Reg. Date: 18-07-2012

Supplementary Item Repair Cost to Vehicle No :PC2396P

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
PC2396P TOYOTA HIACE				
List Price				
1 Front Cable Socket Handle LH	58.0000	1 PC	58.00	X 654
2 Front Door Side Mirror	1,130.000	1 PCS	1,130.00	
			1,188.00	
		Less 25%	297.00	891.00
Special Net				
3 Front Door Sound Insulator	180.0000	2 PCS	360.00	200 150
			360.00	
Total				SS 1,251.00

TOTAL: SINGAPORE DOLLAR ONE THOUSAND TWO HUNDRED FIFTY ONE ONLY

For PROGRESSIVE AUTO PTE LTD

Progressive Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Autobay

#02-48/50 Singapore 417883

TEL: 6844 4620 Fax: 6844 4625

AUTHORISED SIGNATURE