



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9909



Dept Direct: 6417 9794

Dept Direct: 6417 9796

Dept Direct: 6417 9796

Dept Direct: 6417 9792

Wiper blade: NWB (Nippon Wiper blade), Saliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
BLK 03 #01-18 PIONEER ROAD NOR  
SPORE 628457  
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429  
ATTN : VIVIAN / SHARON / BERTHA JANICE

TAX INVOICE : AR201708-10490  
DATE : 17/08/2017  
CUSTOMER ID : SNG001  
VEH REG. NO. : GBE8185Y  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR : SGD

| SQ | STOCKID              | DESCRIPTION     | Stk Loc      | QTY | U PRICE | AMOUNT   |
|----|----------------------|-----------------|--------------|-----|---------|----------|
| 1. | N28840-MA000<br>F24  | FRT WIPER LINK  | SG<br>K1-11B | 1   | 75.00   | 75.00 ✓  |
| 2. | N28815-MA000<br>F24  | FRT WIPER MOTOR | SG<br>N1-3B  | 1   | 320.00  | 320.00 ✓ |
| 3. | N68110-MA010A<br>F24 | MEMBER          | SG<br>P1-5   | 1   | 480.00  | 480.00 ✓ |

SUB-TOTAL 875.00  
ADD GST 7.00 % 61.25

E & O E TOTAL AMOUNT SGD 936.25

[P] 17/08/2017 5:58:29PM

[E] 17/08/2017 5:54:00PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte Ltd.

Sales Executive : GUAN

This is computer generated document.

No signature is required.



\* A H 2 0 1 7 0 8 - 1 0 4 9 0 \*

ORIGINAL

Goods Received in Good Order

Signature : Co Stamp : Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

AutoSCREEN 4-4-55  
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9910

Dept Direct: 6305 9911

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWE (Nippon Wiper blades, Siliper (Made in Korea),  
Forch (Made in Germany))

Spark plug: Nippon Denso, NGK (Made in Japan)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

BLK 03 #01-18 PIONEER ROAD NOR

SPORE 628457

CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429

ATTN : VIVIAN SHARON BERTHA JANICE

TAX INVOICE AR201708-10669

DATE 18/08/2017

CUSTOMER ID SNG001

VEH REG. NO. GBE8185Y

TERMS 30 days

PO NO.

PAGE NO. Page 1 of 1

CURR SGD

| SQ STOCKID                  | DESCRIPTION | Stk/Lec          | QTY | U PRICE | AMOUNT |
|-----------------------------|-------------|------------------|-----|---------|--------|
| X N07110-MAGIA-MADOC<br>F24 | HEATER UNIT | PA<br>PL3-C1-090 | 1   | 950.00  | 950.00 |

SUB-TOTAL 950.00  
ADD GST 7.00 % 66.50

E & OR

TOTAL AMOUNT SGD 1,016.50

[P] 18/08/2017 10:21:24AM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Accounts.

[E] 18/08/2017 10:19:31AM

JAE Auto Pte Ltd

Sales Executive GUAN

This is computer generated document.

No signature is required.



\* A # 2 0 1 7 0 8 - 1 0 6 6 9 \*

ORIGINAL

Goods Received in good order

Signature (No Stamp) Date



# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
BLK 03 #01-18 PIONEER ROAD NOR  
SPORE 628457  
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429  
ATTN : VIVIAN / SHARON / BERTHA/JANICE

WINDSCREEN GLASS  
Dept Direct: 8417 9791 / 8748 9839



Dept Direct: 8305 9810



Dept Direct: 8417 9794



Dept Direct: 8417 9795



Dept Direct: 8305 9811



Dept Direct: 8417 9792



Dept Direct: 8417 97

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

**TAX INVOICE : AR201708-10004**  
**DATE : 17/08/2017**  
**CUSTOMER ID : SNG001**  
**VEH REG. NO. : GBE8185Y**  
**TERMS : 30 days**  
**PO NO. :**  
**PAGE NO. : Page 1 of 1**  
**CURR. : SGD**

| SO STOCKID                   | DESCRIPTION                           | StkLoc                  | QTY | U/PRICE | AMOUNT |
|------------------------------|---------------------------------------|-------------------------|-----|---------|--------|
| 1. N62320-MA000/MA02B<br>F24 | RAD GRILLE                            | MO<br>3A1               | 1   | 260.00  | 260.00 |
| 2. N65092-MB40A<br>F24       | CABSTAR EMBLEM WIPER<br>PANEL         | MO                      | 1   | 25.00   | 25.00  |
| 3. N26075-MA000/A<br>F24     | H/LAMP UNIT LH                        | 2L23A<br>MO<br>SUPPLIER | 1   | 270.00  | 270.00 |
| 4. N61877-MA100/B<br>F24     | FINISHER SIDE GARNISH UPPER<br>LH (B) | MO<br>SUPPLIER          | 1   | 85.00   | 85.00  |
| 5. N99081-MB40A/C<br>F24     | NISSAN GRILLIE EMBLEM LOGO            | MO<br>SUPPLIER          | 1   | 55.00   | 55.00  |
| 6. N76988-41B00<br>F24       | GRILLE CLIP (WHITE)                   | MO<br>SUPPLIER          | 4   | 5.00    | 20.00  |
| 7. N62318-EG00A<br>F24       | GRILLE LOW CLIP "BOY"                 | MO<br>SUPPLIER          | 2   | 5.00    | 10.00  |

SUB-TOTAL : 725.00  
ADD GST 7.00 % 50.75

E. & O.E TOTAL AMOUNT SGD : 775.75

[P] 17/08/2017 11:34:44AM

[E] 17/08/2017 11:07:57AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : GUAN



\* AR201708-10004 \*

Goods Received in Good Order

*[Signature]*

Signature / Co Stamp / Date

This is computer generated document.

No signature is required.

ORIGINAL



# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
BLK 03 #01-18 PIONEER ROAD NOR  
SPORE 628457  
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429  
ATTN : VIVIAN / SHARON / BERTHA/JANICE

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9938



Dept Direct: 6305 9810



Dept Direct: 6417 9794



Dept Direct: 6305 9810



Dept Direct: 6417 9795



Dept Direct: 6417 9796



Dept Direct: 6417 9796



Dept Direct: 6305 9811



Dept Direct: 6417 9796



Dept Direct: 6417 9792



Dept Direct: 6417 9796



Dept Direct: 6417 9792



Dept Direct: 6417 9792

Wiper blade: NWB (Nippon Wiper blade), Siliper ( Made in Korea ),  
Forch ( Made in Germany )  
Spark plug: Nippon Denso, NGK (Made In Japan)

TAX INVOICE : AR201708-13421  
DATE : 23/08/2017  
CUSTOMER ID : SNG001  
VEH REG. NO. : GBE8185Y  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

| SQ STOCKID      | DESCRIPTION                           | StkLoc   | QTY | U/PRICE | AMOUNT |
|-----------------|---------------------------------------|----------|-----|---------|--------|
| 1. N62319-AU000 | GRILLE CLIP ""GIRL"" (HEAD LAMP CLIP) | MO       | 2   | 5.00    | 10.00  |
| F24 T32         |                                       | SUPPLIER |     |         |        |

SUB-TOTAL : 10.00  
ADD GST 7.00 % 0.70

E. & O.E TOTAL AMOUNT SGD : 10.70

[P] 23/08/2017 11:38:38AM

[E] 23/08/2017 11:37:43AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : GUAN



\* AR 201708-13421 \*

This is computer generated document.  
No signature is required.

Goods Received in Good Order

*[Signature]*

Signature / Co Stamp / Date

ORIGINAL





# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
BLK 03 #01-18 PIONEER ROAD NOR  
SPORE 628457  
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429  
ATTN : VIVIAN / SHARON / BERTHA/JANICE



Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6417 9794



Dept Direct: 6417 9795



Dept Direct: 6417 9796



Dept Direct: 6417 9797



Dept Direct: 6417 9798



Dept Direct: 6417 9799



Dept Direct: 6417 9800



Dept Direct: 6417 9801




Dept Direct: 6417 9802



Dept Direct: 6417 9803

|            |        |
|------------|--------|
| Arrange By | Driver |
|------------|--------|



Dept Direct: 6417 9804



Dept Direct: 6417 9805



Dept Direct: 6417 9806



Dept Direct: 6417 9807

Wiper blade: NWB (Nippon Wiper blade), Siliper ( Made in Korea ),  
Forch ( Made in Germany )  
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201708-10936  
DATE : 18/08/2017  
CUSTOMER ID : SNG001  
VEH REG. NO. : GBE8185Y  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR : SGD

| SQ STOCKID                    | DESCRIPTION       | StkLoc           | QTY | U/PRICE | AMOUNT |
|-------------------------------|-------------------|------------------|-----|---------|--------|
| 1 DN80301-MA000<br>F24CABSTAR | FRT DOOR GLASS LH | PA<br>PL1-P1-14P | 1   | 380.00  | 380.00 |

SUB-TOTAL : 380.00  
ADD GST 7.00 % 26.60

E & OE TOTAL AMOUNT SGD : 406.60

[P] 18/08/2017 1:47:41PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 18/08/2017 1:39:51PM

JAE Auto Pte Ltd.

Sales Executive : GUAN

This is computer generated document.  
No signature is required.



\* A R 2 0 1 7 0 8 - 1 0 9 3 6 \*

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  
BLK 03 #01-18 PIONEER ROAD NOR  
SPORE 628457  
CHENG PAGER :94008212

TEL : 62686183 9624964 FAX : 62681429  
ATTN : VIVIAN / SHARON / BERTHA/JANICE

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9920



Dept Direct: 6305 9810



Dept Direct: 6417 9794



Dept Direct: 6305 9811



Dept Direct: 6417 9795



Dept Direct: 6417 9792



Dept Direct: 6417 9796



Dept Direct: 6417 9792



Dept Direct: 6417 9796

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201708-13422  
DATE : 23/08/2017  
CUSTOMER ID : SNG001  
VEH REG. NO. : GBE8185Y  
TERMS : 30 days  
PO NO. :  
PAGE NO. :  
CURR : SGD  
Page 1 of 1

| SQ STOCKID             | DESCRIPTION      | StkLoc      | QTY | U/PRICE | AMOUNT |
|------------------------|------------------|-------------|-----|---------|--------|
| 1. N68101-MA000<br>F24 | PANEL INSTRUMENT | SG<br>KT-3B | 1   | 250.00  | 250.00 |

Handwritten signature/initials.

SUB-TOTAL : 250.00  
ADD GST 7.00 % 17.50

E. & O.E

TOTAL AMOUNT SGD : 267.50

[P] 23/08/2017 11:46:19AM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 23/08/2017 11:39:05AM

JAE Auto Pte. Ltd.

Sales Executive : GUAN



\* A R 2 0 1 7 0 8 - 1 3 4 2 2 \*

Goods Received in Good Order

This is computer generated document.  
No signature is required.

ORIGINAL

Signature / Co Stamp / Date



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |                                                      |                                             |                                                      |                                                       |                                                 |            |                                                                 |
|--------------------------|------------------------------------------------------|---------------------------------------------|------------------------------------------------------|-------------------------------------------------------|-------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified                                             | Est Submitted                               | Adj Assigned                                         | Adj Rpt                                               | Adj Submitted                                   | Ins Auth'd | Status                                                          |
| Main                     | 10 Aug 2017<br>10:54<br><a href="#">Sendback Est</a> | 10 Aug 2017<br>11:50<br><b>S\$11,308.50</b> | 14 Aug 2017<br>15:21<br><a href="#">Edit Adj Rpt</a> | <b>S\$11,821.70</b><br><a href="#">Edit Estimates</a> | <b>S\$11,821.70</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |
|                          | 23 Aug 2017<br>17:48                                 | 23 Aug 2017<br>17:52<br><b>S\$2,685.20</b>  | 23 Aug 2017<br>17:52                                 |                                                       |                                                 | (Combined) | <b>Combined with Main</b><br><a href="#">Uncombine Suppl.</a>   |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

#### CLAIM SUBFOLDER DETAILS

|                          |                                                                                                                         |                               |                                                                   |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------|-------------------------------|-------------------------------------------------------------------|
| <b>Insured:</b>          | ACP METAL FINISHING PTE LTD, Co. Reg. No.: 198802408E                                                                   |                               |                                                                   |
| <b>Vehicle Reg. No.:</b> | GBE8185Y                                                                                                                | <b>Date of Loss:</b>          | 02/08/2017 17:00 - :59                                            |
| <b>Claim Type:</b>       | OD / 525340                                                                                                             | <b>Policy/Cover Note No.:</b> | B28871336MKF (Comprehensive)<br>Coverage: 01/01/2017 - 31/12/2017 |
|                          |                                                                                                                         | <b>Excess:</b>                | S\$750.00                                                         |
| <b>Repairer:</b>         | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer<br>- Tel: 6268 6183 |                               |                                                                   |
| <b>Handling Insurer:</b> | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Joslin Lim - 6643 1327]                  |                               |                                                                   |
| <b>Adjuster:</b>         | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/09/2017]           |                               |                                                                   |
| <b>Driver/Custodian:</b> | LOH THIAM HWEE (51 / Male), NRIC: S1743477B, Tel: +6596664449                                                           |                               |                                                                   |
| <b>Adj Asg. Remarks:</b> | PLEASE SURVEY AND REVERT.                                                                                               |                               |                                                                   |

**ASSOCIATED MAIL RECEIVED**
[View All](#)
[Compose Case Mail](#)

- MSIG\_SG (27/11/2017): Alert - Adj Mandate Approved (S\$11821.70) - GBE8185Y - Claim Handler: Joslin Lim
- MSIG\_SG (16/08/2017): Alert - Adj Mandate Approved (S\$6393.50) - GBE8185Y - Claim Handler: Joslin Lim

**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

GBE8185Y (525340)  
OD  
Aug 2 2017 5:00PM  
[ACP METAL FINISHING PTE LTD]  
Sng Ah Tee Motor & Panel Service Pte Ltd

|                           |                 |                                                    |                    |                   |                                     |
|---------------------------|-----------------|----------------------------------------------------|--------------------|-------------------|-------------------------------------|
| Upload Documents          |                 | Upload Photos                                      | Compose New Letter | View Use Viewer ▾ |                                     |
| <b>Assessment Reports</b> |                 |                                                    |                    | 1 per page ▾      | <input checked="" type="checkbox"/> |
| No                        | Finalized On    | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) |                    | Thumbnail         | Print                               |
| 1                         | 03/08/17 15:04  | Accident Statement                                 |                    | Load HTM          |                                     |
| 2                         | 10/08/17 11:50  | Repairer Estimates                                 |                    | Load HTM          |                                     |
| 3                         | 23/08/17 17:52  | Repairer Estimates Suppl. #1                       |                    | Load HTM          |                                     |
| No                        | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                  |                    | Thumbnail         | Print                               |
| 1                         | 16/08/17 13:56  | Adjuster Immediate Advice                          |                    | Load HTM          |                                     |
| 2                         | 24/11/17 14:34  | Adjuster Immediate Advice                          |                    | Load HTM          |                                     |
| <b>Photos/Images</b>      |                 |                                                    |                    | 3 per page ▾      | <input checked="" type="checkbox"/> |
| No                        | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                  |                    | Thumbnail         | Print                               |
| 1                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 2                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 3                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 4                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 5                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 6                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 7                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 8                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 9                         | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 10                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 11                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 12                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 13                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 14                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 15                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 16                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 17                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 18                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 19                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 20                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 21                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 22                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 23                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 24                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 25                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 26                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 27                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 28                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 29                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 30                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 31                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 32                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |
| 33                        | 16/08/17 11:03  | General View                                       |                    | Load JPG          | <input checked="" type="checkbox"/> |



|    |                |                 |  |          |                                     |
|----|----------------|-----------------|--|----------|-------------------------------------|
| 34 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 35 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 36 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 37 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 38 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 39 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 40 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 41 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 42 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 43 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 44 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 45 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 46 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 47 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 48 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 49 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 50 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 51 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 52 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 53 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 54 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 55 | 16/08/17 11:03 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 56 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 57 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 58 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 59 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 60 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 61 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 62 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 63 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 64 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 65 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 66 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 67 | 16/08/17 11:04 | General View    |  | Load JPG | <input checked="" type="checkbox"/> |
| 68 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 69 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 70 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 71 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 72 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 73 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 74 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 75 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 76 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 77 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 78 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 79 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 80 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 81 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 82 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 83 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |
| 84 | 24/11/17 12:36 | RE-SURVEY PHOTO |  | Load JPG | <input checked="" type="checkbox"/> |

|                      |                 |                                   |  |            |                                     |
|----------------------|-----------------|-----------------------------------|--|------------|-------------------------------------|
| 85                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 86                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 87                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 88                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 89                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 90                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 91                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 92                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 93                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 94                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 95                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 96                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 97                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 98                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 99                   | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 100                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 101                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 102                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 103                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 104                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 105                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 106                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 107                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 108                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 109                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 110                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 111                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 112                  | 24/11/17 12:36  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 113                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 114                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 115                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 116                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 117                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 118                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 119                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 120                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 121                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 122                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| 123                  | 24/11/17 12:37  | RE-SURVEY PHOTO                   |  | Load JPG   | <input checked="" type="checkbox"/> |
| <b>Documentation</b> |                 |                                   |  | 1 per page | <input checked="" type="checkbox"/> |
| No                   | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail  | Print                               |
| 1                    | 24/11/17 14:12  | SUPPLEMENTARY                     |  | Load PDF   |                                     |
| 2                    | 28/11/17 12:03  | Parts Invoice                     |  | Load PDF   |                                     |

## Linked Accident Report Documents

|                           |                |                                                    |  |             |            |                                     |
|---------------------------|----------------|----------------------------------------------------|--|-------------|------------|-------------------------------------|
|                           |                |                                                    |  | <b>View</b> | Use Viewer | <input checked="" type="checkbox"/> |
| <b>Assessment Reports</b> |                |                                                    |  | 1 per page  |            | <input checked="" type="checkbox"/> |
| No                        | Finalized On   | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) |  | Thumbnail   | Print      |                                     |
| 1                         | 03/08/17 15:04 | Accident Statement                                 |  | Load HTM    |            |                                     |
| <b>Photos/Images</b>      |                |                                                    |  | 3 per page  |            | <input checked="" type="checkbox"/> |
| No                        | Finalized On   | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) |  | Thumbnail   | Print      |                                     |



|               |                |                                                    |  |            |       |
|---------------|----------------|----------------------------------------------------|--|------------|-------|
| 1             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 2             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 3             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 4             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 5             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 6             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 7             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 8             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 9             | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 10            | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 11            | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 12            | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 13            | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 14            | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 15            | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| 16            | 03/08/17 15:01 | Accident Photo                                     |  | Load JPG   |       |
| Documentation |                |                                                    |  | 1 per page |       |
| No            | Finalized On   | Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) |  | Thumbnail  | Print |
| 1             | 03/08/17 15:04 | Sketch Plan                                        |  | Load TIF   |       |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                                                  |  | Reset | Save | Print |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|-------|------|-------|
| There are no document checklists configured.                                                                                                                                         |  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid #ccc; height: 100px; width: 100%;"></div>                                             |  |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |  |       |      |       |

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG17015630/R1GBE2

Date: 28/11/2017

### REFERENCE

Insured/Claimant: ACP METAL FINISHING PTE LTD  
Date of Loss: 02/08/2017

Policy No: B28871336MKF

Nature of Claim: OD

Claim No: 525340

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE8185Y  
Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A) Engine No: ZD30009794N  
Reg. Date: 31/03/2016 (Man. Year: 2016) Chassis No: JN1SC2F24Z0858335  
Colour: White Odometer: 35476 km  
Engine Capacity: 2953 cc  
Market Value/New Car Price: S\$75,000.00  
Sum Insured (\$\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 175/80 R15 Rear Tyre Size: 155 R13 (D)  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6/6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

|                                      | Repairer's       | Adjuster's       | Difference      | Diff %       |
|--------------------------------------|------------------|------------------|-----------------|--------------|
| Parts                                | 10,983.70        | 9,091.70         | 1,892.00        | 17.23        |
| Miscellaneous Items                  | 0.00             | 0.00             | 0.00            |              |
| Labour                               | 3,010.00         | 2,730.00         | 280.00          | 9.30         |
| Paintwork Labour                     | 0.00             | 0.00             | 0.00            |              |
| Towing                               | 0.00             | 0.00             | 0.00            |              |
| <b>Calculated Gross Total (\$\$)</b> | <b>13,993.70</b> | <b>11,821.70</b> | <b>2,172.00</b> | <b>15.52</b> |
| <b>- Excess (\$\$)</b>               | <b>750.00</b>    | <b>750.00</b>    | <b>0.00</b>     | <b>0.00</b>  |
| <b>(\$\$)</b>                        | <b>13,243.70</b> | <b>11,071.70</b> | <b>2,172.00</b> | <b>16.40</b> |
| <b>+ GST 7.00/7.00% (\$\$)</b>       | <b>927.06</b>    | <b>775.02</b>    | <b>152.04</b>   | <b>16.40</b> |
| <b>Nett Amount (\$\$)</b>            | <b>14,170.76</b> | <b>11,846.72</b> | <b>2,324.04</b> | <b>16.40</b> |

### INSPECTION

Date of Assignment: 14/08/2017

Date Inspected: 15/08/2017 Inspected At:

Sng Ah Tee Motor & Panel Service Pte  
Ltd (Pioneer)  
Blk 3 Pioneer Road North, #01-18  
Singapore 628457

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





## REPAIR DETAILS

|                      |                                                                                                                                                                              |                                                                                  |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------|
| <b>Reference</b>     |                                                                                                                                                                              |                                                                                  |
| <b>Part Source:</b>  | (Last Synchronised: 28 Nov 2017)                                                                                                                                             |                                                                                  |
| <b>Parts:</b>        | N/A                                                                                                                                                                          | NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                                |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for GBE8185Y)                                                                                                                                    |                                                                                  |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                                  |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                                  |

## Recommended Parts

| No.                     | Qty | Part No. | Particulars                         | Condition                       | Repairer's | Amount    |
|-------------------------|-----|----------|-------------------------------------|---------------------------------|------------|-----------|
| 1                       | 1   |          | *FRONT BUMPER WITH REINFORCEMENT    | Cut                             | 450.00 F   | *450.00 F |
| 2                       | 1   |          | *FRONT GRILLE                       | Cracked                         | 260.00 F   | *260.00 F |
| 3                       | 8   |          | *FRONT GRILLE CLIP                  | Necessary                       | 40.00 F    | *40.00 F  |
| 4                       | 1   |          | *FRONT GRILLE EMBLEM                | Not Necessary                   | 55.00 F    | *- F      |
| 5                       | 1   |          | *FRONT CORNER PANEL                 | Bent                            | 185.00 F   | *185.00 F |
| 6                       | 1   |          | *FRONT CORNER PANEL CABSTAR LOGO    | Necessary                       | 25.00 F    | *25.00 F  |
| 7                       | 1   |          | *FRONT WIPER PANEL                  | Deformed                        | 320.00 F   | *320.00 F |
| 8                       | 1   |          | *FRONT HEADLAMP                     | N/S Cracked / O/S Not Necessary | 540.00 F   | *270.00 F |
| 9                       | 1   |          | *FRONT HEADLAMP LOWER GARNISH LH    | Deformed                        | 55.00 F    | *55.00 F  |
| 10                      | 1   |          | *FRONT SIDE MIRROR ARM COVER LH     | Missing                         | 85.00 F    | *85.00 F  |
| 11                      | 1   |          | *FRONT SIDE MIRROR ARM TOP COVER LH | Missing                         | 15.00 F    | *15.00 F  |
| 12                      | 1   |          | *FRONT SIDE MIRROR ROUND CAP LH     | Not Necessary                   | 15.00 F    | *- F      |
| 13                      | 1   |          | *FRONT SIDE MIRROR ARM LH           | Not Necessary                   | 135.00 F   | *- F      |
| 14                      | 1   |          | *FRONT DOOR LH                      | Bent                            | 680.00 F   | *680.00 F |
| 15                      | 1   |          | *FRONT DOOR INNER WEATHER STRIPS LH | Not Necessary                   | 75.00 F    | *- F      |
| 16                      | 1   |          | *FRONT DOOR GLASS LH                | Cut                             | 380.00 F   | *380.00 F |
| 17                      | 1   |          | *FRONT DOOR REGULATOR LH            | Not Necessary                   | 80.00 F    | *- F      |
| 18                      | 1   |          | *FRONT DOOR LOCK LH                 | Not Necessary                   | 110.00 F   | *- F      |
| 19                      | 2   |          | *FRONT DOOR HINGE                   | Not Necessary                   | 80.00 F    | *- F      |
| 20                      | 1   |          | *FRONT DOOR WEATHER STRIPE LH       | Not Necessary                   | 75.00 F    | *- F      |
| 21                      | 1   |          | *FRONT WINDSCREEN                   | Cracked                         | 650.00 F   | *650.00 F |
| 22                      | 1   |          | *ERP BRACKET                        | Necessary                       | 26.00 FS   | *26.00 FS |
| 23                      | 1   |          | *FRONT WINDSCREEN SEALANT           | Necessary                       | 40.00 FS   | *40.00 FS |
| 24                      | 1   |          | *FRONT WINDSCREEN INNER GARNISH LH  | Deformed                        | 90.00 F    | *90.00 F  |
| 25                      | 1   |          | *FRONT WINDSCREEN MOULDING          | Necessary                       | 200.00 F   | *200.00 F |
| 26                      | 1   |          | *FRONT DASHBOARD                    | Deformed                        | 900.00 F   | *320.00 F |
| 27                      | 1   |          | *FRONT DASHBOARD LOWER COVER LH     | Not Necessary                   | 125.00 F   | *- F      |
| 28                      | 1   |          | *FRONT DASHBOARD SUPPORT BEAM LH    | Bent                            | 500.00 F   | *480.00 F |
| 29                      | 1   |          | *AIR CON BLOWER ASSY                | Cracked                         | 450.00 F   | *400.00 F |
| 30                      | 1   |          | *HEATER BLOWER ASSY                 | Cracked                         | 1,000.00 F | *950.00 F |
| 31                      | 1   |          | *ROC STICKER                        | Necessary                       | 20.00 FS   | *20.00 FS |
| <b>Supplementary #1</b> |     |          |                                     |                                 |            |           |
| 32                      | 1   |          | *FRT PANEL                          | Bent                            | 600.00 F   | *600.00 F |
| 33                      | 1   |          | *FRT SIDE MIRROR LH                 | Cut                             | 80.00 F    | *80.00 F  |

Report was unsubmitted during this print-out.



| No. | Qty | Part No. | Particulars                    | Condition | Repairer's | Amount    |
|-----|-----|----------|--------------------------------|-----------|------------|-----------|
| 34  | 1   |          | *FRT WIPER PANEL TOP SEAL      | Cut       | 32.00 F    | *32.00 F  |
| 35  | 1   |          | *FUSE BOX HOUSING              | Cracked   | 300.00 F   | *300.00 F |
| 36  | 1   |          | *FRT WIPER LINKAGE ASSY        | Bent      | 75.00 F    | *75.00 F  |
| 37  | 1   |          | *FRT WIPER MOTOR               | Dented    | 320.00 F   | *320.00 F |
| 38  | 1   |          | *FRT DOOR CHECKER(LH)          | Bent      | 35.00 F    | *35.00 F  |
| 39  | 1   |          | *FRT DASHBOARD LH              | Deformed  | 320.00 F   | *320.00 F |
| 40  | 1   |          | *FRT DASHBOARD RH              | Deformed  | 320.00 F   | *320.00 F |
| 41  | 1   |          | *FRT DASHBOARD TOP FRONT COVER | Cracked   | 250.00 F   | *250.00 F |

F=Franchise part. S=SpcNett.

|                                          |          |          |
|------------------------------------------|----------|----------|
| Sub Total (S\$)                          | 9,993.00 | 8,273.00 |
| + Margin on L,N Items 10.00/10.00% (S\$) | 990.70   | 818.70   |

|                   |           |          |
|-------------------|-----------|----------|
| Total Parts (S\$) | 10,983.70 | 9,091.70 |
|-------------------|-----------|----------|

|                                               |
|-----------------------------------------------|
| Report was unsubmitted during this print-out. |
|-----------------------------------------------|

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                 | Lab.Type | Repairer's | Amount   |
|-------------------------|---------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>     |                                             |          |            |          |
| 1                       | TO REMOVE & REFIX ROOFLING                  | New      | 100.00     | 60.00    |
| 2                       | TO REMOVE & REFIX FRONT DASHBOARD           | New      | 180.00     | 180.00   |
| 3                       | TO REMOVE & REFIX FRONT WINDSCREEN          | New      | 120.00     | 120.00   |
| 4                       | TO TRANSFER FRONT DOOR GLASS                | New      | 60.00      | 60.00    |
| 5                       | TO REFILL AIR CON GAS                       | New      | 100.00     | 100.00   |
| 6                       | TO CHECK WIRING                             | New      | 30.00      | 30.00    |
| 7                       | TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS   | New      | 1,200.00   | 1,100.00 |
| 8                       | TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS | New      | 1,100.00   | 1,000.00 |
| <u>Supplementary #1</u> |                                             |          |            |          |
| <u>Labour Items</u>     |                                             |          |            |          |
| 9                       | TO REMOVE & REFIT FRT SEAT & UPHOLSTERY     | New      | 120.00     | 80.00    |
| Gross Labour Cost (S\$) |                                             |          | 3,010.00   | 2,730.00 |

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;