

ASS. REC. BY:

REF: CG/smo17010664/Dqbn2

Special Instruction:

Surveyor

Byron

ASSIGNMENT (Office)

From (Person):

Irene

of

SMO

Date/Time: 11/08/07 12:42pm

Estimated Cost:

Bill to:

OD (X) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJU 9133L

Insured:

GBC 9256E

at Workshop m/s

Teamwork

Tel:

6344 2475

of

53 Ubi Ave 1 #01-24

Policy No:

Claim No:

CMTD1703790 / ASG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 1103207

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

11/08/07 1:14pm

Person Contacted:

Chris

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJU 9133L - X
	GBC 9256E - X



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17015664/Dgb

50 RAFFLES PLACE
#05-01/06

Date : 14-08-2017



SINGAPORE LAND TOWERSINGAPORE 048623

Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 9256E	Veh. Inspected	SJU 9133L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1702790/GSG	Excess (\$)	0.00
Assign From	IRENE	Assign Date	14/08/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	11/08/2017	Inspection Date	14/08/2017
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Catherine Chong (LKK Auto)

From: Henry, Irene James <irene.henry@sompo.com.sg>
Sent: Monday, 14 August, 2017 12:42 PM
To: assignments@lkkauto.com
Cc: Ashley Chong (LKK Auto)
Subject: RE: OUR REF: 1708-27 YOUR REF: GBC9256E PRE-REPAIR INSPECTION FOR SJU9133L

Our Reference: CMTD1702790/GSG

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SJU 9133L).

Please refer to the email correspondence below.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: CLAIMS@TEAMWORKGARAGE.COM [mailto:claims@teamworkgarage.com]
Sent: Monday, 14 August, 2017 11:38 AM
To: Henry, Irene James <irene.henry@sompo.com.sg>; assignments@lkkauto.com
Cc: Goh, Siew Geok Janice <janice.goh@sompo.com.sg>; claims@teamworkgarage.com
Subject: OUR REF: 1708-27 YOUR REF: GBC9256E PRE-REPAIR INSPECTION FOR SJU9133L
Importance: High

WITHOUT PREJUDICE

OUR REF: 1708-27
YOUR REF: GBC9256E

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SJU9133L
ACCIDENT INVOLVING SJU9133L & GBC9256E ON 11.08.2017

We have agreed and selected the surveyor / surveyor company proposed by you to conduct the pre-repair inspection as a single joint expert whereby the cost of the pre-repair survey carried out by single joint expert will be bear by you.

We have selected :

LKK AUTO CONSULTANTS

as the motor surveyor / surveyor company named in your attached list.

Kindly forward your assignment to them asap so that we can arrange for the survey with them.

**Do get the surveyor / surveyor office to check with us on the availability of the car at the workshop before sending their surveyor down for PRI survey. We'll not be held responsible for wasted trips made to the workshop.*

Jc

Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

.....
IMPORTANT NOTICE:

This message is intended only for the attention of the addressee and may contain legally privileged and/or confidential information. Its unauthorised use, disclosure, storage or copying is not permitted. If you are not the intended recipient, please permanently delete the original, destroy all copies and inform the sender.
.....

From: Henry, Irene James [<mailto:irene.henry@sompo.com.sg>]
Sent: Monday, 14 August 2017 09:55 AM
To: TEAMWORK GARAGE CLAIMS
Cc: Goh, Siew Geok Janice
Subject: ***SPAM*** RE: OUR REF: 1708-27 YOUR REF: GBC9256E PRE-REPAIR INSPECTION FOR SJU9133L

Our Reference: CMTD1702790/GSG
Your Reference: 1708-27

Date: 14TH August 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S TEAMWORK GARAGE PTE LTD

ACCIDENT INVOLVING GBC 9256E & SJU 9133L ON 11 AUGUST 2017

Dear Sir

We refer to your Notice of Accident via email dated 12.08.2017.

Please be informed that Janice Goh is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Irene Henry

Claims Division

D: 6322 4618 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: TEAMWORK GARAGE CLAIMS [<mailto:claims@teamworkgarage.com>]
Sent: Saturday, 12 August, 2017 11:15 AM
To: Motor Survey <MotorSurvey@sompo.com.sg>
Cc: claims@teamworkgarage.com
Subject: OUR REF: 1708-27 YOUR REF: GBC9256E PRE-REPAIR INSPECTION FOR SJU9133L
Importance: High

WITHOUT PREJUDICE

OUR REF: 1708-27
YOUR REF: GBC9256E

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SJU9133L
ACCIDENT INVOLVING SJU9133L & GBC9256E ON 11.08.2017

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

Please let us have your list of surveyors for us to select as stated in the Practice Direction – Amendment No. 1 of 2016; Pre-action Protocol within 2 working days as of the date of our notice to you.

Please take notice: We will not entertain any of your surveyor calling us for the above inspection, without you giving us your list of surveyors for us to select by the Practice Direction of Pre-repair Inspection.

Darren Ng
Teamwork Garage Pte Ltd
53 Ubi Avenue 1
#01-24 Paya Ubi Industrial Park
Singapore 408934
Tel: 68442475
Fax: 68442474

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/08/2017 17:43
Date Of Accident	11/08/2017 16:00
Exact Location Of Accident	UBI AVE 1 - UBI CRES
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJU9133L
Insured/Policyholder	
Name Of Registered Owner	SGZ SERVICES
Co Reg No	53365774A
Email Address	SIMONTAN76@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-86665557
Vehicle Particulars	
Manufacturer	NISSAN
Model	LATIO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	ACT
Fleet Policy	NO
Policy Number	2017-V0101575-VDP
Cover Note Number	
Driver	
Name of Driver	SIMON TAN LIE HWANG
NRIC No	S7632423I
Date Of Birth	09/10/1976
Occupation	OUTDOOR
Date Of Driving Pass	24/09/1997
Driving Experience	19 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83331383
Fax Number	
Contact Number	
EMail Address	SIMONTAN76@GMAIL.COM

Address BLK 308B PUNGGOL WALK #160358 8222308
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC9256E
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver NA
 NRIC/Passport Number
 Contact Number NA
 Address NA
 Postcode NA
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name NA
 Phone Number NA
 Email Address NA

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SJK7482U

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver NA

NRIC/Passport Number NA

Contact Number NA

Address NA

Postcode NA

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name NA

Phone Number NA

Email Address NA

DETAILS OF INJURED PERSON 1

Name SIMON TAN LIE HWANG

Approximate Age

Injuries Sustain UNKNOWN

Injured person in which vehicle? SJU9133L

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
SGZ SERVICES
 Policyholder's Signature / Date & Time

[Signature]
 Driver's Signature (If driver is not the policyholder) / Date & Time
 11 August 5:40 PM

[Signature]
 Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

My car was completely stationary without any contact with the front stationary vehicle. All of sudden, I felt a huge impact from my car rear. The huge impact from the rear caused my car to thrust forward and hit onto the front vehicle. After the accident, I came out of my car and found that total 3 vehicles involved in the accident.




SGZ SERVICES

Declaration

We declare the foregoing particulars are true in every respect.


SGZ SERVICES
Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Teamwork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475 Fax : 6844 2474
 E-mail : claims@teamworkgarage.com
 Register number : 201015366H
 ROC number : 201015366H

Sompo Insurance Pte Ltd
 50 Raffles Place , #05-01/06
 Singapore Land Tower
 Singapore 048623

3RD PARTY CLAIM ESTIMATION

Vehicle number	: SJU9133L
Make / Model	: NISSAN/LATIO
Chassis number	: JN1BAAC11Z0021552
Accident date	: 11 August 201
Reference	: 1708-27

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER <i>distorted</i>	436.00 736.30 ✓
1	CENTRE TOP PANEL <i>ry</i>	645.90 X
1	BONNET <i>ry</i>	891.20 X
1	REAR BUMPER <i>ry</i>	519.80 709.90 ✓
1	END PANEL <i>ry</i>	442.60 641.70 ✓
2	TAILLAMP PANEL <i>ols Bnc n/s ry</i>	132.40 264.80 ✓
1	REAR RH FENDER <i>Dented</i>	1142.80 ✓
1	BOOTLID <i>ry</i>	764.69 ✓
1	SPARE TYRE COMPARTMENT <i>ry</i>	1071.50 X
		6868.79
	Less 30%	2060.63
		4808.16
<u>PARTS REPLACEMENT - NETT ITEMS</u>		
2	FRONT BUMPER RETAINER <i>ry</i>	120.10 X
1	FRONT BUMPER REINFORCEMENT <i>Dented</i>	533.90 ✓
1	FRONT BUMPER SPONGE <i>torn</i>	282.90 ✓
1	FRONT BUMPER EMBLEM LOGO <i>ry</i>	45.80 ✓
1	FRONT GRILLE <i>crack</i>	226.80 ✓
1	CENTRE TOP PANEL GARNISH <i>ry</i>	296.10 X
2	FRONT HEADLAMP <i>n/s crack ols n/s</i>	344.59 699.10 ✓ <i>349.55</i>
2	FRONT HEADLAMP BRACKET <i>ry</i>	127.50 X
1	BONNET LOCK <i>ry</i>	132.60 X
2	REAR BUMPER SIDE RETAINER <i>ry</i>	135.10 X
1	REAR END PANEL GARNISH <i>distorted</i>	173.80 ✓
1	END PANEL KEY ACCESS CONTROL <i>broken</i>	157.49 ✓
2	REAR TAILLAMP <i>broken</i>	619.10 ✓
2	FENDER INNER TRIM <i>torn</i>	542.10 ✓
1	REAR WINDSCREEN GLASS <i>ry</i>	189.60 X
1	BOOTLID WEATHERSTRIP <i>distorted</i>	159.70 ✓
1	BOOTLID EMBLEM LOGO-NISSAN <i>ry</i>	54.00 ✓
1	BOOTLID EMBLEM LOGO - LATIO <i>ry</i>	66.29 ✓
1	BOOTLID OUTER CHROME STRIP <i>crack mounting</i>	257.40 357.30 ✓
1	BOOTLID LOCK <i>ry</i>	197.50 ✓
1	BOOTLID LOCK STRIKER <i>ry</i>	80.70 ✓

Vehicle number : SJU9133L

Make Model : NISSAN/LATIO

Reference : 1708-27

Qty	Particulars	Unit Price - SGD \$
2	BOOTLID HINGE <i>1st</i>	151.80 ✓
1	SPARE TYRE BOARD <i>1st</i>	495.13 ✓
1	EXHAUST ASSY <i>MM</i>	720.56 x
2	EXHAUST MOUNTING <i>MM</i>	80.00 x
		6644.97
	Less 10 %	664.49
	Subtotal	5980.48
	Balance C/F	10788.64
	<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>	
	Balance B/F	10788.64
1	FRONT NUMBER PLATE <i>Crack</i>	80.00 35/-
1 SET	FRONT BUMPER CLIP <i>Mc</i>	70.00 30/-
1 SET	REAR REVERSE SENSOR <i>Dem</i>	400.00 220/-
1 SET	REAR BUMPER CLIP <i>Mc</i>	70.00 30/-
1 SET	REAR FENDER INNER TRIM CLIP <i>Mc</i>	60.00 30/-
1	JOINT SEALANT <i>Mc</i>	150.00 40/-
1	WINDSCREEN SEALANT <i>Mc</i>	150.00 40/-
	Subtotal	37294.71
	Balance C/F	48083.35
	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	48083.35
1	CHECK FRONT, REAR WIRING AND LIGHTNING SYSTEM	80.00 60/-
2	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
3	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 60/-
5	REMOVE AND REFIT FUEL TANK	150.00 40/-
6	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
7	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60/-
8	PANEL BEATING ON AFFECTED AREAS	1800.00 1400/-
9	SPRAY PAINTING ON AFFECTED AREAS	1500.00 1200/-
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00 80/-
	Subtotal	4530.00
	Grand total	52613.35
		20956.80
		9886.36
		157900/-

4393.96
3954.56

4251-

3100/-

LKK Auto Consultants hence notify
 9. **SPRAY PAINTING ON AFFECTED AREAS**
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 10. **APPLY ANTI RUST ON AFFECTED AREAS**
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Admitted by Repairer
 Signature:
 Date:

14/08/2017 @ 1430ms
 H/A Antimal
 L/Sum
 9 days.
 LKK Auto

✓ Check MV
 ✓ Check Part Prices.

16298.64



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17015664/Dgbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 22-12-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 9256E	Veh. Inspected	SJU 9133L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1702790/GSG	Excess (\$)	0.00
Assign From	IRENE	Assign Date	14/08/2017

2. Vehicle Particulars & Condition

Make & Model	NISSAN LATIO	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JN1BAAC11Z0021552	Colour	RED
Odometer	127904	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R15	CRUCERO	5 mm
L/H Front Tyre	195/60 R15	CRUCERO	5 mm
R/H Rear Tyre	195/60 R15	CRUCERO	5 mm
L/H Rear Tyre	195/60 R15	CRUCERO	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/08/2017	Inspection Date	14/08/2017
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 9133L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DISTORTED	736.30	436.00
1	CENTRE TOP PANEL	TO REPAIR SEE LABOUR	645.90	-
1	BONNET	TO REPAIR SEE LABOUR	891.20	-
1	REAR BUMPER	BUCKLED	709.90	519.80
1	END PANEL	BUCKLED	641.70	442.60
2	TAILLAMP PANEL	O/S BUCKLED / N/S TO REPAIR SEE LABOUR	264.80	132.40
1	REAR RH FENDER	DENTED	1,142.80	1,142.80
1	BOOTLID	BUCKLED	764.69	764.69
1	SPARE TYRE COMPARTMENT	TO REPAIR SEE LABOUR	1,071.50	-
	LESS 30% DISCOUNT		-2,060.63	-1,031.49
			4,808.16	2,406.80
<u>NETT ITEMS</u>				
2	FRONT BUMPER RETAINER (N)	SERVICEABLE	120.10	-
1	FRONT BUMPER REINFORCEMENT (N)	DENTED	533.90	533.90
1	FRONT BUMPER SPONGE (N)	TORN	282.90	282.90
1	FRONT BUMPER EMBLEM LOGO (N)	NECESSARY	45.80	45.80
1	FRONT GRILLE (N)	CRACKED	226.80	226.80
1	CENTRE TOP PANEL GARNISH (N)	SERVICEABLE	296.10	-
2	FRONT HEADLAMP (N)	N/S CRACKED / O/S NOT NECESSARY	699.10	349.55
2	FRONT HEADLAMP BRACKET (N)	SERVICEABLE	127.50	-
1	BONNET LOCK (N)	SERVICEABLE	132.60	-
2	REAR BUMPER SIDE RETAINER (N)	SERVICEABLE	135.10	-
1	REAR END PANEL GARNISH (N)	DEFORMED	173.80	173.80
1	END PANEL KEY ACESS CONTROL (N)	BROKEN	157.49	157.49
2	REAR TAILLAMP (N)	BROKEN	619.10	619.10
2	FENDER INNER TRIM (N)	TORN	542.10	542.10
1	REAR WINDSCREEN GLASS (N)	SERVICEABLE	189.60	-
1	BOOTLID WEATHERSTRIP (N)	DEFORMED	159.70	159.70
1	BOOTLID EMBLEM LOGO-NISSAN (N)	NECESSARY	54.00	54.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID EMBLEM LOGO-LATIO (N)	NECESSARY	66.29	66.29
1	BOOTLID OUTER CHROME STRIP (N)	MTG CRACKED	357.30	257.40
1	BOOTLID LOCK (N)	BENT	197.50	197.50
1	BOOTLID LOCK STRIKER (N)	BENT	80.70	80.70
2	BOOTLID HINGE (N)	BENT	151.80	151.80
1	SPARE TYRE BOARD (N)	BENT	495.13	495.13
1	EXHAUST ASSY (N)	NOT NECESSARY	720.56	-
2	EXHAUST MOUNTING (N)	NOT NECESSARY	80.00	-
	LESS 10% DISCOUNT		-664.49	-439.40
			5,980.48	3,954.56
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	CRACKED	80.00	35.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	70.00	30.00
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	400.00	220.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	70.00	30.00
1	SET REAR FENDER INNER TRIM CLIP (SN)	NECESSARY	60.00	30.00
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	150.00	40.00
			980.00	425.00
	<u>LABOUR</u>			
	CHECK FRONT,REAR WIRING AND LIGHTING SYSTEM.		80.00	60.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH.		200.00	80.00
	REMOVE AND RENEW REAR EXHAUST ASSY.		150.00	60.00
	REMOVE AND REFIT FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE AND REFIT REAR WINDSCREEN.		150.00	120.00
	TRANSFER PARTS,ATTACHMENT FROM OLD BOOTLID TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF CENTRE TOP PANEL,BONNET,N/S TAILLAMP PANEL AND SPARE TYRE COMPARTMENT.		1,800.00	1,400.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,500.00	1,200.00
	APPLY ANTI-RUST ON AFFECTED AREAS.		150.00	80.00
			4,530.00	3,100.00
	GRAND TOTAL		16,298.64	9,886.36

Report Ref No. CS/SMO17015664/Dgbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,900.00
---	--	--	-----------------

Report Ref No. CS/SMO17015664/Dgbn2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.