

2002/10/02

ASS. REC. BY:

REF:

08/CTU7015752/Turb

Special Instruction:

Surveyor:

Toufik

ASSIGNMENT (Office)

From (Person):

Merimen

Jawyn Tay

of

CTU

Date/Time: 15082017 4:02pm

Estimated Cost:

Bill to:

☒ TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

XD 5577G

Insured:

at Workshop m/s

Singapore Technologies

Tel:

6660 3571

of

31 Corporation Road

Policy No:

DMCVGN13U 261605

Claim No:

SNM170 01172001

Sum Insured:

Excess:

\$ 5000.00

Make of Veh:

D.O.A

21022017

(Client's Record)

CA / ☒ REV / REP. / REV 24 HRS

16-08-2017

H.O.D. Endorsement:

Date/Time:

15082017 4:17pm

Person Contacted:

Jumari

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

9699 2818

XD 5577G -X

31/8-

Revert via merimen

6/9/17

Authorise repair ; called Singapore Technologies for authorise repair and excess

Confirm

\$11,089.87 @ 10 days (Red: \$ 5321.24, 32%)

2011/13

REF: CTL

Surveyor

Tanjong

Mufiman

ASSIGNMENT

From:

Date:

16082017

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

XD 5597G

at Workshop m/s

Singapore Technologies

of

31 Corporation Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$ 5000.00

(Client's Record)

Make of Veh:

Jumari

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
XX	XX

Bal. or Market Value:

\$90K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

XD5597G. Yr Regn: 2011/Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAN TGS 26.400

c.c 10518

Colour

Yellow

A/C:

Insured / Std / NI / NA

Sp. Reading

—

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WM A26527X BM 572793

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: W / S/Rim / STD A/Rim or

Tyre Size:

F:

315/80R27.5

R:

1. (D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

D.O.I.

10/8/17 @ 1130

Survey held at

Singapore Technologies

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear body, platform.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Jumari

bs@stengg.com

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

1)

typist

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

10

Resurvey No. of Trip:

3

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format:

09

Lump Sum / I.B.I: (\$ 11089.87)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CS/CTI17015752/T1rb	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 15-08-2017	
			Code : CTI	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.			Veh. Inspected	XD 5597G
Policy No.	DMCVSN1134261605		Coverage (\$)	0.00
Claim No.	SNM17D01172C01		Excess (\$)	5,000.00
Assign From	MERIMEN (JOWYN TAY)		Assign Date	15/08/2017
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/02/2017		Inspection Date	16/08/2017
Survey held at	31 CORPORATION RD			
Repairer	SINGAPORE TECHNOLOGIES KINETICS LTD			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Aug 2017		15 Aug 2017 16:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		KIM HENG MARINE & OILFIELD PTE LTD, Co. Reg. No.: 197800703R							
Vehicle Reg. No.:		XD5597G	Date of Loss:	21/02/2017 14:00 - :59					
Claim Type:		OD / SNM17D01172C01	Policy/Cover Note No.:	DMCVSN1134261605 (Comprehensive) Coverage: 29/12/2016 - 28/12/2017					
			Excess:	S\$5,000.00					
Repairer:		Singapore Technologies Kinetics Ltd (Jalan Boon Lay) STAR Building, No 249 Jalan Boon Lay, 619523 Boon Lay - Tel: 6515 3011							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/08/2017]							
Driver/Custodian:		WONG YONG CHIN (46 / Male), NRIC: S7101551C							
Adj Asg. Remarks:		PLEASE PROCEED TO SURVEY/REVERT AND TO CONTACT JUMARI SULMAN. EXCESS OF \$5,000.00 APPLIES.							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 31 Aug 2017

Preliminary Advice

Vehicle No	: XD5597G	Accident Date	: 21/02/2017
Make	: MAN TGS 26.400	Policy No.	: DMCVSN1134261605
Assignment Date	: 15/08/2017	Excess	: S\$5,000.00
Date of Inspection	: 16/08/2017	Est. Duration of Repair	: 10.00
Inspection At	: SINGAPORE TECHNOLOGIES KINETICS LTD (JALAN BOON LAY) STAR BUILDING, NO 249 JALAN BOON LAY SINGAPORE 619523		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear body platform portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,411.11
Revised Amount	:S\$	9,521.19
Check Items (Estimated)	:S\$	5,152.33
Total	:S\$	14,673.52

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	16,008.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,992.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

***XD5597G (SNM17D01172C01)**

OD

Feb 21 2017 2:00PM

[KIM HENG MARINE & OILFIELD PTE LTD]
Singapore Technologies Kinetics Ltd

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 06/09/2017 12:08 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14673.52) - XD5597G - Claim Handler: Jowyn Tay

Approved:14673.52:Please proceed to authorize repairs UP TO \$14,673.52 BEFORE Excess of \$5,000.00. RE-INSPECTION of vehicle required.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0703R

Vehicle Details

Vehicle No.: XD5597G

Vehicle to be Exported: No

Intended De-registration
Date: 17 Aug 2018

Vehicle Make: MAN

Vehicle Model: TGS 26.400 6X4 BBS

Primary Colour: Yellow

Manufacturing Year: 2011

Engine No.: 50526751602876

Chassis No.: WMA26SZZXBM572793

Maximum Power Output: -

Open Market Value: \$120,447.00

Original Registration Date: 29 Dec 2011

First Registration Date: 29 Dec 2011

Transfer Count: 0

Actual ARF Paid: \$6,023.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Dec 2021

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$37,011.00

COE Rebate Amount: \$12,446.00

Total Rebate Amount: \$12,446.00

The information contained herein is correct as at 17 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 13 Aug 2017 at 12:41 AM

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 0703R

Vehicle Details

Vehicle No.: XD5597G

Vehicle to be Exported: No

Intended De-registration
Date: 31 Aug 2017

Vehicle Make: MAN

Vehicle Model: TGS 26 400 6X4 BBS

Primary Colour: Yellow

Manufacturing Year: 2011

Engine No.: 50528751602876

Chassis No.: WMA26SZZXBM572793

Maximum Power
Output: -

Open Market Value: \$120,447.00

Original Registration
Date: 29 Dec 2011

First Registration Date: 29 Dec 2011

Transfer Count: 0

Actual ARF Paid: \$6,023.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry
Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 28 Dec 2021

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$37,011.00

COE Rebate Amount: \$16,008.00

Total Rebate Amount: \$16,008.00

The information contained herein is correct as at 31 Aug 2017

OK



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 27 Aug 2017 at 01:09 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/02/2017 11:07
Date Of Accident	21/02/2017 14:10
Exact Location Of Accident	AYE TOWARDS TUAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD5597G
Insured/Policyholder	
Name Of Registered Owner	KIM HENG MARINE & OILFIELD PTE LTD
Co Reg No	197800703R
Email Address	VINCENT.POH@KIMHENG.COM.SG
Mobile Phone No	(LOCAL) +65-91880013
Alternative Phone No	OFFICE-91880013

Vehicle Particulars

Manufacturer	MAN
Model	TGS 26.400 6X4 BBS

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? **YES**

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1134261605
Cover Note Number	

Driver

Name of Driver	WONG YONG CHIN
NRIC No	S7101551C
Date Of Birth	12/01/1971
Occupation	OUTDOOR
Date Of Driving Pass	22/12/1997
Driving Experience	19 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


[Signature]

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan



[illegible]

We declare the foregoing particulars are true in every respect.



✓ 




Witnessed by Reporting Centre
Personnel

S/No	Part No.	Description	Qty
1	81-41860-0274	COVER	1
2	06-43809-0185	TRUNNION	2
3	06-43809-0184	RETAINING PLATE	2
4	81-15110-0512	GUARD PLATE	1
5	81-61210-0675	MUDGUARDS LEFT REAR	1
6	81-62750-0042	REAR WINDOW	1
7	81-42902-5375	BRACKET	1
8	81-42902-5389	CARRIER	1
9	81-42902-0288	STEP	2
10	06-01471-0509	HEXAGON SCREW	8
11	81-42902-5402	RADIUS ROD	2
12	81-42902-0292	CATWALK	1
13	06-02253-0404	PAN-HEAD SCREW	2
14	06-02259-0046	PAN-HEAD SCREW	2
15	06-02253-0405	PAN-HEAD SCREW	4
16	06-04303-2915	OVAL-HEAD COUNTERSUNK SCREW	4
17	06-04309-0038	OVAL-HEAD COUNTERSUNK SCREW	4
18	81-42902-5327	SUPPORT	1
19	81-12201-5920	FUEL TANK 390L (8 81-12201-5920	1
20	81-41801-2843	BRACKET	2
21	81-12240-0066	FUEL TANK SUPPORT	2
22	81-97460-6077	STRAP	2
23	81-12210-6027	BAYONET CAP 80-ML-S-ST-ZN	1
		END	

Type L 26S 00	Pet 10.11	Group 610 0	Chassis No. 5373 WMA26SZZXBM572793	
Table rear window				
Reference No. 81.62750-7001 - rear window centre right tinted green F99L/R15-37				

610310600



Pos	Part No.	Description	Pat	All	Unit	Qty
1	81.62750-0035	rear window centre 1090-1046X391, 2X5-ESG-SD-GNGT tinted green			1	Pcs
2	81.62750-0042	rear window right 276,5/246,6X390, 2X5-ESG-SD-GNG tinted green			1	Pcs

Type L 26S 00	Pat 10.11	Group 661 0	Chassis No. 5373 WMA26SZZXBM572793	
Table mudguard, rear				
Reference No. 81.#0482-0499 34.08 - mudguards 3-part + mud flap SH 468-538 (NBA)				


Pos	Part No.	Description	Pat	All	Unit	Qty
7	81.66420-6393	Mudguard support			1	Pcs
8	81.66420-6393	Mudguard support			1	Pcs
9	81.66420-6392	Mudguard support			1	Pcs
10	81.66420-6131	Mudguard support			1	Pcs
11	81.66420-6132	Mudguard support			1	Pcs
12	81.66410-6606	mudguards centre part 690			4	Pcs
13	81.66440-0192	> rubber mounting			4	Pcs
14	81.66410-6599	mudguards assembly 690			1	Pcs
14		for individual parts see reference number not available as complete unit			*	Pcs
15	81.66410-6599	mudguards assembly 690			1	Pcs
15		for individual parts see reference number not available as complete unit			*	Pcs
16	81.66410-6627	mudguards assembly 690X918			1	Pcs
16		not available as complete unit for individual parts see plate and/or reference number			*	Pcs
17	81.66410-6628	mudguards assembly 690X918			1	Pcs
17		not available as complete unit for individual parts see plate and/or reference number			*	Pcs
18	81.66410-6626	mudguards assembly			1	Pcs
19	81.66410-6631	mudguards assembly			1	Pcs
20	81.66410-6605	mudguards assembly 690X918 rear			1	Pcs
20		for individual parts see reference number not available as complete unit			*	Pcs
21	81.66410-6605	mudguards assembly 690X918 rear			1	Pcs
21		for individual parts see reference number not available as complete unit			*	Pcs

Type L 26S 00	Pet 10.11	Group 261 0	Chassis No. 5373 WMA26SZZXBM572793	
Table battery box				
Reference No. 81.#0460-0327 26.06 - battery 2X155AH and battery box small version				

Pos	Part No.	Description	Pat	All	Unit	Qty
10	81.97809-0814	adhesive label 65X28/KST-GE/SW			1	Pcs
11	81.41860-0144	cover battery box	21.16		1	Pcs
11	81.41860-0274	cover			1	Pcs
12	06.43809-0176	locking pin	24.12		2	Pcs
12	06.43809-0185	trunnion lock			2	Pcs
13	06.43809-0074	retaining plate	24.12		2	Pcs
13	06.43809-0184	retaining plate			2	Pcs
14	81.41801-0286	intermediate bracket battery box			1	Pcs
15	06.02813-4913	hex lock screw M14X1,5X40-10.9-MAN183-B1			6	Pcs
16	06.02813-4914	hex lock screw M14X1,5X45-10.9-MAN183-B1			2	Pcs
17	06.11251-2005	hex lock nut M14X1,5-10-MAN183-B1			8	Pcs
18		fig. deleted			*	Pcs
19	81.41860-5369	angle bracket assembly	25.14		1	Pcs
19	81.41860-5419	angle bracket left			1	Pcs
20	81.41860-5368	angle bracket assembly	25.14		1	Pcs
20	81.41860-5418	angle bracket assembly right			1	Pcs


Type L 26S 00	Pet 10.11	Group 261 0	Chassis No. 5373 WMA26SZZXBM572793	
Table battery box				
Reference No. 81.#0460-0327 26.06 - battery 2X155AH and battery box small version				

260058200



Pos	Part No.	Description	Pat	All	Unit	Qty
1	81.41860-5392	battery box lower part small version	24.12		1 Pcs	
1	81.41860-5400	battery box assembly small version	36.13		1 Pcs	
1	81.41860-5410	battery box assembly for individual parts see reference number			1 Pcs * Pcs	
2	81.41820-0221	packing 437X460X4			1 Pcs	
3	81.95101-0142	stud M8X50X50X260-ST50-2K-MAN183-B1			4 Pcs	
4	06.11251-2018	hex lock nut M8-10-MAN183-B1			8 Pcs	
5	81.41860-0148	retainer			1 Pcs	
6	81.41860-0149	retainer			1 Pcs	
7	06.11229-0015	hex collar lock nut M8-8-MAN183-B1			4 Pcs	
8		deleted			* Pcs	
9	81.97801-0935	adhesive label 90X33/KST-SW/CR			1 Pcs	

Type L 26S 00	Pet 10.11	Group 412 0	Chassis No. 5373 WMA26SZZXBM572793	
Table working platform				
Reference No. 81.#04P1-0002 21.99 - working platform + foothold right (with fuel tank)				




Pos	Part No.	Description	Pat	All	Unit	Qty
1	81.42902-0297	catwalk centre			1 Pcs	
2	81.42902-0301	bracket catwalk rear			1 Pcs	
3	81.42902-0299	bracket catwalk left front			1 Pcs	
4	81.42902-5329	bracket assembly			1 Pcs	
5	06.02813-4911	hex lock screw M14X1,5X30-10.9-MAN183-B1			1 Pcs	
6	06.02813-4912	hex lock screw M14X1,5X35-10.9-NACHGER-MAN183			3 Pcs	
7	06.11251-2005	hex lock nut M14X1,5-10-MAN183-B1			4 Pcs	
8	81.96210-0528	rubber-to-metal pad M8X6X6-30X20-NR/SBR4-70			6 Pcs	
9	06.01283-5110	hexagon screw M8X12-8.8-MAN183-B1	12.16		3 Pcs	
9	06.01283-5139	hexagon screw M8X14-8.8-MAN183-B1			3 Pcs	
	06.15193-0309	washer 8X24X2-200HV-MAN183-B1			3 Pcs	

Type L 26S 00	Pet 10.11	Group 412 0	Chassis No. 5373 WMA26SZZXBM572793	
Table working platform				
Reference No. 81.#04P1-0002 21.99 - working platform + foothold right (with fuel tank)				

Pos	Part No.	Description	Pat	All	Unit	Qty
24	06.04309-0038	oval-head countersunk screw with internal torx M8X30-8.8-FE//ZNNI8//CN			4	Pcs
25	81.42902-5327	support assembly			1	Pcs
26	06.02813-4912	hex lock screw M14X1,5X35-10. 9-NACHGER-MAN183	12.12		2	Pcs
26	06.02813-4914	hex lock screw M14X1,5X45-10.9-MAN183-B1			2	Pcs
27	06.02813-4911	hex lock screw M14X1,5X30-10.9-MAN183-B1			2	Pcs
28	06.11251-2005	hex lock nut M14X1,5-10-MAN183-B1			4	Pcs
29	06.02813-4406	hex lock screw M10X16-10.9-MAN183-B1			2	Pcs
30	06.02813-4306	hex lock screw M8X16-10.9-MAN183-B1			4	Pcs
30	06.11251-2018	hex lock nut M8-10-MAN183-B1			4	Pcs
31	81.42902-5335	hand rail assembly			1	Pcs
32	06.02813-4908	hex lock screw M14X1,5X20-10.9-MAN183-B1	11.12		2	Pcs
32	06.02813-4910	hex lock screw M14X1,5X25-10.9-MAN183-B1			2	Pcs
33	06.02813-4910	hex lock screw M14X1,5X25-10.9-MAN183-B1	12.12		2	Pcs
33	06.02813-4912	hex lock screw M14X1,5X35-10. 9-NACHGER-MAN183			2	Pcs
34	06.11251-2005	hex lock nut M14X1,5-10-MAN183-B1			4	Pcs

Type L 26S 00	Pet 10.11	Group 120 0	Chassis No. 5373 WMA26SZZXBM572793	
Table fuel prefilter				
Reference No. 81.#1240-0454 - fuel prefilter SEPAR (unheated)				

120144103



Pos	Part No.	Description	Pat	All	Unit	Qty
1	81.12501-6085	fuel prefilter assembly unheated > for individual parts see plate and/or reference number			1 Pcs * Pcs	
2	81.98130-6046	straight union			2 Pcs	
3	81.12540-0110	bracket			1 Pcs	
4	06.02813-4411	hex lock screw M10X30-10.9-MAN183-B1			3 Pcs	
5	06.11251-2001	hex lock nut M10-10-MAN183-B1			3 Pcs	
6	06.02813-4309	hex lock screw M8X22-10.9-MAN183-B1			2 Pcs	
7	06.11229-0015	hex collar lock nut M8-8-MAN183-B1			2 Pcs	
8	81.12540-6004	hose pipe assembly	27.11		1 Pcs	
8	81.96330-0193	hose 10X2,5X300-SW			1 Pcs	
9		item number 9 - 10 deleted			* Pcs	



ST Kinetics

A company of ST Engineering

Singapore Technologies
Kinetics Ltd
No.31 Corporation Road
Singapore 649025
Tel: (65) 6060 3995
Fax: (65) 6264 1296
http://www.stengg.com
(Regn. No.: 197100253n)



QUOTATION FOR SPECIFIED REPAIRS AND SERVICES

To	: CHINA TAIPING	Date of Quotation	: 04-08-17
Vehicle No.	: XD5597G	Quotation No	: STK / AR / 2017 / 0032
Make/Model	: MAN TGS 26.400 6X4 BBS	Date Vehicle In	:
Attention	: Joel Goh	Telephone	: 6389 6184
JobCardNo	:	Fax	: 6224 7175 / 6224 7478

S/N	Description	Qty	Unit Price	Selling Price
	<u>Labour Charges.</u>			
1	To panel beat & straighten chassis area. <i>400</i>			\$ 2,800.00
2	To spray paint cabin head.			\$ 1,500.00
				\$ 4,300.00
	<u>Material Replace.</u>			
1	COVER	1	\$ 194.58	\$ 194.58
2	TRUNNION	2	\$ 13.50	\$ 27.00
3	RETAINING PLATE	2	\$ 1.20	\$ 2.40
4	GUARD PLATE	1	\$ 203.60	\$ 203.60
5	MUDGUARDS LEFT REAR	1	\$ 358.29	\$ 358.29
6	REAR WINDOW	1	\$ 87.99	\$ 87.99
7	BRACKET	1	\$ 339.68	\$ 339.68
8	CARRIER	1	\$ 306.54	\$ 306.54
9	STEP	2	\$ 33.46	\$ 66.92
10	HEXAGON SCREW	8	\$ 3.91	\$ 31.28
11	RADIUS ROD	2	\$ 48.86	\$ 97.72
12	CATWALK <i>top panel side step RH</i>	1	\$ 288.81	\$ 288.81
13	PAN-HEAD SCREW	2	\$ 2.59	\$ 5.18
14	PAN-HEAD SCREW	2	\$ 0.79	\$ 1.58
15	PAN-HEAD SCREW	4	\$ 1.34	\$ 5.36
16	OVAL-HEAD COUNTERSUNK SCREW	4	\$ 2.28	\$ 9.12
17	OVAL-HEAD COUNTERSUNK SCREW	4	\$ 1.86	\$ 7.44
18	SUPPORT	1	\$ 504.92	\$ 504.92
19	FUEL TANK 390L	1	\$ 2,631.68	\$ 2,631.68
20	BRACKET	2	\$ 748.85	\$ 1,493.70
21	FUEL TANK SUPPORT	2	\$ 59.90	\$ 119.80
22	STRAP	2	\$ 94.09	\$ 188.18
23	BAYONET CAP 80-ML-S-ST-ZN	1	\$ 79.33	\$ 79.33
24	3" HIGH STANDARD STEEL PLATFORM	3	\$ 550.00	\$ 1,650.00
25	STEEL PIPE CAB GUARD STANDARD *	1	\$ 1,100.00	\$ 1,100.00
26	TAIL LAMP	2	\$ 55.00	\$ 110.00

**ST Kinetics**

A company of ST Engineering

Singapore Technologies

Kinetics Ltd

No.31 Corporation Road

Singapore 64825

Tel: (65) 6880 3995

Fax: (65) 6294 1298

http://www.stengg.com

(Regn. No.: 197100263n)

**QUOTATION FOR SPECIFIED REPAIRS AND SERVICES**

To : CHINA TAIPING

Date of Quotation : 04-08-17

Vehicle No. : XD5597G

Quotation No : STK / AR / 2017 / 0032

Make/Model : MAN TGS 26.400 6X4 BBS

Date Vehicle In :

Attention : Joel Goh

Telephone : 6389 6184

JobCardNo :

Fax : 6224 7175 / 6224 7478

S/N	Description	Qty	Unit Price	Selling Price
<u>Labour Charges.</u>				
1	To panel boat & straighten chassis area.			\$ 2,300.00
2	To spray paint cabin head.			\$ 800.00
				\$ 3,100.00
<u>Material Replace.</u>				
1	MUDGUARDS LEFT REAR	1	\$ 358.29	\$ 358.29
2	REAR WINDOW	1	\$ 87.99	\$ 87.99
3	BRACKET	1	\$ 339.68	\$ 339.68
4	CARRIER	1	\$ 306.54	\$ 306.54
5	STEP	2	\$ 33.46	\$ 66.92
6	HEXAGON SCREW	8	\$ 3.91	\$ 31.28
7	CATWALK	1	\$ 288.81	\$ 288.81
8	PAN-HEAD SCREW	2	\$ 2.59	\$ 5.18
9	PAN-HEAD SCREW	2	\$ 0.79	\$ 1.58
10	PAN-HEAD SCREW	4	\$ 1.34	\$ 5.36
11	OVAL-HEAD COUNTERSUNK SCREW	4	\$ 2.28	\$ 9.12
12	OVAL-HEAD COUNTERSUNK SCREW	4	\$ 1.85	\$ 7.44
13	FUEL TANK 390L	1	\$ 2,631.68	\$ 2,631.68
14	3" HIGH STANDARD STEEL PLATFORM	3	\$ 550.00	\$ 1,650.00
15	STEEL PIPE CAB GUARD STANDARD	1	\$ 1,100.00	\$ 1,100.00
16	TAIL LAMP	2	\$ 55.00	\$ 110.00
17	AIR COUPLING ANGLE BAR FRAME	1	\$ 330.00	\$ 330.00
18	STEEL STEP UP RACK	1	\$ 660.00	\$ 660.00
				\$ 7,989.87
<u>Note:</u>				
1. This quotation is an estimate list based on our visual inspection. Additional parts need replacement will be advised accordingly.				
2. Subject to parts availability.				
3. Duration of repair : 8 - 10 working days				

Payment Term: Cash payment upon delivery.
 Validity of Quote: 14 - working days from quotation.

Total	\$ 11,089.87
GST	\$ 776.29
Grand Total	\$ 11,866.16

**ST Kinetics**

A subsidiary of ST Engineering

Singapore Technologies
Kinetics Ltd
No.31 Corporation Road
Singapore 649825
Tel: (65) 6900 3688
Fax: (65) 6254 1296
<http://www.stengg.com>
(Regn. No.: 197100253N)

**QUOTATION FOR SPECIFIED REPAIRS AND SERVICES**

To	: CHINA TAIPING	Date of Quotation	: 04-08-17
Vehicle No.	: XD5597G	Quotation No	: STK / AR / 2017 / 0032
Make/Model	: MAN TGS 26.400 6X4 BBS	Date Vehicle In	:
Attention	: Joel Goh	Telephone	: 6389 6184
JobCardNo	:	Fax	: 6224 7175 / 6224 7478

Please contact the undersigned should you require details or clarifications
Thank You.

Yours faithfully,

Jumar Sulman

NELSON SEAH
Assistant Manager
Kinetics Automotive Services

Commercial Vehicle Division

Tel: 66603971

Fax: 62647642

Confirm by,

Authorized Signature
& Company Stamp

Name

Date

**ST Kinetics**

A company of ST Engineering

Singapore Technologies
Kinetics Ltd
No. 51 Corporation Road
Singapore 645025
Tel: (65) 6680 3936
Fax: (65) 6284 1296
http://www.kinetics.com
(Regn. No.: 107100282C)

**QUOTATION FOR SPECIFIED REPAIRS AND SERVICES**

To : CHINA TAIPING

Date of Quotation : 04-08-17

Vehicle No. : XD5597G

Quotation No : STK / AR / 2017 / 0032

Make/Model : MAN TGS 26.400 6X4 BBS

Date Vehicle In :

Attention : Joel Goh

Telephone : 8389 8184

JobCardNo :

Fax : 6224 7175 / 6224 7478

S/N	Description	Qty	Unit Price	Selling Price
	<u>Labour Charges.</u>			
1	To panel beat & straighten chassis area. 300			\$ 2,800.00
2	To spray paint cabin head.			\$ 1,500.00
				\$ 4,300.00
	<u>Material Replace.</u>			
1	COVER	1	\$ 194.58	\$ 194.58 X
2	TRUNNION	2	\$ 13.50	\$ 27.00 X
3	RETAINING PLATE	2	\$ 1.20	\$ 2.40 X
4	GUARD PLATE	1	\$ 203.60	\$ 203.60 X
5	MUDGUARDS LEFT REAR	1	\$ 358.29	\$ 358.29 der
6	REAR WINDOW	1	\$ 87.99	\$ 87.99 cre
7	BRACKET	1	\$ 339.88	\$ 339.88 bt
8	CARRIER	1	\$ 308.54	\$ 308.54 bt
9	STEP	2	\$ 33.48	\$ 66.92 bt
10	HEXAGON SCREW	8	\$ 3.91	\$ 31.28 new
11	RADIUS ROD	2	\$ 48.86	\$ 97.72 7
12	CATWALK top panel side step RH.	1	\$ 288.81	\$ 288.81 bt
13	PAN-HEAD SCREW	2	\$ 2.59	\$ 5.18 ?
14	PAN-HEAD SCREW	2	\$ 0.79	\$ 1.58 ?
15	PAN-HEAD SCREW	4	\$ 1.34	\$ 5.36 ?
16	OVAL-HEAD COUNTERSUNK SCREW	4	\$ 2.28	\$ 9.12 ?
17	OVAL-HEAD COUNTERSUNK SCREW	4	\$ 1.86	\$ 7.44 ?
18	SUPPORT	1	\$ 504.92	\$ 504.92 ?
19	FUEL TANK 390L	1	\$ 2,031.68	\$ 2,031.68 dd
20	BRACKET	2	\$ 746.85	\$ 1,493.70 ?
21	FUEL TANK SUPPORT	2	\$ 59.90	\$ 119.80 ?
22	STRAP	2	\$ 94.09	\$ 188.18 ?
23	BAYONET CAP 80-ML-S-ST-ZN	1	\$ 79.33	\$ 79.33 ?
24	3" HIGH STANDARD STEEL PLATFORM	3	\$ 550.00	\$ 1,650.00 bt
25	STEEL PIPE CAB GUARD STANDARD *	1	\$ 1,100.00	\$ 1,100.00 ? bt
26	TAIL LAMP cabin tail lamp	2	\$ 55.00	\$ 110.00 new



ST Kinetics

A company of ST Engineering

Singapore Technologies
Kinetics Ltd
No. 51 Corporation Road
Singapore 649025
Tel: (65) 6800 8888
Fax: (65) 6264 1288
http://www.stengg.com
(Regn. No.: 197100283s)



QUOTATION FOR SPECIFIED REPAIRS AND SERVICES

To	: CHINA TAIPING	Date of Quotation	: 04-08-17
Vehicle No.	: XD5597G	Quotation No.	: STK / AR / 2017 / 0032
Make/Model	: MAN TGS 26.400 6X4 BBS	Date Vehicle In	:
Attention	: Joel Goh	Telephone	: 6389 6184
JobCardNo	:	Fax	: 6224 7175 / 6224 7478

27	STEEL TOOL BOX MOUNT ON TOP CHASSIS FRAME	1	\$ 880.00	\$ 880.00
28	AIR COUPLING ANGLE BAR FRAME	1	\$ 330.00	\$ 330.00
29	STEEL STEP UP RACK	1	\$ 660.00	\$ 660.00
30	PAINTING GREEN PRIMER & FINISHING BLACK PAINT (nett)	1	\$ 330.00	\$ 330.00
				\$ 12,111.11
Note: 1. This quotation is an estimate list based on our visual inspection. Additional parts need replacement will be advised accordingly. 2. Subject to parts availability. 3. Duration of repair : 8 - 10 working days				

Total \$ 16,411.11

GST \$ 1,148.78

Grand Total \$ 17,559.88

Payment Term: Cash payment upon delivery.

Validity of Quote: 14 - working days from quotation.

Please contact the undersigned should you require details or clarifications

Thank You.

Yours faithfully,

Juman Sultan

Commercial Vehicle Division

Tel: 66603971

Fax: 62647642

Bryan Yeo

Head,

Kinetics Automotive Services

Confirm by:

Authorized Signature
& Company Stamp

Name

Date

Taufik 97495719

Ex \$5000.

16/8/17

Revent Not Authorized

* Resurvey before paint.

* Resurvey new parts

sur@1kleant.com

taufik@1kleant.com

10 days.

DISCHARGE VOUCHER

This is to certify the Vehicle Number: 960 5597 G has repaired in Singapore Technologies Kinetics LTD to my satisfaction and I had taken the delivery at 0930 am/pm on this date 31/10/2017



Signature & Co. Stamp (if applicable)

Janice Lee (LKKAuto)

From: jumaribs@stengg.com
Sent: Thursday, July 19, 2018 9:44 AM
To: Janice Lee (LKKAuto)
Cc: yap.kimhong@stengg.com
Subject: XD5597G - Own Damaged Claim (China Taiping).
Attachments: XD5597G - APPROVED SURVEYOR MARKING.pdf; XD5597G - DISCHARGE VOUCHER.pdf; XD5597G - FINALIZE (AFTER SURVEYOR MARKING)..pdf

Hi Ms Janice,

As spoken and explained, please assist to take a look into this case.

Best regards,
Jumari Sulman

ST Engineering Land Systems Ltd.

Email: jumaribs@stengg.com

We are now  **ST Engineering**
Land Systems

*Formerly known as ST Kinetics

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	15 Aug 2017		15 Aug 2017 16:02 Edit Adj Rpt	S\$11,089.87 Edit Estimates	S\$11,089.87 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	KIM HENG MARINE & OILFIELD PTE LTD, Co. Reg. No.: 197800703R								
Vehicle Reg. No.:	XD5597G	Date of Loss:	21/02/2017 14:00 - :59 [61 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM17D01172C01	Policy/Cover Note No.:	DMCVSN1134261605 (Comprehensive) Coverage: 29/12/2016 - 28/12/2017						
		Excess:	S\$5,000.00						
Repairer:	Singapore Technologies Kinetics Ltd (Jalan Boon Lay) STAR Building, No 249 Jalan Boon Lay, 619523 Boon Lay - Tel: 6515 3011								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/08/2017]								
Driver/Custodian:	WONG YONG CHIN (46 / Male), NRIC: S7101551C								
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY/REVERT AND TO CONTACT JUMARI SULMAN. EXCESS OF \$5,000.00 APPLIES.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
CHINA_TAIPING (06/09/2017): Alert - Adj Mandate Approved (S\$14673.52) - XD5597G - Claim Handler: Jowyn Tay									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*XD5597G (SNM17D01172C01)
 OD
 Feb 21 2017 2:00PM
 [KIM HENG MARINE & OILFIELD PTE LTD]
 Singapore Technologies Kinetics Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)		Thumbnail	Print
1	23/02/17 09:21	Accident Statement		Load HTM	
2	12/07/17 14:11	Addendum Sheet		Load JPG	☒
3	12/07/17 14:12	Accident Statement Addm. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/08/17 16:36	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)		Thumbnail	Print
1	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
2	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
3	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
4	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
5	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
6	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
7	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
8	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
9	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
10	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
11	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
12	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
13	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
14	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
15	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
16	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
17	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
18	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
19	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
20	22/02/17 11:30	Accident Photo [Linked Accident Report Documents]		Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/08/17 16:37	General View		Load JPG	☒
2	31/08/17 16:37	General View		Load JPG	☒
3	31/08/17 16:37	General View		Load JPG	☒
4	31/08/17 16:37	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
5	31/08/17 16:37	General View	 Load JPG	☒
6	31/08/17 16:37	General View	 Load JPG	☒
7	31/08/17 16:37	General View	 Load JPG	☒
8	31/08/17 16:37	General View	 Load JPG	☒
9	31/08/17 16:37	General View	 Load JPG	☒
10	31/08/17 16:37	General View	 Load JPG	☒
11	31/08/17 16:37	General View	 Load JPG	☒
12	31/08/17 16:37	General View	 Load JPG	☒
13	31/08/17 16:37	General View	 Load JPG	☒
14	23/07/18 10:57	General View	 Load JPG	☒
15	23/07/18 10:57	General View	 Load JPG	☒
16	23/07/18 10:57	General View	 Load JPG	☒
17	23/07/18 10:57	General View	 Load JPG	☒
18	23/07/18 10:57	General View	 Load JPG	☒
19	23/07/18 10:57	General View	 Load JPG	☒
20	23/07/18 10:57	General View	 Load JPG	☒
21	23/07/18 10:57	General View	 Load JPG	☒
22	23/07/18 10:57	General View	 Load JPG	☒
23	23/07/18 10:57	General View	 Load JPG	☒
24	23/07/18 10:57	General View	 Load JPG	☒
25	23/07/18 10:57	General View	 Load JPG	☒
26	23/07/18 10:57	General View	 Load JPG	☒
27	23/07/18 10:57	General View	 Load JPG	☒
28	23/07/18 10:57	General View	 Load JPG	☒
29	23/07/18 10:57	General View	 Load JPG	☒
30	23/07/18 10:57	General View	 Load JPG	☒
31	23/07/18 10:57	General View	 Load JPG	☒
32	23/07/18 10:57	General View	 Load JPG	☒
33	23/07/18 10:57	General View	 Load JPG	☒
34	23/07/18 10:57	General View	 Load JPG	☒
35	23/07/18 10:57	General View	 Load JPG	☒
36	23/07/18 10:57	General View	 Load JPG	☒
37	23/07/18 10:57	General View	 Load JPG	☒
38	23/07/18 10:57	General View	 Load JPG	☒
39	23/07/18 10:57	General View	 Load JPG	☒
40	23/07/18 10:57	General View	 Load JPG	☒
41	23/07/18 10:57	General View	 Load JPG	☒
42	23/07/18 10:57	General View	 Load JPG	☒
43	23/07/18 10:57	General View	 Load JPG	☒
44	23/07/18 10:57	General View	 Load JPG	☒
45	23/07/18 10:57	General View	 Load JPG	☒
46	23/07/18 10:57	General View	 Load JPG	☒
47	23/07/18 10:57	General View	 Load JPG	☒
48	23/07/18 10:57	General View	 Load JPG	☒
49	23/07/18 10:57	General View	 Load JPG	☒
50	23/07/18 10:57	General View	 Load JPG	☒
51	23/07/18 10:57	General View	 Load JPG	☒
52	23/07/18 10:57	General View	 Load JPG	☒
53	23/07/18 10:57	General View	 Load JPG	☒
54	23/07/18 10:57	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
55	23/07/18 10:57	General View	 Load JPG	☒
56	23/07/18 10:57	General View	 Load JPG	☒
57	23/07/18 10:57	General View	 Load JPG	☒
58	23/07/18 10:57	General View	 Load JPG	☒
59	23/07/18 10:57	General View	 Load JPG	☒
60	23/07/18 10:57	General View	 Load JPG	☒
61	23/07/18 10:57	General View	 Load JPG	☒
62	23/07/18 10:57	General View	 Load JPG	☒
63	23/07/18 10:57	General View	 Load JPG	☒
64	23/07/18 10:57	General View	 Load JPG	☒
65	23/07/18 10:57	General View	 Load JPG	☒
66	23/07/18 10:57	General View	 Load JPG	☒
67	23/07/18 10:57	General View	 Load JPG	☒
68	23/07/18 10:57	General View	 Load JPG	☒
69	23/07/18 10:57	General View	 Load JPG	☒
70	23/07/18 10:57	General View	 Load JPG	☒
71	23/07/18 10:57	General View	 Load JPG	☒
72	23/07/18 10:57	General View	 Load JPG	☒
73	23/07/18 10:57	General View	 Load JPG	☒
74	23/07/18 10:57	General View	 Load JPG	☒
75	23/07/18 10:57	General View	 Load JPG	☒
76	23/07/18 10:57	General View	 Load JPG	☒
77	23/07/18 10:57	General View	 Load JPG	☒
78	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
79	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
80	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
81	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
82	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
83	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
84	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
85	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
86	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
87	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
88	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
89	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
90	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
91	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
92	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
93	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
94	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
95	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
96	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
97	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
98	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
99	23/07/18 10:58	Reinspection Photo 1	 Load JPG	☒
100	23/07/18 10:59	Reinspection Photo 2	 Load JPG	☒
101	23/07/18 10:59	Reinspection Photo 2	 Load JPG	☒
102	23/07/18 10:59	Reinspection Photo 2	 Load JPG	☒
103	23/07/18 10:59	Reinspection Photo 2	 Load JPG	☒
104	23/07/18 10:59	Reinspection Photo 2	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
105	23/07/18 10:59	Reinspection Photo 2	 Load JPG	☒
106	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
107	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
108	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
109	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
110	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
111	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
112	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
113	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
114	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
115	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
116	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
117	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
118	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
119	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
120	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
121	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
122	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
123	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
124	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
125	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
126	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
127	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
128	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
129	23/07/18 11:01	Reinspection Photo 3	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/08/17 15:50	Quotation/Replacement/Repair invoice	 Load PDF	
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	22/02/17 11:28	CI-CHINA TAIPING [Linked Accident Report Documents]	 Load JPG	☒
2	22/02/17 11:28	CI-CHINA TAIPING [Linked Accident Report Documents]	 Load JPG	☒
3	22/02/17 11:28	BACK IC & DL DRIVER [Linked Accident Report Documents]	 Load JPG	☒
4	22/02/17 11:28	FRONT IC & DL DRIVER [Linked Accident Report Documents]	 Load JPG	☒
5	22/02/17 11:28	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
6	22/02/17 11:28	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
7	22/02/17 11:28	POLICE DEPT REPORT NO. [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	23/02/17 09:21	Accident Statement	 Load HTM	
2	12/07/17 14:11	Addendum Sheet	 Load JPG	☒
3	12/07/17 14:12	Accident Statement Addm. #1	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print

Assessment Reports			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	22/02/17 11:30	Accident Photo	 Load JPG	☒
2	22/02/17 11:30	Accident Photo	 Load JPG	☒
3	22/02/17 11:30	Accident Photo	 Load JPG	☒
4	22/02/17 11:30	Accident Photo	 Load JPG	☒
5	22/02/17 11:30	Accident Photo	 Load JPG	☒
6	22/02/17 11:30	Accident Photo	 Load JPG	☒
7	22/02/17 11:30	Accident Photo	 Load JPG	☒
8	22/02/17 11:30	Accident Photo	 Load JPG	☒
9	22/02/17 11:30	Accident Photo	 Load JPG	☒
10	22/02/17 11:30	Accident Photo	 Load JPG	☒
11	22/02/17 11:30	Accident Photo	 Load JPG	☒
12	22/02/17 11:30	Accident Photo	 Load JPG	☒
13	22/02/17 11:30	Accident Photo	 Load JPG	☒
14	22/02/17 11:30	Accident Photo	 Load JPG	☒
15	22/02/17 11:30	Accident Photo	 Load JPG	☒
16	22/02/17 11:30	Accident Photo	 Load JPG	☒
17	22/02/17 11:30	Accident Photo	 Load JPG	☒
18	22/02/17 11:30	Accident Photo	 Load JPG	☒
19	22/02/17 11:30	Accident Photo	 Load JPG	☒
20	22/02/17 11:30	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Cheng Auto Bodyworks (HQ)	Thumbnail	Print
1	22/02/17 11:28	CI-CHINA TAIPING	 Load JPG	☒
2	22/02/17 11:28	CI-CHINA TAIPING	 Load JPG	☒
3	22/02/17 11:28	BACK IC & DL DRIVER	 Load JPG	☒
4	22/02/17 11:28	FRONT IC & DL DRIVER	 Load JPG	☒
5	22/02/17 11:28	Accident Sketch Plan	 Load JPG	☒
6	22/02/17 11:28	Accident Sketch Plan	 Load JPG	☒
7	22/02/17 11:28	POLICE DEPT REPORT NO.	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI17015752/T1RBQ2

Date: 26/07/2018

REFERENCE

Insured/Claimant: KIM HENG MARINE & OILFIELD PTE LTD Policy No: DMCVSN1134261605
Date of Loss: 21/02/2017 Nature of Claim: OD Claim No: SNM17D01172C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XD5597G
Make & Model: MAN TGS 26.400, 10.5 D 6X4 BBS (M) Engine No: 50528751602876
Reg. Date: 29/12/2011 (Man. Year: 2011) Chassis No: WMA26SZZXBM572793
Colour: Yellow Odometer: 0 km
Engine Capacity: 10518 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 315/80 R22.5 Rear Tyre Size: 315/80 R22.5 (D)
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8/8 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,111.10	7,989.87	4,121.23	34.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	3,100.00	1,200.00	27.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,411.10	11,089.87	5,321.23	32.42
- Excess (S\$)	5,000.00	5,000.00	0.00	0.00
(S\$)	11,411.10	6,089.87	5,321.23	46.63
+ GST 7.00/7.00% (S\$)	798.78	426.29	372.49	46.63
Nett Amount (S\$)	12,209.88	6,516.16	5,693.72	46.63

INSPECTION

Date of Assignment: 15/08/2017

Date Inspected: 16/08/2017 Inspected At:

31 CORPORATION ROAD
Repairer: Singapore Technologies Kinetics
Ltd (Jalan Boon Lay)

Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jul 2018)	
Parts:	N/A	MAN TGS 26.400 10.5 D 6X4 BBS (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD5597G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page.	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER	Not Necessary	194.58 F	*- F
2	2	*TRUNNION	Not Necessary	27.00 F	*- F
3	2	*RETAINING PLATE	Not Necessary	2.40 F	*- F
4	1	*GUARD PLATE	Not Necessary	203.60 F	*- F
5	1	*MUDGUARDS LEFT REAR	Deformed	358.29 F	*358.29 F
6	1	*REAR WINDOW	Cracked	87.99 F	*87.99 F
7	1	*BRACKET	Bent	339.68 F	*339.68 F
8	1	*CARRIER	Bent	306.54 F	*306.54 F
9	2	*STEP	Bent	66.92 F	*66.92 F
10	8	*HEXAGON SCREW	Necessary	31.28 F	*31.28 F
11	2	*RADIUS ROD	Not Necessary	97.72 F	*- F
12	1	*CATWALK	Bent	288.81 F	*288.81 F
13	2	*PAN -HEAD SCREW	Necessary	5.18 F	*5.18 F
14	2	*PAN -HEAD SCREW	Necessary	1.58 F	*1.58 F
15	4	*PAN -HEAD SCREW	Necessary	5.36 F	*5.36 F
16	4	*OVAL-HEAD COUNTERSUNK SCREW	Necessary	9.12 F	*9.12 F
17	4	*OVAL-HEAD COUNTERSUNK SCREW	Necessary	7.44 F	*7.44 F
18	1	*SUPPORT	Not Necessary	504.92 F	*- F
19	1	*FUEL TANK 390L	Dented	2,631.68 F	*2,631.68 F
20	2	*BRACKET	Not Necessary	1,493.70 F	*- F
21	2	*FUEL TANK SUPPORT	Not Necessary	119.80 F	*- F
22	2	*STRAP	Not Necessary	188.18 F	*- F
23	1	*BAYONET CAP 80-ML-S-ST-ZN	Not Necessary	79.33 F	*- F
24	3	*3 HIGH STANDARD STEEL PLATFORM	Bent	1,650.00 F	*1,650.00 F
25	1	*STEEL PIPE CAB GUARD STANDARD	Bent	1,100.00 F	*1,100.00 F
26	2	*TAIL LAMP	Cracked	110.00 F	*110.00 F
27	1	*STEEL TOOL BOX MOUNT ON TOP CHASSIS FRAME	Not Necessary	880.00 F	*- F
28	1	*AIR COUPLING ANGLE BAR FRAME	Bent	330.00 F	*330.00 F
29	1	*STEEL STEP UP BACK	Bent	660.00 F	*660.00 F
30	1	*PAINTING GREEN PRIMER & FINISHING BLACK PAINT	Not Necessary	330.00 F	*- F

F=Franchise part.

Total Parts (\$\$) **12,111.10** **7,989.87**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT & STRAIGHTEN CHASSIS AREA	New	2,800.00	2,300.00
2	TO SPRAY PAINT CABIN HEAD	New	1,500.00	800.00
Gross Labour Cost (\$\$)			4,300.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >