

ASS. REC. BY:

REF: CS/MSG17015764/Tlgbe2 Special Instruction:

SUPERVISOR:

Tallith

ASSIGNMENT (Office)

Medium

From (Person): Vimmala

of

MSH

Date/Time: 15082017 11:26am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

9JZ 7932J

Insured:

at Workshop m/s

Performance

Tel:

9116 599

of

303 Alexander Road

Policy No:

B27121149SMP

Claim No:

526249

Sum Insured:

Excess:

\$1500.00

Make of Veh:

D.O.A. 12-08-2017

(Client's Record)

CA / KEY / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15082017 11:8pm

Person Contacted:

Meina

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	9JZ 7932J - X
16/8/17@ 3:30pm	Revert to Vimmala via Meina.
16/8/17@ 5:12pm	Kenny Ong informed C/A via Meina.
16/8/17@ 5:37pm	Informed Meina C/A \$ ex: \$1500 by email.
25/1/18@ 5:40pm	Did revert to Vimmala via Meina. (Supplementary)
26/1/18@ 4:25pm	Kenny Ong informed C/A at \$75449.40 via Meina.

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$1500.

(Client's Record)

Make of Veh: 1142K

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: 137K - already checked

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT
Merina

Veh No: SJZ 7932J Yr Regn: 2/11, May

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: BMW 640I c.c. 2979

Colour: Burple A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 45706 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: W8ALW72006C582694

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☐ Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 275/35R19

R: 275/35R19

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIG / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 158/17 @ 1350

Survey held at PML

Des. of Damages: ☐ Frt / ☐ Rear / ☒ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction To check MV, not repair limit.

29/1/18 @ 10.31am Confirmed with Caroline from fig & 25449.40, 12 days.

(Bed & 2376.40, 27/10)

Date/Time, File Pass to? ☐ : Preli. Report

1) 20/1 Taylor ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee: _____

Transportation: _____

_____ S + RS. _____ SI

Photos _____

Others _____

TOTAL

Report Format : MPR - 07

Lump Sum / I.B.I.: (\$ 25449.40)

Add Fee: ☐ Site Insp (\$ _____)

☐ Interview (\$ _____)

☐ Tech. Invs (\$ _____)

☐ Weekend (\$ _____)

350
10
360



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17015764/T1qb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 15-08-2017



Code : MSG

1. Policy Particulars - OWN DAMAGE

Insured Veh.		Veh. Inspected	SJZ 7932J
Policy No.	B27121149SMP	Coverage (\$)	0.00
Claim No.	526249	Excess (\$)	1,500.00
Assign From	MERIMEN (VIMMALA)	Assign Date	15/08/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	12/08/2017	Inspection Date	15/08/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No: CA/MSK17015764/7196
 Policy Type: OD/TP RES / TL / EVA

SJ27932J

Case Handler

Typist

Admin (CAH): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		

Surveyor (Taufik): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-------------------------------------	--------------------------	--------------------------

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
-------------------------------------	--------------------------	--------------------------

Check By:

[Signature] 29/11/18
 Case Handler Date

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2017		15 Aug 2017 11:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured: ALFRED CHENG HONG WING, ID: S6817280B, Tel: +6597667902, Email: ALFRED.HW.CHENG@GMAIL.COM

Vehicle Reg. No.: SJZ7932J

Claim Type: OD / 526249

Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941
Alexandra - Tel: 63190172/63190174

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Vimmala D/O Raja Singam - 65942471]

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 16/08/2017]

Driver/Custodian: ALFRED CHENG HONG WING (49 / Male), NRIC: S6817280B, Tel: +6597667902

Adj Asg. Remarks: Please revert. URGENT SURVEY BY TODAY. Surveyor, please check on the market value and rebate if it is economical to repair. Thank you

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 29 January 2018 10:31 AM
To: 'PBSP'; SUR; Taufikh (LKKAUTO)
Subject: RE: FINAL REPORT / SJZ7932J

Dear Caroline,

Confirm final fig \$25449.40 before excess \$1,500.00 & GST and 12 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@sime-darby.com.sg]

Sent: Thursday, 14 December 2017 5:24 PM

To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Subject: FINAL REPORT / SJZ7932J

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 15,787.00

Total Parts : 9,662.40

Total Labour & Parts : 25,449.40

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	15 Aug 2017 10:27	Clim Veh Model Changed	(202061) BMW 630I 3.0 AT (A).	[I] Vimmala D/O Raja Singam
2	15 Aug 2017 10:27	Clim Created	Reg No: SJZ7932J, Policy No: B27121149SMP, Acct Date: 2017/08/12, Claim Type: SC, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Ins.Status => Notification, Created from SAS:MPML17106915	[I] Vimmala D/O Raja Singam
3	15 Aug 2017 11:11	Notification Status Changed	Ins.Status => Incoming Claim	[I] Vimmala D/O Raja Singam
4	15 Aug 2017 11:11	Clim Registration Modified	Setl.Type:3->0, Rep:1137->200071, Claim Type:SC->OD, Init.Est.:>30,000 - 40,000.	[I] Vimmala D/O Raja Singam
5	15 Aug 2017 11:14	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert. Surveyor, please check on the market value and rebate if it is economical to repair. Thank you	[I] Vimmala D/O Raja Singam
6	15 Aug 2017 11:14	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/08/16	[I] Vimmala D/O Raja Singam
7	15 Aug 2017 11:14	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
8	15 Aug 2017 11:23	Assignment 1st Accessed		[A] Pauline Soh Li Ping
9	15 Aug 2017 11:25	Adj Assignment Cancelled	IHS APPT FULL	[I] Vimmala D/O Raja Singam
10	15 Aug 2017 11:25	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Vimmala D/O Raja Singam
11	15 Aug 2017 11:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert. URGENT SURVEY BY TODAY. Surveyor, please check on the market value and rebate if it is economical to repair. Thank you	[I] Vimmala D/O Raja Singam
12	15 Aug 2017 11:26	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2017/08/16	[I] Vimmala D/O Raja Singam
13	15 Aug 2017 11:26	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
14	15 Aug 2017 12:10	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
15	15 Aug 2017 16:47	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] CATHERINE CHONG KAI LING
16	16 Aug 2017 11:14	Adj Rpt Initiated		[A] SHIAU CHAN
17	16 Aug 2017 15:29	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/09/14	[A] SHIAU CHAN
18	16 Aug 2017 15:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/14	[A] SHIAU CHAN
19	16 Aug 2017 15:30	Adj Mandate Request	Cur.Reg:27572.20:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT A UTHORISE REPAIR.	[A] SHIAU CHAN
20	16 Aug 2017 17:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/14	[I] Keny Ong Thiam Beng
21	16 Aug 2017 17:12	Adj Mandate Set	Approved:27572.20.	[I] Keny Ong Thiam Beng
22	25 Jan 2018 17:39	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/09/14	[A] SHIAU CHAN
23	25 Jan 2018 17:40	Adj Mandate Request	Cur.Reg:25449.40:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
24	26 Jan 2018 16:25	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/14, Mandate Remarks: A IF C	[I] Keny Ong Thiam Beng
25	26 Jan 2018 16:25	Adj Mandate Set	Approved:25449.40:A IF C	[I] Keny Ong Thiam Beng

ACTIVITY

[15/08/2017 11:24] Pauline Soh Li Ping:

Mala informed urgent case, IHS unable to attend (ET-Attending other appt, AL-East side)

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1553772	16/08/2017 11:14	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SJ27932J		10.70
1570578	15/08/2017 10:33	Motor	MSIG Insurance (Singapore) Pte. Ltd.	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	SJ27932J	526249	xx.xx

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearlyn Kang Yen Lin

Date: 25 Jan 2018

Preliminary Advice

Vehicle No	: SJZ7932J	Accident Date	: 12/08/2017
Make	: BMW 630i	Policy No.	: B27121149SMP
Assignment Date	: 15/08/2017	Excess	: S\$1,500.00
Date of Inspection	: 15/08/2017	Est. Duration of Repair	: 12.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,825.80	(ESTIMATE \$31,683.55 + SUPPLEMENTARY \$1,142.25)
Revised Amount	:S\$	25,449.40	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	25,449.40	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	137,000.00
COE / PARF Rebate	:S\$	75,300.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,700.00

Remarks

- (X) The vehicle is economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.
KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 16 August, 2017 5:37 PM
To: 'Merina Chia San San'
Cc: SUR
Subject: VEHICLE SJZ 7932J (DOA: 12/08/2017)

Dear Merina,

As spoken with you.

As instructed by our client MSIG Insurance, please proceed to repair the insured vehicle **SJZ 7932J (Excess \$1,500)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL

No	Date	Action	Remarks	By
1	15 Aug 2017 10:27	Clim Veh Model Changed	(202061) BMW 630I 3.0 AT (A).	[I] Vimmala D/O Raja Singam
2	15 Aug 2017 10:27	Clim Created	Reg No: SJZ7932J, Policy No: B27121149SMP, Acct Date: 2017/08/12, Claim Type: SC, Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Ins.Status => Notification. Created from SAS:MPML17106915	[I] Vimmala D/O Raja Singam
3	15 Aug 2017 11:11	Notification Status Changed	Ins.Status => Incoming Claim	[I] Vimmala D/O Raja Singam
4	15 Aug 2017 11:11	Clim Registration Modified	Setl.Type:3->0, Rep:1137->200071, Claim Type:SC->OD, Init.Est.:->30,000 - 40,000.	[I] Vimmala D/O Raja Singam
5	15 Aug 2017 11:14	Adj Co Assigned	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert. Surveyor, please check on the market value and rebate if it is economical to repair. Thank you	[I] Vimmala D/O Raja Singam
6	15 Aug 2017 11:14	Adj Next Rpt Changed	Next Rpt:Im, Advice.Due Date:2017/08/16	[I] Vimmala D/O Raja Singam
7	15 Aug 2017 11:14	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
8	15 Aug 2017 11:23	Assignment 1st Accessed		[A] Pauline Soh Li Ping
9	15 Aug 2017 11:25	Adj Assignment Cancelled	IHS APPT FULL	[I] Vimmala D/O Raja Singam
10	15 Aug 2017 11:25	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Vimmala D/O Raja Singam
11	15 Aug 2017 11:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):Please revert. URGENT SURVEY BY TODAY. Surveyor, please check on the market value and rebate if it is economical to repair. Thank you	[I] Vimmala D/O Raja Singam
12	15 Aug 2017 11:26	Adj Next Rpt Changed	Next Rpt:Im, Advice.Due Date:2017/08/16	[I] Vimmala D/O Raja Singam
13	15 Aug 2017 11:26	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Vimmala D/O Raja Singam
14	15 Aug 2017 12:10	Assignment 1st Accessed		[A] CATHERINE CHONG KAI LING
15	15 Aug 2017 16:47	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH	[A] CATHERINE CHONG KAI LING
16	16 Aug 2017 11:14	Adj Rpt Initiated		[A] SHIAU CHAN
17	16 Aug 2017 15:29	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2017/09/14	[A] SHIAU CHAN
18	16 Aug 2017 15:29	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/14	[A] SHIAU CHAN
19	16 Aug 2017 15:30	Adj Mandate Request	Cur Req:27572.20:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	16 Aug 2017 17:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2017/09/14	[I] Keny Ong Thiam Beng
21	16 Aug 2017 17:12	Adj Mandate Set	Approved:27572.20.	[I] Keny Ong Thiam Beng

ACTIVITY

[15/08/2017 11:24] Pauline Soh Li Ping:

View Received Message

This mail is associated with :

***SJZ7932J (526249)**

OD

Aug 12 2017 5:00PM

[ALFRED CHENG HONG WING]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 16/08/2017 17:12 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$27572.20) - SJZ7932J - Claim Handler: Vimmala D/O Raja Singam

Approved:27572.20.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala D/O Raja Singam

Date: 16 Aug 2017

Preliminary Advice

Vehicle No	: SJZ7932J	Accident Date	: 12/08/2017
Make	: BMW 630I	Policy No.	: B27121149SMP
Assignment Date	: 15/08/2017	Excess	: S\$1,500.00
Date of Inspection	: 15/08/2017	Est. Duration of Repair	: 12.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,683.55
Revised Amount	:S\$	23,980.40
Check Items (Estimated)	:S\$	3,591.80
Total	:S\$	27,572.20

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	137,000.00
COE / PARF Rebate	:S\$	75,300.00
Salvage Value	:S\$	
Margin for Repair	:S\$	61,700.00

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7280B

Vehicle Details

Vehicle No.: SJZ7932J

Vehicle to be Exported: No

Intended De-registration
Date: 16 Aug 2017

Vehicle Make: B.M.W.

Vehicle Model: 640i 3.0 AT ABS D/AB HID DSC NAV HUD

Primary Colour: Brown

Manufacturing Year: 2011

Engine No.: 15347765N55B30A

Chassis No.: WBALW72000C582694

Maximum Power
Output: 235.0 kW (315 bhp)

Open Market Value: \$83,215.00

Original Registration
Date: 31 May 2011

First Registration Date: 31 May 2011

Transfer Count: 0

Actual ARF Paid: \$83,215.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 30 May 2021

PARF Rebate Amount: \$54,089.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2021

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$56,001.00

COE Rebate Amount: \$21,211.00

Total Rebate Amount: \$75,300.00

The information contained herein is correct as at 16 Aug 2017



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 13 Aug 2017 at 12:41 AM

SGCARMART.COM
 THE ONLY PLACE FOR SMART CAR BUYERS
SGCARMART
APP DOWNLOAD

All Car Make or Model

Search

HOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

PRODUCT GUIDE

ARTICLES

FORUM

TOOLS & TIPS



Username / Email Add
 password Submit Qu
 f Connect * Sign Up New Account
 * Forgot Password

BMW 640

Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced
Search

Home Used Cars Lay Auto Pte Ltd BMW 6 Series 640i Cabriolet

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Leasing



BMW 6 Series 640i Cabriolet

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD



LAY AUTO PTE LTD

ESTABLISHED IN 1998

Add to Compare

Add to Shortlist

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$146,800**Depreciation **\$27,420 /yr**

View models with similar depreciation

Reg Date **09-Jun-2011**



(3yrs 9mths 23days COE left)

Manufactured **2011**Mileage **29,000 km**Transmission **Auto**Engine Cap **2,979 cc**Road Tax **\$2,362 /yr**Power **235.0 kW (315 bhp)**

View specs of the BMW 640i

Curb Weight **1,840 kg**
Features 3.0L Inline 6 Cylinder Soft Top Convertible, Twin Power Turbocharged Engine Producing 315hp And 450nm, 8 Speed Auto Transmission With Paddle Shifters.

Accessories Full Option, Heads-up Display, Multi Function Steering, Integrated I-Drive With Navigation Bluetooth, Memory Seats, Bi-Xenon Headlight, Keyless.

Description Timeless Sporty Design, Unparalleled Handling And Exhilarating Performance, Immaculate Condition, High OMV Value, Fully Maintained And Serviced By Agent PML, Excellent Condition Just Feels Like New, View To Believe, Trade In And Loan Available, Hurry Call Now Before Its Gone.
COE **\$63,000**OMV **\$84,440**ARF **\$84,440**Dereg Value **\$78,912 as of today (change)**No. of Owners **1**Type of Veh **Sports Car**Category **PARF Car, Premium Ad Car, Low Mileage Car**Availability **Available**

Seller Information

Company Lay Auto Pte Ltd
 * dealer's pricelist
 * 58 vehs sold | 36 vehs available

Address 21 Toh Guan Road East #01-16/17
 Search cars nearby this location

Location Toh Guan Centre

Office No 64625828

Contact Person(s) Victor Tan 96613989

Posted on: 11-Aug-2017 | Last Updated on: 11-Aug-2017

Tags: BMW 640i, 2011 BMW 640i, BMW, 640i, Used BMW

Upfront Payment

» more Financial info

Transfer Fee

\$11

GET JOBS



bmw 6

Price Range

Depreciation

2011

Vehicle Type

Home » Used Cars » Lay Auto Pte Ltd » BMW 6 Series 640i Cabriolet

Tools & Tips

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

Car Tyres

MICHELIN
PILOT SPORT 4
AS RESPONSIVE
AS YOU ARE

BMW 6 Series 640i Cabriolet

Overview Financial Accessories Similar Research Photos Map




LAY AUTO PTE
ESTABLISHED IN 1998

Add to Compare Add to Shortlist Add a Note Report Error More Actions

Car Details

Price	\$146,800	
Depreciation	\$27,420 /yr View models with similar depreciation	?
Reg Date	09-Jun-2011 (3yrs 9mths 23days COE left)	
Manufactured	2011	?
Mileage	29,000 km	
Transmission	Auto	
Engine Cap	2,979 cc	
Road Tax	\$2,362 /yr	?
Power	235.0 kW (315 bhp) View specs of the BMW 640i	
Curb Weight	1,840 kg	?
Features	3.0L Inline 6 Cylinder Soft Top Convertible, Twin Power Turbocharged Engine Producing 315hp And 450nm, 8 Speed Auto Transmission With Paddle Shifters.	
Accessories	Full Option, Heads-up Display, Multi Function Steering, Integrated I-Drive With Navigation Bluetooth, Memory Seats, Bi-Xenon Headlight, Keyless.	
Description	Timeless Sporty Design, Unparalleled Handling And Exhilarating Performance, Immaculate Condition, High OMV Value, Fully Maintained And Serviced By Agent PML, Excellent Condition Just Feels Like New, View To Believe, Trade In And Loan Available, Hurry Call Now Before Its Gone.	



Location Map

Seller Informat

Company

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/08/2017 11:18
Date Of Accident	12/08/2017 17:00
Exact Location Of Accident	23 ANDERSON RD CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ7932J
Insured/Policyholder	
Name Of Registered Owner	ALFRED CHENG HONG WING
NRIC No	S6817280B
Email Address	ALFRED.HW.CHENG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97667902
Alternative Phone No	OFFICE-97667902

Vehicle Particulars

Manufacturer	BMW
Model	6 SERIES
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B27121149SMP
Cover Note Number	

Driver

Name of Driver	ALFRED CHENG HONG WING
NRIC No	S6817280B
Date Of Birth	10/05/1968
Occupation	INDOOR
Date Of Driving Pass	17/08/1985
Driving Experience	31 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97667902
Fax Number	
Contact Number	OFFICE-97667902
EMail Address	ALFRED.HW.CHENG@GMAIL.COM

Address	23 ANDERSON RD #07-02
Postcode	259985
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time
14 AUG 2017

Driver's Signature (If driver is not the policyholder) / Date & Time

MERINA CHIA SAN SAN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159944
Witnessed by Reporting Centre
Personnel

14 AUG 2017

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

Was reversing car at home (condo) carpark.
Right side of car hit pillar.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

14 AUG 2017

Driver's Signature (If driver is not the policyholder) / Date
& Time

MERINA CHIA SAN SAN
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Witnessed by Reporting Centre
Personnel

14 AUG 2017

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

Key level 6

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

15 AUG 2017

Estimate No. : b1 43768
Date Estimated : 14/08/2017
Prepared By : Merina Chia San San

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Alfred Cheng Hong Wing
23 Anderson Road
#07-02

Singapore 259985

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ7932J	C582694	31/05/2011	640iA-C	0

DESCRIPTION

To replace rear right fender, right door, right side
skirting including attachments etc and to knock out dented
area caused by accident

7650 6800.8,075.00

To paint rear right fender, right door, right side
skirting, front right fender, right side wing mirror cover
and right side door handle

3266 3,629.00

To remove and install fuel tank to facilitate repairs
including conduct checks for leak.

photo. 451.7 531.00

To check steering geometry and conduct wheel alignment in
accordance with BMW specifications. (2x).

902 1,062.00

To replace tyre and wheel rim including balancing. (2x) Fr + RH only

80, 159 188.00

To remove and install rear hat-tray, rear seat, carpet
and roof top lining to facilitate repairs.

742 873.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To replace rear door fixed side window including conduct
water leak tests.

351 413.00

To supply and install rear left or right window glass
solar film.

mm 425.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

451 531.00

To conduct checks on all doors and bootlid central locking
system for proper function.

150 177.00

To reconnect electrical components and wirings at the

300 354.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 43768
Date Estimated : 14/08/2017
Prepared By : Merina Chia San San

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ7932J	C582694	31/05/2011	640iA-C	0

DESCRIPTION

VALUE

rear section including conduct checks for proper function.

To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.

photo. 451 531.00

To conduct checks on the electrical wiring system on the left/right side member for proper function.

150 177.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

Sundries.

me 17 150.00

Total Labour 1: 17,918.00

PART NUMBER	DESCRIPTION	QTY	PRIC	VALUE
36116794690	ALLOY RIM 81/2JX19 STY SPK366	2	1,276.70	2,553.40
41007228156	FRT RH DOOR HINGE UPPER	1	51.85	51.85
41217263808	RR RH FENDER	1	2,379.90	2,379.90
41219240146	Reinforcemnt	1	48.00	48.00
41517228570	FRT RH DOOR	1	2,488.25	2,488.25
41517263540	FRT RH DOOR HINGE LOWER	1	55.75	55.75
51167186588	RH MIRROR GLASS HEATED WIDE-ANGLE	1	739.30	739.30
51167187432	RH WINGMIRROR COVER (PRIMED)	1	109.90	109.90
51167283460N	RH OUTSIDE MIRROR W/O GLASS HE	1	967.85	967.85
51217198947	DOOR BRAKE	1	99.15	99.15
51217226198	LOCK COMPLETE RH (SCA)	1	679.70	679.70
51217231932	FRT RH GRAB HANDLE PAINT FINISH (CA	1	560.40	560.40
51217286102	Carrier	1	638.15	638.15
51217312545	CATCH BRACKET	1	52.25	52.25
51337217490	RH CORNER MOULDING INTERIOR	1	38.30	38.30
51337217492	WINDOW GUIDE DOOR RH	1	104.40	104.40
51337221178	INNER RH WINDOW CHANNEL COVER	1	272.85	272.85
51337221180	SEAL DOOR SEAM ENTRY RH	1	114.70	114.70
51337221310	DUCT COVER SHORT OUTER RH (CHROM)	1	104.30	104.30
51337221314	DUCT COVER LONG OUTER RH (CHROM)	1	120.40	120.40
51337224222	Seal	1	22.10	22.10
51337291088	Seal	1	19.25	19.25
51377219888N	SIDE WINDOW GREEN RR RH	1	490.20	490.20
51767301294	DOOR WEATHERSTRIP RH	1	140.20	140.20
51777265202N	RH DOOR SILL COVER PRIMED	1	426.65	426.65
83190301421	BLIND RIVET AVIBVLB	10	0.55	5.50
83190301639	SCREW (SF PLUS M5X15)	1	0.55	0.55
83192157298	(DG/SL) BODY ADHESIVE K5B (195ML)	1	281.55	281.55
83192158079	PUNCH RIVET N5	3	0.55	1.65
83192158080	PUNCH RIVET N4	33	0.55	18.15
83192158654	(DG) BODYWORK ADHESIVE K5A (50ML)	1	118.35	118.35

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 43768**
Date Estimated : **14/08/2017**
Prepared By : **Merina Chia San San**

Page No. : **3 of 3**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJZ7932J	C582694	31/05/2011	640iA-C	0

PART NUMBER	DESCRIPTION	QTY	PRIC	VALUE
83192211217	(DG) CLEANER R1 (100ML)	1	23.85	23.85
83422409985	(S/L) SEAM SEAL 300ML	2	33.80	67.60

Total Parts : **13,765.55**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15/8/17 @ 1350
Taufik
97495744
Revert

1500
Taufik

16/8/17

Taufik @ lkkauto.com
12 days

32261 20

Labour 1	:	17,918.00
Parts	:	13,765.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,217.85
Grand Total	:	33,901.40

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 43768**
Date Estimated : **14/08/2017**
Prepared By : **Merina Chia San San**

Page No. :

REPAIR FOR -

Alfred Cheng Hong Wing
23 Anderson Road
#07-02

Singapore 259985

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SJZ7932J	C582694	31/05/2011	640iA-C	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
* To replace front RH door and attachments, rear RH fender, RH wingmirror assembly, RH door sill cover include making good the front RH fender and knocking out dents caused by the accident	7650.00		7,650.00			
To spray paint rear RH fender, front RH door, RH side skirting, front RH fender, RH wingmirror cover and front RH door handle	3266.00		3,266.00			
* To remove and install fuel tank to facilitate repairs include conducting checks for leak.	451.00		451.00			
To check steering geometry and conduct wheel alignment in accordance with BMW specifications (2x)	902.00		902.00			
To replace wheel rim include balancing	80.00		80.00			
To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.	742.00		742.00			
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00			
* To remove and install rear RH fender fixed side window to facilitate repairs include conducting water leak tests	413.00		413.00			
To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function	451.00		451.00			
To conduct checks on all doors and boot lid central locking system for proper function	150.00		150.00			
To reconnect electrical components and wirings at the rear section including conduct checks for proper function. (For cut panel)	300.00		300.00			
* To remove and install wire harness, control units and battery at the rear section to facilitate panel replacement.	451.00		451.00			

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

# To carry out body cavity preservation for front RH door (Per panel)	100.00	100.00	64
To carry out body cavity preservation for rear RH fender (For cut panel).	451.00	451.00	
Sundries.	150.00	150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
ALLOY RIM 81/2JX19 STY SPK366	1,276.70	1.00		1,276.70
RR RH FENDER	2,379.90	1.00		2,379.90
FRT RH DOOR	2,488.25	1.00		2,488.25
RH MIRROR GLASS HEATED WIDE-ANGLE	739.30	1.00		739.30
RH WINGMIRROR COVER (PRIMED)	109.90	1.00		109.90
# RH OUTSIDE MIRROR W/O GLASS HEATED *	967.85	1.00		967.85
FRT RH GRAB HANDLE PAINT FINISH (CA	560.40	1.00		560.40
SEAL DOOR SEAM ENTRY RH	114.70	1.00		114.70
RH DOOR SILL COVER PRIMED	426.65	1.00		426.65
# TYPE IDENTIFICATION PLATE (CODED) *	27.90	1.00		27.90
# LABEL RESET *	23.25	1.00		23.25
# TIRE PRESSURE LABEL *	23.25	1.00		23.25
BLIND RIVET AVIBVLB	0.55	20.00		11.00
SCREW (SF PLUS M5X15)	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N5	0.55	10.00		5.50
PUNCH RIVET N4	0.55	20.00		11.00
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85
(S/L) SEAM SEAL 300ML	33.80	2.00		67.60

SUPPLEMENTARY ITEMS

Total Labour :	15,787.00
Total Parts :	9,662.40
Total Labour & Parts :	25,449.40
Deduction for Excess :	1,500.00
Total Repair Costs less Excess:	23,949.40
GST @7%:	1,676.46
Grand Total :	25,625.86

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 43768
Date Estimated : 14/08/2017
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Alfred Cheng Hong Wing
23 Anderson Road
#07-02

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 259985

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SJZ7932J	C582694	31/05/2011	640IA-C	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To carry out body cavity preservation for front RH door (Per panel)	100.00		100.00 (100) <i>all</i>

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RH OUTSIDE MIRROR W/O GLASS HEATED *	967.85	1.00	<i>Reported</i>	967.85 <i>mis</i>
# TYPE IDENTIFICATION PLATE (CODED) *	27.90	1.00		27.90 <i>un</i>
# LABEL RESET *	23.25	1.00		23.25 <i>un</i>
# TIRE PRESSURE LABEL *	23.25	1.00		23.25 <i>un</i>

Total Labour :	100.00
Total Parts :	1,042.25
Total Labour & Parts :	1,142.25


...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Aug 2017		15 Aug 2017 11:26 Edit Adj Rpt	S\$25,449.40 Edit Estimates	S\$25,449.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by Insurer]
Insured:	ALFRED CHENG HONG WING, ID: S6817280B, Tel: +6597667902, Email: ALFRED.HW.CHENG@GMAIL.COM	
Vehicle Reg. No.:	SJZ7932J	Date of Loss: 12/08/2017 17:00 - :59
Claim Type:	OD / 526249	Policy/Cover Note No.: B27121149SMP (Comprehensive) Coverage: 31/05/2017 - 30/05/2018
		Excess: S\$1,500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 14/09/2017]	
Driver/Custodian:	ALFRED CHENG HONG WING (49 / Male), NRIC: S6817280B, Tel: +6597667902	
Adj Asg. Remarks:	Please revert. URGENT SURVEY BY TODAY. Surveyor, please check on the market value and rebate if it is economical to repair. Thank you	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> MSIG_SG (26/01/2018): Alert - Adj Mandate Approved (S\$25449.40) - SJZ7932J - Claim Handler: Pearllyn K... MSIG_SG (23/01/2018): Please upload final survey report urgently. Thank you. MSIG_SG (16/08/2017): Alert - Adj Mandate Approved (S\$27572.20) - SJZ7932J - Claim Handler: Vimmala D/... 		

ALL ASSOCIATED TASKS 										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

*SJZ7932J (526249)
OD
Aug 12 2017 5:00PM
[ALFRED CHENG HONG WING]
Performance Motors Limited


Upload Documents			Upload Photos			Compose New Letter			View <div>View in Browser</div>		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)							Thumbnail	Print	
1	14/08/17 11:25	Accident Statement							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	16/08/17 15:29	Adjuster Immediate Advice							Load HTM		
2	25/01/18 17:39	Adjuster Immediate Advice							Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)							Thumbnail	Print	
1	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
2	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
3	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
4	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
5	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
6	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
7	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
8	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
9	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
10	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
11	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
12	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
13	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
14	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
15	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
16	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
17	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
18	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
19	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
20	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
21	14/08/17 11:22	Accident Photo [Linked Accident Report Documents]							Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	16/08/17 15:31	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	16/08/17 15:31	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	

3	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
4	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
5	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
6	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
7	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
8	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
9	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
10	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
11	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
12	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
13	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
14	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
15	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
16	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
17	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
18	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
19	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
20	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
21	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
22	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
23	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
24	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
25	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
26	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
27	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
28	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
29	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
30	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
31	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
32	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
33	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
34	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
35	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
36	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
37	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
38	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
39	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
40	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
41	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
42	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
43	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
44	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
45	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
46	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
47	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
48	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
49	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
50	16/08/17 15:31	General View	1	Load JPG	<input checked="" type="checkbox"/>
51	25/01/18 09:42	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
52	25/01/18 09:42	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>

53	25/01/18 09:42	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
54	25/01/18 09:42	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
55	25/01/18 09:42	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
56	25/01/18 09:42	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
57	25/01/18 09:42	Replacement Part Photo	1	Load JPG	<input checked="" type="checkbox"/>
58	25/01/18 09:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
59	25/01/18 09:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
60	25/01/18 09:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
61	25/01/18 09:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
62	25/01/18 09:44	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	15/08/17 11:13	Estimate repair bill from Performance Motor/NRIC	1	Load PDF	
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	14/08/17 11:21	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/01/18 17:37	SUPPLEMENTARY LIST	1	Load PDF	
2	26/01/18 10:29	ESTIMATE	1	Load PDF	

Linked Accident Report Documents

			View	View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	14/08/17 11:25	Accident Statement	1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
13	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
14	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
15	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
16	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
17	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
18	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
19	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
20	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
21	14/08/17 11:22	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	14/08/17 11:21	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div><div></div><div>^</div><div>v</div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17015764/T1QBE2

Date: 01/02/2018

REFERENCE

Insured/Claimant: ALFRED CHENG HONG WING

Policy No: B27121149SMP

Date of Loss: 12/08/2017

Nature of Claim: OD

Claim No: 526249

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ7932J**

Make & Model: BMW 630i, 3.0 AT (A)

Engine No: 15347765N55B30A

Reg. Date: 31/05/2011 (Man. Year: 2011)

Chassis No: WBALW72000C582694

Colour: Bronze

Odometer: 45706 km

Engine Capacity: 2979 cc

Market Value/New Car Price: S\$137,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/35 R19

Rear Tyre Size: 275/35 R19

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,993.80	9,812.40	5,181.40	34.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	17,868.00	15,637.00	2,231.00	12.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,861.80	25,449.40	7,412.40	22.56
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	31,361.80	23,949.40	7,412.40	23.64
+ GST 7.00/7.00% (S\$)	2,195.33	1,676.46	518.87	23.64
Nett Amount (S\$)	33,557.13	25,625.86	7,931.27	23.64

INSPECTION

Date of Assignment: 15/08/2017

Date Inspected: 15/08/2017 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 12.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Feb 2018)

Parts: M1-COUPE BMW 630I 3.0 AT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJZ7932J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*ALLOY RIM 81/2JX19 STY SPK366	FrtO/SCut/RearO/SNotNecessary	2,553.40 FS	*1,276.70 FS
3	1		*FRT RH DOOR HINGE UPPER	Not Necessary	51.85 FS	*- FS
4	1		*RR RH FENDER	Bent	2,379.90 FS	*2,379.90 FS
5	1		*REINFORCEMENT	Not Necessary	48.00 FS	*- FS
6	1		*FRT RH DOOR	Bent	2,488.25 FS	*2,488.25 FS
7	1		*FRT RH DOOR HINGE LOWER	Not Necessary	55.75 FS	*- FS
8	1		*RH MIRROR GLASS HEATED WIDE-ANGLE	Broken	739.30 FS	*739.30 FS
9	1		*RH WINGMIRROR COVER (PRIMED)	Missing	109.90 FS	*109.90 FS
10	1		*RH OUTSIDE MIRROR W/O GLASS HE	Missing	967.85 FS	*967.85 FS
11	1		*DOOR BRAKE	Not Necessary	99.15 FS	*- FS
12	1		*LOCK COMPLETE RH (SCA)	Not Necessary	679.70 FS	*- FS
13	1		*FRT RH GRAB HANDLE PAINT FINISH (CA	Cut	560.40 FS	*560.40 FS
14	1		*CARRIER	Not Necessary	638.15 FS	*- FS
15	1		*CATCH BRACKET	Not Necessary	52.25 FS	*- FS
16	1		*RH CORNER MOULDING INTERIOR	Not Necessary	38.30 FS	*- FS
17	1		*WINDOW GUIDE DOOR RH	Not Necessary	104.40 FS	*- FS
18	1		*INNER RH WINDOW CHANNEL COVER	Not Necessary	272.85 FS	*- FS
19	1		*SEAL DOOR SEAM ENTRY RH	Deformed	114.70 FS	*114.70 FS
20	1		*DUCT COVER SHORT OUTER RH (CHROM)	Not Necessary	104.30 FS	*- FS
21	1		*DUCT COVER LONG OUTER RH (CHROM)	Not Necessary	120.40 FS	*- FS
22	1		*SEAL	Not Necessary	22.10 FS	*- FS
23	1		*SEAL	Not Necessary	19.25 FS	*- FS
24	1		*SIDE WINDOW GREEN RR RH	Not Necessary	490.20 FS	*- FS
25	1		*DOOR WEATHERSTRIP RH	Not Necessary	140.20 FS	*- FS
26	1		*RH DOOR SILL COVER PRIMED	Necessary	426.65 FS	*426.65 FS
27	10		*SCREW (SF PLUS M5X15)	Necessary	5.50 FS	*5.50 FS
28	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Necessary	281.55 FS	*281.55 FS
29	10		*PUNCH RIVET N5	Necessary	5.50 FS	*5.50 FS
30	20		*PUNCH RIVET N4	Necessary	11.00 FS	*11.00 FS
31	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	118.35 FS	*118.35 FS
32	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
33	2		*(S/L) SEAM SEAL 300ML	Necessary	67.60 FS	*67.60 FS
34	1			Repeated	967.85 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*RH OUTSIDE MIRROR W/O GLASS HEATED			
35	1		*TYPE IDENTIFICATION PLATE (CODED)	Necessary	27.90 FS	*27.90 FS
36	1		*LABEL RESET	Necessary	23.25 FS	*23.25 FS
37	1		*TIRE PRESSURE LABEL	Necessary	23.25 FS	*23.25 FS
38	20		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
Total Parts (S\$)						14,993.80 9,812.40

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR RIGHT FENDER, RIGHT DOOR, RIGHT SIDE SKIRTING INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	8,075.00	7,650.00
2	TO PAINT REAR RIGHT FENDER, RIGHT DOOR, RIGHT SIDE SKIRTING, FRONT RIGHT FENDER, RIGHT SIDE WING MIRROR COVER AND RIGHT SIDE DOOR HANDLE	New	3,629.00	3,266.00
3	TO REMOVE AND INSTALL FUEL TANK TO FACILITATE REPAIRS INCLUDING CONDUCT CHECKS FOR LEAK	New	531.00	451.00
4	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS (2X)	New	1,062.00	902.00
5	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING (FRT RH ONLY)	New	188.00	80.00
6	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	742.00
7	TO REMOVE AND INTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
8	TO REPLACE REAR DOOR FIXED SIDE WINDOW INCLUDING CONDUCT WATER LEAK TESTS	New	413.00	413.00
9	TO SUPPLY AND INSTALL REAR LEFT OR RIGHT WINDOW GLASS SOLAR FILM	New	425.00	0.00
10	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
11	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
12	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	354.00	300.00
13	TO REMOVE AND INSTALL WIRE HARNESS, CONTROL UNITS AND BATTERY AT THE REAR SECTION TO FACILITATE PANEL REPLACEMENT	New	531.00	451.00
14	TO CONDUCT CHECKS ON THE ELECTRICAL WIRING SYSTEM ON THE LEFT / RIGHT SIDE MEMBER FOR PROPER FUNCTION	New	177.00	0.00
15	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	451.00
16	TO CARRY OUT BODY CAVITY PRESERVATION FOR FRONT RH DOOR (PER PANEL)	New	100.00	100.00
Gross Labour Cost (\$\$)			17,868.00	15,637.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >