

fax on 15/11 @ 1700

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 16 August 2017

To : LKK

By Fax: 6256-4315

Attn : Rasul (HP 90010068)

VEHICLE NO : FBA 8773X

Yamaha Spark 135

ACCIDENT DATE: 11 August 2017 / 2006

Description	Qty	Quotation \$
1 Handle Bar	1	185.00 Xsvc
2 Gear Pedal	1	50 95.00 PA
3 Footrest	1	75.00 cut PA
4 Footrest Rubber	1	56.00 cut
5 Mudguard	1	155.00 R (Local repair - 100) labor
6 Mirror LH	1	65.00 Svc
7 Brake Lever	1	40 68.00 PA
8 Front Cowling	1	195.00 Xsvc
9 Fork Tube	1 set	480.00 R (Local repair - 100) labor
10 Front Panel Guard	1	100 150.00 Svc

Sub-Total 1,524.00
Less 10% 152.40
Sub-Total 1,371.60

386
102
347.40

- Nett items
- 1 Rear box
 - 2 Towing fee
 - 3 Remove & replace parts, align & etc
 - 4 Remove & replace fork tube, bracket & top up fork oil

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Sub-Total 690.00
Acknowledged by Repairer
Signature: Net Total 2,061.60
Date:

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion, thank you

SG 98 MOTOR PTE LTD

Rasul
Hp 90010068

3 days

45

15/08/17 @ 1720

280.00 150 Svc
40.00
250.00 180
120.00 60
430
+ 200 = 630

347.40
630.00
977.40

202
781.92

43-800