



Systematic Airconditioning Pte Ltd

29 Senoko Way, Singapore 758059 • ROC No:199800703G
Tel: 6484 7188 • Fax: 6484 1334 • systairc@singnet.com.sg

Prepared for:

Yee Pei Li

ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE
038985

Tel: 6829 9199 EXT 194 | Fax: 6829 9199

QUOTATION

Date : 14 August 2017
Quotation No. : SAPL/20170269
Validity : 14/8/2017
Terms : COD

for YP704Y

Thank you for your invitation to quote, we are pleased to offer our best price as follows:

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1	Accident Damage Between YP704Y & GBB2350S On 12 August 2017 Remove and Replace 1 Lot Of Rubber Rear Door Seal (Left)	1	\$800.00 1) 300	\$800.00 300 -10% 270
2	Remove & Rework on Rear Door (Left) - Replace 1 Lot Of Door FRP	1	3) \$1,200.00 400	\$1,200.00
3	Repair Of Stainless Steel Frame (Cut And Joint)	1	\$1,200.00	\$1,200.00
4	Redo the Artwork	1	2) \$500.00	\$500.00 300
5	Loss Of Use	6	\$280.00	\$1,680.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1) Part : \$ 270
2) S/Nett: \$ 500
3) Labour: \$ 400

Part by part = \$ 1170 @ 4 days.

Trust that the above quotation is in order and look forward to your
favorable reply. Kindly acknowledge and place your company stamp and
signature below and fax us a copy for our action.

Thank you.

Best Regards,

Sub-Total : \$5,380.00
Add GST @ 7.00% : \$376.60
TOTAL : \$5,756.60

CUSTOMER'S CONFIRMATION

Prepared for:

QUOTATION

Yee Pei Li

ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE
038985

Tel : 6829 9199 EXT 194 | Fax : 6829 9199

24 Senoko Way Singapore
758046

Date : 14 August 2017
Quotation No. : SAPL/20170269
Validity : 14/8/2017
Terms : COD

for YP704Y

Thank you for your invitation to quote, we are pleased to offer our best price as follows:

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
1	Accident Damage Between YP704Y & GBB2350S On 12 August 2017 Remove and Replace 1 Lot Of Rubber Rear Door Seal (Left)	1	\$800.00	\$800.00
2	Remove & Rework on Rear Door (Left) - Replace 1 Lot Of Door FRP	1	\$1,200.00	\$1,200.00
3	Repair Of Stainless Steel Frame (Cut And Joint)	1	\$1,200.00	\$1,200.00
4	Redo the Artwork	1	nec \$500.00	\$500.00
5	Loss Of Use	6	\$280.00	\$1,680.00

total: 2000 3000
45 15K 45 2.4K

Trust that the above quotation is in order and look forward to your favorable reply. Kindly acknowledge and place your company stamp and signature below and fax us a copy for our action.

Sub-Total : \$5,380.00
Add GST @ 7.00% : \$376.60
TOTAL : \$5,756.60

Thank you.

Best Regards,

CUSTOMER'S CONFIRMATION

Company Stamp/Signature Over Printed Name