

ASS. REC. BY:

REF: CS/11117016073/ Garbez

Special Instruction:

Surveyor: GU

ASSIGNMENT (Office)

From (Person) Gabriel Wu of ITT Date/Time: 18082017

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: STT31478 Insured: SHA47247at Workshop m/s HUPLEY Huat motor.

Tel: _____

of BK 1 KAKI BUKIT AVE 6 #01-35

Policy No: _____

Claim No: _____

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 13/2/17CA / REV / REP. / REV 24 HRS wp

H.O.D. Endorsement: _____

Date/Time: _____

Person Contacted: _____

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	STT 31478 - xx
	SHA 47247 - CS/1111522221 / F6d1
	Confirm L/s \$2050, 5 days
	Re d: \$ 6189.01, 75%.

(08/11/13)

ASS. REC. BY: PKSREF: IV**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Hup ley Huat

of _____

Insured: Seng 96773832

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time : _____ Action / Instruction

Veh No: ST3147S Yr Regn: 01 Oct 2009Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Uios c.c. 1497Colour: Black A/C: Insured / Std / NI / NASp. Reading: 217086 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053 H 930 5/ 26706Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 185/60 R15R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 21-08-17Survey held at W/S 4pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED

Date/Time, File Pass to?



: Preli. Report

1) typist

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5Resurvey No. of Trip: -

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) S + RS, SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Report Format : TPLump Sum / T.B.I. (\$) 2050

250

10

260

catherine

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Sent: Friday, 18 August, 2017 12:01 PM
To: motorclaim@iii.com.sg; assignments
Cc: mail@cheonghoh.sg; SUR
Subject: FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJT3147S (Accident involving SJT3147S and SHA4724T on 13.08.2017)
Attachments: sha4724t_20170817095643.pdf

Dear Sir,

Thank you for your assignment.

For the efficiency of future assignment arrangement, we will highly appreciate if you could send to the email address below:

assignments@lkkauto.com @ Phone: 6741-8434/ 6841-1972

Thank you for your cooperation and we look forward to serve you.

Dear Catherine,
FYNA

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: Friday, August 18, 2017 11:53 AM
To: Chris Tan <mail@cheonghoh.sg>; SUR <sur@lkkauto.com>
Cc: Hup Ley Huat <hup.ley.huat@gmail.com>
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJT3147S (Accident involving SJT3147S and SHA4724T on 13.08.2017)

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SJT3147S and let us have your report urgently.

This claim will be handled by Ms Natalie.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee
Motor Claims Dept.

wesp; ~~Mr Tan~~
IN Ram.

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street #04/#05 IOB Building

Singapore 049711

Tel : 63476100, Ext-248, Fax : 62244174

e-mail: Gabriel@iii.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

<sha4724t_20170817095643.pdf>

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission

or any modification.

- Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

India International Insurance Pte Ltd
64 Cecil Street #04/#05 IOB Building
Singapore 049711
Tel : 63476100, Ext-248, Fax : 62244174
e-mail: Gabriel@iii.com.sg

From: Chris Tan [<mailto:mail@cheonghoh.sg>]
Sent: Thursday, 17 August, 2017 2:18 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Hup Ley Huat <hup.ley.huat@gmail.com>
Subject: Re: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJT3147S (Accident involving SJT3147S and SHA4724T on 13.08.2017)

Dear Gabriel

We refer to your below email.

Our client hereby nominates LKK Auto Consultants Pte Ltd to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SJT 3147 S will be at our client's workshop as follows :-

Hup Ley Huat Motor Spray Painting Services
Blk 1 Kaki Bukit Avenue 6 #01-35
Singapore 417883

Person to contact : Mr Tan Boon Seng (contact no. 96773832)

Kindly proceed to do the needful and contact Mr Tan prior to attending at the workshop for the pre-repair surveyor.

Thank you.

Regards,
Chris Tan
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

On 17 Aug 2017, at 10:03 AM, Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Business
Owner ID	47978

Vehicle Details

Vehicle No.	SJT3147S
Vehicle to be Exported	No
Intended De-registration Date	27 Nov 2017
Vehicle Make	TOYOTA
Vehicle Model	VIOS E AUTO
Primary Colour	Black
Manufacturing Year	2009
Engine No.	1NZX958138
Chassis No.	MR053HY9305126706
Maximum Power Output	80.0 kW (107 bhp)
Open Market Value	\$12,717.00
Original Registration Date	01 Oct 2009
First Registration Date	01 Oct 2009
Transfer Count	1
Actual ARF Paid	\$12,717.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	30 Sep 2019
PARF Rebate Amount	\$6,994.00

Intended COE Rebate Details

COE Expiry Date	30 Sep 2019
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$15,589.00
COE Rebate Amount	\$2,870.00
Total Rebate Amount	\$9,864.00

The information contained herein is correct as at 27 Nov 2017

OK

From: Motor Claim - III motorclaim@iil.com.sg
 Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SJT3147S (Accident involving SJT3147S and SHA4724T on 13.08.2017)
 Date: 17 August 2017 at 10:02 AM
 To: Cheonghoh Law mail@cheonghoh.sg

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street #04/#05 IOB Building

Singapore 049711

Tel : 63476100, Ext-248, Fax : 62244174

e-mail: Gabriel@iil.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment

India International Insurance Pte Ltd.

Registration No. 198703792-K

sha4724t_20170
817095643.pdf

CHEONGHON LAW CORPORATION Date:	
To:	Fax:
Attn:	From:
<input type="checkbox"/> for your records <input type="checkbox"/> as per your request <input checked="" type="checkbox"/> for your urgent instructions and revision <input type="checkbox"/> for your information <input type="checkbox"/> for your approval and return	

17/8/17
 Attn: Mr. Seng
 (HLH)

21/8/2017
 4-12pm
 Wilson
 LKK 96404178

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/08/2017 14:45
Date Of Accident	13/08/2017 01:00
Exact Location Of Accident	CHOA CHU KANG AVE 3 / CHOA CHU KANG CENTRAL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT3147S
Insured/Policyholder	
Name Of Registered Owner	ESC TRANSPORT
Co Reg No	53314797B
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88289862

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS E AUTO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5089729210 CLASSIC
Cover Note Number	

Driver

Name of Driver	LOOI WEI KEAT
NRIC No	S7871664I
Date Of Birth	29/12/1978
Occupation	OUTDOOR
Date Of Driving Pass	21/01/1997
Driving Experience	20 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88289862
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	3 WOODLANDS DRIVE 72 #10-05 WOODSVALE
Postcode	738090
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I STOPPED MY CAR ALONG CHOA CHU KANG AVE 3 JUNCTION DUE TO TRAFFIC TURNED RED. SUDDENLY A TAXI(SHA4724T) CAME FROM BEHIND, HIT ONTO THE REAR OF MY CAR. THE IMPACT CAUSED MY CAR TO SURGE FORWARD. ATTENDED BY AINI

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA4724T
Vehicle Make/Model/Colour	TOYOTA PRIUS HYBRID 1.8 CVT (TAXI)

Details Of Properties

Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel. 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

KEAT


14 AUG 2017

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident

Refer 2-file.

Declaration

We declare the following particulars are true in every respect.



Policyholder's Signature / Date & Time

KEAT

Driver's Signature (If driver is not the policyholder) / Date & Time

14 AUG 2017

IDAC KAKI BUKIT (VAC)
12 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416597 Fax: 67482305
Email: vackb@singnet.com.sg

Witnessed by Reporting Centre Personnel

21/8

HUP LEY HUAT MOTOR SPRAY PAINTING SERVICES

1 Kaki Bukit Ave 6, #01-35/33 Singapore 417883 (Autobay @ Kaki Bukit)
Tel: 67460674 Fax: 68417639 Email: hup.ley.huat@gmail.com

Vehicle No.: SJT 31475

Model: TOYOTA VIOS E AUTO

MR 053H Y930

QTY	List Items:	Price (\$)
1	Boot Lid <i>X Repair</i>	781.70 X
2	Boot Lid Hinge <i>X SNN</i>	322.80 X
2	Boot Lid Stopper <i>X</i>	95.40 X
1	Boot Lid Lock <i>/ BT</i>	123.05 <i>/ 89.4</i>
1	Boot Lid Lock Striker <i>X NN</i>	121.01 X
1	Boot Lid Emblem "Vios" <i>/ YMC</i>	32.90 <i>/</i>
1	Boot Lid Emblem "E" <i>/</i>	27.20 <i>/</i>
1	Boot Lid Center Garnish <i>X</i>	187.70 X
2	Boot Lid Center Garnish Clips <i>X SNN</i>	25.80 X
1	Boot Lid Weather Stripe <i>/ Tw:</i>	187.25 <i>/ 106.2</i>
1	Boot Lid Key Cylinder <i>X NN</i>	181.85 X
2	Tail Lamp <i>RH - CPA</i>	578.20 <i>289.1</i>
2	Tail Lamp Sealant <i>X NN</i>	100.00 X
1	Rear Bumper <i>/ Or</i>	381.85 <i>/</i>
2	Rear Bumper Side Retainer <i>/ MC</i>	246.10 <i>70.8</i>
2	Rear Bumper Reflector <i>RH - CPA</i>	282.80 <i>54.7</i>
8	Rear Bumper Clips <i>/ MC</i>	103.20 <i>22</i>
2	Rear Bumper Stay Bracket <i>X NN</i>	344.80 X
1	Rear End Panel <i>X Repair - buc</i>	671.40 <i>516.25</i>
Spare Parts Subtotal:		4795.01 <i>1590.4</i>

25%: 805.61
1192.8

Special Nett Items

QTY	List Items:	Price (\$)
1 set	Reverse Sensor <i>/ DM</i>	280.00 <i>100</i>
1	Number Plate <i>X</i>	45.00 X
1	Number Plate Casing <i>X SNN</i>	29.00 X
Special Nett Subtotal:		354.00
Spare Parts Total:		5149.01

Labour Charges:

To check and repair snap wiring
To remove and replace reverse sensor
To respray affected areas
To check and adjust computer wheel alignment
To renew damaged parts, straighten and repair door rear end panel
To tuff coat affected areas

180.00	30
150.00	46
1200.00	600
180.00	X NN
1200.00	400 600
180.00	40
<u>3090.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL:

8,239.01 H# 1310

~~Totals~~ 2402.8
2%: 1000 ~~1900~~ 2050
5 & Days.

HUP LEY HUAT MOTOR SPRAY PAINTING SERVICES

1 Kaki Bukit Ave 6, #01-35/33 Singapore 417883 (Autobay @ Kaki Bukit)

Tel: 67460674

Fax: 68417639

Email: hup.ley.huat@gmail.com

Vehicle No.: SJT 3147S

Model: TOYOTA VIOS E AUTO

<u>QTY</u>	<u>List items:</u>	<u>Price (S\$)</u>
1	Boot Lid	781.70
2	Boot Lid Hinge	322.80
2	Boot Lid Stopper	95.40
1	Boot Lid Lock	123.05
1	Boot Lid Lock Striker	121.01
1	Boot Lid Emblem "Vios"	32.90
1	Boot Lid Emblem "E"	27.20
1	Boot Lid Center Garnish	187.70
2	Boot Lid Center Garnish Clips	25.80
1	Boot Lid Weather Stripe	187.25
1	Boot Lid Key Cylinder	181.85
2	Tail Lamp	578.20
2	Tail Lamp Sealant	100.00
1	Rear Bumper	381.85
2	Rear Bumper Side Retainer	246.10
2	Rear Bumper Reflector	282.80
8	Rear Bumper Clips	103.20
2	Rear Bumper Stay Bracket	344.80
1	Rear End Panel	671.40
Spare Parts Subtotal:		4795.01

Special Nett Items

<u>QTY</u>	<u>List items:</u>	<u>Price (S\$)</u>
1 set	Reverse Sensor	280.00
1	Number Plate	45.00
1	Number Plate Casing	29.00
Special Nett Subtotal:		354.00
Spare Parts Total:		5149.01

Labour Charges:

To check and repair snap wiring	180.00
To remove and replace reverse sensor	150.00
To respray affected areas	1200.00
To check and adjust computer wheel alignment	180.00
To renew damaged parts, straighten and repair door rear end panel	1200.00
To tuff coat affected areas	180.00
	<hr/>
	3090.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL: 8,239.01

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Mar 2018		05 Mar 2018 11:54 Edit Adj Rpt	S\$2,050.00 Edit Estimates	S\$2,050.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	ESC TRANSPORT , Co. Reg. No.: 53314797B		
Vehicle Reg. No.:	SJT3147S	Date of Loss:	13/08/2017 01:00 - :59
Claim Type:	TP / MCT17080396	Policy/Cover Note No.:	MCOM0016 (Third Party Only)
Vehicle Reg. No. (Insured):	SHA4724T	Policy No. (Claimant):	MCOM0016
		Excess:	
Repairer:	VAC (Sin Ming) 385 Sin Ming Drive, 575718 Sin Ming - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/03/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?


No results.

Claim Documents

***SJT3147S (MCT17080396)**
[SHA4724T]
TP
ESC TRANSPORT
Aug 13 2017 1:00AM
[COMFORT TRANSPORTATION PTE LTD]
VAC


[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

























View [View in Browser ▼](#)

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/03/18 12:10	TPD LOD FROM CHEONGHOH LAW CORPORATION	 Load PDF	

Linked Accident Report Documents

View [View in Browser ▼](#)

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	14/08/17 08:47	Accident Statement	 Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	14/08/17 08:42	Accident Photo	 Load JPG	
2	14/08/17 08:42	Accident Photo	 Load JPG	
3	14/08/17 08:42	Accident Photo	 Load JPG	
4	14/08/17 08:42	Accident Photo	 Load JPG	
5	14/08/17 08:42	Accident Photo	 Load JPG	
6	14/08/17 08:42	Accident Photo	 Load JPG	
7	14/08/17 08:42	Accident Photo	 Load JPG	
8	14/08/17 08:42	Accident Photo	 Load JPG	
9	14/08/17 08:42	Accident Photo	 Load JPG	
10	14/08/17 08:42	Accident Photo	 Load JPG	
11	14/08/17 08:42	Accident Photo	 Load JPG	
12	14/08/17 08:42	Accident Photo	 Load JPG	

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Sin Ming)	Thumbnail	Print
1	14/08/17 08:46	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III17016033/GRBE2

Date: 06/03/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0016
Claimant Vehicle No :	SJT3147S	Insured Vehicle No :	SHA4724T
Date of Loss:	13/08/2017	Nature of Claim:	TP
		Claim No:	MCT17080396

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT3147S	Engine No:	1NZX958138
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305126706
Reg. Date:	01/10/2009 (Man. Year: 2009)	Odometer:	217086 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,149.01	1,292.80	3,856.21	74.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,310.00	1,780.00	57.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,239.01	2,602.80	5,636.21	68.41
Approved Total (Overridden) (\$\$)		2,050.00		
Nett Amount (\$\$)	8,239.01	2,050.00	6,189.01	75.12

INSPECTION

Date of Assignment:	05/03/2018	HUP LEY HUAT MOTOR SPRAY PAINTING SVS BLK 1 KAKI BUKIT AVE 6, #01-35 AUTOBAY SINGAPORE 417883
Date Inspected:	21/08/2017 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 06 Mar 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJT3147S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	781.70 F	*- FL
2	2		*BOOT LID HINGE	Not Necessary	322.80 F	*- FL
3	2		*BOOT LID STOPPER	Not Necessary	95.40 F	*- FL
4	1		*BOOT LID LOCK	Bent	123.05 F	*89.40 FL
5	1		*BOOT LID LOCK STRIKER	Not Necessary	121.01 F	*- FL
6	1		*BOOT LID EMBLEM VIOS	Necessary	32.90 F	*32.90 FL
7	1		*BOOT LID EMBLEM E	Necessary	27.20 F	*27.20 FL
8	1		*BOOT LID CENTER GARNISH	Not Necessary	187.70 F	*- FL
9	2		*BOOT LID CENTER GARNISH CLIPS	Not Necessary	25.80 F	*- FL
10	1		*BOOT LID KEY CYLINDER	Not Necessary	181.85 F	*- FL
11	1		*TAIL LAMP	O/S Cracked	578.20 F	*289.10 FL
12	2		*TAIL LAMP SEALANT	Not Necessary	100.00 F	*- FL
13	1		*REAR BUMPER	Deformed	381.85 F	*381.85 FL
14	2		*REAR BUMPER SIDE RETAINER	Necessary	246.10 F	*70.80 FL
15	1		*REAR BUMPER REFLECTOR	O/S Cracked	282.80 F	*54.70 FL
16	8		*REAR BUMPER CLIPS	Necessary	103.20 F	*22.00 FL
17	2		*REAR BUMPER STAY BRACKET	Not Necessary	344.80 F	*- FL
18	1		*REAR END PANEL	Buckled	671.40 F	*516.25 FL
19	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*100.00 FS
20	1		*NUMBER PLATE	Not Necessary	45.00 FS	*- FS
21	1		*NUMBER PLATE CASING	Not Necessary	29.00 FS	*- FS
22	1		*BOOT LID WEATHER STRIPE	Twisted	187.25 F	*106.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,149.01	1,690.40
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	397.60
Total Parts (\$)	5,149.01	1,292.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK AND REPAIR SNAP WIRING	New	180.00	30.00
2	TO REMOVE AND REPLACE REVERSE SENSOR	New	150.00	40.00
3	TO RESPRAY AFFECTED AREAS	New	1,200.00	600.00
4	TO CHECK AND ADJUST COMPUTER WHEEL ALIGNMENT	New	180.00	0.00
5	TO RENEW DAMAGED PARTS, STRAIGHTEN AND REPAIR DOOR REAR END PANEL	New	1,200.00	600.00
6	TO TUFF COAT AFFECTED AREAS	New	180.00	40.00
Gross Labour Cost (S\$)			3,090.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >