

ASS. REC. BY: Adrian King

REF: CC3/A19/7016037/Atbel

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$400/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 205K

IDAC Accident Rpt: _____ Consistent? : **Yes** or **No**

GIA / PR Seen: _____ Consistent? : **Yes** or **No**

Est. Repairs: 06 Wks days Res.: **Yes** or **No**

Lum Sum: _____ % 3 Val.: **Yes** or **No**

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: **IN / OUT**

Veh No: SLP3560D Yr Regn: 2017 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A6 c.c. 1798

Colour: Bronze A/C: **Insured / Std / NI / NA**

Sp. Reading: 5805 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: WAUZZ24G1HX044125

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 18/08/17

Survey held at Premium

Des. of Damages: **Fr** / **Rear** / **O/S** / **N/S** / **U/C** / Rooftop or

Front o/s.

The **U/C** / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 A19.

21/8 - Report via Maximen

23/8 - 15:12 authorize by Victor Koh

24/8 - 833am inform premium authorize repair excess \$400/-

Part by part \$8723.56

(Red: 14499.94 : 62%)

RECEIVED 15 DEC 2017

Date/Time, File Pass to?

1/15/12 Typist

Date/Time, File Return to?

2)

: Preli. Report
 : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee: 200
Transportation: _____
S + RS, SI _____
Photos 10
Others _____
TOTAL 210

Report Format: OD

Lump Sum / I.B. (\$ 8723.56)

View Received Message

This mail is associated with :

***SLP3560P (2611216939SG)**

OD

Aug 15 2017 6:00PM

[KELVIN HOO POH SAN]

Premium Automobiles Pte Ltd

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 23/08/2017 15:12 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$7944.00) - SLP3560P - Claim Handler: Loo, Tong Shing

Approved:7944.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 21 Aug 2017

Preliminary Advice

Vehicle No	: SLP3560P	Accident Date	: 15/08/2017
Make	: AUDI A6	Policy No.	: 1700011689
Assignment Date	: 18/08/2017	Excess	: S\$0.00
Date of Inspection	: 18/08/2017	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,309.00
Revised Amount	:S\$	7,944.00
Check Items (Estimated)	:S\$	11,916.00
Total	:S\$	19,860.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	205,000.00
COE / PARF Rebate	:S\$	83,533.00
Salvage Value	:S\$	
Margin for Repair	:S\$	121,467.00

Remarks

(x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 24 August, 2017 8:33 AM
To: 'Claims'; SUR
Subject: RE: SLP 3560 D Own Damage Claim

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLP 3560D (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 23 August, 2017 8:09 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SLP 3560 D Own Damage Claim

Dear all,

Attached video footage for your kind reference. kindly advise on the repair approval and excess amount.

Thank you and Have a nice day ahead!

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
 Owner ID: 9961E

Vehicle Details

Vehicle No.: SLP3560D
 Vehicle to be Exported: No
 Intended De-registration Date: 21 Aug 2017
 Vehicle Make: AUDI
 Vehicle Model: A6 1.8 TFSI ULTRA (PI) (NAV)
 Primary Colour: Grey
 Manufacturing Year: 2016
 Engine No.: CYG016746
 Chassis No.: WAUZZZ4G1HN044125
 Maximum Power Output: 140.0 kW (187 bhp)
 Open Market Value: \$40,436.00
 Original Registration Date: 31 May 2017
 First Registration Date: 31 May 2017
 Transfer Count: 0
 Actual ARF Paid: \$43,611.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 30 May 2027
 PARF Rebate Amount: \$32,708.00

Intended COE Rebate Details

COE Expiry Date: 30 May 2027
 COE Category: E - Open - all except motorcycle
 COE Period(Years): 10
 QP Paid: \$52,000.00
 COE Rebate Amount: \$50,825.00

Total Rebate Amount: \$83,533.00

The information contained herein is correct as at 21 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
 Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
 Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
 Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
 Last updated on 20 Aug 2017 at 12:36 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/08/2017 17:05
Date Of Accident	15/08/2017 18:00
Exact Location Of Accident	UPPER CHANGI ROAD /
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP3560P /
Insured/Policyholder	
Name Of Registered Owner	KELVIN HOO POH SAN /
NRIC No	S7029961E
Email Address	HPS001SG@YAHOO.COM
Mobile Phone No	(LOCAL) +65-91762854 /
Alternative Phone No	OTHERS-91762854

Vehicle Particulars

Manufacturer	AUDI
Model	A6 1.8 TFSI S TRONIC /
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700011689 /
Cover Note Number	

Driver

Name of Driver	KELVIN HOO POH SAN
NRIC No	S7029961E
Date Of Birth	05/09/1970
Occupation	INDOOR
Date Of Driving Pass	11/06/1996
Driving Experience	21 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91762854
Fax Number	
Contact Number	OTHERS-91762854
EEmail Address	HPS001SG@YAHOO.COM

Email Address

Sketch Plan #2

Describe Circumstances of the Accident

I was driving along Upper Changs Rd N, when a scooter hit my vehicle by the side of front bumper.

The impact damaged the R side bumper. As his damage was only scratches, he I did not notice he wished to stop until I drove up to him to settle the accident.

He claimed I tried to cut him here. But he ~~took~~ ^{ride fast} into my lane as it is only a 1 lane road.

Pls see ^{video} ~~photos~~ of the damage.

No reported injury ^{on} ~~to~~ ^{both} parties & we drove off after exchange particulars.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

16/08/17 1530hrs

Witnessed by Reporting Centre Personnel

Hk:



Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo





AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 1700011689
 Period of Insurance : 31 May 2017 to 30 May 2018

Issued Date : 07 Jun 2017

ABOUT THE POLICYHOLDER

Name of Policyholder : KELVIN HOO POH SAN
 Address : 138 JALAN SENANG
 SINGAPORE 418503

Occupation/Nature of Business : Executive/Admin

ABOUT THE VEHICLE

Registration No. :
 Chassis No. : WAUZZZ4G1HN044125
 Seating Capacity : 5
 Make/Model : AUDI A6 1.8 TFSI ULTRA
 Hire Purchase Company/Employer's Loan : DBS BANK LTD

Engine Capacity/Tonnage : 1,798.00 CC
 Engine No. : CYG016746
 Body Type : Sedan
 First Year of Registration : 2017

ABOUT THE COVER

Sum Insured : Market Value
 Driver Restriction : NA
 Off Peak Car : No
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive :

- a) The Policyholder
 - b) Any other person who is driving on the Policyholder's order or with his/her permission
- This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIOR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Strike, Riots and Civil Commotions, PA to Authorised Driver / Unnamed Passengers- \$10000, Dealer + AIG Authorised Workshops, PA Insured- \$100000, Fixture and Accessories (Cosmetic)- \$5000, Solar Film- \$1150, New For Old (24 months), NCD Protector

EXCESS

Section 1
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver
 KELVIN HOO POH SAN - \$800 (Own Damage)

PREMIUM

Premium : \$ 2,009.58
 GST (7%) : \$ 140.67

Total : \$ 2,150.25

Your Premium includes the following discount(s):
 Safe Driver Discount - 5.00%, No Claim Discount - 50%

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7029961E



Name

KELVIN HOO POH SAN



何宝旋

Race
CHINESE

Date of Birth 05-09-1970 Sex M

Country of Birth
SINGAPORE

S7029961E

1088874



NRIC No: S7029961E



Blood Group A+ Date of issue 06-07-1993

Address

NRIC No: S7029961E Date: 06-07-1993 No: 2673936

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7029961E

Name:

KELVIN HOO POH SAN

Birth Date: 05 Sep 1970

Issue Date: 07 Jun 2004




001232795K

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg

PASS DATE

11 Jun 1996



Licence No: S7029961E

NP 428A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0822/2017/DY
Date : 17-Aug-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kelvin Hoo Poh San
Address : 131 Jalan Senang
Singapore 418503
Telephone : HP +65 9176 2854
Type of Claim : Own Damage Claims
Policy No. : 1700011689
Vehicle No : **SLP 3560 P**
Model Code : Audi A6 1.8T FSI S-Tronic
Model / Year : May-17
Engine No : CYG 016746
Chassis No : WAUZZZ4G1HN044125
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-17
Place of Accident : Upper Changi Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 3560 D.

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓ ✓
2	To dismantle and renew front bumper and rhs headlight. Re-organize front crash management components. Re-install all parts removed.	\$ 1,400.00	1000. ✓
3	To respray front bumper, rhs front fender and bonnet.	\$ 2,500.00	1650. ✓
5	To carry out diagnostics.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 4,572.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 3560 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Del'd</i>	\$ 2,445.00	✓ 1956
2	FRONT BUMPER LOWER GRILLE <i>cracked</i>	\$ 106.00	? 84.40
3	FRONT BUMPER BRACKET - LHS/RHS <i>new</i>	2 \$ 62.00	? X
4	FRONT BUMPER CLOSING ELEMENT <i>Del'd</i>	\$ 178.00	? 142.40
5	FRONT BUMPER LOWER SPOILER <i>new</i>	\$ 768.00	? 614.40
6	RADIATOR GRILLE <i>at</i>	\$ 1,640.00	✓ 1312
7	EMBLEM BASE <i>new</i>	\$ 311.00	? X
8	FRONT BUMPER FOG LAMP COVER - RHS <i>Missing</i>	\$ 412.00	✓ 329.60
9	FRONT BUMPER SIDE AIR BAFFLE - RHS <i>new</i>	\$ 225.00	? X
10	FRONT FENDER INNER SHIELD - RHS <i>new</i>	\$ 238.00	x X
11	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$ 61.00	+ X
12	FRONT BUMPER SIDE GUIDE - LHS/RHS <i>Ripped</i>	2 \$ 62.00	? 24.08
13	FRONT BUMPER BRACE - LHS/RHS <i>new</i>	2 \$ 48.00	? X
14	FRONT SUPPORT PANEL TOP COVER <i>Del'd</i>	\$ 100.00	✓ 79.60
15	FRONT BUMPER FOAM FILLER <i>new</i>	\$ 193.00	+ }
16	FRONT BUMPER PARKING AID <i>new</i>	\$ 208.00	+ }
17	FRONT PARKING AID HARNESS <i>new</i>	\$ 499.00	+ }
18	LED HEADLIGHT - RHS <i>new</i>	\$ 9,454.00	? } X
19	HEADLIGHT MOUNTING <i>new</i>	\$ 100.00	? }
20	STONE GUARD FILM <i>new</i>	\$ 102.00	? }
SUB TOTAL SPARE PARTS		\$ 17,212.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

23038.46

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 3560 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT NO. PLATE <i>me</i>	\$ 25.00 ✓	<i>25</i>
22	SUNDRIES <i>neu</i>	\$ 500.00 ?	<i>779366104.72</i>
	TOTAL SPARE PARTS	\$ 17,737.00	
	TOTAL LABOUR CHARGES	\$ 4,572.00	
	GRAND TOTAL	\$ 22,309.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lij*
Surveyed Date : *18/08/17.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, OS Pays.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0822/2017/DY
Date : 17-Aug-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

We took 6 days with addition parts

jb 16/10

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kelvin Hoo Poh San
Address : 131 Jalan Senang
Singapore 418503
Telephone : HP +65 9176 2854
Type of Claim : Own Damage Claims
Policy No. : 1700011689
Vehicle No : **SLP 3560 P**
Model Code : Audi A6 1.8T FSI S-Tronic
Model / Year : May-17
Engine No : CYG 016746
Chassis No : WAUZZZ4G1HN044125
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 15-Aug-17
Place of Accident : Upper Changi Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 3560 D.

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper and rhs headlight. Re-organize front crash management components. Re-install all parts removed.	\$ 1,400.00	\$ 1,000.00
3	To respray front bumper, rhs front fender and bonnet.	\$ 2,500.00	\$ 1,650.00
5	To carry out diagnostics.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 4,572.00	\$ 3,322.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 3560 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,445.00	\$ 1,956.00
2	FRONT BUMPER LOWER GRILLE	\$ 106.00	\$ 84.40
3	FRONT BUMPER BRACKET - LHS/RHS	2 \$ 62.00	
4	FRONT BUMPER CLOSING ELEMENT	\$ 178.00	\$ 142.40
5	FRONT BUMPER LOWER SPOILER	\$ 768.00	\$ 614.40
6	RADIATOR GRILLE	\$ 1,640.00	\$ 1,312.00
7	EMBLEM BASE	\$ 311.00	
8	FRONT BUMPER FOG LAMP COVER - RHS	\$ 412.00	\$ 329.60
9	FRONT BUMPER SIDE AIR BAFFLE - RHS	\$ 225.00	
10	FRONT FENDER INNER SHIELD - RHS	\$ 238.00	
11	FRONT FENDER ATTACHMENT PARTS	\$ 61.00	
12	FRONT BUMPER SIDE GUIDE - LHS/RHS	2 \$ 62.00	\$ 24.08
13	FRONT BUMPER BRACE - LHS/RHS	2 \$ 48.00	
14	FRONT SUPPORT PANEL TOP COVER	\$ 100.00	\$ 79.60
15	FRONT BUMPER FOAM FILLER	\$ 193.00	
16	FRONT BUMPER PARKING AID	\$ 208.00	
17	FRONT PARKING AID HARNESS	\$ 499.00	
18	LED HEADLIGHT - RHS	\$ 9,454.00	
19	HEADLIGHT MOUNTING	\$ 100.00	
20	STONE GUARD FILM	\$ 102.00	
SUB TOTAL SPARE PARTS		\$ 17,212.00	\$ 4,542.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 3560 D.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 4,542.48
			\$ 25.00
21	FRONT NO. PLATE	\$ 25.00	\$ 25.00
22	Added parts - see attached	\$ 914.50	\$ 729.36
23	SUNDRIES	\$ 500.00	\$ 104.72
	TOTAL SPARE PARTS	\$ 18,651.50	\$ 5,401.56
	TOTAL LABOUR CHARGES	\$ 4,572.00	\$ 3,322.00
	GRAND TOTAL	\$ 23,223.50	\$ 8,723.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0822/2017/DY 28-Aug-17 Chang 1 of 1 SLP 3560 D Audi A6 1.8T FSI
Quantity	Description	Unit Price	Amount
Parts			
1	FRONT WHEEL SPOILER - LH <i>tom</i>	\$ 225.00	\$ 179.60
2	FRONT AIR GRILLE COVER - RH INNER <i>returned</i>	\$ 42.00	\$ 33.44
3	SIGN ' CAUTION ' STICKER <i>new</i>	\$ 12.00	\$ 9.04
4	HEADLIGHT WASHER HOSE <i>wt</i>	\$ 379.50	\$ 303.60
5	FRONT WHEEL SPOILER - RH <i>tom</i>	\$ 225.00	\$ 179.60
6	FRONT BUMPER ADAPTER - RH <i>2yrd</i>	\$ 31.00	\$ 24.08
GRAND TOTAL :		\$ 914.50	\$ 729.36

For Premium Automobiles Pte Ltd

Adrian Ling
[Signature]

33078-3L

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLP 3560 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0822/2017/MAS

13 Dec 2017

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLP 3560 D, Audi A6 1.8 TFSI S-Tronic

With reference to the above-mentioned vehicle, no **SLP 3560 D**, claimant, **Mr. Kelvin Hoo Poh San**, please find the related document per attached.

1. A copy of the Original invoice no. 85011901 – S\$8,906.21
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLP 3560 D

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408669
Telephone: 6388 2223

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2223
9828 1233

INS TAX INVOICE

Page 1 14:28

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85011901 Date : 12/12/2017 Order : SLP35600 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLP35600 (V 32041) Regn Date: 31/05/2017 Mileage: 8939 WIP No.: 34970
Model: A6 1.8 TFSI S tronic 4GC06G (N Chassis: WAUZZZ4G1HN044125 Engine: CYG 016746 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AI	480.00	1.00	480.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-400.00	1.00	-400.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. RE-INSTALL ALL PARTS REMOVED.	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONN	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTICS.	192.00	1.00	192.00
X	A4G0807084A	ADAPTER(V) Less 020%	1.00	30.10	24.08
X	A4G0807717B GRU	SPOILER(V) Less 020%	1.00	768.00	614.40
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone: 6386 2223

Customer Service
Service Appointment: 6366 2323
24-hour Breakdown Service: 9828 1233
Email: customer.care@premiumauto.com.sg

Page 2 14:28

INS TAX INVOICE
Company Reg. No: 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85011901 Date : 12/12/2017 Order : SLP35600 Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLP35600 (V 32041) Regn Date: 31/05/2017 Mileage: 8939 WIP No.: 34970
Model: A6 1.8 TFSI S tronic 4GC066 (N Chassis: WAUZZZ4G1HN044125 Engine: CYG 016746 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
X	A4G0807648B BMT	GRILL (V) Less 020%	1.00	412.00	329.60
X	A4G0807246D	COVER (V) Less 020%	1.00	41.80	33.44
X	A4G0955970D	HOSE (V) (G) Less 020%	1.00	379.50	303.60
X	A4G0853651AET94	GRILLE Less 020%	1.00	1640.00	1,312.00
X	A4G0853888J	SPOILER Less 020%	1.00	224.50	179.60
X	A4G0853887J	SPOILER Less 020%	1.00	224.50	179.60
X	A4G0807065ASGRU	COVER Less 020%	1.00	2445.00	1,956.00
X	A4G0807081D	COVER Less 020%	1.00	99.50	79.60
X	A4G0807611F	PLATE Less 020%	1.00	178.00	142.40
X	A000979034EC	SINGL. LEAD Less 020%	1.00	53.80	43.04
X	A000979940	CONNECTOR (WHITE) Less 020%	2.00	8.70	13.92
X	A7L5018897A	CLIP Less 020%	15.00	3.30	39.60
X	A8E0805163	CLIP Less 020%	2.00	2.30	3.68
X	A4G0807284	GUIDE Less 020%	1.00	30.10	24.08
X	ABK0010520A	PLATE Less 020%	1.00	11.30	9.04
X	A4G0807683C	GRILLE Less 020%	1.00	105.50	84.40
X	AN 90346302	RIVET Less 020%	4.00	1.40	4.48

Parts	5,376.56	Sub-Total	8,323.56
Labour	0.00	7% GST	582.65
Sublet	3,347.00	Grand Total	8,906.21
Menus	0.00		
Lubricant	0.00		



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLP 3560 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0822/2017/MAS
31 August 2017

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 1.8 T FSI S-TRONIC
Vehicle Chassis No. : WAUZZZAG1HN044125
Vehicle Regn No. : **SLP 3560 D**
Vehicle Mileage : 6557 KM
Vehicle Owner : Mr. Kelvin Hoo Poh San
Certificate No : 1700011689
Policy Excess : **SS428.00 (inclusive GST)**
Accident Date : 15 August 2017
Place : Upper Changi Road
Repair Cost : \$ 8,906.21
WIP No. : 34970
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



31/8/17

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7029961E



Name

KELVIN HOO POH SAN



何宝旋

Race

CHINESE

Date of Birth

05-09-1970

Country of Birth

SINGAPORE

Sex

M

S7029961E

1088874



NRIC No. S7029961E



Blood Group Date of Issue

A+ 06-07-1993

Address

NRIC No.

Date:

No: 2673936

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 1700011689
 Period of Insurance : 31 May 2017 to 30 May 2018

Issued Date : 07 Jun 2017

ABOUT THE POLICYHOLDER

Name of Policyholder : KELVIN HOO POH SAN
 Address : 138 JALAN SENANG
 SINGAPORE 418503

Occupation/Nature of Business : Executive/Admin

ABOUT THE VEHICLE

Registration No. : SLP3560D Engine Capacity/Tonnage : 1,798.00 CC
 Chassis No. : WAUZZZ4G1HN044125 Engine No. : CYG016746
 Seating Capacity : 5 First Year of Registration : 2017 Body Type : Sedan
 Make/Model : AUDI A6 1.8 TFSI ULTRA
 Hire Purchase Company/Employer's Loan : DBS BANK LTD

ABOUT THE COVER

Sum Insured : Market Value Off Peak Car : No
 Driver Restriction : NA Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive :

- a) The Policyholder
 - b) Any other person who is driving on the Policyholder's order or with his/her permission.
- This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :
 Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Strike, Riots and Civil Commotions, PA to Authorised Driver / Unnamed Passengers- \$10000, Dealer + AIG Authorised Workshops, PA Insured- \$100000, Fixture and Accessories (Cosmetic)- \$5000, Solar Film- \$1150, New For Old (24 months), NCD Protector

EXCESS	PREMIUM
Section 1 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0 Section 2 Property Damage - \$0 Windscreen : \$100 Named Driver KELVIN HOO POH SAN - \$800 (Own Damage)	Premium : \$ 2,009.58 GST (7%) : \$ 140.67 <hr/> Total : \$ 2,150.25 Your Premium includes the following discount(s): Safe Driver Discount - 5.00%, No Claim Discount - 50%

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2017 10:03		18 Aug 2017 17:11 Edit Adj Rpt	S\$8,723.56 Edit Estimates	S\$8,723.56 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	KELVIN HOO POH SAN, ID: S7029961E, Tel: +6591762854, Email: HPS001SG@YAHOO.COM	
Vehicle Reg. No.:	SLP3560D	Date of Loss: 15/08/2017 18:00 - :59
Claim Type:	OD / 2611216939SG	Policy/Cover Note No.: 1700011689 (Comprehensive)
		Excess: S\$400.00
Repairer:	Premium Automobiles Pte Ltd (HQ) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/08/2017]	
Driver/Custodian:	KELVIN HOO POH SAN (46 / Male), NRIC: S7029961E, Tel: +6591762854	
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail
<ul style="list-style-type: none"> • AIG_SG (23/11/2017): Alert - Adj Mandate Approved (S\$8723.56) - SLP3560P - Claim Handler: Loo, Tong S... • AIG_SG (23/08/2017): Alert - Adj Mandate Approved (S\$7944.00) - SLP3560P - Claim Handler: Loo, Tong S... • AIG_SG (23/08/2017): SLP3560P / OD / 15/08/2017 / Coverage & Excess update 		
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete
Due Date	Priority	Type
Task Group	Subject	Handler
Assigned By	Completed On	Created On
Done?	No results.	

Claim Documents

*SLP3560D (2611216939SG)
OD
Aug 15 2017 6:00PM
[KELVIN HOO POH SAN]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			Use Viewer			View
Video															1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	Premium Automobiles Pte Ltd (HQ)										Thumbnail	Print					
1	16/08/17 17:40	Video - Accident [Linked Accident Report Documents]										Load MP4	<input type="checkbox"/>					
Assessment Reports															1 per page	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print					
1	21/08/17 11:38	Adjuster Immediate Advice										Load HTM	<input type="checkbox"/>					
2	21/11/17 11:16	Adjuster Immediate Advice										Load HTM	<input type="checkbox"/>					
Photos/Images															3 per page	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print					
1	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
2	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
3	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
4	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
5	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
6	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
7	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
8	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
9	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
10	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
11	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
12	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
13	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
14	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
15	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
16	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
17	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
18	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
19	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
20	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
21	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
22	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
23	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
24	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
25	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
26	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
27	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
28	21/08/17 09:36	General View										Load JPG	<input checked="" type="checkbox"/>					
29	20/11/17 14:43	Reinspection Photo										Load JPG	<input checked="" type="checkbox"/>					
30	20/11/17 14:43	Reinspection Photo										Load JPG	<input checked="" type="checkbox"/>					
31	20/11/17 14:43	Reinspection Photo										Load JPG	<input checked="" type="checkbox"/>					

32	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
33	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
34	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
35	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
36	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
37	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
38	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
39	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
40	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
41	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
42	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
43	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
44	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
45	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
46	20/11/17 14:43	Reinspection Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/08/17 09:36	Singapore Accident Statement	1	Load PDF	
2	21/08/17 09:36	workshop estimate	1	Load PDF	
3	21/08/17 09:36	Drivers Driving License and NIRC	1	Load PDF	
4	21/08/17 09:36	Certificate of Insurance	1	Load PDF	
5	21/11/17 11:09	SUPPLEMENTARY	1	Load PDF	
6	21/11/17 11:09	ESTIMATE 2	1	Load PDF	
7	20/12/17 11:11	Workshop Invoice	1	Load PDF	
8	20/12/17 11:11	Discharge Voucher	1	Load PDF	

Linked Accident Report Documents

				View Use Viewer	
Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (HQ)		Thumbnail	Print
1	16/08/17 17:40	Video - Accident	1	Load MP4	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (HQ)		Thumbnail	Print
1	16/08/17 17:42	Accident Statement	1	Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (HQ)		Thumbnail	Print
1	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
2	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
3	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
4	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
5	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
6	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
7	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
8	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
9	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
10	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
11	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
12	16/08/17 17:33	Accident Photo	1	Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (HQ)		Thumbnail	Print
1	16/08/17 17:26	Sketch Plan	1	Load JPG	<input checked="" type="checkbox"/>

2	16/08/17 17:26	Sketch Plan #2		Load JPG	<input checked="" type="checkbox"/>
---	----------------	----------------	---	----------	-------------------------------------

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid gray; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17016037/ATBE2
Date: 20/12/2017

REFERENCE

Insured/Claimant: KELVIN HOO POH SAN **Policy No:** 1700011689
Date of Loss: 15/08/2017 **Nature of Claim:** OD **Claim No:** 2611216939SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP3560D	Engine No:	CYG016746
Make & Model:	AUDI A6, 1.8 TFSI S-tronic (A)	Chassis No:	WAUZZZ4G1HN044125
Reg. Date:	31/05/2017 (Man. Year: 2016)	Odometer:	5805 km
Colour:	Bronze		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$205,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	18,466.36	5,401.56	13,064.80	70.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,572.00	3,322.00	1,250.00	27.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,038.36	8,723.56	14,314.80	62.13
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	22,638.36	8,323.56	14,314.80	63.23
+ GST 7.00/7.00% (S\$)	1,584.69	582.65	1,002.04	63.23
Nett Amount (S\$)	24,223.05	8,906.21	15,316.84	63.23

INSPECTION

Date of Assignment: 18/08/2017
Date Inspected: 18/08/2017 **Inspected At:** Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT BUMPER	Deformed	2,445.00 FS	*1,956.00 FS	
2	1		*FRONT BUMPER LOWER GRILLE	Cracked	106.00 FS	*84.40 FS	
3	2		*FRONT BUMPER BRACKET - LHS/RHS	Not Necessary	62.00 FS	*- FS	
4	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	178.00 FS	*142.40 FS	
5	1		*FRONT BUMPER LOWER SPOILER	Torn	768.00 FS	*614.40 FS	
6	1		*RADIATOR GRILLE	Cut	1,640.00 FS	*1,312.00 FS	
7	1		*EMBLEM BASE	Not Necessary	311.00 FS	*- FS	
8	1		*FRONT BUMPER FOG LAMP COVER - RHS	Missing	412.00 FS	*329.60 FS	
9	1		*FRONT BUMPER SIDE AIR BAFFLE - RHS	Not Necessary	225.00 FS	*- FS	
10	1		*FRONT FENDER INNER SHIELD - RHS	Not Necessary	238.00 FS	*- FS	
11	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	61.00 FS	*- FS	
12	1		*FRONT BUMPER SIDE GUIDE - LHS/RHS	O/S Damaged	62.00 FS	*24.08 FS	
13	2		*FRONT BUMPER BRACE - LHS/RHS	Not Necessary	48.00 FS	*- FS	
14	1		*FRONT SUPPORT PANEL TOP COVER	Deformed	100.00 FS	*79.60 FS	
15	1		*FRONT BUMPER FOAM FILLER	Not Necessary	193.00 FS	*- FS	
16	1		*FRONT BUMPER PARKING AID	Not Necessary	208.00 FS	*- FS	
17	1		*FRONT PARKING AID HARNESS	Not Necessary	499.00 FS	*- FS	
18	1		*LED HEADLIGHT - RHS	Not Necessary	9,454.00 FS	*- FS	
19	1		*HEADLIGHT MOUNTING	Not Necessary	100.00 FS	*- FS	
20	1		*STONE GUARD FILM	Not Necessary	102.00 FS	*- FS	
21	1		*FRONT NO PLATE	Necessary	25.00 FS	*25.00 FS	
22	1		*SUNDRIES	Necessary	500.00 FS	*104.72 FS	
23	1		*FRONT WHEEL SPOILER - LH	Torn	179.60 FS	*179.60 FS	
24	1		*FRONT AIR GRILLE COVER - RH INNER	Deformed	33.44 FS	*33.44 FS	
25	1		*SIGN CAUTION STICKER	Necessary	9.04 FS	*9.04 FS	
26	1		*HEADLIGHT WASHER HOSE	Cut	303.60 FS	*303.60 FS	
27	1		*FRONT WHEEL SPOILER - RH	Torn	179.60 FS	*179.60 FS	
28	1		*FRONT BUMPER ADAPTER - RH	Damaged	24.08 FS	*24.08 FS	
					Total Parts (\$\$)	18,466.36	5,401.56

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORN, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. RE-INSTALL ALL PARTS REMOVED	New	1,400.00	1,000.00
3	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	2,500.00	1,650.00
4	TO CARRY OUT DIAGNOSTICS	New	192.00	192.00
Gross Labour Cost (\$\$)			4,572.00	3,322.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >