

REC BY: Adrian King

REF: CC3/ALG17016120/Arbe2

ASSIGNMENT

SCE80064

From: _____ Date: _____

Veh No: ~~SCE 1006411~~ Yr Regn: 2017, March

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: _____

Make: Audi A4 cc 1395

at Workshop m/s _____

Colour: Black A/C: Insured / Std / NI / NA

of _____

Sp. Reading: 5260 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. 2106504081

C/No: WAU22274XH40713S1

Claims No. 131811771756

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: 600

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 205/60R16

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Bal. or Market Value: 155K.

Front Rear

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 06 mm R/Bal. 06 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 06 mm L/Bal. 06 mm

Est. Repairs: 12 days Res.: Yes or No

D.O.A. D.O.I. 21/08/17

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at Premium

CA / REV / REP. / 24 HRS

Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD AIG.
	SCE 80064 - X
22/8/17	Sent preli through menimen, seek mandate
23/8/17	Mandate approve
	Confirm \$26,160.44, 12 Days
	Red: \$11572.56, 31%
	RECEIVED 10/09/2017

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 12

1) typst : Final Report

Resurvey No. of Trip: 3

Date/Time, File Return to?

Survey Fee:	200
Transportation:	
S + RS, SI	
Photos	10
Other:	
TOTAL	210

2)

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invc (\$)
 : Weekend (\$)

Report Format: 0D

Lump Sum / I.B.I: (\$ 26,160.44)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG17016120/Arb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 21-08-2017



Code : AIG

1. Policy Particulars : OWN DAMAGE

Insured Veh.		Veh. Inspected	SCE 8006U
Policy No.	2100504081	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/08/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/08/2017	Inspection Date	21/08/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 22 Aug 2017

Preliminary Advice

Vehicle No	: SCE8006U	Accident Date	: 17/08/2017
Make	: AUDI A4	Policy No.	: 2100504081-00000
Assignment Date	: 21/08/2017	Excess	: S\$0.00
Date of Inspection	: 21/08/2017	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,533.00
Revised Amount	:S\$	9,332.00
Check Items (Estimated)	:S\$	21,671.00
Total	:S\$	31,003.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	155,000.00
COE / PARF Rebate	:S\$	71,346.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,654.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

***SCE8006U (1318117717SG)**

OD

Aug 17 2017 7:05AM

[KOH KIA JENG LEWIS]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 23/08/2017 15:04 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$9332.00) - SCE8006U - Claim Handler: Loo, Tong Shing

Approved:9332.00:Re-inspection to be done for damage check and supplementary items / labour.

Print Received Message

This mail is associated with :

***SCE8006U (1318117717SG)**

OD

Aug 17 2017 7:05AM

[KOH KIA JENG LEWIS]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 23/08/2017 08:55 AM.
To LKK_HQ
Subject SCE8006U / OD / 17/08/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$600.00

Thank you
Loo, Tong Shing

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Wednesday, August 23, 2017 5:21 PM
To: 'Claims Department'
Cc: SUR
Subject: RE: SCE 8006 U Own Damage Claim (Vehicle IN)

Dear Sir,

As instructed by our client , please proceed to repair the insured vehicle **SCE 8006U (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [mailto:claims@premiumauto.com.sg]

Sent: Wednesday, August 23, 2017 2:05 PM

To: SUR <sur@lkkauto.com>

Cc: 'Claims Department' <claims@premiumauto.com.sg>

Subject: SCE 8006 U Own Damage Claim (Vehicle IN)

Dear all,

Kindly assist in the Own Damage Claim approval for the above mentioned vehicle.

Your urgent revert is very much appreciated.

Many thanks!

Best regards,
Claims Advisor

Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 10 Feb 2018

Preliminary Advice

Vehicle No	: SCE8006U	Accident Date	: 17/08/2017
Make	: AUDI A4	Policy No.	: 2100504081
Assignment Date	: 21/08/2017	Excess	: S\$600.00
Date of Inspection	: 21/08/2017	Est. Duration of Repair	: 12.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	37,733.00	(Include Supplementary Labour \$1,200)
Revised Amount	:S\$	26,160.44	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	26,160.44	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	155,000.00
COE / PARF Rebate	:S\$	71,346.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,654.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Janice Lee (LKKAUTO)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Monday, February 12, 2018 2:03 PM
To: SUR
Cc: Fong, Andy-SY
Subject: SCE8006U/ OD / 1318117717SG

Hi Adrian,

Kindly provide a breakdown on why 12 repair days are required for replacement of Bonnet, Bumper, LH/RH Headlamp, Reinforcement, Condenser, Radiator?



When the 1st survey was conducted, the bonnet was jammed tight and the bonnet could not be lifted up for assessment. Hence, upon approval for repairs, bonnet lock was dismantled and lifted up. Subsequently, as the bonnet was pushed back down, it was found that the two doors were affected with spray painting has to be done of the 2 doors.

Not to forget the dismantling of reservoir hidden and unconfirmed items.

A job of this nature (including spray paint of 2 doors) usually takes about 8-10 days, however, delays and multiple resurveys contributed to a total of 12 days.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Claims Department

From: Janice Lee (LKKAuto) [JaniceLee@lkkauto.com]
Sent: Thursday, 8 March, 2018 7:14 PM
To: Claims Department
Subject: RE: SCE 8006 U Own Damage Claim (Vehicle IN)

(Resent)

Dear Jeffery,

Please refer to the query from insurance.

“Kindly provide a breakdown on why 12 repair days are required for replacement of Bonnet, Bumper, LH/RH Headlamp, Reinforcement, Condenser, Radiator?”

“Kindly advise why the labour is 5 days at \$2500 since front lock carrier is not damage?”

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)

Sent: Wednesday, August 23, 2017 5:21 PM

To: Claims Department <claims@premiumauto.com.sg>

Cc: SUR <sur@lkkauto.com>

Subject: RE: SCE 8006 U Own Damage Claim (Vehicle IN)

Dear Sir,

As instructed by our client , please proceed to repair the insured vehicle **SCE 8006U (excess \$600/-)**.

If there are any check items or supplementary items please inform our office’s Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 3995J

Vehicle Details

Vehicle No.: SCE8006U

Vehicle to be Exported: No

Intended De-registration Date: 22 Aug 2017

Vehicle Make: AUDI

Vehicle Model: A4 1.4 TFSI S TRONIC

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: CVN024832

Chassis No.: WAUZZZF4XHA071351

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$32,219.00

Original Registration Date: 21 Mar 2017

First Registration Date: 21 Mar 2017

Transfer Count: 0

Actual ARF Paid: \$27,107.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 20 Mar 2027

PARF Rebate Amount: \$20,330.00

Intended COE Rebate Details

COE Expiry Date: 20 Mar 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$53,300.00

COE Rebate Amount: \$51,016.00

Total Rebate Amount: \$71,346.00

The information contained herein is correct as at 22 Aug 2017

OK

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 20 Aug 2017 at 12:36 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/08/2017 09:48
Date Of Accident	17/08/2017 07:05
Exact Location Of Accident	PIE BEF JLN EUNOS EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCE8006U
Insured/Policyholder	
Name Of Registered Owner	KOH KIA JENG LEWIS
NRIC No	S1533995J
Email Address	LEWISKOH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90017557
Alternative Phone No	HOME-64542575
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100504081-00000
Cover Note Number	
Driver	
Name of Driver	KOH KIA JENG LEWIS
NRIC No	S1533995J
Date Of Birth	18/01/1962
Occupation	INDOOR
Date Of Driving Pass	26/04/1980
Driving Experience	37 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90017557
Fax Number	
Contact Number	HOME-64542575
Email Address	LEWISKOH@GMAIL.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A = SCE 8006U

B = SKG 710ST

Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1533995J



Name
KOH KIA JENG LEWIS

许佳仁

Race
CHINESE
Date of Birth
18-01-1962 Sex
M
Country of Birth
SINGAPORE



Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 26 Apr 1980

NP 428A

Licence No: S1533995J



1288753



NRIC No: S1533995J



Blood Group B Date of issue 13-09-1992

2 RIDGEWOOD CLOSE #07-01
SINGAPORE 276693
NRIC No: S1533995J Date: 11/02/2013 No: 7277307



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

<p>AUDI AUTO PROTECTOR</p> <p>CERTIFICATE NO. 2100504081-00000</p> <p>1) VEHICLE REGISTRATION NO.</p> <p>2) NAME OF INSURED</p> <p>3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT</p> <p>4) DATE OF EXPIRY OF INSURANCE</p> <p>5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION :All Age Condition a) The Insured. b) Any other person who is driving on the Insured's order or with his permission. This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions. A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in additional to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.</p> <p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>6) LIMITATION AS TO USE * Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.</p> <p>APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS 1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323) APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS) 2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501) 4. Ethoz - 30 Bukit Batok Cres(Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only 6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 10. SME Motor - 1 Kaki Bukit Ave 6 Blk D (Tel: 67476106)</p>	<p>OWN DAMAGE EXCESS S\$600.00 (1)</p> <p>WINDSCREEN EXCESS S\$100.00 <small>(for policies with effect from 1st November 2002)</small></p> <p>SUM INSURED Market Value</p> <p>INSURING WITH COE/PARF Yes</p> <p>SCE8006U</p> <p>KOH KIA JENG LEWIS</p> <p>21 Mar 2017</p> <p>20 Mar 2018</p>
<p>LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre</p> <p>NAMED DRIVER NA</p> <p>HIRE PURCHASE COMPANY / EMPLOYER'S LOAN DBS BANK LTD</p> <p><small>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</small></p>	

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 22 Mar 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-251
PREMIUM LEASING -LES
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE
CENTRE SINGAPORE 159938



AUTHORISED REPRESENTATIVE

ORIGINAL

PRL.YCQ.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0825/2017/CCS
Date : 18-Aug-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Koh Kia Jeng Lewis
Address : 2 Ridgewood Close
#07-01
Singapore 276693
Telephone : HP +65 90017557
Type of Claim : Own Damage Claims
Policy No. : 2100504081
Vehicle No : **SCE 8006 U**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Mar-17
Engine No : CVN 024832
Chassis No : WAUZZZF4XHA071351
Mileage : -
Date In : 18-Aug-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Aug-17
Place of Accident : PIE Bef Jln Eunost exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lij*
Surveyed Date : *21/08/17*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, OS Pays*

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Customer of the following must notify the repairer in writing:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- To display
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCE 8006 U.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ /
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system.	S/N \$ 1,000.00	? /
3	To dismantle front bumper and bonnet. Renew front lock carrier and align to position. Renew front bumper, bonnet and both headlights. Re-organise front crash management components. Reinstall all parts removed.	\$ 4,200.00	1500 - 2500
4	To remove both front door panel trims and wing mirror assy. Renew both front window chrome molding.	S/N \$ 600.00	? x
5	To respray front bumper, bonnet and both front fenders.	\$ 3,000.00	1100 - 1650
6	To carry out diagnostic check.	S/N \$ 192.00	✓ /
TOTAL LABOUR CHARGES		: \$ <u>9,352.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCE 8006 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Disturbed</i>	\$ 1,703.00	✓ 1404
2	FRONT BUMPER GRILLE - LOWER CENTER <i>Not New</i>	\$ 163.00	? x
3	RADIATOR GRILLE <i>Smashed</i>	\$ 1,473.00	✓ 1446.40
4	FRONT REINFORCEMENT BEAM <i>Best</i>	\$ 674.00	✓ 531.20
5	FRONT BUMPER GUIDE - LH/RH <i>Not New</i>	2 \$ 62.00	? x
6	FRONT BUMPER FOAM <i>Delid</i>	\$ 101.00	✓ 80.80
7	FRONT BUMPER TOP COVER <i>Delid</i>	\$ 104.00	✓ 92.80
8	SIGN ' CAUTION ' STICKER <i>m</i>	\$ 12.00	✓ 9.04
9	STICKER FOR AIR CONDITIONER <i>m</i>	\$ 6.00	✓ 4.64
10	BONNET RELEASE LEVER <i>Prod</i>	\$ 12.00	✓ 9.04
11	BONNET BOWDEN CABLE <i>Prod</i>	\$ 49.00	? 38.64
12	FRONT LOCK CARRIER BRACKET <i>Smashed.</i>	\$ 112.00	? 89.20
13	FRONT BUMPER SUPPORT - LH/RH <i>m</i>	2 \$ 46.00	+ 36.00
14	LED HEADLIGHT - LH/RH <i>Smashed.</i>	2 \$ 15,722.00	? 12577.60
15	HEADLIGHT WASHER CYLINDER BRACKET <i>2 x 1</i>	2 \$ 10.00	+
16	HEADLIGHT WASHER CYLINDER - LH/RH <i>2 x 1</i>	2 \$ 360.00	+ 288
17	CORRUGATED PIPE <i>Not New</i>	\$ 75.00	x
18	BONNET <i>Disturbed</i>	\$ 2,001.00	✓ 1600.80
19	BONNET ATTACHMENT PARTS <i>Not New</i>	\$ 103.00	x
20	BONNET HINGE - LH/RH <i>Not New</i>	2 \$ 514.00	+
SUB TOTAL SPARE PARTS		\$ 23,302.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCE 8006 U.

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
21	BONNET IMPACT PROTECTION - LH/RH <i>2 pair</i>	2 \$	46.00	✓ 36.32
22	BONNET IMPACT PROTECTION - CENTER	\$	23.00	✓ 15.16
23	BONNET LOCK STRIKER - LH/RH <i>Bent</i>	2 \$	86.00	? 67.36
24	BONNET LOCK <i>Not New</i>	2 \$	360.00	?
25	FRONT LOCK CARRIER <i>Not New</i>	\$	878.00	?
26	LOCK CARRIER AIR GUIDE - LH/RH INNER <i>Not New</i>	2 \$	44.00	?
27	LOCK CARRIER AIR GUIDE - LH/RH UPPER <i>Not New</i>	2 \$	20.00	? 14.72
28	A/C CONDENSER <i>Bent</i>	\$	525.00	? 419.60
29	CONDENSER HIGH PRESSURE VALVE <i>Not New</i>	\$	45.00	?
30	A/C CONDENSER PRESSURE SENSOR <i>Not New</i>	\$	163.00	?
31	RADIATOR <i>Bent</i>	\$	576.00	? 460.40
32	RADIATOR RUBBER BUSH <i>Not New</i>	\$	38.00	?
33	COOLANT <i>Not New</i>	\$	132.00	? 105.28
34	FRONT DOOR WINDOW CHROME TRIM - LH/RH <i>Not New</i>	2 \$	518.00	?
35	FRONT NUMBER PLATE <i>Bent</i>	S/N \$	25.00	✓ /
36	SUNDRIES <i>New</i>	\$	400.00	? 544
TOTAL SPARE PARTS		:	\$ 27,181.00	
TOTAL LABOUR CHARGES		:	\$ 9,352.00	
GRAND TOTAL		:	\$ 36,533.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

37733.00

Premium Automobiles

55.Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0825/2017/DY 28-Aug-17 Chang 1 of 1 SCE 8006 U Audi A4 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	BONNET LOCK BOWDEN CABLE	\$ 49.00	<i>sundries</i>
Labour			
1	To respray both front door /	\$ 1,200.00	\$ 1,100.00
GRAND TOTAL :		\$ 1,249.00	\$ 1,100.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg


Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0825/2017/CCS
Date : 18-Aug-17

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120



Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Koh Kia Jeng Lewis
Address : 2 Ridgewood Close
#07-01
Singapore 276693
Telephone : HP +65 90017557
Type of Claim : Own Damage Claims
Policy No. : 2100504081
Vehicle No : **SCE 8006 U**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Mar-17
Engine No : CVN 024832
Chassis No : WAUZZZF4XHA071351
Mileage : -
Date In : 18-Aug-17
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Aug-17
Place of Accident : PIE Bef Jln Eunus exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SCE 8006 U.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum / regas and to pressurise cooling system. <i>(Condenser, radiator replaced)</i>	S/N \$ 1,000.00	\$ 1,000.00
3	To dismantle front bumper and bonnet. Renew front lock carrier and align to position. Renew front bumper, bonnet and both headlights. Re-organise front crash management components. Reinstall all parts removed. <i>(Lock carrier removed and reinstall)</i>	\$ 4,200.00	\$ 2,500.00
4	To remove both front door panel trims and wing mirror assy. Renew both front window chrome molding.	S/N \$ 600.00	<i>nil</i>
5	To respray front bumper, bonnet and both front fenders. <i>(RHS front fender resprayed)</i>	\$ 3,000.00	\$ 1,650.00
5a	<i>Added labour - see attached</i>	\$ 1,200.00	\$ 1,100.00
6	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 10,552.00	\$ 6,802.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCE 8006 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,703.00	\$ 1,404.00
2	FRONT BUMPER GRILLE - LOWER CENTER	\$ 163.00	
3	RADIATOR GRILLE	\$ 1,473.00	\$ 1,446.40
4	FRONT REINFORCEMENT BEAM	\$ 674.00	\$ 539.20
5	FRONT BUMPER GUIDE - LH/RH	2 \$ 62.00	
6	FRONT BUMPER FOAM	\$ 101.00	\$ 80.80
7	FRONT BUMPER TOP COVER	\$ 104.00	\$ 82.80
8	SIGN ' CAUTION ' STICKER	\$ 12.00	\$ 9.04
9	STICKER FOR AIR CONDITIONER	\$ 6.00	\$ 4.64
10	BONNET RELEASE LEVER	\$ 12.00	\$ 9.04
11	BONNET BOWDEN CABLE	\$ 49.00	\$ 38.64
12	FRONT LOCK CARRIER BRACKET	\$ 112.00	\$ 89.20
13	FRONT BUMPER SUPPORT - LH/RH	2 \$ 46.00	\$ 36.00
14	LED HEADLIGHT - LH/RH	2 \$ 15,722.00	\$ 12,577.60
15	HEADLIGHT WASHER CYLINDER BRACKET	2 \$ 10.00	
16	HEADLIGHT WASHER CYLINDER - LH/RH	2 \$ 360.00	\$ 288.00
17	CORRUGATED PIPE	\$ 75.00	
18	BONNET	\$ 2,001.00	\$ 1,600.80
19	BONNET ATTACHMENT PARTS	\$ 103.00	
20	BONNET HINGE - LH/RH	2 \$ 514.00	
SUB TOTAL SPARE PARTS		\$ 23,302.00	\$ 18,206.16

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCE 8006 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
		<i>cf</i>	\$ 18,206.16
21	BONNET IMPACT PROTECTION - LH/RH	2 \$ 46.00	\$ 36.32
22	BONNET IMPACT PROTECTION - CENTER	\$ 23.00	\$ 18.16
23	BONNET LOCK STRIKER - LH/RH	2 \$ 86.00	\$ 67.36
24	BONNET LOCK	2 \$ 360.00	
25	FRONT LOCK CARRIER	\$ 878.00	
26	LOCK CARRIER AIR GUIDE - LH/RH INNER	2 \$ 44.00	
27	LOCK CARRIER AIR GUIDE - LH/RH UPPER	2 \$ 20.00	\$ 14.72
28	A/C CONDENSER	\$ 525.00	\$ 419.60
29	CONDENSER HIGH PRESSURE VALVE	\$ 45.00	
30	A/C CONDENSER PRESSURE SENSOR	\$ 163.00	
31	RADIATOR	\$ 576.00	\$ 460.40
32	RADIATOR RUBBER BUSH	\$ 38.00	
33	COOLANT	\$ 132.00	\$ 105.28
34	FRONT DOOR WINDOW CHROME TRIM - LH/RH	2 \$ 518.00	
35	FRONT NUMBER PLATE	S/N \$ 25.00	\$ 25.00
36	SUNDRIES	\$ 400.00	\$ 5.44
TOTAL SPARE PARTS		\$ 27,181.00	\$ 19,358.44
TOTAL LABOUR CHARGES		\$ 10,552.00	\$ 6,802.00
GRAND TOTAL		\$ 37,733.00	\$ 26,160.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Janice Lee (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, October 11, 2017 5:13 PM
To: Adrian Ling (LKKAuto); Janice Lee (LKKAuto); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION FOR SCE8006U - OD AIG - SURVEYED 21 AUG 17
Attachments: PA08252017 - SCE 8006 U - A4 SEDAN 1.4 TFSI - FRONT (AIG) + SUPP.xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$26,160.44 @ 12 days of repairs exclude 2 Sundays and 1 Public Holiday. You re-inspected vehicle on 24 Aug 17.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCE 8006 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
✓ 1	FRONT BUMPER <i>Disturbed</i>	\$ 1,703.00	✓
X 2	FRONT BUMPER GRILLE - LOWER CENTER ?	\$ 163.00	?
3	RADIATOR GRILLE <i>smashed</i>	\$ 1,473.00	✓
✓ 4	FRONT REINFORCEMENT BEAM <i>Best</i>	\$ 674.00	✓
5 X	FRONT BUMPER GUIDE - LH/RH ?	2 \$ 62.00	?
6 ✓	FRONT BUMPER FOAM <i>Del'd</i>	\$ 101.00	✓
7 ✓	FRONT BUMPER TOP COVER <i>Del'd</i>	\$ 104.00	✓
8 ✓	SIGN ' CAUTION ' STICKER <i>m</i>	\$ 12.00	✓
9 ✓	STICKER FOR AIR CONDITIONER <i>m</i>	\$ 6.00	✓
10	BONNET RELEASE LEVER <i>Payd</i>	\$ 12.00	✓
11 ?	BONNET BOWDEN CABLE ?	\$ 49.00	?
12 ✓	FRONT LOCK CARRIER BRACKET ? ✓	\$ 112.00	?
<i>113/114</i> 13	FRONT BUMPER SUPPORT - LH/RH <i>m</i> ✓	2 \$ 46.00	+
14	LED HEADLIGHT - LH/RH ? <i>Atk wack/</i> ✓	2 \$ 15,722.00	?
<i>115</i> 15	HEADLIGHT WASHER CYLINDER BRACKET <i>For</i>	2 \$ 10.00	+
<i>wacked</i> 16	HEADLIGHT WASHER CYLINDER - LH/RH ✓	2 \$ 360.00	+
<i>2 pcs</i> 17 X	CORRUGATED PIPE ?	\$ 75.00	?
18	BONNET <i>Disturbed</i>	\$ 2,001.00	✓
19	BONNET ATTACHMENT PARTS ?	\$ 103.00	?
20	BONNET HINGE - LH/RH <i>m</i>	2 \$ 514.00	+
SUB TOTAL SPARE PARTS		\$ 23,302.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SCE 8006 U.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET IMPACT PROTECTION - LH/RH <i>fan</i>	2 \$	46.00 ✓
22	BONNET IMPACT PROTECTION - CENTER <i>fan</i>	\$	23.00 ✓
<i>used/OK</i> 23	BONNET LOCK STRIKER - LH/RH ✓	2 \$	86.00 ?
24	X BONNET LOCK ?	2 \$	360.00 ?
<i>cracked</i> 25	FRONT LOCK CARRIER ?	\$	878.00 ?
26	LOCK CARRIER AIR GUIDE - LH/RH INNER ?	2 \$	44.00 ?
<i>dented</i> 27	LOCK CARRIER AIR GUIDE - LH/RH UPPER ✓	2 \$	20.00 ?
28	A/C CONDENSER ?	\$	525.00 ?
29	CONDENSER HIGH PRESSURE VALVE ?	\$	45.00 ?
30	A/C CONDENSER PRESSURE SENSOR ?	\$	163.00 ?
31	RADIATOR ? ✓	\$	576.00 ?
32	RADIATOR RUBBER BUSH?	\$	38.00 ?
33	COOLANT ? ✓	\$	132.00 ?
X 34	FRONT DOOR WINDOW CHROME TRIM - LH/RH ?	2 \$	518.00 ?
35	FRONT NUMBER PLATE <i>Bent</i>	S/N \$	25.00 ✓
36	SUNDRIES	\$	400.00 ?
TOTAL SPARE PARTS		:	\$ 27,181.00
TOTAL LABOUR CHARGES		:	\$ 9,352.00
GRAND TOTAL		:	\$ 36,533.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0825/2017/DY 28-Aug-17 Chang 1 of 1 SCE 8006 U Audi A4 SEDAN 1.4 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	BONNET LOCK BOWDEN CABLE /	\$ 49.00	(A)	
GRAND TOTAL :		\$ 49.00		

paid 29/8/17

For Premium Automobiles Pte Ltd



 Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SCE 8006 U

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0825/2017/MAS

12 April 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SCE 8006 U, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SCE 8006 U**, claimant, **Mr. Koh Kia Jeng Lewis**, please find the related document per attached.

1. A copy of the Original invoice no. 85012318 – S\$27,349.67
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept


Encls

AIG – SCE 8006 U

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
 281 Alexandra Road
 Singapore 159938
 Main Telephone 6836 2223
 Main Telefax 6471 3733

Alexandra Service Centre
 281 Alexandra Road
 Singapore 159938
 Telephone 6388 2223
 Telefax 6475 1023

Ubi Service Centre
 55 Ubi Road 1
 Singapore 408699
 Telephone 6388 2223

Customer Service
 Service Appointment 6366 2323
 24-hour Breakdown Service 9828 1233
 Email customer.care@premiumauto.com.sg

INS TAX INVOICE
 Company Reg. No. 199902271W
 GST Reg. No. 199902271W

Page 1 10:25

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012318 Date : 09/04/2018 Order : SCE8006U Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SCE8006U (V 32121) Regn Date: 21/03/2017 Mileage: 15918 WIP No.: 35030
 Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XHA071351 Engine: CVN 024832 Dept: U
 VSB No.:

You have been assisted by :- UB-Carrine (33)

	Details	Qty	Unit Price	Amount
S	BODYWORK M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FPG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	SUBLET M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL U TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM.	1000.00	1.00	1,000.00
S	BODYWORK M: TO DISMANTLE FRONT BUMPER AND BONNET. ALIGN FRONT LOCK CARRIER. RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	2500.00	1.00	2,500.00

Sub-Total	
7% GST	
Grand Total	



Premium Automobiles Pte Ltd

Audi Centre Singapore
 281 Alexandra Road
 Singapore 159938
 Main Telephone 6836 2223
 Main Telefax 6471 3733

Alexandra Service Centre
 281 Alexandra Road
 Singapore 159938
 Telephone 6388 2223
 Telefax 6475 1023

Ubi Service Centre
 55 Ubi Road 1
 Singapore 408600
 Telephone 6388 2323

Customer Service
 Service Appointment 6366 2323
 24-hour Breakdown Service 9828 1233
 Email customer.care@premiumauto.com.sg

INSURANCE INVOICE

Company Reg. No. 199902271W
 GST Reg. No. 199902271W

Page 2 10:25

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012318 Date : 09/04/2018 Order : SCE8006U Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--


Regn No.: SCE8006U (V 32121) Regn Date: 21/03/2017 Mileage: 15918 WIP No.: 35030

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XH0071351 Engine: CVN 024832 Dept: U

USB No.:

You have been assisted by :- UB-Carrine (33)

	Details	Qty	Unit Price	Amount
S	BODYWORK M: TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER.	1650.00	1.00	1,650.00
S	BODYWORK M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
S	BODYWORK M: TO RESPRAY BOTH FRONT DOOR.	1100.00	1.00	1,100.00
X	AG A13A8JM1 COOLANT ADDITIVE Less 020%	4.00	32.90	105.28
X	A8W0053651ACRN4 GRILLE (A) Less 020%	1.00	1808.00	1,446.40
X	A8W0941773A HEADLIGHT Less 020%	1.00	7861.00	6,288.80
X	A8W0941774A HEADLIGHT (A) Less 020%	1.00	7861.00	6,288.80
X	A8W0023029A HOOD Less 020%	1.00	2001.00	1,600.80
X	A8W0007065D GRU COVER Less 020%	1.00	1755.00	1,404.00
X	A8W0007001 COVER Less 020%	1.00	103.50	82.80
X	A8W0121251K RADIATOR Less 020%	1.00	575.50	460.40
X	A8W0016421H CONDENSER Less 020%	1.00	524.50	419.60
X	A8W0007550A FOAM INSER Less 020%	1.00	101.00	80.80
X	A8W0007113 BRACKET Less 020%	1.00	674.00	539.20
Sub-Total				
7% GST				
Grand Total				



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Telephone 6386 2323

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 3 10:25

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012318 Date : 09/04/2018 Order : SCE8006U Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SCE8006U (V 32121) Regn Date: 21/03/2017 Mileage: 15918 WIP No.: 35030

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XHA071351 Engine: CVN 024832 Dept: U

USB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
X	A8W0007334	SUPPORT Less 020%	1.00	22.50	18.00
X	A8W0007333	SUPPORT Less 020%	1.00	22.50	18.00
X	A8W0023185D	CATCH Less 020%	1.00	42.10	33.68
X	A8W0023186D	CATCH Less 020%	1.00	42.10	33.68
X	A8W0121673A	AIR DUCT Less 020%	1.00	9.20	7.36
X	A8W0121674A	AIR DUCT Less 020%	1.00	9.20	7.36
X	A8W0023661D	LEVER Less 020%	1.00	11.30	9.04
X	A8W0023125	PROTECTION Less 020%	1.00	22.70	18.16
X	A8W0023126	PROTECTION Less 020%	1.00	22.70	18.16
X	A4E0260749A	WASHER Less 020%	1.00	3.10	2.48
X	A3D0260749C	WASHER Less 020%	1.00	3.70	2.96
X	A8W0023529E	BOWD CABLE Less 020%	1.00	48.30	38.64
X	A8W0955102A	CYLINDER Less 020%	1.00	180.00	144.00
X	A8W0955101A	CYLINDER Less 020%	1.00	180.00	144.00
X	A8W0010515A	STICKER Less 020%	1.00	5.80	4.64
X	A8K0010520A	PLATE Less 020%	1.00	11.30	9.04
X	A8W0007771	BRACKET Less 020%	1.00	111.50	89.20
X	A8W0023124	PROTECTION Less 020%	1.00	22.70	18.16

Parts 19,333.44
Labour 0.00
Sublet 6,827.00
Menus 0.00
Lubricant 0.00

Sub-Total 25,560.44
7% GST 1,789.23
Grand Total 27,349.67



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SCE 8006 U

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0825/2017/MAS
29 August 2017

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI
Vehicle Chassis No. : WAUZZZFAXHA071351
Vehicle Regn No. : SCE 8006 U
Vehicle Mileage : 5261km
Vehicle Owner : Mr. Koh Kia Jeng Lewis
Certificate No : 2100504081-00000
Policy Excess : **S\$642.00 (inclusive GST)**
Accident Date : 17 Aug 2017
Place : PIE Bef Jalan Eunus Exit
Repair Cost : \$ 27,349.67
WIP No. : 35030
Repairer’s Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer’s charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 29/8/17

REPUBLIC OF SINGAPORE DRIVING LICENCE



18 Jan 1962
03 Nov 2013

000973395J

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1533995J



Name
KOH KIA JENG LEWIS

许佳仁
Race
CHINESE
Date of Birth 18-01-1962
Country of Birth SINGAPORE

Sex

M

ST

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms 26 Apr 1980

NP 428A

Licence No: S1533995J

1268753



NRIC No. S1533995J



Blood Group B+ Date of issue 13-09-1993

2 RIDGEWOOD CLOSE #07-01
SINGAPORE 276693
NRIC No: S1533995J Date: 11/02/2013 No: 7277307



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT(CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

M.X.1

<p>AUDI AUTO PROTECTOR</p> <p>CERTIFICATE NO. 2100504081-00000</p> <p>1) VEHICLE REGISTRATION NO. SCE8006U</p> <p>2) NAME OF INSURED KOH KIA JENG LEWIS</p> <p>3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT 21 Mar 2017</p> <p>4) DATE OF EXPIRY OF INSURANCE 20 Mar 2018</p> <p>5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE * SUBJECT TO AGE CONDITION :All Age Condition a) The Insured. b) Any other person who is driving on the Insured's order or with his permission. This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions. A Young and/or Inexperienced Driver Excess ("YIDR") of S\$3,000.00, in addition to the Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.</p> <p>Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.</p> <p>6) LIMITATION AS TO USE * Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or rewards, tuition, driving test, racing, pace-making, reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.</p> <p>APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS 1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63662323) APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS) 2. ComfortDelgro Engrg - 205 Braddell Rd (Tel: 63837118) 3. DPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501) 4. Ethoz - 30 Bukit Batok Cres (Tel:66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only 6. Kan Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lai Huat (Meng Kee) Motor - 21 Sin Ming Ind (Tel: 64538110) 8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336) 10. SME Motor - 1 Kaki Bukit Ave 6 Bik D (Tel: 67476106)</p> <p>LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre</p> <p>NAMED DRIVER NA</p> <p>HIRE PURCHASE COMPANY / EMPLOYER'S LOAN DBS BANK LTD</p> <p><small>* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.</small></p>	<p>OWN DAMAGE EXCESS S\$600.00 (I)</p> <p>WINDSCREEN EXCESS S\$100.00 <small>(for policies with effect from 1st November 2002)</small></p> <p>SUM INSURED Market Value</p> <p>INSURING WITH COE/PARF Yes</p>
---	--

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 22 Mar 2017

AIG Asia Pacific Insurance Pte. Ltd.

504125-251
PREMIUM LEASING - LES
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE
CENTRE SINGAPORE 159938

AUTHORISED REPRESENTATIVE

ORIGINAL

PRLYCQ.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2017		21 Aug 2017 15:51 Edit Adj Rpt	S\$26,160.44 Edit Estimates	S\$26,160.44 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	KOH KIA JENG LEWIS, ID: S1533995J, Tel: +6590017557, Email: LEWISKOH@GMAIL.COM		
Vehicle Reg. No.:	SCE8006U	Date of Loss:	17/08/2017 07:00 - :59 [4 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1318117717SG	Policy/Cover Note No.:	2100504081 (Comprehensive)
		Excess:	S\$600.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/08/2017]		
Driver/Custodian:	KOH KIA JENG LEWIS (55 / Male), NRIC: S1533995J, Tel: +6590017557		

ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (27/03/2018): Alert - Adj Mandate Approved (S\$26160.44) - SCE8006U - Claim Handler: Loo, Tong ... AIG_SG (21/02/2018): Alert - Adj Mandate Maintained - SCE8006U - Claim Handler: Loo, Tong Shing AIG_SG (23/08/2017): Alert - Adj Mandate Approved (S\$9332.00) - SCE8006U - Claim Handler: Loo, Tong S... AIG_SG (23/08/2017): SCE8006U / OD / 17/08/2017 / Coverage & Excess update 			

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCE8006U (1318117717SG)
 OD
 Aug 17 2017 7:00AM
 [KOH KIA JENG LEWIS]
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <input type="button" value="View in Browser"/>
Assessment Reports						1 per page <input type="button" value="1"/> <input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	22/08/17 15:18	Adjuster Immediate Advice			Load HTM	<input type="checkbox"/>
2	10/02/18 16:25	Adjuster Immediate Advice			Load HTM	<input type="checkbox"/>
Photos/Images						3 per page <input type="button" value="3"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
2	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
3	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
4	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
5	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
6	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
7	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
8	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
9	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
10	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
11	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
12	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
13	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
14	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
15	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
16	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
17	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
18	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
19	22/08/17 15:48	General View			Load JPG	<input checked="" type="checkbox"/>
20	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
21	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
22	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
23	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
24	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
25	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
26	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
27	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
28	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
29	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
30	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
31	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
32	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
33	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>
34	19/12/17 19:30	Reinspection Photo			Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
36	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
37	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
38	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
39	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
40	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
41	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
42	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
43	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
44	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
45	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
46	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
47	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
48	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
49	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
50	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
51	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
52	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
53	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
54	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
55	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
56	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
57	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
58	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
59	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
60	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
61	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
62	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
63	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
64	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
65	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
66	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
67	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
68	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
69	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
70	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
71	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
72	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
73	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
74	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
75	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
76	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
77	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
78	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
79	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
80	19/12/17 19:30	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/08/17 15:43	Certificate of Insurance		<input type="checkbox"/>
2	22/08/17 15:43	WORKSHOP ESTIMATE		<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	22/08/17 15:43	Singapore Accident Statement		Load PDF
4	22/08/17 15:43	Insured's NRIC & DRIVING LICENSE		Load PDF
5	10/02/18 16:26	SCE 8006U ADJUSTED MARKING ESTIMATE		Load PDF
6	16/04/18 08:28	Workshop Invoice		Load PDF
7	16/04/18 08:28	Discharge Voucher		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/08/17 10:08	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
4	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	17/08/17 10:06	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	17/08/17 10:01	Sketch Plan		Load JPG <input checked="" type="checkbox"/>
2	17/08/17 10:01	Sketch Plan #2		Load JPG <input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17016120/ARBE2

Date: 16/04/2018

REFERENCE

Insured/Claimant:	KOH KIA JENG LEWIS	Policy No:	2100504081
Date of Loss:	17/08/2017	Nature of Claim:	OD
		Claim No:	1318117717SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCE8006U	Engine No:	CVN024832
Make & Model:	AUDI A4, 1.4 T (A)	Chassis No:	WAUZZZF4XHA071351
Reg. Date:	21/03/2017 (Man. Year: 2016)	Odometer:	5260 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,181.00	19,358.44	7,822.56	28.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,552.00	6,802.00	3,750.00	35.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	37,733.00	26,160.44	11,572.56	30.67
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	37,133.00	25,560.44	11,572.56	31.17
+ GST 7.00/7.00% (S\$)	2,599.31	1,789.23	810.08	31.17
Nett Amount (S\$)	39,732.31	27,349.67	12,382.64	31.17

INSPECTION

Date of Assignment:	21/08/2017		
Date Inspected:	21/08/2017	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,703.00 FS	*1,404.00 FS
2	1		*FRONT BUMPER GRILLE - LOWER CENTER	Not Necessary	163.00 FS	*- FS
3	1		*RADIATOR GRILLE	Smashed	1,473.00 FS	*1,446.40 FS
4	1		*FRONT REINFORCEMENT BEAM	Bent	674.00 FS	*539.20 FS
5	2		*FRONT BUMPER GUIDE - LH/RH	Not Necessary	62.00 FS	*- FS
6	1		*FRONT BUMPER FOAM	Deformed	101.00 FS	*80.80 FS
7	1		*FRONT BUMPER TOP COVER	Deformed	104.00 FS	*82.80 FS
8	1		*SIGN CAUTION STICKER	Necessary	12.00 FS	*9.04 FS
9	1		*STICKER FOR AIR CONDITIONER	Necessary	6.00 FS	*4.64 FS
10	1		*BONNET RELEASE LEVER	Damaged	12.00 FS	*9.04 FS
11	1		*BONNET BOWDEN CABLE	Damaged	49.00 FS	*38.64 FS
12	1		*FRONT LOCK CARRIER BRACKET	Cracked	112.00 FS	*89.20 FS
13	2		*FRONT BUMPER SUPPORT - LH/RH	Necessary	46.00 FS	*36.00 FS
14	2		*LED HEADLIGHT - LH/RH	Cracked	15,722.00 FS	*12,577.60 FS
15	2		*HEADLIGHT WASHER CYLINDER BRACKET	Not Necessary	10.00 FS	*- FS
16	2		*HEADLIGHT WASHER CYLINDER - LH/RH	Necessary	360.00 FS	*288.00 FS
17	1		*CORRUGATED PIPE	Not Necessary	75.00 FS	*- FS
18	1		*BONNET	Distorted	2,001.00 FS	*1,600.80 FS
19	1		*BONNET ATTACHMENT PARTS	Not Necessary	103.00 FS	*- FS
20	2		*BONNET HINGE - LH/RH	Not Necessary	514.00 FS	*- FS
21	2		*BONNET IMPACT PROTECTION - LH/RH	Necessary	46.00 FS	*36.32 FS
22	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	23.00 FS	*18.16 FS
23	2		*BONNET LOCK STRIKER - LH/RH	Bent	86.00 FS	*67.36 FS
24	2		*BONNET LOCK	Not Necessary	360.00 FS	*- FS
25	1		*FRONT LOCK CARRIER	Not Necessary	878.00 FS	*- FS
26	2		*LOCK CARRIER AIR GUIDE - LH/RH INNER	Not Necessary	44.00 FS	*- FS
27	2		*LOCK CARRIER AIR GUIDE - LH/RH UPPER	Damaged	20.00 FS	*14.72 FS
28	1		*A/C CONDENSER	Dented	525.00 FS	*419.60 FS
29	1		*CONDENSER HIGH PRESSURE VALVE	Not Necessary	45.00 FS	*- FS
30	1		*A/C CONDENSER PRESSURE SENSOR	Not Necessary	163.00 FS	*- FS
31	1		*RADIATOR	Dented	576.00 FS	*460.40 FS
32	1		*RADIATOR RUBBER BUSH	Not Necessary	38.00 FS	*- FS
33	1		*COOLANT	Necessary	132.00 FS	*105.28 FS
34	2		*FRONT DOOR WINDOW CHROME TRIM - LH/RH	Not Necessary	518.00 FS	*- FS
35	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
36	1		*SUNDRIES	Necessary	400.00 FS	*5.44 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 27,181.00 19,358.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,000.00	1,000.00
3	TO DISMANTLE FRONT BUMPER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,200.00	2,500.00
4	TO REMOVE BOTH FRONT DOOR PANEL TRIMS AND WING MIRROR ASSY. RENEW BOTH FRONT WINDOW CHROME MOLDING	New	600.00	0.00
5	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO RESPRAY BOTH FRONT DOOR	New	1,200.00	1,100.00
Gross Labour Cost (S\$)			10,552.00	6,802.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >