

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 166P -**AAD1708-207**

Not Authored
8 5865.83
Resumy B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 166P - ROEL

VF1ABL15AUC281596

RENAULT

LATITUDE

16.08.2017

AXA

PART**LIST**

1	1	BUMPER COVER REAR	\$	Bu	1,108.46	✓
2	1	BUMPER LOWER REAR	\$	Sn	768.84	X
3	1	BUMPER BRACKET CTR REAR	\$	Sn	113.47	X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	Sn	135.97	X
5	1	BUMEPR BRACKET CTR RH REAR	\$	Sn	44.99	X
6	1	BUMPER REFLECTOR RH	\$	Sn	43.61	X
7	1	BUMPER BEAM REAR	\$	R	777.52	X
8	1	BUMPER BEAM BRACKET RH REAR	\$	R	225.95	X
9	1	FENDER PANEL REAR RH	\$	Bt	3,299.13	✓
10	1	WHEELARCH REAR RH	\$	Sn	543.47	X
11	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	R	3,039.04	X
12	1	KUCKLE ARM REAR RH	\$	Sn	736.67	X
13	1	ABSORBER REAR	\$	Sn	389.75	X
14	1	LOWER ARM REAR RH	\$	Sn	905.99	X
15	1	TAILLAMP PANEL RH	\$	Sn	986.70	X
16	1	AIR VENT	\$	Sn	97.29	X
17	1	BOOT REAR	\$	R	2,872.68	X
18	1	BOOT FINISHER	\$	Sn	470.06	
19	1	BOOT WHEATERSTRIP	\$	Sn	323.05	
20	1	BOOT REFLECTOR LAMP RH	\$	Sn	493.35	
21	1	BOOT BADGE 'RENAULT'	\$	Sn	225.36	
22	1	BOOT BADGE	\$	Sn	225.36	
23	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
24	1	EXHAUST REAR	\$	R	7,488.00	X
25	1	EXHAUST CAP REAR	\$	R	230.49	
26	1	ROCKER PANEL OUTER RH	\$	R	987.49	
27	1	DOOR PANEL REAR RH	\$	R	2,844.66	

TOTAL	\$	31,567.22
10%	\$	3,156.72
	\$	28,410.50

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 166P -**AAD1708-207****Specical Nett**

1	1SET	PARKING AID	\$	Sh	600.00	X
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	✓
4	1SET	BUMEPB BRACKET SIDE CLIP RH RR	\$	nn	10.00	X
5	1SET	BUMEPB RETAINER RH CLIP RR	\$	nn	20.00	X
6	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	X
7	1SET	BUMPER BEAM BOLT	\$	Sh	33.00	X
8	1SET	WHEELARCH CLIP REAR RH	\$	nn	45.00	X
9	2	Rear Windscreen Sealant	\$	nn	80.00	605m
10	1	Rear Windscreen Inner Sponge Seal	\$	nn	150.00	305m
11	1	RIM (ROUE 7J 16H 2547)RH RR	\$	Sh	385.00	X
12	1	TYRE RH RR	\$	Sh	330.00	X
13	1	CAP HUB RH REAR	\$	Sh	35.60	X
14	1	DOOR STICKER "6555-3333"	\$	nn	80.00	605m
15	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	X
16	1	BOOT STICKER "6555-3333"	\$	nn	30.00	X
17	1	EXHAUST MOUNTING REAR	\$	Sh	65.50	X
18	1	EXHAUST BRACKET REAR	\$	X	22.22	X

TOTAL	\$	2,081.32
TOTAL PARTS	\$	30,491.82

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	700
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	660
To Rust-Proofing Of The Affected Areas.	\$	170.00	30
To reinstall rear bumper parking sensor.	\$	170.00	60
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
Towing Fees	\$	nn 120.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 166P -**AAD1708-207**

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	100%
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120%
To repair and realign rear exhaust pipe.	\$	170.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	X

TOTAL	\$	7,750.00
Over All Total	\$	38,241.82

Repair Days

5 days ~~10 Days~~
(PARTS BY PARTS)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: