

ASS. REC. BY:

REF: CS/MSG17016266/T1+b22

Special Instruction:

Surveyor:
MUMUEN

Taufik

ASSIGNMENT (Office)

From (Person):

Catherine Tria

of

MSLG

Date/Time:

22082017 301pm

Estimated Cost:

Bill to:

~~OD~~ / IT / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFU 4070P

Insured:

SLQ 7026Z

at Workshop m/s

Car life Auto

Tel:

6273 3810

of

Bik 1002 Bukit Meriah Lane 3 # 01-75

Policy No:

28993722 AWW

Claim No:

527129

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19082017

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

22082017 430pm

Person Contacted:

C-

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFU 4070P - NBA/AIG17016185/Y - 19082017

SLQ 7026Z - CC3/AIG17016178 /pb3 - 19082017

lump sum \$2200f (Red: 1620.88 :42%)

200

10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17016266/T1tb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-08-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 7026Z	Veh. Inspected	SFU 4070P
Policy No.	28993722AVW	Coverage (\$)	0.00
Claim No.	527129	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	22/08/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/08/2017	Inspection Date	22/08/2017
Survey held at	CAR LIFE AUTO ENGINEERING SERVICES BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Aug 2017		22 Aug 2017 15:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ALLOOR VERKEY PIUS, ID: S2689933H		
Main Claimant:	KOH LIAN YEW, ID: S0122472G		
Vehicle Reg. No.:	SFU4070P	Date of Loss:	19/08/2017 15:00 - :59
Claim Type:	TP / 527129	Policy/Cover Note No.:	28993722AVW (Comprehensive) Coverage: 19/07/2017 - 18/07/2018
Vehicle Reg. No. (Insured):	SLQ7026Z	Policy No. (Claimant):	
	Excess:		
Repairer:	Car Life Auto Engineering Services (TOWN) BLK 1002 #01-75 BUKIT MERAH LANE 3, 159719 Bukit Merah - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/08/2017]		
Driver/Custodian (Insured):	ALLOOR MATHEW PIUS (), NRIC: S9571870A, Tel: +6597978782		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: CarLife <autolife_sin@yahoo.com.sg>
Sent: Saturday, 13 January 2018 4:39 PM
To: Taufikh (LKKAUTO)
Cc: SUR
Subject: RECOMMENDATION OF REPAIR COST TO SFU 4070P.

Hi Mr. Taufikh

Vehicle SFU 40470P was surveyed by your good self on 27/08/17.

Kindly make your recommendation to us.

Thank you.

Regds.
Tan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/08/2017 12:05
Date Of Accident	19/08/2017 15:55
Exact Location Of Accident	ALONG CHOA CHU KANG AVENUE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFU4070P
Insured/Policyholder	
Name Of Registered Owner	KOH LIAN YEOW
NRIC No	S0122472G
Email Address	HUMPTN@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-90048201
Alternative Phone No	OTHERS-90048201

Vehicle Particulars

Manufacturer	HONDA
Model	CITY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	2100294798-04000
Cover Note Number	

Driver

Name of Driver	KOH LIAN YEOW
NRIC No	S0122472G
Date Of Birth	13/05/1954
Occupation	INDOOR
Date Of Driving Pass	30/04/1978
Driving Experience	39 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90048201
Fax Number	
Contact Number	OTHERS-90048201
Email Address	HUMPTN@SINGNET.COM.SG

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I/We do/and, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes");


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers, law firms/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms) which may be based outside of Singapore for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



CAR LIFE AUTO ENGINEERING SERVICES

Mailing address: 20, BINCHANG RISE SINGAPORE 579887

W/shop address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : autolife_sin@yahoo.com.sg

Tel: 6273 3810 Fax: 6278 7522

Date : 21-Aug-17

Address : KOH LIAN YEW
BLK 458 CHO A CHU KANG
AVENUE 4 # 11-193
SINGAPORE 680458

Reference : TP 1127/08/17
Vehicle No : SFU 4070P
Make/Model : HONDA CITY
Insurance Co. : AIG

RE : QUOTATION REPAIRS TO SFU 4070P FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>	<u>QTY</u>	<u>AMT \$</u>	
1) FRONT BUMPER	1	\$ 446.50	mis ✓
2) FRONT BUMPER RETAINER	1	\$ 16.20	rel ✓
3) FRONT BUMPER ENFORCEMENT	1	\$ 215.20	X NA ✓
4) HEADLAMP LH	1	\$ 448.90	cut ✓
5) HEADLAMP BRACKET LH	1	\$ 22.10	rel ✓
6) FENDER LH	1	\$ 343.80	bt ✓
7) FENDER COWLING LH	1	\$ 75.10	fn ✓
8) FRONT GRILLE BASE	1	\$ 103.50	oa ✓
9) FRONT GRILLE CHROME	1	\$ 78.30	mis ✓
10) BUMPER GRILLE LOWER	1	\$ 183.80	mis ✓
11) TOW HOOK COVER	1	\$ 28.50	mis ✓
12) "HONDA" LOGO	1	\$ 38.20	rel ✓
13) FENDER COWLING CLIPS	10	\$ 38.00	rel ✓
14) BUMPER CLIPS	10	\$ 38.00	rel ✓
LIST PRICE TOTAL		\$ 2,076.10	1860.90
LESS DISCOUNT 20%		\$ 415.22	
LIST PRICE TOTAL AFTER LESS		\$ 1,660.88	1488.72
NETT PRICE TOTAL		\$0.00	

TOTAL PARTS COST

\$1,660.88

LABOUR AND MISCELLANEOUS CHARGES

1)	TO PANEL REMOVE & REPALCE FRONT BUMPER, FENDER , HEADLAMP AND TO PANEL BEAT AND ALIGN CHASSIS PANEL.	\$ 1,000.00	600
		(5 DAYS)	
2)	TO PUTTY & SPRAY PAINT FRONT BUMPER, FENDER & OTHER AFFECTED AREA.	\$ 800.00	600
		(4 PANEL)	
3)	TO CHECK AND RECTIFY WIRING & FOCUS HEADLAMP.	\$ 80.00	30
4)	TUFF KOTE	\$ 280.00	30

1488.72
1260
2748.72
1/6 2200

4 days.

30/1/18

LABOUR TOTAL

\$ 2,160.00

TOTAL ESTIMATED REPAIR COST

\$ 3,820.88

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Aug 2017		22 Aug 2017 15:51 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		ALOR VERKEY PIUS, ID: S2689933H							
Main Claimant:		KOH LIAN YEW, ID: S0122472G							
Vehicle Reg. No.:		SFU4070P	Date of Loss:	19/08/2017 15:00 - :59					
Claim Type:		TP / 527129	Policy/Cover Note No.:	28993722AVW (Comprehensive) Coverage: 19/07/2017 - 18/07/2018					
Vehicle Reg. No. (Insured):		SLQ7026Z	Policy No. (Claimant):						
			Excess:						
Repairer:		Car Life Auto Engineering Services (TOWN) BLK 1002 #01-75 BUKIT MERAH LANE 3, 159719 Bukit Merah - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Imm.Advice due 23/08/2017]							
Driver/Custodian (Insured):		ALOR MATHEW PIUS (), NRIC: S9571870A, Tel: +6597978782							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFU4070P (527129)**
[SLQ7026Z]
TP
KOH LIAN YEOW
Aug 19 2017 3:00PM
[ALLOOR VERKEY PIUS]
Car Life Auto Engineering Services

Upload Documents Upload Photos Compose New Letter		View View in Browser v
Assessment Reports		1 per page v ☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)
1	22/08/17 15:17	Accident Statement From: SC - Reg. No: SLQ7026Z, Claimant: ALLOOR VERKEY PIUS
		☒ Load HTM
Photos/Images		3 per page v ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	01/02/18 17:16	General View
2	01/02/18 17:16	General View
3	01/02/18 17:16	General View
4	01/02/18 17:16	General View
5	01/02/18 17:16	General View
6	01/02/18 17:16	General View
7	01/02/18 17:16	General View
8	01/02/18 17:16	General View
9	01/02/18 17:16	General View
10	01/02/18 17:16	General View
11	01/02/18 17:16	General View
12	01/02/18 17:16	General View
13	01/02/18 17:16	General View
14	01/02/18 17:16	General View
15	01/02/18 17:16	General View
16	01/02/18 17:16	General View
17	01/02/18 17:16	General View
18	01/02/18 17:16	General View
19	01/02/18 17:16	General View
20	01/02/18 17:16	General View
21	01/02/18 17:16	General View
22	01/02/18 17:16	General View
23	01/02/18 17:16	General View
24	01/02/18 17:16	General View
25	01/02/18 17:16	General View
26	01/02/18 17:16	General View
27	01/02/18 17:16	General View
28	01/02/18 17:16	General View

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

^

v

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17016266/T1TBE2

Date: 07/02/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28993722AVW

Claimant Vehicle No : SFU4070P

Insured Vehicle No : SLQ7026Z

Date of Loss: 19/08/2017

Nature of Claim: TP

Claim No: 527129

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFU4070P

Make & Model: HONDA CITY, 1.5 (A)

Engine No: L15A23800499

Reg. Date: 29/04/2005 (Man. Year: 2005)

Chassis No: MRHGD86905P010036

Colour: Black

Odometer: 233778 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,660.88	1,488.72	172.16	10.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,260.00	900.00	41.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,820.88	2,748.72	1,072.16	28.06
Approved Total (Overridden) (S\$)		2,200.00		
Nett Amount (S\$)	3,820.88	2,200.00	1,620.88	42.42

INSPECTION

Date of Assignment: 22/08/2017

Date Inspected: 22/08/2017 Inspected At:

Car Life Auto Engineering Services
(TOWN)BLK 1002 #01-75 BUKIT MERAH LANE 3
Singapore 159719

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Feb 2018)
Parts: 143 HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SFU4070P)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Missing	446.50 FL	*446.50 FL
2	1		*FRONT BUMPER RETAINER	Necessary	16.20 FL	*16.20 FL
3	1		*FRONT BUMPER ENFORCEMENT	Not Necessary	215.20 FL	*- FL
4	1		*HEADLAMP LH	Cut	448.90 FL	*448.90 FL
5	1		*HEADLAMP BRACKET LH	Necessary	22.10 FL	*22.10 FL
6	1		*FENDER LH	Bent	343.80 FL	*343.80 FL
7	1		*FENDER COWLING LH	Torn	75.10 FL	*75.10 FL
8	1		*FRONT GRILLE BASE	Cracked	103.50 FL	*103.50 FL
9	1		*FRONT GRILLE CHROME	Missing	78.30 FL	*78.30 FL
10	1		*BUMPER GRILLE LOWER	Missing	183.80 FL	*183.80 FL
11	1		*TOW HOOK COVER	Missing	28.50 FL	*28.50 FL
12	1		*HONDA LOGO	Necessary	38.20 FL	*38.20 FL
13	10		*FENDER COWLING CLIPS	Necessary	38.00 FL	*38.00 FL
14	10		*BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,076.10	1,860.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	415.22	372.18
Total Parts (\$\$)	1,660.88	1,488.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL REMOVE & REPLACE FRONT BUMPER, FENDER, HEADLAMP AND TO PANEL BEAT AND ALIGN CHASSIS PANEL	New	1,000.00	600.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER, FENDER & OTHER AFFECTED AREA	New	800.00	600.00
3	TO CHECK AND RECTIFY WIRING & FOCUS HEADLAMP	New	80.00	30.00
4	TUFF KOTE	New	280.00	30.00
Gross Labour Cost (\$\$)			2,160.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >