

REF:

NS/INC17016280 / Sbn2

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 4396X

Yr Regn:

5/4/2012

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Chevrolet Epica

C.C.

1991

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

713703

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KLL1LA69KJB13 124798

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

18/8/2017

D.O.I.

21/8/2017

Survey held at

SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHC 4396X - C03 / ATG15002185 / Klpmsq2
SGJ 5185E - C03 / ICL17010224 / Klpmsq2

DIA: 10015

TAX / 08/17/2011

DIA: 24054

Lklc

NTHC

confirm LIS \$3250.00, 3 days
Ed: \$7294.14, 691.

RECEIVED 27 NOV 2011

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / T.B.I. (\$

TP

3250

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Add Fee:

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

Photos

Others

TOTAL

160
35

195



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17016280/Srb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 22-08-2017

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 5685E	Veh. Inspected	SHC 4396X
Policy No.	5080028785-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/08/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/08/2017	Inspection Date	21/08/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0957596-002	COMFORT TRANSPORTATION PTE LTD	SHA 4488A	SDD 6366L	27/10/2017	\$ 2,681.58	\$ 1,512.61
2	MT/0966458-002	CITYCAB PTE LTD	SHB 3139J	GBB 8774M	20/10/2017	\$ 4,402.60	\$ 4,217.88
3	MT/0967554-002	COMFORT TRANSPORTATION PTE LTD	SHD 3757P	SLL 3494H	28/10/2017	\$ 2,928.40	\$ 1,900.00
4	MT/0967992-001	COMFORT TRANSPORTATION PTE LTD	SHC 3037P	SGN 4639A	26/10/2017	\$ 5,103.62	\$ 2,200.00
5	MT/0967335-002	COMFORT TRANSPORTATION PTE LTD	SHC 8814E	YN 7793D	27/10/2017	\$ 2,352.25	\$ 1,620.18
6	MT/0957052-002	SMRT TAXIS PTE LTD	SHB 1207J	FBD 9610K	08/08/2017	\$ 3,055.01	\$ 2,050.00
7	MT/0958106-003	SMRT TAXIS PTE LTD	SHC 4396X	SGJ 5685E	18/08/2017	\$ 8,248.62	\$ 900.00
8	MT/0957429-002	SMRT TAXIS PTE LTD	SHD 6496Y	SGZ 9052X	13/08/2017	\$ 3,509.87	\$ 2,950.00
9	MT/0967615-002	COMFORT TRANSPORTATION PTE LTD	SHA 6214K	YM 8945G	30/10/2017	\$ 5,670.68	\$ 2,700.00
10	MT/0949758-002	SMRT TAXIS PTE LTD	SHB 276R	YK 1474E	16/06/2017	\$ 17,298.06	\$ 4,400.00
11	MT/0967997-001	CITYCAB PTE LTD	SHC 7994A	PC 5288Z	24/10/2017	\$ 5,483.96	\$ 1,900.00
12	MT/0966296-002	CITYCAB PTE LTD	SHA 8267U	GBA 2943L	19/10/2017	\$ 16,086.38	\$ 9,853.92
13	MT/0963861-002	COMFORT TRANSPORTATION PTE LTD	SHA 4777R	ST 9743A	30/09/2017	\$ 1,030.00	\$ 912.00
14	MT/0964790-002	COMFORT TRANSPORTATION PTE LTD	SHD 6644L	SGY 2639K	06/10/2017	\$ 4,780.83	\$ 3,062.68
15	MT/0965606-002	COMFORT TRANSPORTATION PTE LTD	SH 9784U	SLD 5023M	08/10/2017	\$ 26,139.16	\$ 12,700.00

Claim received from LKX Auto

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)
[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5080028785-01	LKDESTINATION	53310804K	GPC	Third Party, Fire & Theft	SGJ5685E	SGJ5685E	14/07/2017	13/07/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2017 10:46
Date Of Accident	18/08/2017 20:40
Exact Location Of Accident	JALAN BUKIT MERAH TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4396X
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

Driver

Name of Driver	GIAM HO KEAT DONALD
NRIC No	S1241848E
Date Of Birth	14/02/1957
Occupation	OUTDOOR
Date Of Driving Pass	20/01/1978
Driving Experience	39 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 5

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG JALAN BUKIT MERAH TOWARDS CTE WITH FOUR PASSENGERS ON BOARD. SUDDENLY A VEHICLE WHICH WAS IN FRONT OF MY TAXI CAME TO A HALT, I FOLLOWED SUIT AND MANAGED TO STOP IN TIME. AFTER WHICH I FELT AN IMPACT AT THE REAR OF MY TAXI, A VEHICLE SGJ5685E HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: FILE TO BIG
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGJ5685E
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver LIONEL KOH HUI MING
NRIC/Passport Number S8910243Z
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Describe Circumstances of the Accident

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Enquire Transfer Fee

Vehicle Details			
Vehicle No.	SHC4396X		
Vehicle Type	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1	Air-Con (Taxi)		
Vehicle Scheme	Taxi (Company)		
Vehicle Make	CHEVROLET		
Vehicle Model	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO		
Chassis No.	KL1LA69RJBB124798		
Propellant	Diesel		
Engine No.	Z20S1464587K		
Engine Capacity	1991 cc		
Maximum Power Output	110.0 kW (147 bhp)		
Maximum Laden Weight	2055 kg		
Unladen Weight	1625 kg		
Year Of Manufacture	2012		
Original Registration Date	05 Apr 2012		
Lifespan Expiry Date	04 Apr 2020		
COE Category	A - Car (1600cc & below)		
PQP Paid	\$42,384.00		
COE Expiry Date	04 Apr 2020		
Road Tax Expiry Date	04 Apr 2018		
PARF Eligibility Expiry Date	04 Apr 2020		
Inspection Due Date	04 Apr 2018		
Intended Transfer Date	01 Dec 2017		
CO2 Emission	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee (s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	11.00	-	11.00



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SH04396X
 Ref. No : TAX/08/17/2111
 Reg. Date : 05/04/2012
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : GIAM HO KEAT DONALD
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 18/08/2017 08:40:00 PM
 Accident Reported Date / Time : 19/08/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024091584
 Special Instruction to ARC, if any :

SGJ5685E / NTUC - IDAC 45
 AFTER PAINT PHOTO FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
 & Email : sebastianeang@lkkauto.com HP: 81823620
 LUMPSUM REPAIR

Prepared Date : 19/08/2017 10:50:50 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 21-8-17

2nd witness

Date

Vehicle to Wega Date In: 22/8 Towing: _____
 Time In: 11:50 Driver: TMT. SMUT
 Wega Job No: 13471/08
 Vehicle sent to SMRT Date In: 23-8-2017 Towing: _____
 Time In: 4:10 Driver: _____
 Inspected by: (Signature)

23/8/17 17:50 P955

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB124798

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	400.00
Total Spray Painting Charges	: 936.00	400.00
Total Material Charges	: 2,299.40 7893.14	3,007.50
Other Charges	: 870.00	-557.50
TOTAL	: 4,950.40 16544.14	3,250.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	3.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 20/08/2017 03:20:58 AM	21/08/2017 02:25:39 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/08/2017 03:20:58 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1708-0731 Invoice No :
Quotation Date : 28/8 Invoice Date :
Invoice Amount : Prepared Date :

3007.50 /
+ 400.00 /
+ 670.00 /

4077.50 /
- 202 /

3262.00 /
45 \$3250/- /

Sebastian
8/9/17

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	400.00 /
Total Labour	845.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY REAR BOOT LID	378.00	200.00 /
Total Spray Painting & Panel Beating	936.00	400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00 net	140.00 /
Lump Sum Adjustment by Surveyor	0.00	-827.50
Total Other Costs	870.00	-557.50

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No	Defect
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace	No	DT
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Check	No	X
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Check	No	X
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Check	No	X
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace	No	Scr
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace	No	Scr
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace	No	Cut
			EXHAUST PIPE MOUNTING, REAR	0	4.40	10.00	0.00	Replace	Not given	No	X
96418400			MUFFLER A-EXH,RR	1	2,909.00	100.00	0.00	Replace	Repair	No	R
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	mg
96647117	COMMO N		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Check	No	X
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Check	No	X
	COMMO N	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No	X
96636630	REAR	6504631	REAR BOOT LID	1	974.00	100.00	0.00	Replace	Repair	No	R
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No	
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No	
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No	
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No	
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No	
TOTAL MATERIALS							7893.14	3,592.81	3,007.50		
TOTAL MATERIALS(Discounted)								2,299.40	3,007.50		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

REQUEST FOR SUPPLYMENT PARTS

Contractor		WEGA ENGINEERING PTE LTD	
Accident Case Number	TAX/08/17/2111	Date of Collection	22 108 2017
Vehicle No	S4C 4396X	Date of Request	22 08 2017
Vehicle Model	Chevrolet Emars	Number of Days to Extend (if any)	

S/N	Part Number	Part Description	Quantity	Unit Price
		Beam RR Bumper Impact	1	\$1221.00
				Sebastian
				25/8/2017

*** Please submit photographs for damaged parts ***

I, (Name)

(Position)

Do solemnly and sincerely declare that: Supplementary Parts are raised for replacement for the aforesaid vehicle.

Signature of person making this declaration

[To be signed in front of an authorised witness]

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 - PO - WOC - Reservation - Number
Photo Submitted	YES / NO	Date of submission

SMRT Accident Vehicle Repair Estimates

NTUC

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4396X
 Ref. No : TAX/08/17/2111
 Reg. Date : 05/04/2012
 Vehicle Type : TAXI
 Make : CHEVROLET EPICA 2.0 VCDI
 Model : EPICA-2.0
 Name of Driver : GIAM HO KEAT DONALD
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 18/08/2017 08:40:00 PM
 Accident Reported Date / Time : 19/08/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024091584
 Special Instruction to ARC, if any :
 SGJ5685E
 Prepared Date : 19/08/2017 10:50:50 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian 24/8/2017.
 - Lump Sum Repair.
 - Question Mark Item Photo
 - Photo after repair.


 23/8/17.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KL1LA69RJBB124798

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	845.00	0.00
Total Spray Painting Charges	:	936.00	0.00
Total Material Charges	:	5,737.62	5,737.62
Other Charges	:	730.00	0.00
TOTAL	:	8,248.62	0.00
Lum Sum Total	:	8,250.00	0.00
No. of Repair Days	:	5.00	0.00
Prepared / Adjusted By	:		3 days
Arc / Surveyor Sing Off Date	:	20/08/2017 03:20:58 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/08/2017 03:20:58 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00 ?	0.00 300
TO RESPRAY REAR BOOT LID	378.00	0.00 200
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND REFIT WIRE HARDESS	150.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO PROVIDE LABOUR & MATERIAL TO REPLACE SHIELD REAR BUMPER (NET)	140.00	0.00 ✓
Total Other Costs	870.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
93745100	REAR	6504569	BUMPER RR	1	1,238.00	10.00	1,114.20	Replace	Replace	No <i>Defect</i>
96941154	REAR	6504571	BEAM RR BUMPER IMPACT	1	1,221.00	10.00	1,098.90	Replace	Replace	No <i>?</i>
96873838	REAR		ABSORBER ENGY RR BUMPER	1	70.00	10.00	63.00	Replace	Replace	No <i>?</i>
	REAR		BRACKET RR BUMPER SIDE LH	1	49.00	10.00	44.10	Replace	Replace	No <i>?</i>
96633534	REAR		BRACKET RR BUMPER SIDE RH	1	49.00	10.00	44.10	Replace	Replace	No <i>?</i>
96858575		6504584	REFLECTOR REFLEX RR LH	1	264.00	10.00	237.60	Replace	Replace	No <i>✓ sur</i>
96858576	REAR	6504586	REFLECTOR REFLEX RR RH	1	264.00	10.00	237.60	Replace	Replace	No <i>✓ SCR</i>
96873820	REAR		COVER TOWING EYE RR	1	21.00	10.00	18.90	Replace	Replace	No <i>✓ cut</i>
			EXHAUST PIPE MOUNTING, REAR	2	4.40	10.00	7.92	Replace	Replace	No <i>X A</i>
96418400			MUFFLER A-EXH,RR	1	2,909.00	10.00	2,618.10	Replace	Replace	No <i>R</i>
	REAR		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>✓ DMG</i>
96647117	COMMO N		W/HARNESS RR BPR	1	227.34	10.00	204.61	Replace	Replace	No <i>?</i>
96632015	REAR	6504636	PANEL END REAR	1	255.00	10.00	229.50	Replace	Replace	No <i>?</i>
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
96636630	REAR	6504631	REAR BOOT LID	1	974.00	10.00	876.60	Replace	Replace	No <i>R</i>
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>NRG</i>
96634035	REAR	6504564	LETTERING:"CHEVR OLET"	1	29.00	10.00	26.10	Replace	Replace	No
96634897	REAR	6504565	LETTERING:"EPICA LT"	1	28.00	10.00	25.20	Replace	Replace	No
96634023	REAR	6504567	EMBLEM REAR	1	44.00	10.00	39.60	Replace	Replace	No
TOTAL MATERIALS							7,132.43	7,132.43		
TOTAL MATERIALS(Discounted)							5,737.62	5,737.62		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17016280/Srbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 04-12-2017
189556

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 5685E	Veh. Inspected	SHC 4396X
Policy No.	5080028785-01	Coverage (\$)	0.00
Claim No.	MT/0958106-003	Excess (\$)	0.00
Assign From		Assign Date	21/08/2017

2. Vehicle Particulars & Condition

Make & Model	CHEVROLET EPICA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	KL1LA69RJBB124798	Colour	MAROON
Odometer	713703	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R15	FALKEN	6 mm
L/H Front Tyre	205/65 R15	FALKEN	6 mm
R/H Rear Tyre	205/65 R15	FALKEN	6 mm
L/H Rear Tyre	205/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/08/2017	Inspection Date	21/08/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4396X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BUMPER RR (DISC 10%)	DEFORMED	1,238.00	1,114.20
1	BEAM RR BUMPER IMPACT (DISC 10%)	DENTED	1,221.00	1,098.90
1	REFLECTOR REFLEX RR LH (DISC 10%)	SCRATCHED	264.00	237.60
1	REFLECTOR REFLEX RR RH (DISC 10%)	SCRATCHED	264.00	237.60
1	COVER TOWING EYE RR (DISC 10%)	CUT	21.00	18.90
1	LETTERING "CHEVROLET" (DISC 10%)	NECESSARY	29.00	26.10
1	LETTERING "EPICA LT" (DISC 10%)	NECESSARY	28.00	25.20
1	EMBLEM REAR (DISC 10%)	NECESSARY	44.00	39.60
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	SHIELD REAR BUMPER (SN)	NECESSARY	140.00	140.00
1	ABSORBER ENGY RR BUMPER	NOT NECESSARY	70.00	-
1	BRACKET RR BUMPER SIDE LH	NOT NECESSARY	49.00	-
1	BRACKET RR BUMPER SIDE RH	NOT NECESSARY	49.00	-
1	EXHAUST PIPE MOUNTING,REAR	NOT NECESSARY	4.40	-
1	W/HARNESS RR BPR	NOT NECESSARY	227.34	-
1	PANEL END REAR	NOT NECESSARY	255.00	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	MUFFLER A-EXH,RR	TO REPAIR	2,909.00	-
1	REAR BOOT LID	TO REPAIR	974.00	-
			8,033.14	3,147.50
<u>LABOUR</u>				
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,315.00	480.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,036.00	430.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,511.00	930.00
GRAND TOTAL			10,544.14	4,077.50

Report Ref No. NS/INC17016280/Srbn2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,250.00
--	--	--	----------

Report Ref No. NS/INC17016280/Srbn2

YEANG WAI KEEN
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.