Surveyor -	68			(Office)				0004
From (Person):	Yee Peili	of	, L	11	Ds	te/Time:	13087014	462W
Estimated Cost:			Bi	ll to:				
	t TP RES / OD RE	ES / EVA / INV / N	IV/CS		Insured:	×0	6994L	
	v/s	Kah motur			Tel:	H846 51	3 5	
of		15 Wbi Ro	ud U		201			
Policy No:				Claim No: _	XPF991	11/SE/p	\	
Sum Insured:		v		Excess: _		1		
Make of Veh:			Marco Bio		D	.O.A	210820	1
	REP. / REV 24	1	acted:	Any -	Ve	H.O.D. Endo		
	Action/Instructio	n (/) 5	timate.					
Date/Time		55 T -	X					
Date/Time	SKX 36	- V						
Date/Time	The second second second second second	194L -	X					
Date/Time	The second second second second second		X					
Date/Time	The second second second second second		X		41			

RECEIVED 0 8 J	AN 2010			
te/Time: File Pass to? : Preli. Report	Day	s Of Repair: 7		
: Final Report		survey No. of Trip:	Survey Fee:	
te/Time, File Return to?	-	1200	Transportation:	
	Add Fee:	: Site Insp (\$	S + RSSI	
		: Interview (\$) Photos	
port Format : (p		: Tech. Invs (\$) Others	
ump Sum / 1(B)1: (\$ 5743-43) [: Weekend (\$)	
	_		TOTAL	250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

200		VENERAL STREET, SERVED AND	nternationale Des Experts En Auton	
ERG	O INSURANCE P	TE LTD	Ref : CS/EGI170162	98/Ggb
#04-	MASEK BOULEVA 01 SUNTEC TOWI GAPORE 038985		Date: 23-08-2017	
4		Policy Parti	Code : EGI culars :- THIRD PARTY CLA	IM
1.	Insured Veh.	XD 6994L	Veh. Inspected	SKX 3655J
	Policy No.	AD 0334L	Coverage (\$)	0.00
	Claim No.	XD6994L/SE/pl	Excess (\$)	0.00
_	Assign From	YEE PEI LI	Assign Date	23/08/2017
2	Assignition		e Particulars & Condition	
2.	Make & Model	venici	c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	7,1000	Colour	
	Odometer	2	Steering	
	Brakes		Modification	
	General			
3.			Conditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		De	escription of Damages	
5.			General Information	
Э.	Accident Date	21/08/2017	Inspection Date	23/08/2017
	Survey held at	KAH MOTOR CO SDN		्न्या कराक्य (श
	Survey neiu at	15 UBI ROAD 4 SINGAPORE 408610		
5a.	GANGE S		Remarks	

Ai Phing (LKKAuto)

From:

Ai Phing (LKKAuto)

Sent:

Friday, 25 August, 2017 2:42 PM

To:

'Survey Report (ERGO Insurance Pte. Ltd.)'

Cc:

SUR

Subject:

RE: XD6994L / TP: SKX3655J/LKK / DOA: 21.08.2017

Attachments:

SKX 3655J.pdf

Dear Pei Li,

Enclosed herewith preliminary advise of SKX 3655J.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Wednesday, 23 August, 2017 10:30 AM

To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: RE: XD6994L / TP: SKX3655J/LKK / DOA: 21.08.2017

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]

Sent: Wednesday, 23 August, 2017 9:52 AM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Subject: OI: XD6994L / TP: SKX3655J/LKK / DOA: 21.08.2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company LKK AUTO CONSULTANTS PTE LTD to be the "Single Joint Expert".

Please conduct this survey request from KAH MOTOR CO. SDN. BHD (vehicle in today 4pm to 4.30pm).

catherine

From:

Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>

Sent:

Wednesday, 23 August, 2017 9:52 AM

To:

'admin-d@lkkauto.com'

Subject:

OI: XD6994L / TP: SKX3655J/LKK / DOA: 21.08.2017

Attachments:

SKX3655J - ESTIMATE n SAS.pdf; SKX3655J - PRS FORM.pdf; RE: TPDS:

SKX3655J(LIBERTY) & XD6994L(ERGO), DOA: 21/08/2017@08:15AM (20.9 KB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from KAH MOTOR CO. SDN. BHD (vehicle in today 4pm to 4.30pm).

ADDRESS

: 15 UBI ROAD 4

SINGAPORE 408610

PERSON TO CONTACT

: ARY CHUA @ 6846 5673

ERGO OFFICER-IN-CHARGE

: STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident and advise the consistency of damages to third party vehicle that you are require to conduct a resurvey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are insured and TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Best Regards
Yee Pei Li
Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower FiveSingapore 038985
DID: 65 6829 9194
Fax: 65 6829 9247
Website: www.ergo.com.sg



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: XD6994L/SE/pl

Date: 25-08-2017

Our Ref: CS/EGI17016298/Ggb

The Motor Claims Department Ergo Insurance Pte Ltd Without Prejudice

Dear Sirs/Mdm

PDFI	IMINARY	ADVICE OF VEHICLE NO	. SKX 3655J
PKEL	INITIARI	ADVICE OF VEHICLE NO	. DIETE DODGO


We thank you for the instruction on 23-08-2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 23-08-2017 at the premises of M/s KAH MOTOR and have the following to report:

Workshop Estimate Amount	: S\$	6,241.78
Revised Estimate Amount	: <u>S\$</u>	5,653.43
"Check" Items Amount	: <u>S\$</u>	-
Market Value	: <u>S\$</u>	-
LTA Reimbursement Value	: <u>S\$</u>	
Nett Value	: <u>S\$</u>	

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/ Present Status:

Damages Consistent. 07 days of repair.

Yours faithfully

Xing Guo Qiang Automotive Assessor

Text size +

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

1714B

Vehicle Details

Vehicle No.:

SKX3655J

Vehicle to be Exported: No

Intended De-registration

25 Aug 2017

Date:

HONDA

Vehicle Make:

Vehicle Model:

MOBILIO SV 1.5 CVT

Primary Colour:

White

Manufacturing Year:

2015

Engine No.:

L15Z12101417

Chassis No.:

MRHDD4870FP000360

Maximum Power

88.0 kW (118 bhp)

Output: Open Market Value:

\$19,572.00

Original Registration

08 Dec 2015

Date:

First Registration Date: 08 Dec 2015

Transfer Count:

0

Actual ARF Paid:

\$19,572.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry

07 Dec 2025

PARF Rebate Amount: \$14,679.00

Intended COE Rebate Details

COE Expiry Date:

07 Dec 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$56,001.00

COE Rebate Amount:

\$46,383.00

Total Rebate Amount: \$61,062.00

The information contained herein is correct as at 25 Aug 2017

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions. Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service | Last updated on 20 Aug 2017 at 12:36 AM

Date:	22.08.20	017		Sent via Fax		993
ur Reference:	XD 6994	L/SE/pl		22		
	SKX 365			or		
our Reference:	3107 303			Email		
KAH MOTOR CO. SDN BH						arychua@honda.com.sg
Pre-Repair Su	ırvev (PRS) Acknowledgement				
ehicle For Insp		SKX 3655J				
nsured's Vehicle: XD 6994L						
thate Of Accident: 21.08.2017						
		f your request for PRS on:	21.08.2017	7		
		Courts Practice Directions A	mandment No.1	— of 2016" dos	alact an a	essessor from
ne list below a	ind indicate	your selection in the box m	narked *.		*	
AIS	Automobi	le Inspection Services Pte Ltd	LBS	L.B.S Auto Co	nsultants	Pte Ltd
FTA	FormTean	n Consultancy Pte Ltd	LKK	LKK Auto Cor	sultants F	te Ltd
IAS	Infiniti Ap	praisal Service	PS	Priority Servi	ces	
JPK	JP Knights	Pte Ltd	VAC	Vicom Ltd		
		ection does not have your clien				рру.
		r interest for direct settlement				estimate.
				estate w	555	
		as not reported the accident to			aleta tera	1000000
V Others:	we are	therefore not in a posit	ion to discuss c	ni nability at	tilis juli	icture.
Prepared by:	λ	n /)	Pei Li	6829	9194	claims@ergo.com.sg
iignature:	*	to.				FAX: 6829 9247
Assessor use on	ly:		Workshop use		220	
Accionant Dat			Assessor atten Date:	ded workshop o	on:	
Assignment Dat Assignment Tim	36.5		Time	-		
			Inspector:			
Remarks:			Vehicle not av	ailable at the ap	pointed d	late and time.
			Kindly acknow	ledge our Asses	sor prese	nce for the above job .
			,		,	
					0.51	
				knowledgement pection is on a w		mission to liability basis.





www.libertyinsurance.com.sg

Name of Policyholder:

TEO GHEE CHONG JIM

Date of Issue:

31 Oct 2016

Registration No.:

SKX3655J

Effective Date of Commencement:

08 Dec 2016 00:00

Chassis No.:

MRHDD4870FP000360

Certificate No.:

SI16V18906/ VPC / R01

Date of Expiry:

07 Dec 2017 23:59

Type of Certificate:

MX1

Persons or Classes of Persons entitled to drive*:

A) The Policyholder.

B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

Limitations as to use:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- A) Use for hire or reward.
- B) Use for racing, pace-making, reliability trials or speed-testing.
- C) Use for the carriage of goods (other than samples) in connection with any trade or business.
- D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of LIBERTY INSURANCE PTE LTD

Approved Insurers

For Information Only:

Coverage(s):

Comprehensive, Unlimited Windscreen, NCD Protection

Sum Insured:

MARKET VALUE AT THE TIME OF LOSS

Excess

Section I S\$600,Additional Excess for Young, Elderly & Inexperienced Drivers S\$3000,Windscreen

Excess S\$100

Name of Finance Company:

OVERSEA-CHINESE BANKING CORPORATION LTD

Name of Producer:

KAH MOTOR COMPANY SDN BERHAD (A1572-7)



TEO GHEE CHONG JIM



CHINESE

09-04-1970 M

SINGAPORE



DRIVING LICENC Licence Number S7011714B

TEO GHEE CHONG JIM

Birth Date: 09 Apr 1970 Issue Date 03 Jan 2003



40255





05-04-2007

APT BLK 291D COMPASSVALE STREET #12-270 SINGAPORE 544291

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

26 Jan 199€

Licence No: \$70117148

NP 428A



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838 : SQT17003469 Page 1 : ERGO INSURANCE PTE LTD Document No. Customer : 21. Aug 2017 Date 5 TEMASEK BOULEVARD #04-01 OSUNTEC TOWER FIVE : WZN004 Customer No. : ARY CHUA WAI NGEE Svc Advisor SINGAPORE 038985 : L15Z12101417 **Engine No** : SKX3655J Registration No Date | Time : 21. Aug 2017 4:50:19 PM : MRHDD4870FP000360 Chassis No Surveyor Name Model : MOBILIO YM 2015 Survey Date : TEO GHEE CHONG JIM Owner's Name **Authorisation Date** Ins Policy No. **Date of Accident** : 21/8/2017 GST Amount Amt incld GST Qty Unit Price Disc % Amount Description Item) TP DIRECT SETTLEMENT (J/NO: OWNER: TEO GHEE CHONG JIM OWNER INSURER: LIBERTY INSURANCE SURVEYED BY: Office Orang 8280282 DATE: Working days: 08-12 REF NO: TP INSURER: ERGO INSURANCE TP VEH: XD6994L GIST 517.50 36.23 553.73 690.00 25 04636-TE7-K10ZZ PANEL SETR.RR.OUTSIDE 516.30 36.14 552 44 688.40 25 PANEL COMPR.RR.DOOR 67510-TE7-K00ZZ 30.50 25 22.87 1.60 24.47 TAPE SETR.RR.DOOR SASH 67824-TRD-T01 14.25 1.00 15.25 2 9.50 25 RUBBERRR QTR W/SHIELD / 73525-SYY-000 2.70 0.19 2.89 3.60 25 RUBBER AWINDSHIELD DAMPER -73525-TE7-K00 6.52 0.46 6.98 8.70 25 RUBBER BWINDSHIELD DAMPER 73529-TE7-K00 1.30 25 0.97 0.07 1.04 CLIP AQUARTER WINDSHIELD 91501-TE7-K00 1.12 1.20 25 0.08 CLIP BQUARTER WINDSHIELD 1.50 91502-TE7-K00 1.20 / 0.08 1.28 25 CLIP CR. QUARTER WINDSHIELD 1 1.60 91503-TE7-K00 64.20 60.00 4.20 60.00 BO-WS-SEALANT WINDSCREEN SEALANT (N) Sum Item 1143.43 80.05 1,223.48 100.00 - 10 100.00 7.00 107.00 BODY JOINT SEALANT. n €€ BOJSE 1030 30.00 2.10 32.10 30.00 SUNDRIES BOSUN 17.50 267.50 250.00 250.00 / / REMOVE & INSTALL RR. R QTR GLASS.(N) BG52D REMOVE & TRANSFER ITEMS TO NEW RR R DR. 24.50 374.50 350.00 350.00 BKDR22R ADJUST REMOVE & INSTALL SPEAKER BOARD RR SEATS 360.00 25.20 385.20 360.00 BMI02D TRUNK 2400.00 168.00 2568.00 CUT OFF & RENEW RR R FENDER. BKFE22R SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1200.00 1200.00 84.00 1284.00 BP02R (450)

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G



GST Reg No.: M200050223

QUOTATION

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD. (A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer

: ERGO INSURANCE PTE LTD

5 TEMASEK BOULEVARD

#04-01 OSUNTEC TOWER FIVE

SINGAPORE

038985

Registration No

: SKX3655J

Chassis No

: MRHDD4870FP000360

Model Owner's Name

: MOBILIO YM 2015 : TEO GHEE CHONG JIM

Ins Policy No.

Date of Accident

: 21/8/2017

Description

Document No.

Date

: SQT17003469

: 21. Aug 2017 4:50:19 PM

: 21. Aug 2017

Customer No.

: WZN004

Svc Advisor

: ARY CHUA WAI NGEE

Engine No

: L15Z12101417

Date | Time

Surveyor Name

Survey Date

Authorisation Date

GST Amount Amt incld GST

5,018.30

2

Page

Survey By

Item

Date & Time

Excess Status

Signature

Total Amount

Sum Labor

5.833.43

Amount

4690.00

408.35

328.30

6.241.78

Total (Inclusive of GST)

Unit Price Disc %

6,241.78

before paint photos. Mind. Thomas. Mind. Com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

Customer: Chassis No: WZN004 / ERGO INSURANCE

MRHDD4870FP000360

License No:

SKX3655J

Mileage: Engine No: 46403

L15Z12101417

Document No:

SVO17060617

Printed By:

ARYCHUA

Order Date:

19. September 2017

Order Time:

2:27:12 PM

Service Advisor:

ARY CHUA WAI NGEE

TEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt Am	ount incld GST
	TP DIRECT SETTLEMENT (J/NO: 69180) OWNER: TEO GHEE CHONG JIM OWNER INSURER: LIBERTY INSURANCE ACC DATE: 21/08/17 SURVEYED BY: QUO QIANG(LKKAUTO) WORKING DAYS: 7 REF NO:						
	TP INSURER: ERGO INSURANCE						
	TP VEH: XD6994L			0.5	517.50	36.23	553.73
4636-TE7-K10ZZ	PANEL SETR.RR.OUTSIDE	1	690.00	25			552.44
7510-TE7-K00ZZ	PANEL COMPR.RR.DOOR	1	688.40	25	516.30	36.14	24.47
7824-TRD-T01	TAPE SETR.RR.DOOR SASH	1	30.50	25	22.87	1.60	
3525-SYY-000	RUBBERRR QTR W/SHIELD	2	9.50	25	14.25	1.00	15.25
3525-TE7-K00	RUBBER AWINDSHIELD DAMPER	1	3.60	25	2.70	0.19	
3529-TE7-K00	RUBBER BWINDSHIELD DAMPER	- 1	8.70	25	6.52	0.46	6.90
1501-TE7-K00	CLIP AQUARTER WINDSHIELD	1	1.30	25	0.97	0.07	1.04
1502-TE7-K00	CLIP BQUARTER WINDSHIELD	1	1.50	25	1.12	0.08	1.2
1503-TE7-K00	CLIP CR.QUARTER WINDSHIELD	- 4	1.60	25	1.20	0.08	1.2
O-WS-SEALANT	WINDSCREEN SEALANT (N)	81	60.00		60.00	4.20	64.2
			SUM PARTS:		1,143.43	80.05	1,223.4
OJSE	0672 BODY JOINT SEALANT.	1	10.00		10.00	0.70	10.7
BOSUN	0672	- 81	30.00		30.00	2.10	32.1
	SUNDRIES					S (F-2024)0	1120613
3G52D	EXT-YJ REMOVE & INSTALL RR. R QTR GLASS. (N)	1	250.00		250.00	17.50	267.5
BKDR22R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST & ALIGN RR R DR.(N)	1	350,00		350.00	24.50	374.5
BMI02D	EXT-YJ REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK LININGS GARNISHES & ETC.(N)	1	360.00		360.00	25.20	385.2
BP02R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P)	1	1,200.00		1,200.00	84.00	1,284.0
3KFE22R	EXT-YJ	1	2,400.00	ů.	2,400.00	168.00	2,568.0
	CUT OFF & RENEW RR R FENDER.		SUM	LABOUR:	4,600.00	322.00	4,922.0
			TO	TAL SGD	5,743.43	402.05	6,145.4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Intern	ationale Des Experts En Autom	obile
ERGO INSURANCE F	TE LTD	Ref : CS/EGI1701629	98/Ggbn2
5 TEMASEK BOULEV #04-01 SUNTEC TOV SINGAPORE 038985		Date: 08-01-2018	
1.	Policy Particula	ars :- THIRD PARTY CLAI	M
Insured Veh.	XD 6994L	Veh. Inspected	SKX 3655J
Policy No.		Coverage (\$)	0.00
Claim No.	XD6994L/SE/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	23/08/2017
2.	Vehicle Pa	articulars & Condition	
Make & Model	HONDA MOBILIO	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MRHDD4870FP000360	Colour	WHITE
Odometer	45074	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Con	ditions of Tyres	
	Size	Make	Balance
R/H Front Tyre	185/65 R15	DUNLOP	6 mm
L/H Front Tyre	185/65 R15	DUNLOP	6 mm
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm
4.		iption of Damages	
THE VEHICLE S	USTAINED DAMAGES AT THE	O/S BODY.	
DAMAGES SEE	DETAILS.		
5.	Ger	neral Information	
Accident Date	21/08/2017	Inspection Date	23/08/2017
Survey held a	KAH MOTOR CO SDN BER	RHAD	
	15 UBI ROAD 4 SINGAPORE 408610		
5a.	DESIGNATION OF THE PARTY.	Remarks	
A)THE INSPECT B)IN ACCORDA	TION WAS CONDUCTED ON A NCE TO YOUR INSTRUCTION	"WITHOUT PREJUDICE" BA IS, WE HAVE NOT AUTHORI	SIS. SED REPAIRS.
5b.	Estin	nate Days of Repair	
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	7 Working Da	ys



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 3655J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL SETR.TT OUTSIDE (SN)	BUCKLED	517.50	517.50
1	PANEL COMPRIRR DOOR (SN)	BUCKLED	516.30	516.30
1	TAPE SETR.RR DOOR SASH (SN)	NECESSARY	22.87	22.87
	RUBBERRR QTR W/SHIELD (SN)	NECESSARY	14.25	14.25
	RUBBER AWINDSHIELD DAMPER (SN)	NECESSARY	2.70	2.70
	RUBBER BWINDSHIELD DAMPER (SN)	NECESSARY	6.52	6.52
	CLIP AQUARTER WINDSHIELD (SN)	NECESSARY	0.97	0.97
	CLIP BQUARTER WINDSHIELD (SN)	NECESSARY	1.12	1.12
1	CLIP CR.QUARTER WINDSHIELD (SN)	NECESSARY	1.20	1.20
	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	SEALANT (SN)	NECESSARY	100.00	10.00
	SUNDRIES (SN)	NECESSARY	30.00	30.00
	A 10		1,273.43	1,183.43
	LABOUR			
	REMOVE & INSTALL RR R QTR GLASS.		250.00	250.00
	REMOVE & TRANSFER ITEMS TO NEW RR R DR ADHUST.		350.00	350.00
	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK.		360.00	360.00
	CUT OFF & RENEW RR R FENDER.	1	2,400.00	2,400.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (2P).		1,200.00	1,200.00
	8 27		4,560.00	4,560.00
	GRAND TOTAL		5,833.43	5,743.43

5,743.43

Report Ref No. CS/EGI17016298/Ggbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.