

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Our Ref:

Date : 9/9/2017

ATTN:THE MOTOR CLAIMS DEPT
FIRST CAPITAL INSURANCE LTD

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No.	SGK1892U	Model / Year	TOYOTA ALTIS
Date of Accident	17-Aug-17	Policy No.	
Type of Claim	TP FIRST CAP	Prepared By	SHARON
Survey By	TAUFIKH LKK	Chassis No.	

S/NO	Description	Qty	Unit Price	Amount
1	ENGINE MOUNTING FRT	1	\$ 190.30	\$ 190.30 <i>bt</i>
2	ENGINE MOUNTING REAR	1	\$ 286.30	\$ 286.30 <i>bt</i>
3	ENGINE MOUNTING LH	1	\$ 287.40	\$ 287.40 <i>bt</i>
4	ENGINE MOUNTING RH	1	\$ 281.20	\$ 281.20 <i>bt</i>
5	AIRCON LOW PRESSURE HOSE	1	\$ 213.00	\$ 213.00 <i>bt</i>
				\$ 1,258.20
				LESS 25% \$ 314.55
				<u>\$ 943.65</u>

This is a computer printout no signature is required.