

ISS. REC. BY: Adrian King

REF:

CC3 / ALG17016320 / Arbnz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1700015949

Claims No. 8610733271SG

Sum Insured: _____ Excess: 60

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 1SSK

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04/8/17 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SFC6006H Yr Regn: 2017 / June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 c.c. 1395

Colour Grey A/C: Insured / Std / NI / NA

Sp. Reading 2284 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU22G43HA165300

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 225 / 45R18

R: 225 / 45R18

BS / DUN / EXNOVA GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 23/08/17

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	DD A16.
	SFC 6006H - X
22/8/17	Sent preli through menimen, seek mandate
28/8/17	Inform authorise repair & excess
	Confirm \$4,985.84, 4 days
	Red. \$8637.16, 63%.

RECEIVED 13 SEP 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) typist

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, \$ _____

Photos

Others

TOTAL

Report Format: 60

Lump Sum / I.B.I. (\$) 4985.84

200
10
210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17016320/Arb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 23-08-2017	
		Code : AIG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SFC 6006H
Policy No.	1700015949	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/08/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/08/2017	Inspection Date	23/08/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loh, Chee-Heng

Date: 23 Aug 2017

Preliminary Advice

Vehicle No	: SFC6006H	Accident Date	: 17/08/2017
Make	: AUDI A4	Policy No.	: 1700015949
Assignment Date	: 23/08/2017	Excess	: S\$0.00
Date of Inspection	: 23/08/2017	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,623.00
Revised Amount	:S\$	6,293.00
Check Items (Estimated)	:S\$	2,255.00
Total	:S\$	8,548.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	155,000.00
COE / PARF Rebate	:S\$	69,275.00
Salvage Value	:S\$	
Margin for Repair	:S\$	85,725.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

***SFC6006H (8610733271SG)**

OD

Aug 17 2017 5:35PM

[JOSEPH LOK LEONG MOON]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 24/08/2017 14:20 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8548.00) - SFC6006H - Claim Handler: Loo, Tong Shing

Approved:8548.00:Labour 2 - To transfer rear boot lit lock system not payable since Bootlid not affected. Kindly inform and remove labour before re-seek mandate. Re-inspection to be done for damage check and supplementary items / labour.

Noted.

Print Received Message

This mail is associated with :

***SFC6006H (8610733271SG)**

OD

Aug 17 2017 5:35PM

[JOSEPH LOK LEONG MOON]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 24/08/2017 08:55 AM.
To LKK_HQ
Subject SFC6006H / OD / 17/08/2017 / Coverage & Excess update

Dear LKK Auto Consultants Pte Ltd

Please note that policy is in force and excess amount is \$0.00

Thank you
Loo, Tong Shing

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loo, Tong Shing

Date: 28 Aug 2017

Preliminary Advice

Vehicle No	: SFC6006H	Accident Date	: 17/08/2017
Make	: AUDI A4	Policy No.	: 1700015949
Assignment Date	: 23/08/2017	Excess	: S\$0.00
Date of Inspection	: 23/08/2017	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (HQ) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,623.00
Revised Amount	:S\$	6,013.00
Check Items (Estimated)	:S\$	2,255.00
Total	:S\$	8,268.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	155,000.00
COE / PARF Rebate	:S\$	69,275.00
Salvage Value	:S\$	
Margin for Repair	:S\$	85,725.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

***SFC6006H (8610733271SG)**

OD

Aug 17 2017 5:35PM

[JOSEPH LOK LEONG MOON]

Premium Automobiles Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG)**, sent on 28/08/2017 15:46 PM.
To LKK_HQ
Subject **Alert - Adj Mandate Approved (S\$8268.00) - SFC6006H - Claim Handler: Loo, Tong Shing**

Approved:8268.00:Re-inspection to be done for damage check and supplementary items / labour.

Janice Lee (LKKAUTO)

To: Claims Department
Cc: SUR
Subject: RE: SFC 6006 H Own Damage Claim (Vehicle IN)

Dear Sir,

As instructed by our client , please proceed to repair the insured vehicle **SFC 6006H (excess \$0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Department [mailto:claims@premiumauto.com.sg]

Sent: Friday, August 25, 2017 8:36 PM

To: 'Claims Department' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SFC 6006 H Own Damage Claim (Vehicle IN)

Importance: High

Dear all,

Any update on the approval please ?

Best Regards,
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1741G

Vehicle Details

Vehicle No.: SFC6006H
Vehicle to be Exported: No
Intended De-registration Date: 23 Aug 2017
Vehicle Make: AUDI
Vehicle Model: A4 1.4 TFSI S TRONIC
Primary Colour: Grey
Manufacturing Year: 2017
Engine No.: CVN039058
Chassis No.: WAUZZZF43HA165300
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$32,094.00
Original Registration Date: 09 Jun 2017
First Registration Date: 09 Jun 2017
Transfer Count: 0
Actual ARF Paid: \$26,932.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 08 Jun 2027
PARF Rebate Amount: \$20,199.00

Intended COE Rebate Details

COE Expiry Date: 08 Jun 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,110.00
COE Rebate Amount: \$49,076.00
Total Rebate Amount: \$69,275.00

The information contained herein is correct as at 23 Aug 2017

OK

Land Transport  Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 20 Aug 2017 at 12:35 AM

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1621741G



Name

JOSEPH LOK LEONG MOON



Race

CHINESE

Date of Birth

22-05-1963

Sex

M

S1621741G

Country of Birth

SINGAPORE

3257129



NRIC No. S1621741G



Blood Group: O+ Date of issue: 01-03-2001

83 JALAN MAS PUTEH
SINGAPORE 128659

NRIC No. S1621741G

Date: 29/08/2010

No: 6562565

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

25 Feb 1981

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Licence No: S1621741G



NP 428A

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S1621741G

Name

JOSEPH LOK LEONG MOON



Birth Date: 22 May 1963

Valid Date: 06 May 2003

000456127A



CERTIFICATE OF INSURANCE

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : JOSEPH LOK LEONG MOON
Period of Insurance : 09 Jun 2017 To 08 Jun 2018
Engine No. : CVN039058
Chassis No. : WAUZZZF43HA165300

Vehicle No. : SFC6006H
Policy No. : 1700015949
Endorsement No. :
Issued Date : 20 Jun 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2017
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use (15 days)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

JOSEPH LOK LEONG MOON - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323
For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6335 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia).

0504125208

PREMIUM LEASING - SLOH
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

AIG Asia Pacific Insurance Pte. Ltd.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0829/2017/CCS
Date : 21-Aug-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Joseph Lok Leong Moon
Address : 83 Jalan Mas Puteh

Singapore 128659

Telephone : HP +65 96843818
Type of Claim : Own Damage Claims
Policy No. : 1700015949
Vehicle No : **SFC 6006 H**
Model Code : Audi A4 SEDAN 1.4 TFSI
Model / Year : Jun-17
Engine No : CVN 039058
Chassis No : WAUZZZF43HA165300
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Aug-17
Place of Accident : Along Jurong Town Hall

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFC 6006 H.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 ?	×
4	To dismantle rear bumper. Cut out and weld rear outer and inner rear cross panels. Repair rhs rear fender. Renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 3,600.00	1500 750 ✓
5	To respray rear bumper, rhs rear fender and end panelling. To carry out joint selaer works and stone chip treatment.	\$ 2,200.00	1100 ✓
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>7,112.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFC 6006 H.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	REAR BUMPER <i>Distorted</i>	\$ 1,844.00	✓ 1475.20
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 61.00	x } x
3	REAR LID KICK SENSOR SECURING STRIP <i>Not new</i>	\$ 182.00	x } x
4	REAR BUMPER SPOILER <i>distorted</i>	\$ 203.00	✓ 162.40
5	REAR BUMPER LIGHT REFLECTOR - RH <i>Cracked</i>	\$ 24.00	✓ 15.96
6	REAR REINFORCEMENT BEAM <i>Bent</i>	\$ 756.00	✓ 604.40
7	REAR REINFORCEMENT BEAM SEAL <i>Not new</i>	2 \$ 22.00	?
8	REAR BUMPER GUIDE - RH LOWER <i>Not new</i>	\$ 37.00	+
9	REAR BUMPER GUIDE - RH UPPER <i>Not new</i>	\$ 18.00	x
10	REAR PARKING AID SENSOR <i>new</i>	2 \$ 415.00	+
11	REAR PARKING AID SENSOR O-RING SET <i>new</i>	\$ 14.00	x
12	REAR BUMPER WIRING SET <i>new</i>	\$ 580.00	x
13	REAR CROSS PANEL - OUTER <i>Not new</i>	\$ 222.00	?
14	REAR CROSS PANEL REINFORCEMENT - INNER <i>Not new</i>	\$ 431.00	?
15	REAR UNDERBODY TRIM - RH <i>Not new</i>	\$ 94.00	x
16	LED TAIL LIGHT - RH OUTER <i>Damaged</i>	\$ 784.00	✓
17	TAIL LIGHT TRIM - RH OUTER <i>Not new</i>	\$ 24.00	?
18	ACRYLIC SEALER <i>Not new</i>	S/N \$ 180.00	?
19	CAVITY WAX <i>Not new</i>	S/N \$ 140.00	?
20	STONE CHIP <i>Not new</i>	S/N \$ 180.00	?
21	SUNDRIES <i>new</i>	\$ 300.00	42.88
TOTAL SPARE PARTS		: \$ 6,511.00	
TOTAL LABOUR CHARGES		: \$ 7,112.00	
GRAND TOTAL		: <u>\$ 13,623.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Ly*
Surveyed Date : *23/08/17*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, OH Amp.*

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0829/2017/CCS
Date	:	21-Aug-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
4 days - ok - jb - 18/9

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Joseph Lok Leong Moon
Address	:	83 Jalan Mas Puteh
		Singapore 128659
Telephone	:	HP +65 96843818
Type of Claim	:	Own Damage Claims
Policy No.	:	1700015949
Vehicle No	:	SFC 6006 H
Model Code	:	Audi A4 SEDAN 1.4 TFSI
Model / Year	:	Jun-17
Engine No	:	CVN 039058
Chassis No	:	WAUZZZF43HA165300
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	17-Aug-17
Place of Accident	:	Along Jurong Town Hall

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFC 6006 H.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	\$ 360.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	\$ 280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00	
4	To dismantle rear bumper. Cut out and weld rear outer and inner rear cross panels. Repair rhs rear fender. Renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 3,600.00	\$ 750.00
5	To respray rear bumper, rhs rear fender and end panelling. To carry out joint selsaer works and stone chip treatment.	\$ 2,200.00	\$ 1,100.00
6	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 7,112.00	\$ 2,682.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFC 6006 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,844.00	\$ 1,475.20
2	REAR BUMPER FIXING PARTS	\$ 61.00	
3	REAR LID KICK SENSOR SECURING STRIP	\$ 182.00	
4	REAR BUMPER SPOILER	\$ 203.00	\$ 162.40
5	REAR BUMPER LIGHT REFLECTOR - RH	\$ 24.00	\$ 18.96
6	REAR REINFORCEMENT BEAM	\$ 756.00	\$ 604.40
7	REAR REINFORCEMENT BEAM SEAL	2 \$ 22.00	
8	REAR BUMPER GUIDE - RH LOWER	\$ 37.00	
9	REAR BUMPER GUIDE - RH UPPER	\$ 18.00	
10	REAR PARKING AID SENSOR	2 \$ 415.00	
11	REAR PARKING AID SENSOR O-RING SET	\$ 14.00	
12	REAR BUMPER WIRING SET	\$ 580.00	
13	REAR CROSS PANEL - OUTER	\$ 222.00	
14	REAR CROSS PANEL REINFORCEMENT - INNER	\$ 431.00	
15	REAR UNDERBODY TRIM - RH	\$ 94.00	
16	LED TAIL LIGHT - RH OUTER	\$ 784.00	
17	TAIL LIGHT TRIM - RH OUTER	\$ 24.00	
18	ACRYLIC SEALER	S/N \$ 180.00	
19	CAVITY WAX	S/N \$ 140.00	
20	STONE CHIP	S/N \$ 180.00	
21	SUNDRIES	\$ 300.00	\$ 42.88
	TOTAL SPARE PARTS	\$ 6,511.00	\$ 2,303.84
	TOTAL LABOUR CHARGES	\$ 7,112.00	\$ 2,682.00
	GRAND TOTAL	\$ 13,623.00	\$ 4,985.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Tuesday, September 19, 2017 3:21 PM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong; Nora Khai
Subject: FINAL REVISION FOR SFC6006H - OD AIG - SURVEYED 23 AUG 17
Attachments: PA08292017 - SFC 6006 H - A4 SEDAN 1.4 TFSI - REAR (AIG).xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$4985.84 @ 4 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFC 6006 H

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0829/2017/MAS

13 March 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SFC 6006 H, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SFC 6006 H**, claimant, **Mr. Joseph Lok Leong Moon**, please find the related document per attached.

1. A copy of the Original invoice no. 85012238 – S\$5,334.85
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SFC 6006 H

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 1183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2017		23 Aug 2017 14:14 Edit Adj Rpt	S\$4,985.84 Edit Estimates	S\$4,985.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JOSEPH LOK LEONG MOON, ID: S1621741G, Tel: +6596843818, Email: MASPUHE83@GMAIL.COM								
Vehicle Reg. No.:	SFC6006H	Date of Loss:	17/08/2017 17:00 - :59						
Claim Type:	OD / 8610733271SG	Policy/Cover Note No.:	1700015949 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/09/2017]								
Driver/Custodian:	JOSEPH LOK LEONG MOON (54 / Male), NRIC: S1621741G, Tel: +6596843818								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
- AIG_SG (28/08/2017): Alert - Adj Mandate Approved (S\$8268.00) - SFC6006H - Claim Handler: Loo, Tong S... - AIG_SG (24/08/2017): Alert - Adj Mandate Approved (S\$8548.00) - SFC6006H - Claim Handler: Loo, Tong S... - AIG_SG (24/08/2017): SFC6006H / OD / 17/08/2017 / Coverage & Excess update									
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFC6006H (8610733271SG)
 OD
 Aug 17 2017 5:35PM
 [JOSEPH LOK LEONG MOON]
 Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer		
Video										1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UB1)								Thumbnail	Print	
1	18/08/17 13:45	Video - Accident [Linked Accident Report Documents]								1 Load MP4		
Assessment Reports										1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	23/08/17 15:48	Adjuster Immediate Advice								1 Load HTM		
2	28/08/17 10:28	Adjuster Immediate Advice								1 Load HTM		
Photos/Images										3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	23/08/17 16:50	General View								1 Load JPG	☒	
2	23/08/17 16:50	General View								1 Load JPG	☒	
3	23/08/17 16:50	General View								1 Load JPG	☒	
4	23/08/17 16:50	General View								1 Load JPG	☒	
5	23/08/17 16:50	General View								1 Load JPG	☒	
6	23/08/17 16:50	General View								1 Load JPG	☒	
7	23/08/17 16:50	General View								1 Load JPG	☒	
8	23/08/17 16:50	General View								1 Load JPG	☒	
9	23/08/17 16:50	General View								1 Load JPG	☒	
10	23/08/17 16:50	General View								1 Load JPG	☒	
11	23/08/17 16:50	General View								1 Load JPG	☒	
12	23/08/17 16:50	General View								1 Load JPG	☒	
13	23/08/17 16:50	General View								1 Load JPG	☒	
14	23/08/17 16:50	General View								1 Load JPG	☒	
15	23/08/17 16:50	General View								1 Load JPG	☒	
16	23/08/17 16:50	General View								1 Load JPG	☒	
17	23/08/17 16:50	General View								1 Load JPG	☒	
18	23/08/17 16:50	General ViewGeneral View								1 Load JPG	☒	
19	23/08/17 16:50	General View								1 Load JPG	☒	
20	23/08/17 16:50	General View								1 Load JPG	☒	
21	23/08/17 16:50	General View								1 Load JPG	☒	
22	23/08/17 16:50	General View								1 Load JPG	☒	
23	23/08/17 16:50	General View								1 Load JPG	☒	
24	23/08/17 16:50	General View								1 Load JPG	☒	
25	23/08/17 16:50	General Viewl								1 Load JPG	☒	
26	23/08/17 16:50	General View								1 Load JPG	☒	
27	23/08/17 16:50	General View								1 Load JPG	☒	
28	23/08/17 16:50	General View								1 Load JPG	☒	
29	23/08/17 16:50	General View								1 Load JPG	☒	
Documentation										1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	23/08/17 16:39	Certificate of Insurance								1 Load PDF		
2	23/08/17 16:39	Drivers Driving License								1 Load PDF		

3	23/08/17 16:39	WORKSHOP ESTIMATE		Load PDF	
4	23/08/17 16:39	Singapore Accident Statement		Load PDF	
5	23/08/17 16:39	Insureds NRIC		Load PDF	
6	21/03/18 09:25	WORKSHOP INVOICE		Load PDF	
7	21/03/18 09:25	DISCHARGE VOUCHER		Load PDF	

Linked Accident Report Documents

				View	Use Viewer
Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	18/08/17 13:45	Video - Accident		Load MP4	
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	18/08/17 13:53	Accident Statement		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	18/08/17 13:49	Accident Photo		Load JPG	☒
2	18/08/17 13:49	Accident Photo		Load JPG	☒
3	18/08/17 13:49	Accident Photo		Load JPG	☒
4	18/08/17 13:49	Accident Photo		Load JPG	☒
5	18/08/17 13:49	Accident Photo		Load JPG	☒
6	18/08/17 13:49	Accident Photo		Load JPG	☒
7	18/08/17 13:49	Accident Photo		Load JPG	☒
8	18/08/17 13:49	Accident Photo		Load JPG	☒
9	18/08/17 13:49	Accident Photo		Load JPG	☒
10	18/08/17 13:49	Accident Photo		Load JPG	☒
11	18/08/17 13:51	Accident Photo ACCIDENT SCENE PHOTO		Load JPG	☒
12	18/08/17 13:51	Accident Photo ACCIDENT SCENE PHOTO		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	18/08/17 13:37	Sketch Plan		Load JPG	☒
2	18/08/17 13:37	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17016320/ARBN2

Date: 21/03/2018

REFERENCE

Insured/Claimant: JOSEPH LOK LEONG MOON
Date of Loss: 17/08/2017

Policy No: 1700015949
Nature of Claim: OD

Claim No: 8610733271SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFC6006H	Engine No:	CVN039058
Make & Model:	AUDI A4, 1.4 T (A)	Chassis No:	WAUZZZF43HA165300
Reg. Date:	09/06/2017 (Man. Year: 2017)	Odometer:	2284 km
Colour:	Grey		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,511.00	2,303.84	4,207.16	64.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,112.00	2,682.00	4,430.00	62.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,623.00	4,985.84	8,637.16	63.40
+ GST 7.00/7.00% (S\$)	953.61	349.01	604.60	63.40
Nett Amount (S\$)	14,576.61	5,334.85	9,241.76	63.40

INSPECTION

Date of Assignment: 23/08/2017

Date Inspected: 23/08/2017 Inspected At:

Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Distorted	1,844.00 FS	*1,475.20 FS
2	1	*REAR BUMPER FIXING PARTS	Not Necessary	61.00 FS	*- FS
3	1	*REAR LID KICK SENSOR SECURING STRIP	Not Necessary	182.00 FS	*- FS
4	1	*REAR BUMPER SPOILER	Deformed	203.00 FS	*162.40 FS
5	1	*REAR BUMPER LIGHT REFLECTOR-RH	Cracked	24.00 FS	*18.96 FS
6	1	*REAR REINFORCEMENT BEAM	Bent	756.00 FS	*604.40 FS
7	2	*REAR REINFORCEMENT BEAM SEAL	Not Necessary	22.00 FS	*- FS
8	1	*REAR BUMPER GUIDE-RH LOWER	Not Necessary	37.00 FS	*- FS
9	1	*REAR BUMPER GUIDE-RH UPPER	Not Necessary	18.00 FS	*- FS
10	2	*REAR PARKING AID SENSOR	Not Necessary	415.00 FS	*- FS
11	1	*REAR PARKING AID SENSOR O-RING SET	Not Necessary	14.00 FS	*- FS
12	1	*REAR BUMPER WIRING SET	Not Necessary	580.00 FS	*- FS
13	1	*REAR CROSS PANEL-OUTER	Not Necessary	222.00 FS	*- FS
14	1	*REAR CROSS PANEL REINFORCEMENT-INNER	Not Necessary	431.00 FS	*- FS
15	1	*REAR UNDERBODY TRIM-RH	Not Necessary	94.00 FS	*- FS
16	1	*LED TAIL LIGHT-RH OUTER	Not Necessary	784.00 FS	*- FS
17	1	*TAIL LIGHT TRIM-RH OUTER	Not Necessary	24.00 FS	*- FS
18	1	*ACRYLIC SEALER	Not Necessary	180.00 FS	*- FS
19	1	*CAVITY WAX	Not Necessary	140.00 FS	*- FS
20	1	*STONE CHIP	Not Necessary	180.00 FS	*- FS
21	1	*SUNDRIES	Necessary	300.00 FS	*42.88 FS
F=Franchise part. S=SpcNett.					
Total Parts (\$\$)				6,511.00	2,303.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRSNAFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO COMPONENTS	New	480.00	-
4	TO DISMANTLE REAR BUMPER.CUT OUT AND WELD REAR OUTER AND INNER REAR CROSS PANELS.REPAIR RHS REAR FENDER.RENEW REAR BUMPER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	3,600.00	750.00
5	TO RESPRAY REAR BUMPER,RHS REAR FENDER AND END PANELLING.TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	2,200.00	1,100.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			7,112.00	2,682.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >