

ASS. REC. BY:

REF: CS/MSG17016446 / Gmb/n2 Special Instruction:

ASSIGNMENT (Office)

From (Person): Catherine Thia of MSIG Date/Time: 24082017

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB 8073X Insured: SGS 9696 A

at Workshop m/s Progressive Automotive Pte Ltd Tel: 6741 5336

of BIK 3022A Ubi Road 1 #01-45/46

Policy No: A28867776 QMX Claim No: 527171

Sum Insured: Excess:

Make of Veh: D.O.A. 19082017 (Client's Record)

CA / REV / REP. / REV 24 HRS WP. 28082017 @ 10am under writing H.O.D. Endorsement:

Date/Time: 240817 504pm Person Contacted: Pei Wen Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKB 8073X CS/AWA16015806/Kgh3n2 19082016
	SGS 9696 A NA/MSG17001672/K4 24012017

70861113

Director
Mummen

Xbel

REF: NISU1

ASSIGNMENT

29/6/2011

From: _____ Date: 28/08/2017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKB 8073X

at Workshop m/s Progressive

of Blk 3022A Ubi Rd | # 01-45

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: _____

(Policy Condition)

10km
owner waiting

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKB 8073X Yr Regn: 29 Sep 2004

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Fluence cc 1598

Colour: ~~Black~~ Blue A/C: Insured / Std / NI / NA

Sp. Reading: 166331 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VHL 2B50TUC 248557

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 86 mm

L/Bal. 86 mm

D.O.A. _____

Survey held at w/s 10AM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/8/17 REV prep in mummen.

17/1/18 Confirmed \$1440.50 - 3days repair.

RECEIVED 17 JAN 2018

Date/Time, File Pass to?

: Preli. Report

1) 17/1/18 Typist

: Final Report

Date/Time, File Return to?

2) _____

Report Format: TP

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 3days

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: 200

Transportation: 10

S + RS: \$ _____

Photos _____

Others _____

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17016446/Ggb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 24-08-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGS 9696A	Veh. Inspected	SKB 8073X
Policy No.	A28867776QMX	Coverage (\$)	0.00
Claim No.	527171	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	24/08/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/08/2017	Inspection Date	28/08/2017
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Aug 2017 10:46 Sendback Est	22 Aug 2017 12:26 S\$2,743.55	24 Aug 2017 16:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All	
CLAIM SUBFOLDER DETAILS					
Insured:	TAN TECK SAN, ID: S1711503J				
Main Claimant:	CHANG WHAY KHEONG, ID: S7137488B				
Vehicle Reg. No.:	SKB8073X	Date of Loss:	19/08/2017 12:00 - :59		
Claim Type:	TP / 527171	Policy/Cover Note No.:	A28867776QMX (Comprehensive) Coverage: 24/12/2016 - 23/12/2017		
Vehicle Reg. No. (Insured):	SGS9696A	Policy No. (Claimant):	2100264152		
Repairer:	Progressive Automotive Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46, 408716 Ubi - Tel: 67415336				
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]				
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/08/2017]				
			View All	Compose Case Mail	
ASSOCIATED MAIL RECEIVED					
There are no mail for this case.					
ALL ASSOCIATED TASKS					
		View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler
		Assigned By	Completed On	Created On	Done?
No results.					

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 29 Aug 2017

Preliminary Advice

Insured Vehicle No	: SGS9696A	Accident Date	: 19/08/2017
TP Vehicle No	: SKB8073X	Assignment Date	: 24/08/2017
Make	: RENAULT FLUENCE	Est. Duration of Repair	: 3.00
Date of Inspection	: 28/08/2017		
Inspection At	: PROGRESSIVE AUTOMOTIVE PTE LTD (HQ) BLK 3022A UBI ROAD 1, #01-45/46 SINGAPORE 408716		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,743.55
Revised Amount	:S\$	1,440.50
Check Items (Estimated)	:S\$	573.05
Total	:S\$	2,013.55

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

Admin ()

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	/			
C	Customer Code	/			
N	Assign From	/			
C	Assign Date	/			
C	Veh No (Inspected)	/			
C	Veh No (Insured)	/			
C	D.O.A	/			
C	Policy No	/			
C	Claim No	/			
C	Insurance Authorisation (CA /REV/REP)	/			
C	Report Type	/			
C	Weekend Charges	/			
N	Survey held at/Repairer				
C	Excess				

Surveyor (Guo Chiang): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	/			
C	Regn Month/Year	/			
N	Vehicle Type	/			
N	Make & Model	/			
C	Engine Capacity. (C.C)	/			
N	Colour	/			
C	Odometer. (Sp.Reading)	/			
C	Chassis No	/			
N	General Condition	/			
N	Steering	/			
N	Brake	/			
N	Modification (Modi)	/			
C	Tyre Size	/			
N	Tyre Make	/			
C	Tyre Balance	/			
C	Date of Inspection	/			
N	Survey held	/			
N	Des.of Damages	/			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Rita | 16/1/2018
 Case Handler | Date

*C: Critical *N: Non-Critical

Norrita (LKKAuto)

From: Norrita (LKKAuto)
Sent: Tuesday, 16 January 2018 5:40 PM
To: Ray Progressive; SUR
Subject: RE: SKB8073X - TO FINALIZE

Dear Ray,

Kindly ignore the previous email.

Confirmed finalize for Vehicle SKB 8073X amount \$1440.50 – 3 days

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ray Progressive [<mailto:ray@progauto.com.sg>]
Sent: Tuesday, 16 January 2018 3:15 PM
To: SUR <sur@lkkauto.com>
Subject: FW: SKB8073X - TO FINALIZE

Hi Janice,

Please see attached after paint photo

Regards,
Ray

From: Ray Progressive [<mailto:ray@progauto.com.sg>]
Sent: Thursday, November 02, 2017 2:13 PM
To: 'Guo Qiang (LKKAuto)'
Cc: 'Wayne Lim'; 'bhlim@progauto.com.sg'; 'msho@progauto.com.sg'; 'Peiwen PROGAUTO'; 'siewwei@progauto.com.sg'
Subject: SKB8073X - TO FINALIZE

Hi Guo Qiang,

Please refer to finalize

Parts	\$1000.50
Lab	\$440.00
Total	\$1440.50

Thank you

Best regard,

Ray

Progressive Automotive Pte Ltd

Tel: 6741-5336 Fax: 6741-7208

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7488B

Vehicle Details

Vehicle No.: SKB8073X

Vehicle to be Exported: No

Intended De-registration Date: 29 Aug 2017

Vehicle Make: RENAULT

Vehicle Model: FLUENCE 1.6L CVT ABS D/AB 2WD 4DR SR

Primary Colour: Blue

Manufacturing Year: 2011

Engine No.: H4MC721F096909

Chassis No.: VF1LZB50TUC248557

Maximum Power Output: 82.0 kW (109 bhp)

Open Market Value: \$15,864.00

Original Registration Date: 29 Jun 2011

First Registration Date: 29 Jun 2011

Transfer Count: 0

Actual ARF Paid: \$15,864.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Jun 2021

PARF Rebate Amount: \$10,311.00

Intended COE Rebate Details

COE Expiry Date: 28 Jun 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$50,244.00

COE Rebate Amount: \$19,259.00

Total Rebate Amount: \$29,570.00

The information contained herein is correct as at 29 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 27 Aug 2017 at 01:09 AM



Kian Hua Motor Co. Pte Ltd
 7 Jalan Lembah Kallang, S(339563)
 Tel: (+65) 6293 3850
 Fax: (+65) 6355 1800
 Email: sales@kianhuamotor.com
 Co. Reg No: 200106569G



SALES ORDER

NO: SOR1008214
 PAGE: 1/1
 DATE: 14 Sep 2017
 A/C CODE: KPROGR
 TERM: 30Days
 P/O NO: SKB8073X

M/S : Progressive Automotive Pte Ltd

Bik 3022A Ubi Rd 1 #01-45/46
 Singapore 408716 Attn : Wendy Fax 68444802
 A/C FAX 6741-4906 A/C TEL:6741-5336

TEL: 6741-1743 Wendy Soo FAX: 6741-7208 Ana =AXA 6

SKB8073X - Renault Fluence
 Description

- 1 BUMPER R/FLU REAR
- 2 BUMPER SIDE BKT R/FLU R/LH
- 3 BUMPER SIDE BKT R/FLU R/RH
- 4 RIVET R/FLU REAR BUMPER

Quantity	Unit Price SGD	Amount SGD
1 PC	660.00	660.00
1 PC	95.00	95.00
1 PC	95.00	95.00
10 PC	2.00	20.00
Total Qty: 13 PC	Total	SGD 870.00
	Add GST @ 7%	60.90
	Grand Total	SGD 930.90

SGD NINE HUNDRED THIRTY AND CENTS NINETY ONLY

Progressive Automotive Pte Ltd

For Kian Hua Motor Co. Pte Ltd

AUTHORISED SIGNATURE
 KEVIN

CONFIRMED & ACCEPTED BY

Once the order is confirmed, it cannot be cancelled. Goods sold are not returnable.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Aug 2017)
 Parts: 143 RENAULT FLUENCE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SKB8073X/22/08/2017 12:26
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	NA	*REAR BUMPER / ee	0.00	0.00	*660.00 F	
2	1	NA	*REAR BUMPER SIDE HOLDER -LH = } rec	0.00	0.00	*95.00 F	
3	1	NA	*REAR BUMPER SIDE HOLDER - RH = } rec	0.00	0.00	*95.00 F	
4	10	NA	*REAR BUMPER CLIPS	0.00	0.00	*20.00 F	
5	1	NA	*REAR BUMPER REINFORCEMENT ?	0.00	0.00	*265.00 F	
6	1	NA	*REAR BUMPER FOAM ?	0.00	0.00	*42.00 F	
						Sub Total (\$\$)	1,177.00 870
						+ Margin on L,N Items 15.00% (\$\$)	176.55
						Total Parts (\$\$)	1,353.55 (1000.50)

Progressive Automotive Pte Ltd/SKB8073X/22/08/2017 12:26. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

PARTS. 1000.50
 LAB. 440.00

 1440.50

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR BUMPER SENSOR ?	220.00
Sub Total (\$\$)			220.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	200 500.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; REAR PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	200 400.00
3	TO CHECK WIRING	New	X 20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	40 50.00
5	TO RESET CHECK LIGHT	New	X 60.00
6	TO TUFF-KOTE	New	X 60.00
7	TO REMOVE; REFIX REAR GARNISH	New	X 80.00
Gross Labour Cost (\$\$)			1,170.00

440

Progressive Automotive Pte Ltd/SKB8073X/22/08/2017 12:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

3 Days.
part by part
before paint photo's.
Geno Aiary - 62889282
28/8/17

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			220.00
1	1	REAR BUMPER SENSOR ?	
Sub Total (\$\$)			220.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	200 500.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; REAR PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	200 400.00
3	TO CHECK WIRING	New	X 20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	40 50.00
5	TO RESET CHECK LIGHT	New	X 60.00
6	TO TUFF-KOTE	New	X 60.00
7	TO REMOVE; REFIX REAR GARNISH	New	X 80.00
Gross Labour Cost (\$\$)			1,170.00 <i>440</i>

Progressive Automotive Pte Ltd/SIKB8073X/22/08/2017 12:26. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS
 < END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

*3 Days.
 part by part
 before paint photo's.
 Geno Aiary - 8288 9282
 28/8/17*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Aug 2017)
 Parts: 143 RENAULT FLUENCE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SKB8073X/22/08/2017 12:26
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BUMPER / ee	0.00	0.00	*660.00 F —
2	1	NA	*REAR BUMPER SIDE HOLDER -LH =	0.00	0.00	*95.00 F —
3	1	NA	*REAR BUMPER SIDE HOLDER - RH = } rec	0.00	0.00	*95.00 F —
4	10	NA	*REAR BUMPER CLIPS /	0.00	0.00	*20.00 F —
5	1	NA	*REAR BUMPER REINFORCEMENT ?	0.00	0.00	*265.00 F
6	1	NA	*REAR BUMPER FOAM ?	0.00	0.00	*42.00 F
						F=Franchise part.
Sub Total (S\$)						1,177.00 870
+ Margin on L,N Items 15.00% (S\$)						176.55
Total Parts (S\$)						1,353.55 1000.50

Progressive Automotive Pte Ltd/SKB8073X/22/08/2017 12:26. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

PARTS. 1000.50
 LAB. 440.00

 1440.50



PROGRESSIVE AUTOMOTIVE PTE LTD

Bik 3022A Ubi Road 1 #01-45/46 Singapore 408716
 Tel:: 6741 5336 (6 Lines) Fax: 6741 7208
 E-mail: progauto@progauto.com.sg
 Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
TAN TECK SAN
 NA
 Singapore

Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP 0817-4706
Policy No:		Date of Loss:	19/08/2017
Vehicle Reg. No.:	SKB8073X	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHANG WHAY KHEONG		
Make/Model:	RENAULT FLUENCE, 1.6 (A)	Vehicle Reg. Date:	29/06/2011
Vehicle Colour:	BLUE	Chassis No:	VF1LZB50TUC248557
Engine No:	H4MC721F096909		
Odometer:	165986 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO THE ATTACH STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD TEL 6741 5336		
Remarks:	VEHICLE IS NOT IN WORKSHOP		
Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,353.55
Miscellaneous Items	220.00
Labour	670.00
Paintwork Labour	500.00
Towing	0.00
Gross Total (S\$)	2,743.55
+ GST 7.00% (S\$)	192.05
Nett Amount (S\$)	2,935.60

This claim is handled by: PEIWEN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Aug 2017)
Parts: 143 RENAULT FLUENCE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: **Progressive Automotive Pte Ltd/SKB8073X/22/08/2017 12:26**
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	NA	*REAR BUMPER / ee	0.00	0.00	*660.00 F	
2	1	NA	*REAR BUMPER SIDE HOLDER -LH = spec	0.00	0.00	*95.00 F	
3	1	NA	*REAR BUMPER SIDE HOLDER - RH = spec	0.00	0.00	*95.00 F	
4	10	NA	*REAR BUMPER CLIPS	0.00	0.00	*20.00 F	
5	1	NA	*REAR BUMPER REINFORCEMENT X spec	0.00	0.00	*265.00 F	
6	1	NA	*REAR BUMPER FOAM X spec	0.00	0.00	*42.00 F	
						Sub Total (S\$)	1,177.00
						+ Margin on L,N Items 15.00% (S\$)	176.55
						Total Parts (S\$)	1,353.55

F=Franchise part.

Progressive Automotive Pte Ltd/SKB8073X/22/08/2017 12:26. Not valid without Reference section.
 Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			220.00
1	1	REAR BUMPER SENSOR <i>X NN</i>	
Sub Total (S\$)			220.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	<i>200</i> 500.00
Labour Items			
2	TO KNOCK OUT DENTS; REAR PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	<i>200</i> 400.00
3	TO CHECK WIRING	New	<i>NN X</i> 20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	<i>40</i> 50.00
5	TO RESET CHECK LIGHT	New	<i>X</i> 60.00
6	TO TUFF-KOTE	New	<i>mf X</i> 60.00
7	TO REMOVE; REFIX REAR GARNISH	New	<i>X</i> 80.00
Gross Labour Cost (S\$)			1,170.00

Progressive Automotive Pte Ltd/SKB8073X/22/08/2017 12:26. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS
 < END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

*3 Days.
 part by part
 before paint phot.S.
 Gen. Ai ang - 8288 9282
 28/8/17*

[Signature]
 30/8/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17016446/GNBN2
Date: 19/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28867776QMX
Claimant: SKB8073X Insured Vehicle No: SGS9696A
Vehicle No: SKB8073X Nature of Claim: TP Claim No: 527171
Date of Loss: 19/08/2017

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB8073X Engine No: H4MC721F096909
Make & Model: RENAULT FLUENCE, 1.6 (A) Chassis No: VF1LZB50TUC248557
Reg. Date: 29/06/2011 (Man. Year: 2011) Odometer: 166331 km
Colour: Blue
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,353.55	1,000.50	353.05	26.08
Miscellaneous Items	220.00	0.00	220.00	100.00
Labour	670.00	240.00	430.00	64.18
Paintwork Labour	500.00	200.00	300.00	60.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,743.55	1,440.50	1,303.05	47.50
+ GST 7.00/7.00% (S\$)	192.05	100.84	91.21	47.49
Nett Amount (S\$)	2,935.60	1,541.34	1,394.26	47.49

INSPECTION

Date of Assignment: 24/08/2017 Present Location: Progressive Automotive Pte Ltd (HQ)
Date Inspected: 28/08/2017 Inspected At: Progressive Automotive Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Norrita Binte AB Hamid

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jan 2018)
 Parts: 143 RENAULT FLUENCE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKB8073X)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*REAR BUMPER (WCP)	Deformed	660.00 F	*660.00 F
2	1	NA	*REAR BUMPER SIDE HOLDER -LH (WCP)	Necessary	95.00 F	*95.00 F
3	1	NA	*REAR BUMPER SIDE HOLDER - RH (WCP)	Necessary	95.00 F	*95.00 F
4	10	NA	*REAR BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
5	1	NA	*REAR BUMPER REINFORCEMENT (WCP)	Not Necessary	265.00 F	*- F
6	1	NA	*REAR BUMPER FOAM (WCP)	Not Necessary	42.00 F	*- F
Sub Total (S\$)					1,177.00	870.00
+ Margin on L,N Items 15.00/15.00% (S\$)					176.55	130.50
Total Parts (S\$)					1,353.55	1,000.50

F=Franchise part.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR BUMPER SENSOR (Not Necessary)	220.00	0.00
Sub Total (\$\$)			220.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	500.00	200.00
Labour Items				
2	TO KNOCK OUT DENTS; REAR PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	400.00	200.00
3	TO CHECK WIRING	New	20.00	-
4	TO TRANSFER REAR BUMPER SENSOR	New	50.00	40.00
5	TO RESET CHECK LIGHT	New	60.00	-
6	TO TUFF-KOTE	New	60.00	-
7	TO REMOVE; REFIX REAR GARNISH	New	80.00	-
Gross Labour Cost (\$\$)			1,170.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >