

ASS. REC. BY:

REF:

CS/FCU7016565/Gmb⁹²

Special Instruction:

Surveyor:

GB

ASSIGNMENT (Office)

From (Person):

CWS May Chuu

of

FCL

Date/Time: 25082017 3:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 9567U

Insured:

SHD 6900Y

at Workshop m/s

Trans Eunkears

Tel:

9618 5591

of

5 Ubi Close

Policy No:

Claim No:

D17007962MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15082017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

25082017 4:29pm

Person Contacted:

Eric

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 9567U - X
	SHD 6900Y - CCS / TM16024646 / HHbnz
	DLA: 201216
	Sent preli through email.

Surveyor: XHL

REF: FCL

ASSIGNMENT

From: _____ Date: 2509 2017

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLB 9567Uat Workshop m/s Trans Eurocareof 5 Ubi Close

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WPT

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 9567U Yr Regn: 27 Apr 2016Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 31545 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: IM6BM42A 8-G 0340524Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mm

D.O.A. _____

Survey held at w/sDes. of Damages: Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 25-09-175:10pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Confirm \$3,073.11, 3 days
 Rd: \$4,176.32, 58%

RECEIVED 22 JAN 2018

Date/Time, File Pass to?

1) typst

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Report Format: TPLump Sum / I.B.I. (\$) 3073.11150505012262



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17016565/Grb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-08-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6900Y	Veh. Inspected	SLB 9567U
Policy No.		Coverage (\$)	0.00
Claim No.	D17007962MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	25/08/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/08/2017	Inspection Date
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	16-08-2017	Our Ref No. D17007962MFSH
Accident Date	15-08-2017	Claim Type. Third Party
Insured Vehicle	SHD6900Y	Third Party Vehicle. SLB9567U
Survey Location	5 UBI CLOSE, SINGAPORE 408605	
Contact Person.	ERIC PAU	
Contact No.	63958685/ 96185991	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/226997)



PRI Documents



Close



PRI Header Details

Claim No	D17007962MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & TR
Workshop Name	TRANS EUROKARS PTE LTD (Contact Person : ERIC PAU)	Survey Location & Contact Details	5 UBI CLOSE, SINGAPORE 408605 Mobile: 96185991 , Phone: 63958685 , Fax: EmailId: ERIC.PAU@EUROKARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD6900Y	TP Vehicle No	SLB956
PRI Recieved Date	23-08-2017 09:55:53 PM	Surveyor Appointed Date	25-08-2017 03:10:32 PM	Surveyor Accept Date	25-08-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	25-08-2017	Upload Survey Report *:	
-----------------------------	----------------------	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Your Ref: D17007962MFSHOur Ref: CS/FC117016565/GrbThe Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 9567U .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/09/2018 at the premises of M/s TRANS EUROKARS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,269.43</u> .
Revised Estimate Amount	: S\$ <u>3,073.11</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at rear portion.

Yours faithfully
XING GUO QIANG
Automotive Assessor

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 3560Z

Vehicle Details

Vehicle No.: SLB9567U

Vehicle to be Exported: No

Intended De-registration
Date: 25 Sep 2017

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: P520363012

Chassis No.: JM6BM42A8G0340524

Maximum Power
Output: 88.0 kW (118 bhp)

Open Market Value: \$18,694.00

Original Registration
Date: 27 Apr 2016

First Registration Date: 27 Apr 2016

Transfer Count: 0

Actual ARF Paid: \$13,694.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 26 Apr 2026

PARF Rebate Amount: \$10,270.00

Intended COE Rebate Details

COE Expiry Date: 26 Apr 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$47,300.00

COE Rebate Amount: \$40,612.00

Total Rebate Amount: \$50,882.00

The information contained herein is correct as at 25 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 17 Sep 2017 at 12:38 AM



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
QUOTATION



FIRST CAPITAL INSURANCE LTD		NAME : Ms Tan Mei Ling, Serene		WIP : 28299	
36 ROBINSON ROAD		ADDRESS : Blk 272d Punggol Walk		EXCESS :	
#16-01 CITY HOUSE		#07-593		DATE: 23-Aug-17	
SINGAPORE 068877		Singapore 824272			
ATTN. : MOTOR CLAIMS		TEL : 90884005			
FAX :					
VEH NO :	SLB9567U	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6BM42A8G0340524	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	27-Apr-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO		QTY		REVISED	PRICES
1	REAR BUMPER / <i>ee</i>	1	MBPD8-50-221ABB	<i>1074.80</i>	\$ 1,074.80
2	RETAINER(LHS), REAR BUMPER / <i>nee</i>	1	MBHN1-50-2J1A	<i>36.10</i>	\$ 36.10
3	RETAINER(RHS), REAR BUMPER / <i>nee</i>	1	MBHN1-50-2H1A	<i>36.10</i>	\$ 36.10
4	BRACKET(LHS), REAR BUMPER X	1	MBHN9-51-077B		\$ 45.60
5	BRACKET(RHS), REAR BUMPER X	1	MBHN9-51-067B		\$ 45.60
6	BRACKET LOWER, REAR BUMPER X <i>NN</i>	1	MBHR2-50-251A		\$ 23.70
7	BRACKET CENTER, REAR BUMPER X	1	MKD53-50-251		\$ 5.10
8	REFLECTOR(LHS) X	1	MD350-51-5L0E		\$ 50.40
9	REFLECTOR(RHS) X <i>NN</i>	1	MD350-51-5M0E		\$ 50.40
10	COVER(LHS), TOWING X <i>NN</i>	1	MBHN1-50-EL1 BB		\$ 15.70
11	COVER(RHS), TOWING X <i>NN</i>	1	MBHN1-50-EK1 BB		\$ 16.20
12	REAR REINFORCEMENT X <i>NN</i>	1	MB45A-50-260		\$ 537.30
13	SENSOR,ULTRASONIC X <i>NN</i>	4	MKD47-67-UC1 13		\$ 775.60
14	RETAINER ,SENSOR X <i>NN</i>	4	MKD47-67-UC5A13		\$ 69.20
15	TAPE PROTECTOR, SENSOR X <i>NN</i>	3	MGS1D-50-EM1A	<i>24.30</i>	\$ 24.30
16	FASTENER, REAR BUMPER /	4	MB45A-56-146A	<i>11.20</i>	\$ 11.20
17	CLIP, REAR BUMPER / <i>nee</i>	2	MGJ21-50-049	<i>6.40</i>	\$ 6.40
18	RIVET, REAR BUMPER /	4	MBBM4-50-355	<i>16.80</i>	\$ 16.80
19	GROMMET, REAR BUMPER /	1	M9991-00-501	<i>2.80</i>	\$ 2.80
20	GROMMET, REAR BUMPER /	4	MBHN1-50-021A	<i>10.00</i>	\$ 10.00
21	GASKET(LHS), TAILLAMP /	1	MBHN1-51-163	<i>20.90</i>	\$ 20.90
22	GASKET(RHS), TAILLAMP /	1	MBHN1-51-153	<i>20.90</i>	\$ 20.90
23	FASTENER, TAILLAMP /	2	MKD53-51-146B	<i>7.80</i>	\$ 7.80
24	GROMMET, TAILLAMP /	2	MGJ6A-51-14Y	<i>29.80</i>	\$ 29.80
TOTAL PARTS					\$ 2,932.70
LESS 10%					\$ 293.27
TOTAL PARTS COST					\$ 2,639.43



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
QUOTATION



FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Ms Tan Mei Ling, Serene ADDRESS : Blk 272d Punggol Walk #07-593 Singapore 824272 TEL : 90884005	WIP : 28299 EXCESS : DATE: 23-Aug-17
VEH NO :	SLB9567U	DATE IN :	CONTACT PERSON : VION 6395 7877
CHASSIS NO :	JM6BM42A8G0340524	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.: 27-Apr-16	POLICY NO. :

NATURE OF WORKS

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	630	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	600	\$ 1,500.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.	315	\$ 630.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	NETT 30	\$ 100.00

3 Days.
before part photo's.
Gm. Qian - 82880282
25/9/17.

TOTAL LABOUR	\$ -	\$ 4,630.00
TOTAL PARTS	\$ -	\$ 2,639.43
TOTAL	\$ -	\$ 7,269.43
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) surveyed and is subject to final approval from Insurance Company

Authorised Signature

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIR



FIRST CAPITAL INSURANCE LTD		NAME : Ms Tan Mei Ling, Serene		WIP : 28299	
36 ROBINSON ROAD		ADDRESS : Blk 272d Punggol Walk		EXCESS :	
#16-01 CITY HOUSE		#07-593		DATE: 23-Aug-17	
SINGAPORE 068877		Singapore 824272			
ATTN. : MOTOR CLAIMS		TEL : 90884005			
FAX :					
VEH NO :	SLB9567U	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6BM42A8G0340524	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	27-Apr-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	1	REAR BUMPER	MBPD8-50-221ABB	\$ 1,074.80	\$ 1,074.80
2	1	RETAINER(LHS), REAR BUMPER	MBHN1-50-2J1A	\$ 36.10	\$ 36.10
3	1	RETAINER(RHS), REAR BUMPER	MBHN1-50-2H1A	\$ 36.10	\$ 36.10
4	1	BRACKET(LHS), REAR BUMPER	MBHN9-51-077B		\$ 45.60
5	1	BRACKET(RHS), REAR BUMPER	MBHN9-51-067B		\$ 45.60
6	1	BRACKET LOWER, REAR BUMPER	MBHR2-50-251A		\$ 23.70
7	1	BRACKET CENTER, REAR BUMPER	MKD53-50-251		\$ 5.10
8	1	REFLECTOR(LHS)	MD350-51-5L0E		\$ 50.40
9	1	REFLECTOR(RHS)	MD350-51-5M0E		\$ 50.40
10	1	COVER(LHS), TOWING	MBHN1-50-EL1 BB		\$ 15.70
11	1	COVER(RHS), TOWING	MBHN1-50-EK1 BB		\$ 16.20
12	1	REAR REINFORCEMENT	MB45A-50-260		\$ 537.30
13	4	SENSOR,ULTRASONIC	MKD47-67-UC1 13		\$ 775.60
14	4	RETAINER,SENSOR	MKD47-67-UC5A13		\$ 69.20
15	3	TAPE PROTECTOR, SENSOR	MG51D-50-EM1A	\$ 24.30	\$ 24.30
16	4	FASTENER, REAR BUMPER	MB45A-56-146A	\$ 11.20	\$ 11.20
17	2	CLIP, REAR BUMPER	MGJ21-50-049	\$ 6.40	\$ 6.40
18	4	RIVET, REAR BUMPER	MBBM4-50-355	\$ 16.80	\$ 16.80
19	1	GROMMET, REAR BUMPER	M9991-00-501	\$ 2.80	\$ 2.80
20	4	GROMMET, REAR BUMPER	MBHN1-50-0Z1A	\$ 10.00	\$ 10.00
21	1	GASKET(LHS), TAILLAMP	MBHN1-51-163	\$ 20.90	\$ 20.90
22	1	GASKET(RHS), TAILLAMP	MBHN1-51-153	\$ 20.90	\$ 20.90
23	2	FASTENER, TAILLAMP	MKD53-51-146B	\$ 7.80	\$ 7.80
24	2	GROMMET, TAILLAMP	MGJ6A-51-14Y	\$ 29.80	\$ 29.80
TOTAL PARTS				\$ 1,297.90	\$ 2,932.70
LESS 10%				\$ 129.79	\$ 293.27
TOTAL PARTS COST				\$ 1,168.11	\$ 2,639.43
Labour Description					



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIR



FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN.: MOTOR CLAIMS FAX:		NAME: Ms Tan Mei Ling, Serene ADDRESS: Blk 272d Punggol Walk #07-593 Singapore 824272 TEL: 90884005		WIP: 28299 EXCESS: DATE: 23-Aug-17	
VEH NO:	SLB9567U	DATE IN:		CONTACT PERSON:	VION 6395 7877
CHASSIS NO:	JM6BM42A8G0340524	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA3 1.5L	DATE REG.:	27-Apr-16	POLICY NO.:	
NATURE OF WORKS					
1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 630.00 \$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.			\$ 600.00 \$ 1,500.00
3	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.			\$ 315.00 \$ 630.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 150.00 \$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 180.00 \$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.			\$ 30.00 \$ 100.00
TOTAL LABOUR					\$ 1,905.00 \$ 4,630.00
TOTAL PARTS					\$ 1,168.11 \$ 2,639.43
TOTAL					\$ 3,073.11 \$ 7,269.43
LESS EXCESS					\$ - \$ -
TOTAL AFTER EXCESS					\$ 3,073.11
GST 7%					\$ 215.12 \$ -
GRAND TOTAL					\$ 3,288.23 \$ -

REMARKS: SLB9567U

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Janice Lee (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Monday, January 22, 2018 9:28 AM
To: catherinechua@eurokars.com.sg; Guo Qiang (LKKAUTO); Janice Lee (LKKAUTO)
Cc: CS A Team; Admin A; vion.lim@eurokars.com.sg; SUR
Subject: RE: SLB9567U - FINALISATION OF COR ***LKK REF:CS/FCI17016565/Grb
Attachments: 0326_001.pdf

Dear Catherine,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Guo Qiang / Janice,

For your information and necessary action please.

Thank you

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]
Sent: Saturday, 20 January 2018 8:47 AM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; vion.lim@eurokars.com.sg
Subject: FW: SLB9567U - FINALISATION OF COR

Dear Guo Qiang

This is a gentle reminder for you to finalize the COR with us. Our computation is attached again for your easy reference.

Thanks n Regards
Catherine Chua
Insurance Claims Executive
Trans Eurokars Pte Ltd
DID: 6603 6121
FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Siew Guek Catherine Chua
Sent: Friday, November 10, 2017 2:17 PM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Cc: 'CS A Team' <cs-a@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>; Vion Lim <vion.lim@eurokars.com.sg>
Subject: SLB9567U - FINALISAION OF COR

Dear Guo Qiang

Please find our computation attached for your agreement.

COR: \$3073.11 before GST

3 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Appreciate your confirming the above as soon as possible.

Thanks n Regards
Catherine Chua
Insurance Claims Executive
Trans Eurokars Pte Ltd
DID: 6603 6121
FAX: 6476 7417

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg [mailto:mazdacanon@mazda.com.sg]
Sent: Friday, November 10, 2017 2:05 PM
To: Siew Guek Catherine Chua <catherinechua@eurokars.com.sg>
Subject: Attached Image



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17016565/Grbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-01-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6900Y	Veh. Inspected	SLB 9567U	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17007962MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	25/08/2017	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM42A8G0340524	Colour	BLUE	
Odometer	31545	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	8 mm	
L/H Front Tyre	205/60 R16	TOYO	8 mm	
R/H Rear Tyre	205/60 R16	TOYO	8 mm	
L/H Rear Tyre	205/60 R16	TOYO	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2017	Inspection Date	25/09/2017	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 9567U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,074.80	1,074.80
1	RETAINER (LHS), REAR BUMPER	NECESSARY	36.10	36.10
1	RETAINER (RHS), REAR BUMPER	NECESSARY	36.10	36.10
1	BRACKET (LHS), REAR BUMPER	NOT NECESSARY	45.60	-
1	BRACKET (RHS), REAR BUMPER	NOT NECESSARY	45.60	-
1	BRACKET LOWER, REAR BUMPER	NOT NECESSARY	23.70	-
1	BRACKET CENTER, REAR BUMPER	NOT NECESSARY	5.10	-
1	REFLECTOR (LHS)	NOT NECESSARY	50.40	-
1	REFLECTOR (RHS)	NOT NECESSARY	50.40	-
1	COVER (LHS), TOWING	NOT NECESSARY	15.70	-
1	COVER (RHS), TOWING	NOT NECESSARY	16.20	-
1	REAR REINFORCEMENT	NOT NECESSARY	537.30	-
4	SENSOR, ULTRASONIC	NOT NECESSARY	775.60	-
4	RETAINER, SENSOR	NOT NECESSARY	69.20	-
3	TAPE PROTECTOR, SENSOR	NECESSARY	24.30	24.30
4	FASTENER, REAR BUMPER	NECESSARY	11.20	11.20
2	CLIP, REAR BUMPER	NECESSARY	6.40	6.40
4	RIVET, REAR BUMPER	NECESSARY	16.80	16.80
1	GROMMET, REAR BUMPER	NECESSARY	2.80	2.80
4	GROMMET, REAR BUMPER	NECESSARY	10.00	10.00
1	GASKET (LHS), TAILLAMP	NECESSARY	20.90	20.90
1	GASKET (RHS), TAILLAMP	NECESSARY	20.90	20.90
2	FASTENER, TAILLAMP	NECESSARY	7.80	7.80
2	GROMMET, TAILLAMP	NECESSARY	29.80	29.80
	LESS 10% DISCOUNT		-293.27	-129.79
			2,639.43	1,168.11
SPECIAL NETT ITEMS				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			100.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,800.00	630.00
	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.		1,500.00	600.00
	TO TRANSFER REVERSE SENSORS.		630.00	315.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			4,530.00	1,875.00
	GRAND TOTAL		7,269.43	3,073.11
RECOMMENDED COST OF REPAIRS				3,073.11

Report Ref No. CS/FCI17016565/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.