

ASS. REC. BY:

REF: CS/MSG17016567/Thbn2 Special Instruction:

Survivor:

Tentilch

ASSIGNMENT (Office)

From (Person):

Catherine Thia of Moch

Date/Time: 25082017 6:02pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 6466K

Insured:

SKZ 7086P

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

A28679242BMY

Claim No:

527431

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22082017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

07092017 @ 11am AW

H.O.D. Endorsement:

Date/Time:

26082017

1015am

Person Contacted:

Caroline

Vehicle IN / OUT

(Email)

Date/Time

Action/Instruction (✓) Estimate Ham

SKP 6466K - X

SKZ 7086P - X

08/9/17 @ 21m revised to Catherine Thia via Meiruen.

27/11/17 @ 11.15am confirmed with Caroline final fig \$3331.95, 3 days.

(Red \$2606.70, 44%)

(08/11/13)

REF: MSU

Surveyor:
Melimen

Tanjah

ASSIGNMENT

From:

Date: 07092017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKP 6466K

at Workshop m/s Performana

of 303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

Han

(Policy Condition)

11km
owner waitingRemark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKP 6466K Yr Regn: 2014 1 SEP

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 316I

c.c 1598

Colour:

white.

A/C: Insured / Std / NI / NA

Sp. Reading:

31882.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBA 3A16040WS37906

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

215

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

7/9/17 plus

Survey held at:

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 23 NOV 2017

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

200

10

210

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

3331.95



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17016567/T1qb

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 26-08-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 7086P	Veh. Inspected	SKP 6466K
Policy No.	A28679242QMY	Coverage (\$)	0.00
Claim No.	527431	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	25/08/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	22/08/2017	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (

Cathy)

Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			

Surveyor (

Taufiq)

Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

<input checked="" type="checkbox"/>			
-------------------------------------	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			
<input checked="" type="checkbox"/>			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

<input checked="" type="checkbox"/>			
-------------------------------------	--	--	--

Check By:

[Signature] 23/11/17

Case Handler

Date

*C: Critical *N: Non-Critical

21/05/2014

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Aug 2017		25 Aug 2017 18:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS			[Created by insurer]																					
Insured:	HO KHAI FATT JEFFREY, ID: S0016929C, Tel: +6597737939, Email: jeffreyho6865@hotmail.com																							
Main Claimant:	GOH KNG HUANG, ID: S1648769D																							
Vehicle Reg. No.:	SKP6466K	Date of Loss:	22/08/2017 17:00 - :59																					
Claim Type:	TP / 527431	Policy/Cover Note No.:	A28679242QMY(COMP) (Comprehensive) Coverage: 29/01/2017 - 28/01/2018																					
Vehicle Reg. No. (Insured):	SKZ7086P	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/08/2017]																							
Driver/Custodian (Insured):	HO KHAI FATT JEFFREY (62 / Male), NRIC: S0016929C, Tel: +6597737939																							
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail																				
There are no mail for this case.																								
<input type="checkbox"/> ALL ASSOCIATED TASKS <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 23 November, 2017 11:15 AM
To: Taufikh (LKKAUTO); 'PBSP'
Cc: SUR
Subject: RE: FINAL REPORT / SKP6466K

Dear Caroline,

Confirm final fig \$3,331.95 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Taufikh (LKKAUTO)

Sent: Wednesday, 22 November, 2017 10:26 AM

To: 'PBSP' <pml-pbsp@simeдарby.com.sg>

Cc: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Subject: RE: FINAL REPORT / SKP6466K

Hi Caroline,

Can forward the before paint photos?

Regards

Taufikh

Lkk Auto

-----Original Message-----

From: PBSP [<mailto:pml-pbsp@simeдарby.com.sg>]

Sent: Tuesday, 21 November 2017 5:42 PM

To: taufikh@lkkauto.com; SUR

Subject: FINAL REPORT / SKP6466K

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,164.00

Total Parts : 1,167.95

Total Labour & Parts : 3,331.95

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 08 Sep 2017

Preliminary Advice

Insured Vehicle No	: SKZ7086P	Accident Date	: 22/08/2017
TP Vehicle No	: SKP6466K	Assignment Date	: 25/08/2017
Make	: BMW 316I	Est. Duration of Repair	: 3.00
Date of Inspection	: 07/09/2017		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,938.65
Revised Amount	:S\$	3,198.90
Check Items (Estimated)	:S\$	2,126.35
Total	:S\$	5,325.25

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/08/2017 14:33
Date Of Accident	22/08/2017 18:15
Exact Location Of Accident	BALESTIER RD AFTER MOULMEIN FLYOVER IN DIRECTION T
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP6466K
Insured/Policyholder	
Name Of Registered Owner	GOH KNG HUANG
NRIC No	S1648769D
Email Address	LIMHNGEE@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-96710977
Alternative Phone No	OFFICE-96710977

Vehicle Particulars

Manufacturer	BMW
Model	316
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM1200238101600
Cover Note Number	

Driver

Name of Driver	GOH KNG HUANG
NRIC No	S1648769D
Date Of Birth	13/11/1964
Occupation	INDOOR
Date Of Driving Pass	20/09/1991
Driving Experience	25 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96710977
Fax Number	
Contact Number	OFFICE-96710977
EEmail Address	LIMHNGEE@YAHOO.COM.SG

Address	10 WOODLEIGH CLOSE #10-03
Postcode	357905
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKZ7086P
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	JEFFREY HO
NRIC/Passport Number	
Contact Number	97737939
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

23/08/17 (11.40am)

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



←
traffic direction

Sketch Plan Pg. 2

Describe Circumstances of the Accident

I was knocked from behind while my car was stationary.
The traffic on the road was in congestion.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

23/08/17
(11.40am)

Driver's Signature (if driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

23 AUG 2017

Estimate No. : b1 43891
Date Estimated : 23/08/2017
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Goh Kng Huang
10 Woodleigh Close
#10-03 Blossoms @ Woodleigh

Singapore 357905

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP6466K	NS37906	26/09/2014	316iA/4	0

DESCRIPTION

To replace rear bumper & attachments including to knock out dented area caused by the accident

VALUE
850 1,275.00

To respray rear bumper

934 1,038.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

565? 661.00
m

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

net? 80.00

Total Labour 1: 3,408.00

DESCRIPTION

RR BUMPER BOTTOM REINFORCEMENT
REAR BUMPER CENTRE GUIDE
REAR BUMPER CARRIER (ECE)
REAR BUMPER PANEL PRIMED BASIS
RR BUMPER FLAP TOWING EYE PRIMED
REAR PDC HOLDER SET
PLUG BLACK D=5MM
SENSOR WIRE FOR SMART OPENER TOP
SENSOR WIRE FOR SMART OPENER BOTTOM
EXPANDING NUT
DECOUPLING RING PDC TORQUE CONVERTE
PDC SENSOR MINERALWEISS (A96)
(DG) ADHESIVE SET K6

QTY	PRIC
1	64.50
1	31.30
1	422.30
1	1,073.45
1	30.40
1	22.55
10	0.90
1	42.10
1	40.50
10	0.55
2	4.95
2	363.05
1	53.05

VALUE
? 64.50
? 31.30
? 422.30
de 1,073.45
RX 30.40
net 22.55
net 9.00
? 42.10
? 40.50
? 5.50
net 9.90
? 726.10
net? 53.05

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 43891
Date Estimated : 23/08/2017
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP6466K	NS37906	26/09/2014	316iA/4	0

Total Parts : 2,530.65

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 7/9/17 @ 1115 Claim No. _____Date&Time 7/9/17 @ 1115 Excess \$S _____Surveyor's Name Tan Jiah Sign Tan JiahSurveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR ☒ No PML Yes / No _____Surveyor's E-mail tanjiah@lkkauto.comNo. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Labour 1	:	3,408.00
Parts	:	2,530.65
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	415.71
Grand Total	:	6,354.36

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

5938.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 43891**
Date Estimated : **23/08/2017**
Prepared By : **Han Kwan Yong**

Page No. :

REPAIR FOR -
Goh Kng Huang
10 Woodleigh Close
#10-03 Blossoms @ Woodleigh

Singapore 357905

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKP6466K	NS37906	26/09/2014	316iA/4	0
DESCRIPTION		ORIGINAL PRICE	DISC. %	NET T
To replace rear bumper and attachments include knock out dented areas caused by the accident		850.00		850.00
To respray rear bumper		934.00		934.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.		150.00		150.00
To check electrical wiring systems and lightings at the rear section for proper function.		150.00		150.00
Sundries.		80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED BASIS	1,073.45	1.00		1,073.45
REAR PDC HOLDER SET	22.55	1.00		22.55
PLUG BLACK D=5MM	0.90	10.00		9.00
DECOUPLING RING PDC TORQUE CONVERTER	4.95	2.00		9.90
(DG) ADHESIVE SET K6	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	2,164.00
Total Parts :	1,167.95
Total Labour & Parts :	3,331.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,331.95
GST @7%:	233.24
Grand Total :	3,565.19

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17016567/T1QBN2

Date: 24/11/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28679242QMY (COMP)	
Claimant Vehicle No :	SKP6466K	Insured Vehicle No :	SKZ7086P	
Date of Loss:	22/08/2017	Nature of Claim:	TP	Claim No: 527431

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP6466K	Engine No:	A843J751N13B16A
Make & Model:	BMW 316I, 1.6 AT D/AB 4DR ABS HID (A)	Chassis No:	WBA3A16040NS37906
Reg. Date:	26/09/2014 (Man. Year: 2014)	Odometer:	31882 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,610.65	1,247.95	1,362.70	52.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,328.00	2,084.00	1,244.00	37.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,938.65	3,331.95	2,606.70	43.89
+ GST 7.00/7.00% (S\$)	415.71	233.24	182.47	43.89
Nett Amount (S\$)	6,354.36	3,565.19	2,789.17	43.89

INSPECTION

Date of Assignment:	25/08/2017	
Date Inspected:	07/09/2017 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2017)
Parts:	143	BMW 316I 1.6 AT D/AB 4DR ABS HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP6466K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1	*RR BUMPER BOTTOM REINFORCEMENT	Not Necessary	64.50 FS	*- FS
3	1	*REAR BUMPER CENTRE GUIDE	Not Necessary	31.30 FS	*- FS
4	1	*REAR BUMPER CARRIER (ECE)	Not Necessary	422.30 FS	*- FS
5	1	*REAR BUMPER PANEL PRIMED BASIS	Deformed	1,073.45 FS	*1,073.45 FS
6	1	*RR BUMPER FLAP TOWING EYE PRIMED	Repair	30.40 FS	*- FS
7	1	*REAR PDC HOLDER SET	Necessary	22.55 FS	*22.55 FS
8	10	*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
9	1	*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	42.10 FS	*- FS
10	1	*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	40.50 FS	*- FS
11	10	*EXPANDING NUT	Not Necessary	5.50 FS	-
12	2	*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	9.90 FS	*9.90 FS
13	2	*PDC SENSOR MINERALWEISS (A96)	Not Necessary	726.10 FS	*- FS
14	1	*(DG) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
Total Parts (S\$)				2,610.65	1,247.95

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ATTACHMENTS INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER.	New	1,038.00	934.00
3	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.	New	661.00	0.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.	New	177.00	150.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION.	New	177.00	150.00
Gross Labour Cost (S\$)			3,328.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >