

ASS. REC BY:

REF: 09/MSG17016635/R11b27

Special Instruction:

SUN 28/8/17

Mehmen

Rasul

## ASSIGNMENT (Office)

From (Person): Clara Milah

of MSIG

Date/Time: 28/08/2017 3:17pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJP 8431J

Insured:

at Workshop m/s

Shu Fatt

Tel: 62730119

of BIK 1009 Bkt Merah Lane 3, #01-90

Policy No: D27279275 QMX

Claim No: 527379

Sum Insured:

Excess: \$500.00

Make of Veh:

D.O.A. 21/08/2017

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28/8/2017 3:30pm Person Contacted: Patricia

Vehicle (IN) OUT

| Date/Time | Action/Instruction (✓) Estimate                     |
|-----------|-----------------------------------------------------|
|           | SJP 8431J - x                                       |
| 29/8-     | Report via Mehmen                                   |
| 29/8@     | 16:53 authorise repair by Chen How                  |
| 29/8@     | 5:16pm email Shu Fatt authorise repair excess \$500 |
|           |                                                     |
|           |                                                     |

Rasul

REF:

E889F

## ASSIGNMENT

COE XPCRY: 26/9/APR

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJP 8431J

at Workshop m/s SHU FATT

of

Insured:

MSIA / PKV / 00

Policy No:

Claims No:

Sum Insured:

Excess:

Sov

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

25K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJP 8431J

Yr Regn:

2009 APR

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA COROLLA ALTIS 1.6A cc 1598

Colour:

Grey

A.C. Insured / Std / NI / NA

Sp Reading:

44521

T/Radio: Insured / Std / NI / NA

Eng No:

Ch No:

MR053206 106142620

Gen. Cond: Good / Bad / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

7-

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A:

21/08/17

D.O.I:

28/08/17

Survey held at:

SHU FATT

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

Part by Part \$3940.40 (Red: 2159.30 : 35%)

RECEIVED 22 NOV 2017

Date/Time File Pass to?

☐

Preli. Report

☒

Final Report

Date/Time File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.: (\$ 3940.40 )

200

10

210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17016633/R1tb

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 28-08-2017



Code : MSG

## 1. Policy Particulars :- OWN DAMAGE

|              |                       |                |            |
|--------------|-----------------------|----------------|------------|
| Insured Veh. |                       | Veh. Inspected | SJP 8431J  |
| Policy No.   | D27279275QMX          | Coverage (\$)  | 0.00       |
| Claim No.    | 527379                | Excess (\$)    | 500.00     |
| Assign From  | MERIMEN (CLARA MILAH) | Assign Date    | 28/08/2017 |

## 2. Vehicle Particulars & Condition

|              |        |              |   |
|--------------|--------|--------------|---|
| Make & Model |        | c.c          | 0 |
| Engine No.   | HIDDEN | Year of Reg. |   |
| Chassis No.  |        | Colour       |   |
| Odometer     | -      | Steering     |   |
| Brakes       |        | Modification |   |
| General      |        |              |   |

## 3. Conditions of Tyres

|                | Size | Make | Balance |
|----------------|------|------|---------|
| R/H Front Tyre |      |      | mm      |
| L/H Front Tyre |      |      | mm      |
| R/H Rear Tyre  |      |      | mm      |
| L/H Rear Tyre  |      |      | mm      |

## 4. Description of Damages

|  |  |
|--|--|
|  |  |
|--|--|

## 5. General Information

|                |                                                                             |                 |            |
|----------------|-----------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 21/08/2017                                                                  | Inspection Date | 28/08/2017 |
| Survey held at | SHU FATT AUTO WORKS<br>BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 |                 |            |

## 5a. Remarks

|                                                                    |
|--------------------------------------------------------------------|
| A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)                     |
| B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |

## ...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING |                             |                                     |                                |         |               |            | Status                               |
|--------------------------|-----------------------------|-------------------------------------|--------------------------------|---------|---------------|------------|--------------------------------------|
| Case                     | Notified                    | Est Submitted                       | Adj Assigned                   | Adj Rpt | Adj Submitted | Ins Auth'd |                                      |
| Main                     | 21 Aug 2017<br>Sendback Est | 24 Aug 2017<br>15:11<br>S\$6,033.70 | 28 Aug 2017<br>15:17<br>Assign |         |               |            | <b>New Assignment</b><br>Cancel Case |

|      |           |               |           |          |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

**CLAIM SUBFOLDER DETAILS**

Insured: SUN WU, ID: S2698889F, Tel: +6591285811, Email: FBAP8141@HOTMAIL.COM

|                   |             |                        |                                                                   |
|-------------------|-------------|------------------------|-------------------------------------------------------------------|
| Vehicle Reg. No.: | SJP8431J    | Date of Loss:          | 21/08/2017 07:00 - :59                                            |
| Claim Type:       | OD / 527379 | Policy/Cover Note No.: | D27279275QMX (Comprehensive)<br>Coverage: 14/04/2017 - 13/04/2018 |
|                   |             | Excess:                | S\$500.00                                                         |

Repairer: Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90, 159723 Bukit Merah - Tel: 62730119

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/08/2017]

Driver/Custodian: SUN WU (S2 / Male), NRIC: S2698889F, Tel: +6591285811

Adj Asg. Remarks: Please revert. Thanks

**ASSOCIATED MAIL RECEIVED**

View All Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS**

View All Search Tasks Create New Task Complete

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|

No results.

## Denise Tay (LKKAuto)

---

From: Denise Tay (LKKAuto)  
Sent: Tuesday, 29 August, 2017 5:16 PM  
To: 'shufatt@singnet.com.sg'  
Cc: SUR  
Subject: SJP 8431J OD MSIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJP 8431J (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**SJP8431J (527379)**

OD

Aug 21 2017 7:00AM

[SUN WU]

Shu Fatt Auto Works

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 29/08/2017 16:53 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$3253.20) - SJP8431J - Claim Handler: Clara Milah Yeo

Approved:3253.20.

### DOCUMENTS SUMMARY

There are no documents.

Text size + -

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 8889F

**Vehicle Details**

Vehicle No.: SJP8431J

Vehicle to be Exported: No

Intended De-registration  
Date: 29 Aug 2017

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2009

Engine No.: 3ZZ4874335

Chassis No.: MR053ZEE106142620

Maximum Power  
Output: 80.0 kW (107 bhp)

Open Market Value: \$16,990.00

Original Registration  
Date: 14 Apr 2009

First Registration Date: 14 Apr 2009

Transfer Count: 0

Actual ARF Paid: \$7,538.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes

PARF Eligibility Expiry  
Date: 13 Apr 2019

PARF Rebate Amount: \$4,145.00

**Intended COE Rebate Details**

COE Expiry Date: 13 Apr 2019

COE Category: A - Car (1600cc &amp; below)

COE Period(Years): 10

QP Paid: \$1,046.00

COE Rebate Amount: \$831.00

**Total Rebate Amount: \$4,976.00**

The information contained herein is correct as at 29 Aug 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 27 Aug 2017 at 01:09 AM

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                      |
|----------------------------|--------------------------------------|
| Date Of Report             | 21/08/2017 11:33                     |
| Date Of Accident           | 21/08/2017 07:30                     |
| Exact Location Of Accident | JUNCTION OF WILKINSON RD & ARTHUR RD |
| Country/State of Loss      | SINGAPORE                            |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJP8431J             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | SUN WU               |
| NRIC No                     | S2698889F            |
| Email Address               | FBAP8141@HOTMAIL.COM |
| Mobile Phone No             | (LOCAL) +65-91285811 |
| Alternative Phone No        | OFFICE-91285811      |

### Vehicle Particulars

|                                                                              |             |
|------------------------------------------------------------------------------|-------------|
| Manufacturer                                                                 | TOYOTA      |
| Model                                                                        | ALTIS       |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE     |
| Are you claiming under your own insurance policy for repair to your vehicle? | YES         |
| If No, Please state action to be taken                                       |             |
| Vehicle Category                                                             | PRIVATE CAR |

### Insurance Company

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                        |
| Fleet Policy              | NO                                   |
| Policy Number             | D27279275QMX                         |
| Cover Note Number         |                                      |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | SUN WU               |
| NRIC No              | S2698889F            |
| Date Of Birth        | 03/01/1965           |
| Occupation           | INDOOR               |
| Date Of Driving Pass | 03/01/2009           |
| Driving Experience   | 8 YEARS AND 7 MONTHS |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-91285811 |
| Fax Number           |                      |
| Contact Number       | OFFICE-91285811      |
| EEmail Address       | FBAP8141@HOTMAIL.COM |

Approximate Age

Injuries Sustain

Injured person in which vehicle? SKT8999E

Were seat belts worn? YES

Was injured conveyed to hospital by ambulance? YES

Address

Postcode

Sketch Plan Pg. 2


Describe Circumstances of the Accident

Today morning I drive my car to send my son for school when I

Refer to police report No: T/20170821/2044.

Declaration

We declare the foregoing particulars are true in every respect.

 21/08/17  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

CW  
Witnessed by Reporting Centre Personnel



**SINGAPORE  
POLICE FORCE**



T/20170821/2044

2 of 3

Police Station Of Origin:  
Queenstown N.P.C  
3 Queensway #01-03 SINGAPORE 149073  
Tel No: 1800-4719999

Report No. T/20170821/2044

## CONTINUATION OF REPORT

|                                   |                        |                                        |                                   |
|-----------------------------------|------------------------|----------------------------------------|-----------------------------------|
| <b>Details of Person Involved</b> |                        |                                        |                                   |
| Any Pedestrian Involved: No       |                        |                                        |                                   |
| No. of Pedestrians Injured: NIL   |                        | Use of Pedestrian Crossing: NA         |                                   |
| <b>Driver</b>                     |                        |                                        |                                   |
| Name                              | SUN WU                 | ID No.                                 | S2698889F                         |
| Related Vehicle                   | SJP8431J (Car)         | Contact No.                            | 91285811                          |
| Hospital/Clinic                   | NIL                    | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL   |
| Date Treatment                    | NIL                    | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL                    | Degree of Injury                       | NIL                               |
| <b>Other Person Involved</b>      |                        |                                        |                                   |
| Name                              | Unknown                | ID No.                                 | NIL                               |
| Related Vehicle                   | SKT8999E (Car)         | Contact No.                            | NIL                               |
| Hospital/Clinic                   | TAN TOCK SENG HOSPITAL | Class of Driving Licence & Expiry Date | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                    | NIL                    | Date Discharge                         | NIL                               |
| No. of Days granted Medical Leave | NIL                    | Degree of Injury                       | Slight                            |

**Brief Details.**

On 21/08/1018, at about 7.30 a.m., I was driving my own vehicle(SJP8431J, Silver Corola Altis) along Arthur Road towards Lyndhurst Road approaching the cross junction of Wilkinson Road, with my son inside my car as I am sending him to the school. I stopped at the stop line, and when the traffic was clear, I drove forward. Suddenly, noticed a fast moving vehicle on the left side and I engaged my brake. I was not able to stopped in time and the front part of my car hit the right side of the said car that was driving along Wilkinson Road. The said car bears a registration number SKT8999E, black Honda Vezel. The said car then swerved and it loses control and it was turn over to the right side. My son and I were not injured. Some passer by called for the ambulance for assistance and the said driver managed to get out of the car on her own. I did not managed to exchange any particulars as the said driver was with the ambulance and was informed to me that the driver was injured and will be conveyed to Tan Tock Seng Hospital.

A few minutes later, the police came as well and they advised me to make a traffic accident report with reference to report number G/20170821/0071, In-charge case, IO Daniel Yan. That is all.



# 樹發汽車修理廠 SHU FATT AUTO WORKS

JRC Auto.

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065  
Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

## PARTICULARS OF CLAIM

|                               |                                             |                       |                    |
|-------------------------------|---------------------------------------------|-----------------------|--------------------|
| Claim Type:                   | OD (OWN DAMAGE)                             | Ref. No:              | WSK/JW/SF-SJP8431J |
| Policy No:                    | D27279275QMX                                | Date of Loss:         | 21/08/2017         |
| Vehicle Reg. No.:             | SJP8431J                                    | Driveable?            |                    |
| Driver Age/Info:              | 52 / MALE                                   | Party At Fault:       | UNKNOWN            |
| TP Injury Involved?           | YES                                         | Third Party Involved? | YES                |
| Insured/Claimant:             | SUN WU                                      | Contact No:           | +6591285811        |
| Driver:                       | SUN WU                                      |                       |                    |
| Make/Model:                   | TOYOTA COROLLA ALTIS, 1.6 E (A)             | Vehicle Reg. Date:    | 14/04/2009         |
| Vehicle Colour:               | BLACK                                       | Chassis No:           | MR053ZEE106142620  |
| Engine No:                    | 3ZZ4874335                                  |                       |                    |
| Odometer:                     | 44521 KM                                    |                       |                    |
| Paint Type:                   |                                             |                       |                    |
| Total Loss?                   | NO                                          |                       |                    |
| Est. Duration of Repair (day) | 9                                           |                       |                    |
| Description of Accident/Loss  | REFER TO POLICE REPORT NO. T/20170821/2044. |                       |                    |
| Present Location:             | SHU FATT AUTO WORKS (HQ)                    |                       |                    |

| COST OF CLAIMS                      | Amount          |
|-------------------------------------|-----------------|
| Parts                               | 3,653.70        |
| Miscellaneous Items                 | 0.00            |
| Labour                              | 2,380.00        |
| Paintwork Labour                    | 0.00            |
| Towing                              | 0.00            |
| <b>Calculated Gross Total (S\$)</b> | <b>6,033.70</b> |
| <b>- Excess (S\$)</b>               | <b>500.00</b>   |
| <b>(S\$)</b>                        | <b>5,533.70</b> |
| <b>+ GST 7.00% (S\$)</b>            | <b>387.36</b>   |
| <b>Nett Amount (S\$)</b>            | <b>5,921.06</b> |

This claim is handled by: SHUFATT USER 3

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS****Reference**

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 24 Aug 2017)

**Parts:** 143      **TOYOTA COROLLA ALTIS 1.6 E (A)** (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** Shu Fatt Auto Works/SJP8431J/24/08/2017 15:11

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

| No. | Qty | Part No. | Particulars                        | %Disc    | %Depr | Amount             |
|-----|-----|----------|------------------------------------|----------|-------|--------------------|
| 1   | 1   |          | *Front bonnet                      | 0.00     | 0.00  | *310.00 FB         |
| 2   | 10  |          | *Front bonnet insulator clips      | 0.00     | 0.00  | *25.00 FAE         |
| 3   | 1   |          | *Front bonnet rubber               | 0.00     | 0.00  | *25.00 FAE         |
| 4   | 1   |          | *Front bonnet lock                 | 0.00     | 0.00  | *45.00 FB          |
| 5   | 2   |          | *Front headlights                  | 150 0.00 | 0.00  | RH-2300.00 FLH-CRA |
| 6   | 2   |          | *Front fenders                     | 0.00     | 0.00  | *280.00 FR         |
| 7   | 2   |          | *Front fender cowlings             | 0.00     | 0.00  | *120.00 FDE        |
| 8   | 12  |          | *Left front fender cowlings clips  | 0.00     | 0.00  | *18.00 FAE         |
| 9   | 12  |          | *Right front fender cowlings clips | 0.00     | 0.00  | *18.00 FAE         |
| 10  | 2   |          | *Front fender VVTi emblem          | 0.00     | 0.00  | *30.00 FAE         |
| 11  | 1   |          | *Front grille                      | 0.00     | 0.00  | *110.00 FCA        |
| 12  | 1   |          | *Front grille logo                 | 0.00     | 0.00  | *35.00 FAE         |
| 13  | 8   |          | *Front grille clips                | 0.00     | 0.00  | *12.00 FAE         |
| 14  | 1   |          | *Front support panel               | 0.00     | 0.00  | *280.00 FAE ? Pt   |
| 15  | 1   |          | *Front bumper                      | 0.00     | 0.00  | *170.00 FAE        |
| 16  | 1   |          | *Front bumper reinforcement        | 0.00     | 0.00  | *130.00 FAE        |
| 17  | 2   |          | *Front bumper brackets             | 18 0.00  | 0.00  | *36.00 FAE         |
| 18  | 12  |          | *Front bumper clips                | 0.00     | 0.00  | *18.00 FAE         |
| 19  | 2   |          | *Front bumper side retainers       | 0.00     | 0.00  | *60.00 FAE         |
| 20  | 1   |          | *Front bumper lower grille         | 0.00     | 0.00  | *50.00 FAE         |
| 21  | 1   |          | *Front bumper top rubber           | 0.00     | 0.00  | *30.00 FAE         |
| 22  | 6   |          | *Front bumper top rubber clips     | 0.00     | 0.00  | *15.00 FAE         |
| 23  | 1   |          | *Left front fog light              | 0.00     | 0.00  | *95.00 FAE         |
| 24  | 1   |          | *Left front fog light garnish      | 0.00     | 0.00  | *80.00 FAE         |
| 25  | 1   |          | *Left front fog light bulb         | 0.00     | 0.00  | *35.00 FAE         |
| 26  | 1   |          | *Front lower engine cover          | 0.00     | 0.00  | *45.00 FAE         |
| 27  | 10  |          | *Front lower engine cover clips    | 0.00     | 0.00  | *15.00 FAE         |
| 28  | 1   |          | *Front radiator                    | 0.00     | 0.00  | *480.00 FAE        |
| 29  | 1   |          | *Front air con condenser           | 0.00     | 0.00  | *420.00 FAE        |
| 30  | 1   |          | *Front number plate                | 0        | 0.00  | *45.00 FS          |
| 31  | 1   |          | *Coolant                           | 0        | 0.00  | *15.00 FS          |

F=Franchise part. S=SpcNett.

|                                     |                 |
|-------------------------------------|-----------------|
| Sub Total (\$\$)                    | 3,327.00        |
| + Margin on L,N Items 10.00% (\$\$) | 326.70          |
| <b>Total Parts (\$\$)</b>           | <b>3,653.70</b> |

Shu Fatt Auto Works/SJP8431J/24/08/2017 15:11. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                                                                                                                                                                                                                           | Lab.Type                                             | Amount       |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|--------------|
| <b>Labour Items</b>     |                                                                                                                                                                                                                                       |                                                      |              |
| 1                       | To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt wheel house, rt frt wheel house, rt frt fender, frt lower member, renew frt bonnet, frt support panel, frt fender, frt lights, frt bumper & assembly. | New <sup>600X</sup><br>Replace support panel - 800 ✓ | 1,050.00 ✓   |
| 2                       | To respray damaged parts.                                                                                                                                                                                                             | New                                                  | 1,050.00 900 |
| 3                       | To remove frt radiator, air con condenser to facilitate repairs fill coolant, air con freon, compressor oil and assembly.                                                                                                             | New                                                  | 280.00 100?! |
| Gross Labour Cost (S\$) |                                                                                                                                                                                                                                       |                                                      | 2,380.00     |

Shu Fatt Auto Works/SJP8431J/24/08/2017 15:11. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
Hp 90010068

7 days

P/P

28/08/17 @ 1550

EXCESS: 500

REVERT

Resurvey b p paint

**REPAIR DETAILS****Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2017)  
 Parts: 143 TOYOTA COROLLA ALTIS 1.6 E (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Shu Fatt Auto Works/SJP8431J/24/08/2017 15:11  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

| No. | Qty | Part No. | Particulars                        | %Disc | %Depr | Amount          |
|-----|-----|----------|------------------------------------|-------|-------|-----------------|
| 1   | 1   |          | *Front bonnet                      | 0.00  | 0.00  | *310.00 FBT     |
| 2   | 10  |          | *Front bonnet insulator clips      | 0.00  | 0.00  | *25.00 FAL      |
| 3   | 1   |          | *Front bonnet rubber               | 0.00  | 0.00  | *25.00 FAL      |
| 4   | 1   |          | *Front bonnet lock                 | 0.00  | 0.00  | *45.00 FBT      |
| 5   | 2   |          | *Front headlights LH               | 0.00  | 0.00  | *300.00 FLH-CRA |
| 6   | 2   |          | *Front fenders                     | 0.00  | 0.00  | *280.00 FR      |
| 7   | 2   |          | *Front fender cowlings             | 0.00  | 0.00  | *120.00 FDE     |
| 8   | 12  |          | *Left front fender cowlings clips  | 0.00  | 0.00  | *18.00 FAL      |
| 9   | 12  |          | *Right front fender cowlings clips | 0.00  | 0.00  | *18.00 FAL      |
| 10  | 2   |          | *Front fender VVTi emblem          | 0.00  | 0.00  | *30.00 FAL      |
| 11  | 1   |          | *Front grille                      | 0.00  | 0.00  | *110.00 FCA     |
| 12  | 1   |          | *Front grille logo                 | 0.00  | 0.00  | *35.00 FAL      |
| 13  | 8   |          | *Front grille clips                | 0.00  | 0.00  | *12.00 FAL      |
| 14  | 1   |          | *Front support panel               | 0.00  | 0.00  | *280.00 FBT     |
| 15  | 1   |          | *Front bumper                      | 0.00  | 0.00  | *170.00 FTUR    |
| 16  | 1   |          | *Front bumper reinforcement        | 0.00  | 0.00  | *130.00 FBT     |
| 17  | 2   |          | *Front bumper brackets             | 0.00  | 0.00  | *36.00 FAL      |
| 18  | 12  |          | *Front bumper clips                | 0.00  | 0.00  | *18.00 FAL      |
| 19  | 2   |          | *Front bumper side retainers       | 0.00  | 0.00  | *60.00 FAL      |
| 20  | 1   |          | *Front bumper lower grille         | 0.00  | 0.00  | *50.00 FAL      |
| 21  | 1   |          | *Front bumper top rubber           | 0.00  | 0.00  | *30.00 FAL      |
| 22  | 6   |          | *Front bumper top rubber clips     | 0.00  | 0.00  | *15.00 FAL      |
| 23  | 1   |          | *Left front fog light              | 0.00  | 0.00  | *95.00 FCA      |
| 24  | 1   |          | *Left front fog light garnish      | 0.00  | 0.00  | *60.00 FAL      |
| 25  | 1   |          | *Left front fog light bulb         | 0.00  | 0.00  | *35.00 F        |
| 26  | 1   |          | *Front lower engine cover          | 0.00  | 0.00  | *45.00 F        |
| 27  | 10  |          | *Front lower engine cover clips    | 0.00  | 0.00  | *15.00 F        |
| 28  | 1   |          | *Front radiator                    | 0.00  | 0.00  | *480.00 F       |
| 29  | 1   |          | *Front air con condenser           | 0.00  | 0.00  | *420.00 F       |
| 30  | 1   |          | *Front number plate                | 0     | 0.00  | *45.00 FS       |
| 31  | 1   |          | *Coolant                           | 0     | 0.00  | *15.00 FS       |

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 3,327.00  
 + Margin on L,N Items 10.00% (\$\$) 326.70  
**Total Parts (\$\$) 3,653.70**

Shu Fatt Auto Works/SJP8431J/24/08/2017 15:11. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                                                                                                                                                                                                                           | Lab.Type                                                    | Amount                  |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------|-------------------------|
| <u>Labour Items</u>     |                                                                                                                                                                                                                                       |                                                             |                         |
| 1                       | To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt wheel house, rt frt wheel house, rt frt fender, frt lower member, renew frt bonnet, frt support panel, frt fender, frt lights, frt bumper & assembly. | New <sup>600</sup><br>Replace support panel <sup>800?</sup> | 1,050.00                |
| 2                       | To respray damaged parts.                                                                                                                                                                                                             | New                                                         | 1,050.00 <sup>900</sup> |
| 3                       | To remove frt radiator, air con condenser to facilitate repairs fill coolant, air con freon, compressor oil and assembly.                                                                                                             | New                                                         | 280.00 <sup>100?</sup>  |
| Gross Labour Cost (S\$) |                                                                                                                                                                                                                                       |                                                             | 2,380.00                |

Shu Fatt Auto Works/SJP8431J/24/08/2017 15:11. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul  
Hp 90010068

1 days

P/P

28/08/17 P1550

EXCESS: 500

REVERT

Resurvey b/p paint

31/8/2017 SP in red line, HIC  
fence for repair  
item & systems. Repair  
fence handle

**REPAIR DETAILS****Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 31 Aug 2017)  
**Parts:** 143      TOYOTA COROLLA ALTIS 1.6 E (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SJPB4311)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

| No.                                       | Qty | Part No. | Particulars             | %Disc | %Depr | Amount             |
|-------------------------------------------|-----|----------|-------------------------|-------|-------|--------------------|
| 1                                         | 2   |          | *Bonnet hinges<br>berit | 0.00  | 0.00  | *60.00 F <i>bt</i> |
| <b>Sub Total (S\$)</b>                    |     |          |                         |       |       | <b>60.00</b>       |
| <b>+ Margin on L,N Items 10.00% (S\$)</b> |     |          |                         |       |       | <b>6.00</b>        |
| <b>Total Parts (S\$)</b>                  |     |          |                         |       |       | <b>66.00</b>       |

Report was unsubmitted during this print-out.  
 Generated using **Merimen e-Claims IEAS**

*tyghis*  
 6/9/17

Parts: 1014.00

+10%: 191.40

2105.40

Stef: 35.00

2140.40

labour: 1800.00

3940.40



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 9417 9791 / 9745 9936



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 9417 9792



Dept Direct: 9417 9794

Dept Direct: 9417 9795

Dept Direct: 9417 9796

Dept Direct: 9417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

**SHU FATT AUTO WORKS**  
BLK 1009 #01-90 BUKIT MERAH LANE 3  
S(159723)

SINGAPORE 159723  
TEL : 62730119 FAX : 62707065  
ATTN : PAT/ JULIA

**TAX INVOICE** : AR201709-01213  
DATE : 04/09/2017  
CUSTOMER ID : SHU001  
VEH REG. NO. : SJP8431J  
TERMS : 30 days  
PO NO.  
PAGE NO. : Page 1 of 1  
CURR. : SGD

| SQ STOCKID                            | DESCRIPTION                      | StkLoc | QTY | U/PRICE | AMOUNT |
|---------------------------------------|----------------------------------|--------|-----|---------|--------|
| 1. T90467-T0014/09050<br>ZSU60 ZRE171 | (2) FRT BONET INSULATOR CLIP     | WH     | 10  | 2.50    | 25.00  |
| 2. T90467-07166<br>JB33/ACV30/31R     | CLIP FOR SIMIL.D (2) + (4) + (2) | WH     | 34  | 1.50    | 51.00  |
| 3. T52161-16010<br>ALL MODEL          | BUMPER CLIP (12) + (13)          | WH     | 20  | 1.50    | 30.00  |
| 4. T75443-06151<br>ALL MODEL          | VVTI EMBLEM (10)                 | WH     | 1   | 30.00   | 30.00  |

SUB-TOTAL : 136.00  
ADD GST 7.00 % 9.52

E. & O.E

TOTAL AMOUNT SGD : 145.52

[P] 06/09/2017 1:02:02PM

[E] 04/09/2017 3:19:46PM

Goods Sold are not refundable for Cash.  
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : SAM



This is computer generated document.  
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



# 日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6746 9938



Dept Direct: 6305 9610

Dept Direct: 6305 9811

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9705

Dept Direct: 6417 9796

Dept Direct: 6417 9

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

SHU FATT AUTO WORKS  
BLK 1009 #01-90 BUKIT MERAH LANE 3  
S(159723)

SINGAPORE 159723  
TEL: 62730119 FAX: 62707065  
ATTN: PAT/ JULIA

TAX INVOICE : AR201708-17425  
DATE : 30/08/2017  
CUSTOMER ID : SHU001  
VEH REG. NO. : SJP8431J  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

| SQ STOCKID                            | DESCRIPTION                            | StkLoc       | QTY | U/PRICE | AMOUNT |
|---------------------------------------|----------------------------------------|--------------|-----|---------|--------|
| 1. T81170-02720<br>ALTIS-ZZE141       | (5) HEAD LAMP L.H 08"                  | U1<br>I.2-V1 | 1   | 150.00  | 150.00 |
| 2. T52021-02100/1<br>ALTIS-ZZE121     | (16) FRT BUMPER REINFORCEMENT          | U1<br>I.1-C8 | 1   | 130.00  | 130.00 |
| 3. T90467-05063-C0<br>ZZE141 ALTIS"08 | (22) RETAINER, FR BUMPER, UPPER CENTRE | U1           | 6   | 2.50    | 15.00  |
|                                       | SUPPLIER                               |              |     |         |        |

SUB-TOTAL : 295.00  
ADD GST 7.00 % 20.65

E. & O.E

TOTAL AMOUNT SGD : 315.65

[P] 30/08/2017 2:10:30PM

[E] 30/08/2017 1:52:44PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : SAM



This is computer generated document.  
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580


Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SHU FATT AUTO WORKS  
BLK 1009 #01-90 BUKIT MERAH LANE 3  
S(159723)

SINGAPORE 159723  
TEL : 62730119 FAX : 62707065  
ATTN : PAT/ JULIA

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6365 9610

Dept Direct: 6365 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper ( Made in Korea ),  
Forch ( Made in Germany )  
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201708-17636  
DATE : 30/08/2017  
CUSTOMER ID : SHU001  
VEH REG. NO. : SJP8431J  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

| SQ STOCKID                      | DESCRIPTION              | StkLoc           | QTY | U/PRICE | AMOUNT |
|---------------------------------|--------------------------|------------------|-----|---------|--------|
| 1. T57142-12100<br>ZZE121 ALTIS | (2) FRT BUMPER/BACKET LH | U1<br>I.2-E.11-F | 1   | 18.00   | 18.00  |

SUB-TOTAL : 18.00  
ADD GST 7.00 % 1.26

E. & O.E

TOTAL AMOUNT SGD : 19.26

[P] 30/08/2017 4:51:54PM

[E] 30/08/2017 4:51:37PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : SAM



\* AR201708-17636 \*

This is computer generated document.  
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:  
48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9701 / 6746 9309



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 971

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

SHU FATT AUTO WORKS  
BLK 1009 #01-90 BUKIT MERAH LANE 3  
S(159723)

SINGAPORE 159723  
TEL: 62730119 FAX: 62707065  
ATTN: PAT/ JULIA

TAX INVOICE : AR201708-17422  
DATE : 30/08/2017  
CUSTOMER ID : SHU001  
VEH REG. NO. : SJP8431J  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 2  
CURR : SGD

| SQ | STOCKID                      | DESCRIPTION                    | StkLoc           | QTY | U/PRICE | AMOUNT |
|----|------------------------------|--------------------------------|------------------|-----|---------|--------|
| 1  | T53301-12A50/02230<br>ZZE141 | ① FRT BONET                    | PA<br>PL2-N1-02A | 1   | 310.00  | 310.00 |
| 2  | T53381-02140<br>ZZE141       | ③ BONNET SEAL                  | PA<br>PL2-D1-06A | 1   | 25.00   | 25.00  |
| 3  | T53510-02380/1<br>ZZE141     | ④ FRT BONNET LOCK              | PA<br>PL2-J1-05A | 1   | 45.00   | 45.00  |
| 4  | T53875-12460/02270<br>ZZE141 | ⑦ { FRT FENDER LINER RH(02270) | PA<br>PL2-J1-08S | 1   | 60.00   | 60.00  |
| 5  | T53876-12440<br>ZZE141       | { FRT FENDER LINER LH(12440)   | PA<br>PL2-J1-09S | 1   | 60.00   | 60.00  |
| 6  | T53100-02310<br>ALTIS-ZZE141 | ⑪ FRT GRILLE 08"               | PA<br>PL2-A1-110 | 1   | 110.00  | 110.00 |
| 7  | T52119-02850<br>ZZE141       | ⑮ FRT BUMPER 08"               | PA<br>PL4-E1-28  | 1   | 170.00  | 170.00 |

CONTINUE NEXT PAGE

P] 30/08/2017 2:17:31PM

[E] 30/08/2017 1:52:32PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 8746 9039



Dept Direct: 6305 9010

Dept Direct: 6306 9011

Dept Direct: 6417 9792



Dept Direct: 6417 8794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Saliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

SHU FATT AUTO WORKS  
BLK 1009 #01-90 BUKIT MERAH LANE 3  
S(159723)

SINGAPORE 159723  
TEL : 62730119 FAX : 62707065  
ATTN : PAT/ JULIA

TAX INVOICE : AR201708-17422  
DATE : 30/08/2017  
CUSTOMER ID : SHU001  
VEH REG. NO. : SJP8431J  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 2 of 2  
CURR : SGD

| SQ  | STOCKID                         | DESCRIPTION                 | StkLoc           | QTY | U/PRICE | AMOUNT |
|-----|---------------------------------|-----------------------------|------------------|-----|---------|--------|
| 8.  | T53201-02270<br>ZZE141 ALTIS"08 | (14) RAD SUPPORT ASSY       | PA<br>PL2-A1-12A | 1   | 280.00  | 280.00 |
| 9.  | T53112-02190<br>ZZE141 ALTIS"08 | (80) GRILLE RAD LOWER       | PA<br>PL2-A1-231 | 1   | 50.00   | 50.00  |
| 10. | T53395-12050<br>AZE156 BLADE    | (21) FRT BUMPER TOP RUBBER  | PA<br>PL1-A1-166 | 1   | 30.00   | 30.00  |
| 11. | T81220-02120/1<br>ZZE141        | (22) FOG LAMP LH            | PA<br>PL2-F1-13A | 1   | 95.00   | 95.00  |
| 12. | SPZ060-12059<br>ZZE141          | (24) FOG LAMP ( CHORME ) LH | PA<br>PL2-K1-04G | 1   | 60.00   | 60.00  |

SUB-TOTAL : 1,295.00  
ADD GST 7.00 % 90.65

E. & O.E TOTAL AMOUNT SGD : 1,385.65

[P] 30/08/2017 2:17:31PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 30/08/2017 1:52:32PM

JAE Auto Pte. Ltd.

Sales Executive : SAM

This is computer generated document.  
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 979

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).  
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SHU FATT AUTO WORKS  
BLK 1009 #01-90 BUKIT MERAH LANE 3  
S(159723)

SINGAPORE 159723  
TEL: 62730119 FAX: 62707065  
ATTN: PAT/ JULIA

TAX INVOICE : AR201708-17642  
DATE : 30/08/2017  
CUSTOMER ID : SHU001  
VEH REG. NO. : SJP8431J  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR : SGD

| SO STOCKID                      | DESCRIPTION                   | StkLoc           | QTY | U/PRICE | AMOUNT |
|---------------------------------|-------------------------------|------------------|-----|---------|--------|
| 1. T75301-12380/02050<br>ZZE141 | (12) RAD GRILLE EMBLEM(12380) | PA<br>PL2-G1-06D | 1   | 35.00   | 35.00  |

SUB-TOTAL : 35.00  
ADD GST 7.00 % 2.45

E & OE TOTAL AMOUNT SGD: 37.45

[P] 30/08/2017 5:17:50PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 30/08/2017 4:56:55PM

JAE Auto Pte. Ltd.

Sales Executive: SAM

This is computer generated document.  
No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Bld 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 6030



Dept Direct: 6305 9610

Dept Direct: 6305 8611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9798

Dept Direct: 6417 9

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),  
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

SHU FATT AUTO WORKS  
BLK 1009 #01-90 BUKIT MERAH LANE 3  
S(159723)

SINGAPORE 159723  
TEL: 62730119 FAX: 62707065  
ATTN: PAT/ JULIA

**TAX INVOICE** : AR201708-17664  
**DATE** : 30/08/2017  
**CUSTOMER ID** : SIU001  
**VEH REG. NO.** : SJP8431J  
**TERMS** : 30 days  
**PO NO.** :  
**PAGE NO.** : Page 1 of 1  
**CURR.** : SGD

| SQ STOCKID                | DESCRIPTION      | StkLoc         | QTY | U/PRICE | AMOUNT |
|---------------------------|------------------|----------------|-----|---------|--------|
| 1. T51451-02100<br>ZZE141 | ENGINE COVER CTR | U1<br>SUPPLIER | 1   | 75.00   | 75.00  |

SUB-TOTAL : 75.00  
ADD GST 7.00 % 5.25

E. & O.E

TOTAL AMOUNT SGD : 80.25

[P] 30/08/2017 5:10:12PM

[E] 30/08/2017 5:09:36PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : SAM



This is computer generated document.  
No signature is required.

ORIGINAL

Goods Received in Good Order

*CW*

Signature / Co Stamp / Date



日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710  
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672  
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS  
Dept Direct: 6417 9791 / 6745 9838



Dept Direct: 8305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 97

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),  
Forch (Made in Germany)  
Spark plug: Nippon Denso, NGK (Made in Japan)

SHU FATT AUTO WORKS  
BLK 1009 #01-90 BUKIT MERAH LANE 3  
S(159723)

SINGAPORE 159723  
TEL : 62730119 FAX : 62707065  
ATTN : PAT/ JULIA

TAX INVOICE : AR201708-18076  
DATE : 31/08/2017  
CUSTOMER ID : SHU001  
VEH REG. NO. : SJP8431J  
TERMS : 30 days  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR. : SGD

| SQ STOCKID                             | DESCRIPTION        | StkLoc          | QTY | U/PRICE | AMOUNT |
|----------------------------------------|--------------------|-----------------|-----|---------|--------|
| 1. T53410-12550/02060<br>NZE141 ZZE141 | FRT BONET HINGE RH | U1<br>I.2-D4-I. | 1   | 30.00   | 30.00  |
| 2. T53420-02060/12520<br>ZZE141 NZE141 | FRT BONET HINGE LH | U1<br>I.2-D4-I. | 1   | 30.00   | 30.00  |

SUB-TOTAL : 60.00  
ADD GST 7.00 % 4.20

E. & O.E

TOTAL AMOUNT SGD : 64.20

[P] 31/08/2017 2:27:22PM

[E] 31/08/2017 2:26:50PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : SAM



This is computer generated document.  
Signature is required.

Goods

Signature / Co Stamp / Date

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |                             |                                            |                                      |                                      |                                |            |                                                 |
|--------------------------|-----------------------------|--------------------------------------------|--------------------------------------|--------------------------------------|--------------------------------|------------|-------------------------------------------------|
| Case                     | Notified                    | Est Submitted                              | Adj Assigned                         | Adj Rpt                              | Adj Submitted                  | Ins Auth'd | Status                                          |
| Main                     | 21 Aug 2017<br>Sendback Est | 24 Aug 2017<br>15:11<br><b>S\$6,033.70</b> | 28 Aug 2017<br>15:17<br>Edit Adj Rpt | <b>S\$3,940.40</b><br>Edit Estimates | <b>S\$3,940.40</b><br>View Rpt |            | <b>Pending for Survey Report</b><br>Cancel Case |
|                          | 31 Aug 2017<br>15:08        | 06 Sep 2017<br>15:06<br><b>S\$66.00</b>    | 06 Sep 2017<br>15:06                 |                                      |                                | (Combined) | <b>Combined with Main</b><br>Uncombine Suppl.   |
| Supp #1                  |                             |                                            |                                      |                                      |                                |            |                                                 |

|      |           |               |           |          |
|------|-----------|---------------|-----------|----------|
| Main | Reference | Claim Details | Documents | Show All |
|------|-----------|---------------|-----------|----------|

#### CLAIM SUBFOLDER DETAILS

**Insured:** SUN WU, ID: S2698889F, Tel: +6591285811, Email: FBAP8141@HOTMAIL.COM

**Vehicle Reg. No.:** SJP8431J **Date of Loss:** 21/08/2017 07:00 - :59

**Claim Type:** OD / 527379 **Policy/Cover Note No.:** D27279275QMX (Comprehensive)  
Coverage: 14/04/2017 - 13/04/2018

**Excess:** S\$500.00

**Repairer:** Shu Fatt Auto Works (HQ) Block 1009 Bukit Merah Lane 3, #01-90, 159723 Bukit Merah - Tel: 62730119

**Handling Insurer:** MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Clara Milah Yeo]

**Adjuster:** LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 27/09/2017]

**Driver/Custodian:** SUN WU (52 / Male), NRIC: S2698889F, Tel: +6591285811

**Adj Asg. Remarks:** Please revert. Thanks

#### ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- MSIG\_SG (21/11/2017): Alert - Adj Mandate Approved (S\$3940.40) - SJP8431J - Claim Handler: Clara Milah...
- MSIG\_SG (29/08/2017): Alert - Adj Mandate Approved (S\$3253.20) - SJP8431J - Claim Handler: Clara Milah...

#### ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Claim Documents

SJP8431J (527379)

OD

Aug 21 2017 7:00AM

[SUN WU]

Shu Fatt Auto Works

|                                                                                                   |                |                                     |                                                                                                |                                     |
|---------------------------------------------------------------------------------------------------|----------------|-------------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| <a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> |                |                                     | <b>View</b> <a href="#">Use Viewer</a>                                                         |                                     |
| <b>Assessment Reports</b>                                                                         |                |                                     | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                                                                                                | Finalized On   | Shu Fatt Auto Works (HQ)            | <b>Thumbnail</b>                                                                               | <b>Print</b>                        |
| 1                                                                                                 | 21/08/17 12:33 | <b>Accident Statement</b>           |  Load HTM   |                                     |
| 2                                                                                                 | 24/08/17 15:11 | <b>Repairer Estimates</b>           |  Load HTM   |                                     |
| 3                                                                                                 | 06/09/17 15:06 | <b>Repairer Estimates Suppl. #1</b> |  Load HTM   |                                     |
| No                                                                                                | Finalized On   | LKK Auto Consultants Pte Ltd (HQ)   | <b>Thumbnail</b>                                                                               | <b>Print</b>                        |
| 1                                                                                                 | 29/08/17 11:41 | <b>Adjuster Immediate Advice</b>    |  Load HTM   |                                     |
| 2                                                                                                 | 21/11/17 10:41 | <b>Adjuster Immediate Advice</b>    |  Load HTM   |                                     |
| <b>Photos/Images</b>                                                                              |                |                                     | 3 per page                                                                                     | <input checked="" type="checkbox"/> |
| No                                                                                                | Finalized On   | Shu Fatt Auto Works (HQ)            | <b>Thumbnail</b>                                                                               | <b>Print</b>                        |
| 1                                                                                                 | 24/08/17 15:05 | 1                                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 2                                                                                                 | 24/08/17 15:05 | 2                                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 3                                                                                                 | 24/08/17 15:05 | 3                                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 4                                                                                                 | 24/08/17 15:05 | 4                                   |  Load JPG   | <input checked="" type="checkbox"/> |
| 5                                                                                                 | 24/08/17 15:05 | 5                                   |  Load JPG  | <input checked="" type="checkbox"/> |
| 6                                                                                                 | 24/08/17 15:05 | 6                                   |  Load JPG | <input checked="" type="checkbox"/> |
| 7                                                                                                 | 24/08/17 15:05 | 7                                   |  Load JPG | <input checked="" type="checkbox"/> |
| 8                                                                                                 | 24/08/17 15:05 | 8                                   |  Load JPG | <input checked="" type="checkbox"/> |
| 9                                                                                                 | 24/08/17 15:05 | 9                                   |  Load JPG | <input checked="" type="checkbox"/> |
| 10                                                                                                | 24/08/17 15:05 | 10                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 11                                                                                                | 24/08/17 15:05 | 11                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 12                                                                                                | 24/08/17 15:05 | 12                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 13                                                                                                | 24/08/17 15:05 | 13                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 14                                                                                                | 24/08/17 15:05 | 14                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 15                                                                                                | 24/08/17 15:05 | 15                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 16                                                                                                | 24/08/17 15:05 | 16                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 17                                                                                                | 24/08/17 15:05 | 17                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 18                                                                                                | 24/08/17 15:05 | 18                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 19                                                                                                | 24/08/17 15:05 | 19                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 20                                                                                                | 24/08/17 15:05 | 20                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 21                                                                                                | 24/08/17 15:05 | 21                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 22                                                                                                | 24/08/17 15:05 | 22                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 23                                                                                                | 24/08/17 15:05 | 23                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 24                                                                                                | 24/08/17 15:05 | 24                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 25                                                                                                | 24/08/17 15:05 | 25                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 26                                                                                                | 24/08/17 15:05 | 26                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 27                                                                                                | 24/08/17 15:05 | 27                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 28                                                                                                | 24/08/17 15:05 | 28                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 29                                                                                                | 24/08/17 15:05 | 29                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 30                                                                                                | 24/08/17 15:05 | 30                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 31                                                                                                | 24/08/17 15:05 | 31                                  |  Load JPG | <input checked="" type="checkbox"/> |
| 32                                                                                                | 24/08/17 15:05 | 32                                  |  Load JPG | <input checked="" type="checkbox"/> |

|    |                 |                                   |  |           |                                     |
|----|-----------------|-----------------------------------|--|-----------|-------------------------------------|
| 33 | 24/08/17 15:05  | 33                                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 34 | 24/08/17 15:05  | 34                                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 35 | 24/08/17 15:05  | 35                                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 36 | 24/08/17 15:05  | tyre make                         |  | Load JPG  | <input checked="" type="checkbox"/> |
| 37 | 24/08/17 15:05  | tyre make                         |  | Load JPG  | <input checked="" type="checkbox"/> |
| 38 | 24/08/17 15:05  | tyre size                         |  | Load JPG  | <input checked="" type="checkbox"/> |
| 39 | 24/08/17 15:05  | Chassis Number                    |  | Load JPG  | <input checked="" type="checkbox"/> |
| 40 | 24/08/17 15:05  | Odometer Reading                  |  | Load JPG  | <input checked="" type="checkbox"/> |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  | Thumbnail | Print                               |
| 1  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 2  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 3  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 4  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 5  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 6  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 7  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 8  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 9  | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 10 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 11 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 12 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 13 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 14 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 15 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 16 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 17 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 18 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 19 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 20 | 29/08/17 11:42  | General View                      |  | Load JPG  | <input checked="" type="checkbox"/> |
| 21 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 22 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 23 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 24 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 25 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 26 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 27 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 28 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 29 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 30 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 31 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 32 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 33 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 34 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 35 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 36 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 37 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 38 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 39 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 40 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 41 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |
| 42 | 21/11/17 10:37  | Reinspection Photo                |  | Load JPG  | <input checked="" type="checkbox"/> |

|                      |                 |                                   |            |           |                                     |
|----------------------|-----------------|-----------------------------------|------------|-----------|-------------------------------------|
| 43                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 44                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 45                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 46                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 47                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 48                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 49                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 50                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 51                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 52                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 53                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 54                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 55                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| 56                   | 21/11/17 10:37  | Reinspection Photo                |            | Load JPG  | <input checked="" type="checkbox"/> |
| <b>Documentation</b> |                 |                                   | 1 per page |           | <input checked="" type="checkbox"/> |
| No                   | Finalized On    | Shu Fatt Auto Works (HQ)          |            | Thumbnail | Print                               |
| 1                    | 24/08/17 15:09  | Certificate of Insurance          |            | Load PDF  |                                     |
| 2                    | 24/08/17 15:09  | Drivers Driving License           |            | Load PDF  |                                     |
| 3                    | 24/08/17 15:09  | parf value enquiry                |            | Load PDF  |                                     |
| 4                    | 24/08/17 15:09  | towing receipt                    |            | Load PDF  |                                     |
| No                   | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |            | Thumbnail | Print                               |
| 1                    | 21/11/17 10:36  | SUPPLEMENTARY                     |            | Load TIF  |                                     |
| 2                    | 21/11/17 10:36  | ESTIMATE (2)                      |            | Load PDF  |                                     |
| 3                    | 23/11/17 10:08  | Parts Invoice                     |            | Load PDF  |                                     |

## Linked Accident Report Documents

|                           |                |                          |                        |           |                                     |
|---------------------------|----------------|--------------------------|------------------------|-----------|-------------------------------------|
|                           |                |                          | <b>View</b> Use Viewer |           |                                     |
| <b>Assessment Reports</b> |                |                          | 1 per page             |           | <input checked="" type="checkbox"/> |
| No                        | Finalized On   | Shu Fatt Auto Works (HQ) |                        | Thumbnail | Print                               |
| 1                         | 21/08/17 12:33 | Accident Statement       |                        | Load HTM  |                                     |
| <b>Photos/Images</b>      |                |                          | 3 per page             |           | <input checked="" type="checkbox"/> |
| No                        | Finalized On   | Shu Fatt Auto Works (HQ) |                        | Thumbnail | Print                               |
| 1                         | 21/08/17 11:46 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 2                         | 21/08/17 11:46 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 3                         | 21/08/17 11:46 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 4                         | 21/08/17 11:46 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 5                         | 21/08/17 11:46 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 6                         | 21/08/17 11:46 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 7                         | 21/08/17 11:46 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 8                         | 21/08/17 11:46 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 9                         | 21/08/17 11:55 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 10                        | 21/08/17 11:55 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| 11                        | 21/08/17 11:55 | Accident Photo           |                        | Load JPG  | <input checked="" type="checkbox"/> |
| <b>Documentation</b>      |                |                          | 1 per page             |           | <input checked="" type="checkbox"/> |
| No                        | Finalized On   | Shu Fatt Auto Works (HQ) |                        | Thumbnail | Print                               |
| 1                         | 21/08/17 12:25 | Sketch Plan              |                        | Load TIF  |                                     |

## Documents Checklist

|                                              |  |  |       |      |       |
|----------------------------------------------|--|--|-------|------|-------|
| <b>DOCUMENTS CHECKLIST</b>                   |  |  | Reset | Save | Print |
| There are no document checklists configured. |  |  |       |      |       |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG17016633/R1TB2

Date: 23/11/2017

## REFERENCE

Insured/Claimant: SUN WU Policy No: D27279275QMX  
Date of Loss: 21/08/2017 Nature of Claim: OD Claim No: 527379

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJP8431J  
Make & Model: TOYOTA COROLLA ALTIS, 1.6 E (A) Engine No: 3ZZ4874335  
Reg. Date: 14/04/2009 (Man. Year: 2009) Chassis No: MR053ZEE106142620  
Colour: Grey Odometer: 44521 km  
Engine Capacity: 1598 cc  
Market Value/New Car Price: S\$25,000.00  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS               | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------|------------|------------|------------|--------|
| Parts                        | 3,719.70   | 2,140.40   | 1,579.30   | 42.46  |
| Miscellaneous Items          | 0.00       | 0.00       | 0.00       |        |
| Labour                       | 2,380.00   | 1,800.00   | 580.00     | 24.37  |
| Paintwork Labour             | 0.00       | 0.00       | 0.00       |        |
| Towing                       | 0.00       | 0.00       | 0.00       |        |
| Calculated Gross Total (S\$) | 6,099.70   | 3,940.40   | 2,159.30   | 35.40  |
| - Excess (S\$)               | 500.00     | 500.00     | 0.00       | 0.00   |
| (S\$)                        | 5,599.70   | 3,440.40   | 2,159.30   | 38.56  |
| + GST 7.00/7.00% (S\$)       | 391.98     | 240.83     | 151.15     | 38.56  |
| Nett Amount (S\$)            | 5,991.68   | 3,681.23   | 2,310.45   | 38.56  |

## INSPECTION

Date of Assignment: 28/08/2017

Date Inspected: 28/08/2017 Inspected At:

Shu Fatt Auto Works (HQ)  
Block 1009 Bukit Merah Lane 3, #01-90  
Singapore 159723

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

|               |                                                                                                                                                                              |                                                                  |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------|
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 23 Nov 2017)                    |
| Parts:        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 E (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                |
| Print Code:   | (Unsubmitted, no print-code for SJP8431J)                                                                                                                                    |                                                                  |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                  |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *                                                                                                      |                                                                  |

## Recommended Parts

| No.                     | Qty | Part No. Particulars               | Condition                     | Repairer's | Amount    |
|-------------------------|-----|------------------------------------|-------------------------------|------------|-----------|
| 1                       | 1   | *Front bonnet                      | Bent                          | 310.00 F   | *310.00 F |
| 2                       | 10  | *Front bonnet insulator clips      | Necessary                     | 25.00 F    | *25.00 F  |
| 3                       | 1   | *Front bonnet rubber               | Necessary                     | 25.00 F    | *25.00 F  |
| 4                       | 1   | *Front bonnet lock                 | Bent                          | 45.00 F    | *45.00 F  |
| 5                       | 1   | *Front headlights                  | O/S Serviceable / N/S Cracked | 300.00 F   | *150.00 F |
| 6                       | 2   | *Front fenders                     | Repair                        | 280.00 F   | *- F      |
| 7                       | 2   | *Front fender cowlings             | Deformed                      | 120.00 F   | *120.00 F |
| 8                       | 12  | *Left front fender cowlings clips  | Necessary                     | 18.00 F    | *18.00 F  |
| 9                       | 12  | *Right front fender cowlings clips | Necessary                     | 18.00 F    | *18.00 F  |
| 10                      | 2   | *Front fender VVTi emblem          | Necessary                     | 30.00 F    | *30.00 F  |
| 11                      | 1   | *Front grille                      | Cracked                       | 110.00 F   | *110.00 F |
| 12                      | 1   | *Front grille logo                 | Necessary                     | 35.00 F    | *35.00 F  |
| 13                      | 8   | *Front grille clips                | Necessary                     | 12.00 F    | *12.00 F  |
| 14                      | 1   | *Front support panel               | Bent                          | 280.00 F   | *280.00 F |
| 15                      | 1   | *Front bumper                      | Torn                          | 170.00 F   | *170.00 F |
| 16                      | 1   | *Front bumper reinforcement        | Bent                          | 130.00 F   | *130.00 F |
| 17                      | 1   | *Front bumper brackets             | Necessary                     | 36.00 F    | *18.00 F  |
| 18                      | 12  | *Front bumper clips                | Necessary                     | 18.00 F    | *18.00 F  |
| 19                      | 2   | *Front bumper side retainers       | Not Necessary                 | 60.00 F    | *- F      |
| 20                      | 1   | *Front bumper lower grille         | Missing                       | 50.00 F    | *50.00 F  |
| 21                      | 1   | *Front bumper top rubber           | Cut                           | 30.00 F    | *30.00 F  |
| 22                      | 6   | *Front bumper top rubber clips     | Necessary                     | 15.00 F    | *15.00 F  |
| 23                      | 1   | *Left front fog light              | Cracked                       | 95.00 F    | *95.00 F  |
| 24                      | 1   | *Left front fog light garnish      | Missing                       | 60.00 F    | *60.00 F  |
| 25                      | 1   | *Left front fog light bulb         | Serviceable                   | 35.00 F    | *- F      |
| 26                      | 1   | *Front lower engine cover          | Torn                          | 45.00 F    | *75.00 F  |
| 27                      | 10  | *Front lower engine cover clips    | Necessary                     | 15.00 F    | *15.00 F  |
| 28                      | 1   | *Front radiator                    | Serviceable                   | 480.00 F   | -         |
| 29                      | 1   | *Front air con condenser           | Serviceable                   | 420.00 F   | *- F      |
| 30                      | 1   | *Front number plate                | Scratched                     | 45.00 FS   | *35.00 FS |
| 31                      | 1   | *Coolant                           | Not Necessary                 | 15.00 FS   | *- FS     |
| <b>Supplementary #1</b> |     |                                    |                               |            |           |
| 32                      | 2   | *Bonnet hinges                     | Bent                          | 60.00 F    | *60.00 F  |

F=Franchise part, S=SpcNett.

|                                           |                 |                 |
|-------------------------------------------|-----------------|-----------------|
| Sub Total (\$\$)                          | 3,387.00        | 1,949.00        |
| + Margin on L,N Items 10.00/10.00% (\$\$) | 332.70          | 191.40          |
| <b>Total Parts (\$\$)</b>                 | <b>3,719.70</b> | <b>2,140.40</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                                                                                                                                                                                           | Lab.Type | Repairer's | Amount   |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>     |                                                                                                                                                                                                                                       |          |            |          |
| 1                       | To knock, straighten frt inner panel, frt lower panel, frt side panel, left frt wheel house, rt frt wheel house, rt frt fender, frt lower member, renew frt bonnet, frt support panel, frt fender, frt lights, frt bumper & assembly. | New      | 1,050.00   | 800.00   |
| 2                       | To respray damaged parts.                                                                                                                                                                                                             | New      | 1,050.00   | 900.00   |
| 3                       | To remove frt radiator, air con condenser to facilitate repairs fill coolant, air con freon, compressor oil and assembly.                                                                                                             | New      | 280.00     | 100.00   |
| Gross Labour Cost (S\$) |                                                                                                                                                                                                                                       |          | 2,380.00   | 1,800.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >