WITVEYOF :	Risul	ASSIGN	MENT (Office)		
Trumin From (Person):	Vimmala	of	msili	Date/Time	28082017 858cm
Estimated Cost			Bill to:		
OD FFP+WS To Inspect Vel	TP RES / OD RE	SLQ 5506		Insured:	
at Workshop n		Perfermance		Tel:	
		20: Old 1	ra Road		
Policy No:	C40 899C		Claim No:	527655	(0)(4 444-4)
Sum Insured:			Excess:	\$ (000.00	
Make of Veh:				D.O.A.	24082017
(Client's Record		HRS			ndorsement:
CA / REV		M Person Contac	oted:Tnthird	N Vehicle	DLOUT
NACOSTOC		M Person Contac	nate Tathlic	N Vehicle (E	
Date/Time:	OWLP FIOLE/18C	M Person Contact		n Vehicle(I)	
Date/Time:	Action/Instruction	Person Contact  ( / ) Estiv			
Date/Time:	Action/Instruction SLU 55ULT Rod preli	M Person Contact  ( / ) Estir	nate rennen		

REF: MSU7	7690B
	SSIGNMENT
rom: Date: PEOS DOIT	Veh No: SLQ SSOGT Yr Regn: 2017 / Sury Type: McGr / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
o Inspect Vehicle No: SLQ 5506T	Make: B.M.W 216 GROWT G.C 1496
t Workshop m/s Perfumun (	Colour BLACK A/C: Insured / Std / NI / NA
318 Alexandra Poud	Sp.Reading 632(7 T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:
Policy No.	C/No: WBAZE320465446298
Claims No.	Gen. Cond: Good / Fab / Poor / Burnt
Sum Insured: Excess: 4 1000-0	OD Steering: Inforder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Incorder / Jammed / Leaked / Burnt or
Make of Veh: Inthiran	Modi: Nil / SRim / STD A/Rim or
	Tyre Size: F: 265 55 R17
(Policy Condition)	X:
Remark: The veh had commenced its N/S C	BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: 146 K	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 24 68 17 D.O.I. 28 68 17
Lum Sum: % 3 Val.: Yes or No  CA / REV / REP. / 24 HRS	Des. of Damages Fin / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / Date: Person Contacted:	OUT The U/C / Chassis frame / Body Structure affected due to collision
Date / Time Action / Instruction	41
RECE	VED 2 7 JUN 2018
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 3  Resurvey No. of Trip: 1 Survey Fee:
1) typist : Final Report  Date/Time, File Return to?	Transportation: 100
2) Add	Fee:   : Site Insp (\$ )S+RSS  (0
82	: Interview (\$ ) Photos
Report Format : OD	: Tech. Invs (\$ ) Others
Lump-8um / I.B.I: (\$ 5 99 1.20)	: Weekend (\$ )
	TOTAL 210



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	THE RESERVE	Affiliated to Federation Internat	ionale Des Experts En Auto	mobile		
M:	SIG INSURANCE	(SINGAPORE) PTE LTD	Ref : CS/MSG1701			
16 #2	RAFFLES QUAY 4-01 HONG LEON	IG BLDG SINGAPORE 048581	Date: 28-08-2017 Code: MSG			
1.		Policy Particul	lars :- OWN DAMAGE			
	Insured Veh.		Veh. Inspected	SLQ 5506T		
	Policy No.	28990620QMY	Coverage (\$)	0.00		
	Claim No.	527655	Excess (\$)	1,000.00		
	Assign From	MERIMEN (VIMMALA)	Assign Date	28/08/2017		
2.	4 5 1 2 2 2 1 1 3 4 1	Vehicle Parti	culars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	(*)	Steering			
	Brakes		Modification			
	General			<del></del>		
		Condition	ons of Tyres	Old the State of t		
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
Sili	Constituted	Description	n of Damages			
III)	Participation (State	Consession				
	Accident Date	04/00/0049	Information	ALC: THE PERSON NAMED IN		
	Survey held at	PERFORMANCE MOTORS LTD	Inspection Date	28/08/2017		
	(50)	303 ALEXANDRA ROAD SINGAPORE 159941				
		The state of the s	marks			
	A)THE MARKET V	ALUE IS S\$(EST. AVERA E TO YOUR INSTRUCTIONS, WE	OF			

### LKK Auto Consultants Pte Ltd (Co,Reg,No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Vimmala D/O Raja Singam

Date: 27 Jun 2018

## Preliminary Advice

Vehicle No

: SLQ5506T

Accident Date

: 24/08/2017

Make

: BMW 216D

Policy No.

: 28990620QMY

: 28/08/2017

Excess

Assignment Date Date of Inspection

: 28/08/2017

Est. Duration of Repair

: S\$1,000.00

: 3.00

Inspection At

: PERFORMANCE MOTORS LIMITED (ALEXANDRA)

303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE

SINGAPORE 159941

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,014.35 (Include supplementary \$1,295.90 and check item)
Revised Amount	:S\$	5,091.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,091.20
Lump Sum Repair	:S\$	
Lump Sum Repair	:S\$	

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	146,000.00
COE / PARF Rebate	:S\$	62,736.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,264.00

#### Remarks

(	X	) The	vehicle	is	economical	for	repair.
---	---	-------	---------	----	------------	-----	---------

The above survey was conducted on a 'without prejudice' basis.

#### Note: This document has not been finalised.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Vimmala D/O Raja Singam

Date:

29 Aug 2017

## Preliminary Advice

Vehicle No

: SLQ5506T

Accident Date

: 24/08/2017

Make

: BMW 216D

Policy No.

: 28990620QMY

Assignment Date : 28/08/2017

Excess

: S\$1,000.00

Date of Inspection : 28/08/2017

Est. Duration of Repair

: 3.00

Inspection At

: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE

SINGAPORE 159941

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

s)	Repairer's Estimate (Gross
	Revised Amount
	Check Items (Estimated)
	Total
:S\$ :S\$ :S\$ :S\$	:S\$ :S\$

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	146,000.00
COE / PARF Rebate	:S\$	62,736.00
Salvage Value	:S\$	
Margin for Repair	:S\$	83,264.00

#### Remarks

1	( X )	The	vehicle	IS	economical	for	repair.

The above survey was conducted on a 'without prejudice' basis.

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	25 Aug 2017		28 Aug 2017 08:58 Assign				New Assign Cancel Ca	A STATE OF THE STA
	Main	Re	ference	Cla	im Details	Docum	ents	Show All
CLAIM S	UBFOLDER DET					The second secon	y insurer]	
Insured:		BALAKUMARA	N S/O KATHERA		KRISHNA, ID: S17			
Vehicle I	Reg. No.:	SLQ5506T		D	ate of Loss:		14:00 - :59	
Claim Ty	pe:	OD / 52765	5	P	olicy/Cover Note N		28990620QMY (Comprehensive) Coverage: 14/07/2017 - 13/07/2012	
					xcess: 303 Alexandra Road,	5\$1,000.00		
	g Insurer:	MSIG Insurar 65942471]		Pte. Ltd. (HQ	) - Tel: +65 6827 78			O Raja Singam
Adjuster		LKK Auto Cor	sultants Pte Ltd	(HQ) - Tel: 6	256-3561 [Imm		/00/201/]	
	Custodian:	JACINTA JAMU	NA RAJOO (51 / F	emale), NKI	C: S1737890B, Tel	or today at 9am. T	nank vou	
the state of the state of	THE RESERVE OF STREET	Web and the second second second		rner is waiting	at Periormance Piot	or today at sain i	renn your	
the state of the state of	. Remarks:	Please revert.	Urgent survey. Ow					
Adj Asg.	Remarks:		Urgent survey. Ov			View	All Com	pose Case Mail
Adj Asg.	ATED MAIL REC						All Com	pose Case Mail
Adj Asg.  ASSOCI  MSIG	ATED MAIL REC	CEIVED ): SLQ5506T (52				View	All Comp	

## **Print Received Message**

This mail is associated with:

\*SLQ5506T (527655)

OD Aug 24 2017 2:00PM

[BALAKUMARAN S/O KATHERAYSON RAMAKRISHNA]

Performance Motors Limited

From

MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 29/08/2017 16:16 PM.

To Subject LKK\_HQ

Alert - Adj Mandate Approved (S\$4585.45) - SLQ5506T - Claim Handler: Vimmala D/O Raja Singam

Approved:4585.45:Approved mandate \$4585.45 (including check items \$1468.85) before excess \$1000

## Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Tuesday, August 29, 2017 4:59 PM

To:

inthiran.thurasamy@simedarby.com.sg

Cc:

SUR

Subject:

SLQ 5506T

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SLQ 5506T (excess \$1000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Janice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Janice Lee (LKKAuto)

From:

PBSP <pml-pbsp@simedarby.com.sg>

Sent:

Thursday, October 19, 2017 1:32 PM

To:

Janice Lee (LKKAuto); Rasul (LKKAuto)

Subject:

FINAL REPORT / SLQ5506T

Attachments:

Final Report SLQ5506T.pdf; Final Report SLQ5506T\_2.pdf

Dear Rasul

We refer to the above and attached Final Report.

#### Please confirm COR as follows:

Total Labour :	3,123.00
Total Parts :	1,968.20
Total Labour & Parts :	5,091.20

Thank you.

Regards, Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Gender

Mobile Number

EMail Address

Fax Number Contact Number

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	25/08/2017 09:39
Date Of Accident	24/08/2017 14:30
Exact Location Of Accident	BT BATOK EAST AVE 3
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLQ5506T
Insured/Policyholder	
Name Of Registered Owner	BALAKUMARAN S/O KATHERAYSON RAMAKRISHNA
NRIC No	51737890B 14750 1065 W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84449173
Alternative Phone No	OFFICE-96951650
Vehicle Particulars	
Manufacturer	BMW
Model	216
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	JACINTA JAMUNA RAJOO
NRIC No	S1737890B
Date Of Birth	04/08/1966
Occupation	INDOOR
Date Of Driving Pass	03/04/1995
Driving Experience	22 YEARS AND 4 MONTHS
5 T-54 S S S S S S S S S S S S S S S S S S S	

FEMALE

(LOCAL) +65-84449173

(LOCAL) +65-96951650

CHRIS@CJSC.COM.SG

- Address

BLK 218 LOYANG AVE #01-06

Postcode

509066

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Was any body injured in the Accident?

NO NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

3

Number of Passengers (Including Driver)

**Details of Police Action** 

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SKD2088H

Vehicle Make/Model/Colour

BMW WHITE

Details Of Properties

Name of Driver

TAY BOON SUN

NRIC/Passport Number

S1601062F

Contact Number

Address

BLK 29A CHAI CHEE AVE #04-82

Postcode

461029

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

**Details of Witness** 

Name

Phone Number

Email Address

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the
  report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

& Drivers & Time

Driver's Signaldre (If driver is not the policyholder) / Date

SK02088H

Witnesseld by Reporting Centre Personnel

Sketch Plan

SLQSSO6T

### Sketch Plan Pg. 2

Desc	ribe Circumstances of the Accident	_
	was travelling along Bucit Ruto & East Ave 3, and accidentally his the bumper of the Car ahead of me Accident Ytook place on 24 Aug 2017 at around 2.3	_
	accidentally with the bumper of the car ahead of me	ti:
	Accident Stock place on 24 Aug 2017 at around 23	186
	negard five percent	-
		_
_		
		_
_		
		_
		_
-		_
- 17		_
_		
		_
		_
		_
_		
		_
3		

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Text size +

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

1065W

Vehicle Details

Vehicle No.:

SLQ5506T

Vehicle to be Exported: No

Intended De-registration 29 Aug 2017

Date:

Vehicle Make:

B.M.W.

Vehicle Model:

216D GRAN TOURER LED NAV 7 SEATER

Primary Colour:

Manufacturing Year:

2017

Engine No.:

31849925B37C15A

Chassis No.:

WBA2E320405H46298

Maximum Power

Output:

85.0 kW (113 bhp)

Open Market Value:

\$32,369.00

Original Registration

14 Jul 2017

First Registration Date:

14 Jul 2017

Transfer Count:

Actual ARF Paid:

\$27,317.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry

13 Jul 2027

PARF Rebate Amount: \$20,487.00 + 501 = 10 243.50

Intended COE Rebate Details

COE Expiry Date:

13 Jul 2027\_

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

QP Paid:

\$42,801.00

COE Rebate Amount:

\$42,249.00

Total Rebate Amount: \$62,736.00

The information contained herein is correct as at 29 Aug 2017

146,000 62,736 83,264

= 127,453,33

-127,453.53 + 102\$3.50

= 137,696,83

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer. Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions. Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | Privacy Statement | Terms of Use | Disclaimer | Rate the Website | Rate this e-Service Last updated on 27 Aug 2017 at 01:09 AM

JOME

NEW CARS

USED CARS

SELL CARS

MOTOR DIRECTORY

TOOLS & TIPS



## **GET JOBS FAST!**

## DOWNLOAD NOW



Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

7

Ways of Selling



Direct Owner ShirAd

**\*** 



Browse by Category

2 vehicles

BMW 216d

Model

Price

Depreciation

Any

2017

Anv

Eng Cap

Anv

Mileage

Any

Veh Type

Available

▼ 20 results/page

Search Selection

BMW 216d

Any \$132,800

\$12,920 /yr

27-Feb-2017

1,496 cc

6,100 km

Sort by Date Posted

Hatchback

Available

Tourer Fuel Type: Diesel (Euro 5 Engine and Above)

BMW 2 Series 216d Active

Latest BMW Front Wheel Drive Technology With Extreme Fuel Efficiency. Clad In Metallic Sporty Alpine White With Black Upholstery. Ample Space Of Head And Leg Room, Piles Of Luggages At The Boot. BMW 3...

Performance Premium Selection Limited

Posted: 27-Aug-2017 Tags: 2017 BMW 216d, BMW 216d, BMW, 216d, Used BMW

@ Details



BMW 2 Series 216d Active Tourer

\$126,800

\$12,360 /vr

26-Jan-2017

1,496 cc

9,900 km

Hatchback

Available

Fuel Type: Diesel (Euro 5 Engine and Above)

5 Years Warranty / 100,000km By PML. Cars Comes With 4 Years / 200,000km Free Servicing With PML. Hassle Free Car To Own. Low Maintenance For Next Owner, Pls Call For Viewing,

Posted: 01-Aug-2017 Tags: 2017 BMW 216d, BMW 216d, BMW, 216d, Used BMW

Details

Save this search criteria, to get email alerts whenever a match is found

Model

Depreciation

Eng Cap

Mileage

Veh Type

For old advertisements, view Expired ads

▼ results/page 20

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpank rates & car insurance. Find buy used BMW 216d, BMW 216d Singapore, used BMW 216d Singapore, used BMW 216d, used vehicles Singapore or even buy used BMW 216d Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on spCarMart.com are gathered from sources and based on algorithms that are believed by spCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current, spCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- · Home
- · New Car
- Used Car
- Sell Car Motoring Directory
- Products Guide
- Article Forum
- · Tool & Tip

dep: 12640 | pa year

- About Us
- Careers Contact Us
- Sitemap

© 2004-2017 sgCarMart. \*" ----- --- served.

- Terms of Service
- Personal Data Protection Statement

BMW Dealer

## Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

503. Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel 63170100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

280, Kampong Arang Road Bast Coast Centre Singapore 438180 Tel. 65190889 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel 63190528 (AfterSales) 63190533/330 (Motorrad) Fax, 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

#### ESTIMATE

Page No. : 1 of 2 Estimate No. : b1 43930 Date Estimated : 25/08/2017 Prepared By : Inthiran A/L Thurasamy 66 - ESTIMATE REPAIR FOR -- ACCOUNT -MSIG Insurance (S) Pte Ltd Sime Darby Services Private Limited 305 Alexandra Road 4 Shenton Way #21-01 SGX Centre 2 #02-01 Vantage Automotive Centre Singapore 068807 Singapore 159942 REGN. DATE MODEL MILEAGE REGN. NO. CHASSIS NO.

SLQ5506T	5H46298	14/07/2017	216d	G TOURER		0	
9	DESCRIPTION  To replace front bumper, air de attachments including knock e accident.		and		1275	850 3,82	LUE 5.00
	Painting front bumper.				~	934 1,03	8.00
	To check electrical wiring syst for proper function including a				V	150 17	7.00
	To remove old PDC assembly reconnect to new bumper incluproper function.				~		7.00
	Te supply front emboss numb	er plate.			109	74/8	3.00
	Sundries.				n	ec v 8	0.00
				Tot	al Labour 1:	5,38	0.00
	DESCRIPTION			QTY .	PRIC	CRACA	LUE

			2007-2002
DESCRIPTION	QTY	PRIC	VALUE
FRT IMPACT ABSORBER	1	46.60	CRA 46.60
GRILLE BUMPER MIDDLE CLOSED (PDC)	1	96.20	2- 96.20
RH FINISHER (LUXURY LINE)	1	58.70	SUC 2 58.70
LH SUPPORT FOG LAMP (GESCHLOSSEN)	1	49.70	49.70
RH SUPPORT FOG LAMP (GESCHLOSSEN)	1	49.70	49.70
FRT BUMPER PANEL PRIMED (PMA)	1	821.50	DE 821.50
GRILLE SIDE OPEN RH (LUXURY LINE+PD	1	95.85	95.85
FRT BUMPER TOP CARRIER	1	359.90	X812? 359.90
GROMMET	2	0.75	1.50
AIR DUCT	1	185.90	CPA 185.90
PLAQUE 82MM	1	67.80	67.80
ULTRASONIC SENSOR BLACK	2	242.65	× 50c7 485.30
DECOUPING RING PDC TORQUE CONVERTER	4	4.95	x 82 7 19.80
	Tot	al Parts	: 2,338.45

BMW Dealer

## Performance Motors Limited

A member of the Sime Darby Group Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road Sime Darby Performance Centre Singapore 189941

Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770

East Coast Centre Singapore 438180

Tel. 63190888 (AfterSales) Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

Date Estimated

: b1 43930

: 25/08/2017

Prepared By

: Inthiran A/L Thurasamy

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SLQ5506T

5H46298

14/07/2017

216d G TOURER

0

Page No. : 2 of 2

LKK Auto Consultants hence notify . the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 20001	Claim No.  Excess S\$ [600]  Sign  Authorised Yes / C	veri
TE FLOTO BY SURVEY	OR Yes/No PUL Yes/No	

Labour 1 Parts	:M8.45	5,380.00 2,338.45
Labour 2 Excess	:	0.00
Total GST @ 7%	:	540.29
Grand Total	:	8,258.74

<sup>\*\*</sup> THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

<sup>\*\*</sup> PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

## Performance Motors Limited

A member of the Sime Derby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X.



### FINAL REPORT

Estimate No. : b1 43930

Page No. :

Date Estimated : 25/08/2017

Prepared By Inthiran A/L Thurasamy

REPAIR FOR -

- ACCOUNT -

Sime Darby Services Private Limited

MSIG Insurance (S) Pte Ltd

305 Alexandra Road

4 Shenton Way

#02-01 Vantage Automotive Centre

#21-01 SGX Centre 2 Singapore 068807

Singapore 159942

REGN. NO.	CHASSIS NO.	REGN DATE	MODEL		M L	EAŒ	
SLQ5506T	5H46298	14/07/2017	216d G TOURE	R	0		
DESCRIPTION			ORIGIN	AL PRICE	DISC. %	NETT	
To replace front knocking out de	t bumper and attachments caused by the acc	ents, air duct include ident		1275.00		1,275.00	
To spray paint f	ront bumper.			934.00		934.00	
To check electri for proper functi	ical wiring systems at t on including adjustme	he front section nts of headlights.		150.00		150.00	
To remove old F reconnect to ne proper function.	PDC assembly, replace w bumper including co	e damaged parts and onduct checks for		150.00		150.00	
To supply front	emboss number plate.			83.00		83.00	
	ge air cooler include re irs and conducting che			451.00		451.00	80
Sundries				80.00		80.00	
DESCRIPTION			UNIT PRICE	QTY	DISC. %	NETT	
# CHARGE AIR CO FRT IMPACT A FRT BUMPER F # LICENCE PLAT # FRT LH GRILLE # FRT RH GRILLE GROMMET AIR DUCT PLAQUE 82MM	BSORBER PANEL PRIMED (PMA E HOLDER * E (LUXURY) * E (LUXURY) *	)	609.75 46.60 821.50 67.25 83.95 83.95 0.75 185.90 67.80	1.00 1.00 1.00 1.00 1.00 1.00 2.00 1.00		609.75 <b>A</b> 46.60 821.50 67.25 <b>C</b> 83.95 <b>S</b> 1.50 185.90 67.80	1
# SUPPLEMENTAR	YITEMS		Total Labour: Total Parts: Total Labour & I Deduction for E: Total Repair Co: GST @7%:	xcess:	ess:	3,123.00 1,968.20 5,091.20 1,000.00 4,091.20	
			Cond Total			286.38	

Grand Total:

## LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way, #21-01 SGX Centre 2

Singapore 068807

Our File No:

CS/MSG17016649/R1RBN2

Date:

28/06/2018

REFERENCE

Date of Loss:

Insured/Claimant: RAMAKRISHNA

BALAKUMARAN S/O KATHERAYSON

Policy No:

28990620QMY

Nature of Claim:

OD

Claim No:

527655

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

24/08/2017

Reg No:

SLQ5506T

Black

Make & Model: Reg. Date:

BMW 216D, 1.5 D Gran Tourer (F46) (A)

14/07/2017 (Man. Year: 2017)

Engine No: Chassis No: 31849925B37C15A WBA2E320405H46298

Odometer:

3217 km

Colour: **Engine Capacity:** 

1496 cc S\$146,000.00

Market Value/New Car Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

205/55R17

Rear Tyre Size:

205/55R17

Front Left Side:

Michelin 6 mm

Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

Front Right Side: Michelin 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,346.35	2,131.20	1,215.15	36.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,668.00	2,960.00	2,708.00	47.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,014.35	5,091.20	3,923.15	43.52
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	8,014.35	4,091.20	3,923.15	48.95
+ GST 7.00/7.00% (S\$)	561.00	286.38	274.62	48.95
Nett Amount (S\$)	8,575.35	4,377.58	4,197.77	48.95

INSPECTION

Date of Assignment:

28/08/2017

Date Inspected:

28/08/2017 Inspected At:

Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre Singapore 159941

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 28 Jun 2018) Part Source: MRM-SG

BMW 216D 1.5 D Gran Tourer (F46) (A) (Catalogue:Merimen Singapore 1.0) M1-MPV Parts:

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SLQ5506T) These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Recommende	ed Parts
------------	----------

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT IMPACT ABSORBER	Cracked	46.60 FS	*46.60 FS
2	1		*GRILLE BUMPER MIDDLE CLOSED (PDC)	Serviceable	96.20 FS	*- FS
3	1		*RH FINISHER (LUXURY LINE) *LH SUPPORT FOG LAMP (GESCHLOSSEN)	Serviceable Serviceable	58.70 FS 49.70 FS	*-FS *-FS
5	1		*RH SUPPORT FOG LAMP (GESCHLOSSEN) *FRT BUMPER PANEL PRIMED (PMA)	Serviceable Deformed	49.70 FS 821.50 FS	*- FS *821.50 FS
7	1		*GRILLE SIDE OPEN RH (LUXURY LINE+PD) *FRT BUMPER TOP CARRIER	Serviceable Serviceable	95.85 FS 359.90 FS	*-FS *-FS
9	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
10	1		*AIR DUCT	Cracked	185.90 FS	*185.90 FS
11	1		*PLAQUE 82MM	Necessary	67.80 FS	*67.80 FS
12	2		*ULTRASONIC SENSOR BLACK	Serviceable	485.30 FS	*-FS
13 14	4		*DECOUPING RING PDC TORQUE CONVERTER *CHARGE AIR COOLER	Serviceable Bent	19.80 FS 609.75 FS	*- FS *609.75 FS
15 16	1		*LICENCE PLATE HOLDER *FRT LH GRILLE (LUXURY)	Scratched Scratched	67.25 FS 83.95 FS	
17 18	1		*FRT RH GRILLE (LUXURY) *SUNDRIES	Scratched Necessary	83.95 FS 80.00 FS	
19	1		*FRONT EMBOSS NUMBER PLATE	Missing	83.00 FS	*83.00 FS
F=Fr	anchise	part. S=Spcl	Nett.	Total Parts (S\$)	3,346.35	2,131.20

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	lahour
Reconnended	Laboui

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REPLACE FRONT BUMPER AIR DUCT (INNER SUPPORT PANEL) AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSED BY ACCIDENT	New	3,825.00	1,275.00
2	PAINTING FRONT BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
5	TO REPLACE CHARGE AIR COOLER INCLUDE REMOVING ATTACHMENTS TO FACILITATE REPAIRS AND CONDUCTING CHECKS FOR FUNCTION	New	451.00	451.00
	Gross Labou	r Cost (S\$)	5,668.00	2,960.00
	Report was unsubmitted during	ng this print-out.		

< END OF ESTIMATES >