

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 43930
Date Estimated : 25/08/2017
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Sime Darby Services Private Limited
305 Alexandra Road
#02-01 Vantage Automotive Centre
Singapore 159942

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SLQ5506T	5H46298	14/07/2017	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, air duct include knocking out dents caused by the accident	1275.00		1,275.00	
To spray paint front bumper.	934.00		934.00	
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
To supply front emboss number plate.	83.00		83.00	
# To replace charge air cooler include removing attachments to facilitate repairs and conducting checks for function	451.00		451.00	
Sundries	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CHARGE AIR COOLER *	609.75	1.00		609.75
FRT IMPACT ABSORBER	46.60	1.00		46.60
FRT BUMPER PANEL PRIMED (PMA)	821.50	1.00		821.50
# LICENCE PLATE HOLDER *	67.25	1.00		67.25
# FRT LH GRILLE (LUXURY) *	83.95	1.00		83.95
# FRT RH GRILLE (LUXURY) *	83.95	1.00		83.95
GROMMET	0.75	2.00		1.50
AIR DUCT	185.90	1.00		185.90
PLAQUE 82MM	67.80	1.00		67.80

SUPPLEMENTARY ITEMS

Total Labour :	3,123.00
Total Parts :	1,968.20
Total Labour & Parts :	5,091.20
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	4,091.20
GST @7%:	286.38
Grand Total :	4,377.58