

ASS. EC. BY:

REF: CS / CTI 17016828 / R11602 Special Instruction:

Surveyor: Rosul

ASSIGNMENT (Office)

From (Person):

Joel Goh

of

CTI

Date/Time: 30082011 1135am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMB 3041Y

Insured:

SJA 858R

at Workshop m/s

Tower Transit

Tel:

9818 2143

of

21 Bulim Drive

Policy No:

DMHCSN1739611700

Claim No:

NM17D05036C02/B

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26082017

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

30082017 1207pm

Person Contacted:

Sharifan

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SMB 3041Y - CS / INC14008520 / K11bk3, D.O.A : 01/8/2013

SJA 858R - X

Part by Part \$5042.31 / 5days (Red: 801.19 : 13%)

Basul

REF:

2417K

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SMB 30414**
 at Workshop m/s **Tower Transit**
 of **21, Brunel Dr**
 Insured: **CTI/np**

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum.: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: **SMB 30414** Yr Regn: **2013 MAR**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **MAN NL 320F (A22)** c.c. **10518**Colour: **MULTI** A/C: Insured / Std / NI / NASp. Reading: **280097** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **WMAA2222507001754**

Gen. Cond: Good (Fals) / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

225/70 R22.5

R:

D/O

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal. **8** mm R/Bal. **8/8** mmL/Bal. **8** mm L/Bal. **8/8** mmD.O.A. **26/08/17** D.O.I. **30/08/17**Survey held at: **TOWER TRANSIT**Des. of Damages: Frt / Rear **O/S** / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 24 JUL 2018

[Signature]
 23/7/2018

Date/Time. File Pass to?

☐ : Preli. Report1) **23/7 Typist**☒ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: **5**Resurvey No. of Trip: **1**

Survey Fee:

150

Transportation:

) \$ + RS \$

) Photos

) Others

)

TOTAL

150Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Report Format: **TP**Lump Sum / I.B.I.: (\$ **5042.31**)

LP Auto Consultants Pte Ltd

51 Ubi Avenue 4, #01-01 Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Ref: 19-9607198R GST Reg. No. 19-9607198-R

Operation: Des Experts En Automobile	
Client: LTL	File: CS/CTI17016828/R1tb
3/2017	Date: 30-08-2017
SPI	File: CTI
1.	079900
THIRD PARTY CLAIM	
611700	Inspected SMB 3041Y
COI	Coverage (\$) 0.00
EL CO	Deductible (\$) 0.00
	Inspection Date 30/08/2017
	Condition
	0
	of Reg.
	ing
	ation
51	ures
	Balance
	mm
	mm
	mm
	mm
	Images
	ion
	on Date 30/08/2017
"JUDICE" BASIS.	
NOT AUTHORISED REPAIRS.	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Aug 2017		30 Aug 2017 11:35 Assign				<div>New Assignment</div> <div>Cancel Case</div>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TW PREMIUM AUTOMOBILE PTE LTD, Co. Reg. No.: -		
Main Claimant:	TOWER TRANSIT SINGAPORE PTE LTD, Co. Reg. No.: 201419417K		
Vehicle Reg. No.:	SMB3041Y	Date of Loss:	26/08/2017 14:00 - :59
Claim Type:	TP / SNM17D05036C02/8	Policy/Cover Note No.:	DMHCSN1739611700 (Third Party Only)
Vehicle Reg. No. (Insured):	SJA8598R	Policy No. (Claimant):	D-16086301MFBP
		Excess:	S\$0.00
Repairer:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot, 648170 Jurong West - Tel: 81688950		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]		
Claimant's Insurer:	First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/09/2017]		
Driver/Custodian (Insured):	NORAZMAN BIN MD KHAMIS (41 / Male), NRIC: S7603838D		
Adj Asg. Remarks:	NO ESTIMATES. ASSIGNED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2017 17:30
Date Of Accident	26/08/2017 14:50
Exact Location Of Accident	CLEMENTI AVENUE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB3041Y
Insured/Policyholder	
Name Of Registered Owner	TOWER TRANSIT SINGAPORE PTE LTD
Co Reg No	201419417K
Email Address	SHARIFAH@TOWERTRANSIT.SG
Mobile Phone No	
Alternative Phone No	OFFICE-68171747

Vehicle Particulars

Manufacturer	MAN
Model	NL320F (A22)-10.5 D ABS TURBO (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	D-16086301MFBP
Cover Note Number	

Driver

Name of Driver	LEE EAM SENG
NRIC No	S7161671A
Date Of Birth	24/07/1971
Occupation	OUTDOOR
Date Of Driving Pass	31/10/2001
Driving Experience	15 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 21

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJA8598R
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Clementi AV26
BS17379 Towards
BUKIT BATOK INT



Sketch Plan #2

Describe Circumstances of the Accident

I Bus Captain Lee Fann Sang (10496) was on ser duty 189 P02 on 26/8/17 driving Vehicle number SMG 3041 Y. At around 1450hrs I BC 10496 reported involved in an accident with a private Vehicle SJA 8598R at Clement Ave 6 BS 17379 towards to Bukit Batok Bus Interchange. While I was at bus stop with passenger activity (Alight & Boarding), Suddenly private car SJA 8598R hit my bus at my right side of rear to the Centre. My bus sustained right rear side body dented and scratches. Car SJA 8598R sustained left tyre punctured, front bumper scratches and side body scratches.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



TRANSIT ENGINEERING

BUS REGISTRATION NUMBER	SMB3041Y
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

	Part No.	Part or Item Description	Quantity	Total Cost
	77200023	RH SIDE PANEL R4	1	\$ 74 / 77.05
	77200026	RH SIDE PANEL R6	1	\$ 74 / 132.25
	77200027	RH SIDE PANEL R7	1	\$ 74 / 404.23
	77200028	RH SIDE PANEL R8	1	\$ 74 / 760.73
	77200049	COVER TAIL LAMP - O/S/R	1	\$ 694 / 389.85
	77200759	SIDE PANEL	1	\$ 74 / 78.20
	77200681	FLASHER ASSY - REAR	1	\$ Xm 178.25
				1842.31
			7% GST	\$ 136.05
			FINAL TOTAL COST	\$ 2,079.55

	LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)		TOTAL COST
	TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING & INSTALLATION OF VINYL)	3200	\$ 3800.00
	Repair		
	Hx 900w068		1842.31
	5 clump		3200.00
	30/08/17 @ 1515		5042.31
		7% GST	\$ 273.00
		FINAL TOTAL COST	\$ 4,173.00

5920 56

504350

ESTIMATED ACCIDENT REPAIR COST



SECTION 3: REPAIR DONE BY CONTRACTOR AFTER ASSESSMENT (CONTRACTOR COST)

TOTAL REPAIR COST BASED ON CONTRACTOR'S QUOTE	-
---	---

SECTION 4: ADMINISTRATIVE (OVERHEADS)

TOTAL OVERHEADS COST (10% OF PARTS & LABOUR)	-
--	---

SECTION 5: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST (INCLUSIVE OF LABOUR + 7% GST)	-
--	---

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	29/8/2017
		Date Out From Repairs	8/9/2017
BUS TYPE (SD / DD)	SD	Number of Days Under Repair	10
LOSS OF USE COST		\$	3,000.00

SECTION 8: ENGINEERING RECOVERY OF ACCIDENT BUS (ENGINEERING RECOVERY COST)

ENGINEERING RECOVERY COST	-
---------------------------	---

SUMMARY	
SECTION NO.	COST
1	\$ 2,079.55
2	\$ 4,173.00
3	-
4	-
5	-
6	-
7	\$ 3,000.00
8	-
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5+6+7+8)	\$ 9,252.55




































...CLAIM SUBFOLDER...(Pending for Survey Report)






















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Aug 2017		30 Aug 2017 11:35 Edit Adj Rpt	S\$5,042.31 Edit Estimates	S\$5,042.31 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TW PREMIUM AUTOMOBILE PTE LTD , Co. Reg. No.: -								
Main Claimant:	TOWER TRANSIT SINGAPORE PTE LTD , Co. Reg. No.: 201419417K								
Vehicle Reg. No.:	SMB3041Y	Date of Loss:	26/08/2017 14:00 - :59 [53 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D05036C02/8	Policy/Cover Note No.:	DMHCSN1739611700 (Third Party Only)						
Vehicle Reg. No. (Insured):	SJA8598R	Policy No. (Claimant):	D-16086301MFBP						
		Excess:	S\$0.00						
Repairer:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot, 648170 Jurong West - Tel: 81688950								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Joel Goh]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 11/09/2017]								
Driver/Custodian (Insured):	NORAZMAN BIN MD KHAMIS (41 / Male), NRIC: S7603838D								
Adj Asg. Remarks:	NO ESTIMATES. ASSIGNED AS SJE FOR WP PRS. KINDLY PROVIDE US WITH YOUR RECOMMENDATION								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB3041Y (SNM17D05036C02/8)**
[SJA8598R]
TP
TOWER TRANSIT SINGAPORE PTE LTD
Aug 26 2017 2:00PM
[TW PREMIUM AUTOMOBILE PTE LTD]
Tower Transit Singapore Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print	
1	28/08/17 17:41	Accident Statement	 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>	
34	23/07/18 13:56	General View	 Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>
38	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/07/18 13:56	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/07/18 13:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/07/18 13:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	23/07/18 13:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	23/07/18 13:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/08/17 11:36	OI GIA REPORT	 Load PDF	
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	28/08/17 17:41	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	28/08/17 17:41	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	28/08/17 17:41	Accident Statement	 Load HTM	
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tower Transit Singapore Pte Ltd (HQ)	Thumbnail	Print
1	28/08/17 17:41	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	28/08/17 17:41	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17016828/R1TB2

Date: 26/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN1739611700

Claimant Vehicle No: SMB3041Y Insured Vehicle No: SJA8598R

Date of Loss: 26/08/2017 Nature of Claim: TP Claim No: SNM17D05036C02/8

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMB3041Y**

Make & Model: MAN NL320F (A22), 10.5 D ABS TURBO (A) Engine No: 50333551983346

Reg. Date: 01/03/2013 (Man. Year: 2012) Chassis No: WMAA22ZZ5D7001754

Colour: Multi-colour Odometer: 280097 km

Engine Capacity: 10518 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Continental 8 mm Rear Left Side: Continental 8/8 mm

Front Right Side: Continental 8 mm Rear Right Side: Continental 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,020.56	1,842.31	178.25	8.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	3,200.00	700.00	17.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,920.56	5,042.31	878.25	14.83
+ GST 7.00/7.00% (S\$)	414.44	352.96	61.48	14.83
Nett Amount (S\$)	6,335.00	5,395.27	939.73	14.83

INSPECTION

Date of Assignment: 30/08/2017

Date Inspected: 30/08/2017 Inspected At: Tower Transit Singapore Pte Ltd (HQ)
21 Bulim Drive, Bulim Bus Depot
Singapore 648170

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jul 2018)	
Parts:	N/A	MAN NL320F (A22) 10.5 D ABS TURBO (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMB3041Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH SIDE PANEL R4	Bent	77.05 F	*77.05 F
2	1		*RH SIDE PANEL R6	Bent	132.25 F	*132.25 F
3	1		*RH SIDE PANEL R7	Bent	404.23 F	*404.23 F
4	1		*RH SIDE PANEL R8	Bent	760.73 F	*760.73 F
5	1		*COVER TAIL LAMP - O/S/R	Cracked	389.85 F	*389.85 F
6	1		*SIDE PANEL	Bent	78.20 F	*78.20 F
7	1		*FLASHER ASSY - REAR	Not Necessary	178.25 F	*- F

F=Franchise part.

Total Parts (S\$)	2,020.56	1,842.31
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE / REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING & INSTALLATION OF VINYL)	New	3,900.00	3,200.00
Gross Labour Cost (S\$)			3,900.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >