

ASS. No.

REF: CS/FCI17016869 / Grb⁰⁷

Special Instruction:

SUPERVISOR

ASSIGNMENT (Office)

From (Person): Aung Yin Min of FCI Date/Time: 30/8/17 3.28pm

Estimated Cost: Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC9146 H Insured: SHC0325C

at Workshop m/s: Progressive Tel: 67415336

of Blk 3022A Ubi Road / # 01-45/46

Policy No: Claim No: D17008347 MFSH

Sum Insured: Excess:

Make of Veh: (Client's Record) D.O.A. 26/08/17

CA / REV / REP. / REV 24 HRS 'wp' 25.08.2017 @ 9-9.30am

H.O.D. Endorsement:

Date/Time: 30/8/17 3.53pm Person Contacted: Pei Wern

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC9146 H -X
	SHC0325 -X
	Sent preli through email.

Xhel

REF: FCI

ASSIGNMENT

From _____ Date 25/9/17

Estimated Cost _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No SKC 9146 H

at Workshop mis Progressive Automotive

of Blk 3022A UBI Rd 1# 01-45/46, 048716

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess _____

(Client's Record)

Make of Veh _____

(Policy Condition) 9-9:30 am owner waiting

Remark. The veh had commenced its repair at the time of inspection.

Bal. or Market Value _____

IDAC Accident Rpt. _____ Consistent? Yes or No

GIA / PR Seen. _____ Consistent? Yes or No

Est. Repairs: 3 days Res. Yes or No

Lum Sum _____ % 3 Val. Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date _____ Person Contacted _____

Date / Time _____ Action / Instruction _____

Veh No. SKC 9146 H Yr Regn 14 Oct 2011

Type M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Picasso

Make Citroen C4 cc 1598

Colour Brown A.C. Insured / Std / NI / NA

Sp. Reading 46280 T. Radio: Insured / Std / NI / NA

Eng. No. _____

C. No. VF7UA5FV.8BJ710315

Gen. Cond Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi. Nil / S/Rim / STD A/Rim or

Tyre Size F: 215/50R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Road Stone

Front _____ Rear _____

R. Bal. 6 mm R. Bal. 6 mm

L. Bal. 6 mm L. Bal. 6 mm

D.O.A. _____ D.O.I. 25-09-17

Survey held at w/s 9:30 AM

Des. of Damages Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Confirm \$5,519.10, 3 days
Red: \$3365.80, 38%.

RECEIVED 16 JAN 2018

Date/Time, File Pass to? ☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1Report Format: TPLump Sum / I.B.I. (\$) 5519.10

Add Fee:

- ☐ Site Insp (\$)
- ☐ Interview (\$)
- ☐ Tech. Invs (\$)
- ☐ Weekend (\$)

Survey Fee

Transportation

) S - RS S

) Photos

) Others

TOTAL

160
50
50
72
332



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17016869/Grb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 30-08-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 0325C	Veh. Inspected	SKC 9146H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17008347MFSH	Excess (\$)	0.00	
Assign From	CWS (AUNG YIN MIN)	Assign Date	30/08/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/08/2017	Inspection Date		
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Your Ref: D17008347MFSH

Our Ref: CS/FCI17016869/Grb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKC 9146H

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/09/2017 at the premises of M/s PROGRESSIVE AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ 8,884.90
Revised Estimate Amount	: S\$ 5,519.10
"Check" Items Amount	: S\$
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:
The vehicle sustained damages
at front portion.



Yours faithfully
XING GUO QIANG
Automotive Assessor

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	29-08-2017	Our Ref No. D17008347MFSH
Accident Date	26-08-2017	Claim Type. Third Party
Insured Vehicle	SHC0325C	Third Party Vehicle. SKC9146H
Survey Location	BLK 3022A UBI ROAD 1 #01-45/46	
Contact Person.	LILY LIM	
Contact No.	67415336/ 0	Fax No. 67417208
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PROGRESSIVE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/227479)



PRI Documents



Close



PRI Header Details

Claim No	D17008347MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & PRI PTE LTD
Workshop Name	PROGRESSIVE AUTOMOTIVE PTE LTD (Contact Person : LILY LIM)	Survey Location & Contact Details	BLK 3022A UBI ROAD 1 #01-45/46 Mobile: 0 , Phone: 67415336 , Fax: 6741720 EmailId: BHLIM@PROGAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC0325C	TP Vehicle No	SKC91
PRI Recieved Date	29-08-2017 07:37:28 PM	Surveyor Appointed Date	30-08-2017 03:28:40 PM	Surveyor Accept Date	30-08-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	30-08-2017	Upload Survey Report *:	
-----------------------------	----------------------	----------------------	------------	-------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 7434J

Vehicle Details

Vehicle No.: SKC9146H

Vehicle to be Exported: No

Intended De-registration
Date: 25 Sep 2017

Vehicle Make: CITROEN

Vehicle Model: GRAND C4 PICASSO 1.6 SMT ABS EGS PSR

Primary Colour: Brown

Manufacturing Year: 2011

Engine No.: 10FJBS1254001

Chassis No.: VF7UA5FV8BJ710315

Maximum Power
Output: 115.0 kW (154 bhp)

Open Market Value: \$23,410.00

Original Registration
Date: 14 Oct 2011

First Registration Date: 14 Oct 2011

Transfer Count: 0

Actual ARF Paid: \$23,410.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 13 Oct 2021

PARF Rebate Amount: \$16,387.00

Intended COE Rebate Details

COE Expiry Date: 13 Oct 2021

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$50,289.00

COE Rebate Amount: \$20,361.00

Total Rebate Amount: \$36,748.00

The information contained herein is correct as at 25 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 17 Sep 2017 at 12:38 AM

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

25/9/17 SDO-

4/10/17 917 AM

M/S: CHRISTINA KWAN
1 AMBER ROAD #07-04
SINGAPORE 439845

ATTN: FIRST CAPITAL

Your Ref No: TP 0817-4715
Claim Type: Third Party
Accident Date: 26/08/2017
TP Veh Reg No: SHC325C

Estimate No: EST1502681
Date: 28 Aug 2017
Policy No: 2100276044
Veh Reg No: SKC9146H
Make/Model: CITROEN GRAND C4
PICASSO 1.6 SMT ABS
EGS PSR
Chassis No: VF7UA5FV8BJ10315
Engine No: 10FJBS1254001
Reg. Date: 14/10/2011

Estimate Repair Cost to Vehicle No :SKC9146H

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 BONNET <i>X Repair ?</i>	1,345.000	1 PC	1,345.00	
<i>X</i> BONNET CHROME MOULDING <i>?</i>	185.0000	1 PCS	185.00	
<i>cracked</i> <i>X</i> GRILLE INNER <i>?</i>	162.0000	1 PCS	162.00	
4 GRILLE CHROME MOULDING <i>BR</i>	187.0000	1 PCS	187.00	
5 FRONT BUMPER <i>DE</i>	1,458.000	1 PC	1,458.00	
6 FRONT BUMPER CLIPS	5.5000	10 PC	55.00	
7 FRONT BUMPER SIDE HOLDER - LH <i>MC</i>	156.0000	1 PC	156.00	
8 FRONT BUMPER SIDE HOLDER - RH <i>MC</i>	156.0000	1 PC	156.00	
9 FRONT BUMPER FOGLAMP CHROME - LH <i>MC</i>	278.0000	1 PCS	278.00	
<i>cracked</i> 10 FRONT BUMPER FOG LAMP - LH <i>?</i>	168.0000	1 PC	168.00	
11 FRONT BUMPER FOG LAMP - RH <i>X</i>	168.0000	1 PC	168.00	
<i>cracked</i> 12 FRONT BUMPER CENTRE GRILLE - TOP <i>?</i>	176.0000	1 PCS	176.00	
13 FRONT BUMPER TOP GRILLE - LH <i>MC</i>	158.0000	1 PCS	158.00	
<i>cracked</i> 14 FRONT BUMPER CENTRE GRILLE - LOWER <i>?</i>	215.0000	1 PCS	215.00	
15 FRONT BUMPER FOAM <i>?</i>	86.0000	1 PC	86.00	
16 FRONT BUMPER REINFORCEMENT <i>?</i>	465.0000	1 PC	465.00	
17 HEADLAMP ASSY - LH <i>SCR</i>	450.0000	1 PCS	450.00	
<i>cracked</i> 18 HEADLAMP ASSY - RH <i>?</i>	450.0000	1 PCS	450.00	
19 GRILLE TOP GARNISH <i>CPA</i>	178.0000	1 PCS	178.00	
20 GRILLE TOP GARNISH CLIPS <i>MC</i>	5.5000	4 PCS	22.00	
<i>X</i> SUPPORT PANEL ASSY <i>?</i>	368.0000	1 PCS	368.00	
22 FRONT FENDER COWLING - LH <i>TN</i>	145.0000	1 PC	145.00	
<i>X</i> FRONT FENDER COWLING - RH <i>?</i>	145.0000	1 PC	145.00	
24 FRONT FENDER COWLING CLIPS <i>MC</i>	5.5000	20 PCS	110.00	
<i>W. bin Tan</i> 25 FRONT FENDER PICASSO STICKER - LH <i>MC</i>	76.0000	1 PC	76.00	
26 FRONT FENDER PICASSO STICKER - RH <i>MC</i>	76.0000	1 PC	76.00	
			7,438.00	
		Less 10%	743.80	6,694.20
Labour				
27 TO KNOCK OUT DENTS, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	400?
28 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	600
29 TO CHECK WIRING	20.0000	1 JOB	20.00	?
30 TO REMOVE,REFIT CONDENSER & REFILL GAS	100.0000	1 JOB	100.00	?
31 TO TUFF-KOTE	60.0000	1 JOB	60.00	X

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO.201006949C

M/S : CHRISTINA KWAN
1 AMBER ROAD #07-04
SINGAPORE 439845

ATTN: FIRST CAPITAL

Your Ref No: TP 0817-4715
Claim Type: Third Party
Accident Date: 26/08/2017
TP Veh Reg No: SHC325C

Estimate No: **EST1502681**
Date: 05 Oct 2017
Policy No: 2100276044
Veh Reg No: **SKC9146H**
Make/Model: CITROEN GRAND C4
PICASSO 1.6 SMT ABS
EGS PSR
Chassis No: VF7UA5FV8BJ710315
Engine No: 10FJBS1254001
Reg. Date: 14/10/2011

Estimate Repair Cost to Vehicle No :SKC9146H

Description	U/Price	Quantity	Price <u>S\$</u>	Amount <u>S\$</u>
Supplementary Parts to Repair				
List Price				
FRONT BUMPER PAD - LH	165.0000	1 PC	165.00	
FRONT BUMPER REINFORCEMENT BRACKET - LH	158.0000	1 PC	158.00	
			323.00	
		Less 10%	32.30	290.70
			Total	S\$ 290.70
			GST Amount	S\$ 20.35
			Total Amount Payable	S\$ 311.05

For PROGRESSIVE AUTOMOTIVE PTE
LTD

AUTHORISED SIGNATURE

Missing
checked
2
5/9/2017

PROGRESSIVE AUTOMOTIVE PTE LTD

Bik 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : CHRISTINA KWAN
 1 AMBER ROAD #07-04
 SINGAPORE 439845

ATTN: FIRST CAPITAL

Your Ref No: TP 0817-4715
 Claim Type: Third Party
 Accident Date: 26/08/2017
 TP Veh Reg No: SHC325C

Estimate No: EST1502681
 Date: 28 Aug 2017
 Policy No: 2100276044
 Veh Reg No: SKC9146H
 Make/Model: CITROEN GRAND C4
 PICASSO 1.6 SMT ABS
 EGS PSR
 Chassis No: VF7UA5FV8BJ710315
 Engine No: 10FJBS1254001
 Reg. Date: 14/10/2011

Estimate Repair Cost to Vehicle No :SKC9146H

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 BONNET <i>X Repair -</i>	1,345.000	1 PC	1,345.00	
2 BONNET CHROME MOULDING <i>X NN</i>	185.0000	1 PCS	185.00	
3 GRILLE INNER <i>X / CFA</i>	162.0000	1 PCS	162.00	
4 GRILLE CHROME MOULDING <i>- BR</i>	187.0000	1 PCS	187.00	
5 FRONT BUMPER <i>- BR</i>	1,458.000	1 PC	1,458.00	
6 FRONT BUMPER CLIPS	5.5000	10 PC	55.00	
7 FRONT BUMPER SIDE HOLDER - LH <i>- } MCL</i>	156.0000	1 PC	156.00	
8 FRONT BUMPER SIDE HOLDER - RH <i>- }</i>	156.0000	1 PC	156.00	
9 FRONT BUMPER FOGLAMP CHROME - LH <i>- M's</i>	278.0000	1 PCS	278.00	
10 FRONT BUMPER FOG LAMP - LH <i>X / CFA</i>	168.0000	1 PC	168.00	
11 FRONT BUMPER FOG LAMP - RH <i>X NN</i>	168.0000	1 PC	168.00	
12 FRONT BUMPER CENTRE GRILLE - TOP <i>X / CFA</i>	176.0000	1 PCS	176.00	
13 FRONT BUMPER TOP GRILLE - LH <i>- M's</i>	158.0000	1 PCS	158.00	
14 FRONT BUMPER CENTRE GRILLE - LOWER <i>X / CFA</i>	215.0000	1 PCS	215.00	
15 FRONT BUMPER FOAM <i>X</i>	86.0000	1 PC	86.00	
16 FRONT BUMPER REINFORCEMENT <i>X NN</i>	465.0000	1 PC	465.00	
17 HEADLAMP ASSY - LH <i>- SCR</i>	450.0000	1 PCS	450.00	
18 HEADLAMP ASSY - RH <i>X / CFA</i>	450.0000	1 PCS	450.00	
19 GRILLE TOP GARNISH <i>- CFA</i>	178.0000	1 PCS	178.00	
20 GRILLE TOP GARNISH CLIPS <i>- MCL</i>	5.5000	4 PCS	22.00	
21 SUPPORT PANEL ASSY <i>X NN</i>	368.0000	1 PCS	368.00	
22 FRONT FENDER COWLING - LH <i>- TN</i>	145.0000	1 PC	145.00	
23 FRONT FENDER COWLING - RH <i>X NN</i>	145.0000	1 PC	145.00	
24 FRONT FENDER COWLING CLIPS <i>- MCL</i>	5.5000	20 PCS	110.00	
25 FRONT FENDER PICANSO STICKER - LH <i>- } MCL</i>	76.0000	1 PC	76.00	
26 FRONT FENDER PICANSO STICKER - RH <i>- }</i>	76.0000	1 PC	76.00	
			7,438.00	
		Less 10%	743.80	6,694.20
Labour				
27 TO KNOCK OUT DENTS, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	400
28 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	600
29 TO CHECK WIRING	20.0000	1 JOB	20.00	?
30 TO REMOVE, REFIT CONDENSER & REFILL GAS	100.0000	1 JOB	100.00	?
31 TO TUFF-KOTE	60.0000	1 JOB	60.00	X

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHRISTINA KWAN
1 AMBER ROAD #07-04
SINGAPORE 439845

ATTN: FIRST CAPITAL

Your Ref No: TP 0817-4715
Claim Type: Third Party
Accident Date: 26/08/2017
TP Veh Reg No: SHC325C

Estimate No: EST1502681
Date: 28 Aug 2017
Policy No: 2100276044
Veh Reg No: SKC9146H
Make/Model: CITROEN GRAND C4
PICASSO 1.6 SMT ABS
EGS PSR
Chassis No: VF7UA5FV8BJ710315
Engine No: 10FJBS1254001
Reg. Date: 14/10/2011

Estimate Repair Cost to Vehicle No :SKC9146H

Description	U/Price	Quantity	Price	Amount
			SS	SS
32 TO RESET CHECK LIGHT	120.0000	1 JOB	120.00	X nn
			1,900.00	1,900.00
Total				SS 8,594.20
Add GST @ 7%				601.59
Total Amount Payable				SS 9,195.79

TOTAL: SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED NINETY FIVE AND CENTS SEVENTY NINE ONLY

8884.90

3-4 Days.

part by part

before part photos.

Guo Qiang - 82880282

25/9/17

For PROGRESSIVE AUTOMOTIVE PTE
LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road I #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

25/9/1 SDO-

4/10/17 9:15 AM

M/S: CHRISTINA KWAN
1 AMBER ROAD #07-04
SINGAPORE 439845

ATTN: FIRST CAPITAL

Estimate No: EST1502681
Date: 28 Aug 2017
Policy No: 2100276044
Veh Reg No: SKC9146H
Make/Model: CITROEN GRAND C4
PICASSO 1.6 SMT ABS
EGS PSR
Chassis No: VF7UA5FV8BJ710315
Engine No: 10FJBS1254001
Reg. Date: 14/10/2011

Your Ref No: TP 0817-4715
Claim Type: Third Party
Accident Date: 26/08/2017
TP Veh Reg No: SHC325C

Estimate Repair Cost to Vehicle No :SKC9146H

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 BONNET X Repair	1,345.000	1 PC	1,345.00	
X BONNET CHROME MOULDING ?	185.0000	1 PCS	185.00	
cracked 2 GRILLE INNER ?	162.0000	1 PCS	162.00	
4 GRILLE CHROME MOULDING Per	187.0000	1 PCS	187.00	
5 FRONT BUMPER Re	1,458.000	1 PC	1,458.00	
6 FRONT BUMPER CLIPS	5.5000	10 PC	55.00	
7 FRONT BUMPER SIDE HOLDER - LH NEC.	156.0000	1 PC	156.00	
8 FRONT BUMPER SIDE HOLDER - RH	156.0000	1 PC	156.00	
9 FRONT BUMPER FOGLAMP CHROME - LH Mis	278.0000	1 PCS	278.00	
cracked 10 FRONT BUMPER FOG LAMP - LH ?	168.0000	1 PC	168.00	
11 FRONT BUMPER FOG LAMP - RH X	168.0000	1 PC	168.00	
cracked 12 FRONT BUMPER CENTRE GRILLE - TOP ?	176.0000	1 PCS	176.00	
13 FRONT BUMPER TOP GRILLE - LH Mis	158.0000	1 PCS	158.00	
cracked 14 FRONT BUMPER CENTRE GRILLE - LOWER ?	215.0000	1 PCS	215.00	
15 FRONT BUMPER FOAM ?	86.0000	1 PC	86.00	
16 FRONT BUMPER REINFORCEMENT ?	165.0000	1 PC	165.00	
17 HEADLAMP ASSY - LH SCR.	450.0000	1 PCS	450.00	
cracked 18 HEADLAMP ASSY - RH ?	450.0000	1 PCS	450.00	
19 GRILLE TOP GARNISH CRA	178.0000	1 PCS	178.00	
20 GRILLE TOP GARNISH CLIPS NEC	5.5000	4 PCS	22.00	
21 SUPPORT PANEL ASSY ?	368.0000	1 PCS	368.00	
22 FRONT FENDER COWLING - LH TN	145.0000	1 PC	145.00	
23 FRONT FENDER COWLING - RH ?	145.0000	1 PC	145.00	
24 FRONT FENDER COWLING CLIPS NEC	5.5000	20 PCS	110.00	
W.kun 25 FRONT FENDER PICASSO STICKER - LH NEC	76.0000	1 PC	76.00	
5/9/2017 26 FRONT FENDER PICASSO STICKER - RH NEC	76.0000	1 PC	76.00	
			7,438.00	4676
			Less 10%	6,694.20
Labour				4208.40
27 TO KNOCK OUT DENT'S, CUT/WELD, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	4600 ? v
28 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	600
29 TO CHECK WIRING	20.0000	1 JOB	20.00	1x
30 TO REMOVE, REFIT CONDENSER & REFILL GAS	100.0000	1 JOB	100.00	7x
31 TO TUFF-KOTE	60.0000	1 JOB	60.00	X

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S: CHRISTINA KWAN
1 AMBER ROAD #07-04
SINGAPORE 439845

ATTN: FIRST CAPITAL

Your Ref No: TP 0817-4715
Claim Type: Third Party
Accident Date: 26/08/2017
TP Veh Reg No: SHC325C

Estimate No: EST1502681
Date: 05 Oct 2017
Policy No: 2100276044
Veh Reg No: SKC9146H
Make/Model: CITROEN GRAND C4
PICASSO 1.6 SMT ABS
EGS PSR
Chassis No: VF7UA5FV8BJ710315
Engine No: 10FJBS1254001
Reg. Date: 14/10/2011

Estimate Repair Cost to Vehicle No :SKC9146H

Description	U/Price	Quantity	Price <u>SS</u>	Amount <u>SS</u>
Supplementary Parts to Repair				
List Price				
MISSING FRONT BUMPER PAD - LH	165.0000	1 PC	165.00	
CRACKED FRONT BUMPER REINFORCEMENT BRACKET - LH	158.0000	1 PC	158.00	
			323.00	
		Less 10%	32.30	290.70
			Total	SS 290.70
			GST Amount	SS 20.35
			Total Amount Payable	SS 311.05

For PROGRESSIVE AUTOMOTIVE PTE
LTD

AUTHORISED SIGNATURE

SUPP 290.70
PAID 4208.40
LHS 1020.00
5519.10

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : CHRISTINA KWAN
1 AMBER ROAD #07-04
SINGAPORE 439845

ATTN: FIRST CAPITAL

Your Ref No: TP 0817-4715
Claim Type: Third Party
Accident Date: 26/08/2017
TP Veh Reg No: SHC325C

Estimate No: EST1502681
Date: 28 Aug 2017
Policy No: 2100276044
Veh Reg No: SKC9146H
Make/Model: CITROEN GRAND C4
PICASSO 1.6 SMT ABS
EGS PSR
Chassis No: VF7UA5FV8BJ710315
Engine No: 10FJBS1254001
Reg. Date: 14/10/2011

Estimate Repair Cost to Vehicle No :SKC9146H

Description	U/Price	Quantity	Price S\$	Amount S\$
32 TO RESET CHECK LIGHT	120.0000	1 JOB	120.00	120.00
			1,900.00	1,900.00
			Total	S\$ 8,594.20
			Add GST @ 7%	601.59
			Total Amount Payable	S\$ 9,195.79

TOTAL: SINGAPORE DOLLAR NINE THOUSAND ONE HUNDRED NINETY FIVE AND CENTS SEVENTY NINE ONLY

3-4 Days.
part by part
before paint photos.
Gino Gino - 82880282
25/9/17

For PROGRESSIVE AUTOMOTIVE PTE
LTD

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17016869/Grbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 325C	Veh. Inspected	SKC 9146H	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17008347MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	30/08/2017	
2. Vehicle Particulars & Condition				
Make & Model	CITROEN C4 PICASSO	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	VF7UA5FV8BJ710315	Colour	BROWN	
Odometer	46280	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	ROADSTONE	6 mm	
L/H Front Tyre	215/50 R17	ROADSTONE	6 mm	
R/H Rear Tyre	215/50 R17	ROADSTONE	6 mm	
L/H Rear Tyre	215/50 R17	ROADSTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2017	Inspection Date	25/09/2017	
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 9146H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	TO REPAIR SEE LABOUR	1,345.00	-
1	BONNET CHROME MOULDING	NOT NECESSARY	185.00	-
1	GRILLE INNER	CRACKED	162.00	162.00
1	GRILLE CHROME MOULDING	BROKEN	187.00	187.00
1	FRONT BUMPER	DEFORMED	1,458.00	1,458.00
10	FRONT BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	FRONT BUMPER SIDE HOLDER-LH	NECESSARY	156.00	156.00
1	FRONT BUMPER SIDE HOLDER-RH	NECESSARY	156.00	156.00
1	FRONT BUMPER FOGLAMP CHROME-LH	MISSING	278.00	278.00
1	FRONT BUMPER FOGLAMP-LH	CRACKED	168.00	168.00
1	FRONT BUMPER FOGLAMP-RH	NOT NECESSARY	168.00	-
1	FRONT BUMPER CENTRE GRILLE-TOP	CRACKED	176.00	176.00
1	FRONT BUMPER TOP GRILLE-LH	MISSING	158.00	158.00
1	FRONT BUMPER CENTRE GRILLE-LOWER	CRACKED	215.00	215.00
1	FRONT BUMPER FOAM	NOT NECESSARY	86.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	465.00	-
1	HEADLAMP ASSY-LH	SCRATCHED	450.00	450.00
1	HEADLAMP ASSY-RH	CRACKED	450.00	450.00
1	GRILLE TOP GARNISH	CRACKED	178.00	178.00
4	GRILLE TOP GARNISH CLIPS @\$5.50	NECESSARY	22.00	22.00
1	SUPPORT PANEL ASSY	NOT NECESSARY	368.00	-
1	FRONT FENDER COWLING-LH	TORN	145.00	145.00
1	FRONT FENDER COWLING-RH	NOT NECESSARY	145.00	-
20	FRONT FENDER COWLING CLIPS @\$5.50	NECESSARY	110.00	110.00
1	FRONT FENDER PICANSO STICKER-LH	NECESSARY	76.00	76.00
1	FRONT FENDER PICANSO STICKER-RH	NECESSARY	76.00	76.00
1	FRONT BUMPER PAD-LH (ADDITIONAL)	MISSING	165.00	165.00
1	FRONT BUMPER REINFORCEMENT BRACKET-LH (ADDITIONAL)	CRACKED	158.00	158.00

Report Ref No. CS/FCI17016869/Grbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-776.10	-499.90
			6,984.90	4,499.10
	LABOUR			
	TO KNOCK OUT DENTS,CUT/WELD,REMOVE,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF BONNET.		800.00	400.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		800.00	600.00
	TO CHECK WIRING.		20.00	20.00
	TO REMOVE,REFIT CONDENSER & REFILL GAS.	NOT NECESSARY	100.00	-
	TO TUFF-KOTE.	NOT NECESSARY	60.00	-
	TO RESET CHECK LIGHT.	NOT NECESSARY	120.00	-
			1,900.00	1,020.00
	GRAND TOTAL		8,884.90	5,519.10
	RECOMMENDED COST OF REPAIRS			5,519.10

Report Ref No. CS/FC117016869/Grbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.