

ASS. REC. BY:

REF: CS/MSG17017062/Sgb^{nt}

Special Instruction:

Surveyor

mainman Sebastian

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSIG

Date/Time:

4/9/17 3.26pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE7285E

Insured:

SKQ 3885Z

at Workshop m/s

World Auto

Tel:

97588 347

of

No. 1 Kranji Loop, 739 535

Policy No:

B27814254 SMP

Claim No:

528334

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/8/17

CA / REV / REP. / REV 24 HRS

'wp'

5/9/17

H.O.D. Endorsement:

Date/Time:

4/9/17 3.31pm

Person Contacted:

Sim

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE7285E-X
	SKQ 3885Z-X

Surveyor:

Mofmbr

ASSIGNMENT

From: _____ Date: 05092017

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 7285E

at Workshop m/s World Auto

of No. 1 Krang Loop

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 1.8-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLE 7285E Yr Regn: 29 Jul 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle C.C. 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 107469 T/Radio: Insured / Std / NI / NA

Eng/No: L15B3536077

C/No: Gk8 1005209

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: " "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 31/8/2017 D.O.I. 5/9/2017

Survey held at World Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/9/2017. Ca Reg No Incorrect.

11/9/17 REV preli in meimber.

13/12/17 confirmed p/p \$ 4910.48 with Sim.

(Red: 3588.80, 42%).

RECEIVED 20 DEC

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: 200

Transportation: _____

2)

Add Fee: ☐ : Site Insp (\$)

) S + RS, \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format: TP

Lump Sum / I.B. (\$ 4910.48)

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17017062/Sgb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 04-09-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKQ 3885Z	Veh. Inspected	SLE 7285E
Policy No.	B27814254SMP	Coverage (\$)	0.00
Claim No.	528334	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	04/09/2017
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/08/2017	Inspection Date	
Survey held at	NO,1 KRANJI LOOP 739535		
Repairer	WORLD AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Sep 2017		04 Sep 2017 15:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	YEOW BOON CHIN, ID: S7503405I, Tel: +6597917537, Email: YEOWBC@HCI.EDU.SG		
Main Claimant:	SLE 7285E NAME		
Vehicle Reg. No.:	SLE7285E	Date of Loss:	31/08/2017 16:00 - :59
Claim Type:	TP / 528334	Policy/Cover Note No.:	B27814254SMP (Comprehensive) Coverage: 26/11/2016 - 25/11/2017
Vehicle Reg. No. (Insured):	SKQ3885Z	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/09/2017]		
Driver/Custodian (Insured):	YEOW BOON CHIN (42 / Male), NRIC: S7503405I, Tel: +6597917537		

[View All](#)
[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS View All

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 07 Sep 2017

Preliminary Advice

Insured Vehicle No : SKQ3885Z

TP Vehicle No : SLE7285E

Make : AUDI A1 SPORTBACK

Date of Inspection : 05/09/2017

Inspection At : WORLD AUTO PTE LTD - KRANJI (HQ)
NO 1 KRANJI LOOP
SINGAPORE 739535

Accident Date : 31/08/2017

Assignment Date : 04/09/2017

Est. Duration of Repair : 4.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,499.28
Revised Amount	:S\$	5,230.48
Check Items (Estimated)	:S\$	148.00
Total	:S\$	5,378.48

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

KMSIG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/08/2017 17:35
Date Of Accident	31/08/2017 16:10
Exact Location Of Accident	ECP NEAR EAST COAST PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE7285E
Insured/Policyholder	
Name Of Registered Owner	LCR PTE LTD
Co Reg No	201504621K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE HYBRID-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	GOH SHIN YONG
NRIC No	S7835238H
Date Of Birth	17/11/1978
Occupation	INDOOR
Date Of Driving Pass	20/04/1999
Driving Experience	18 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PAID DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKQ3885Z
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHD6712Z
 Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available a/vised.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured vehicle(s) involved in this accident (all Insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyer/law firm; the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all Insurers(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firm may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firm), which may be based outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A 1002 015
215 925E

B 5K2 3215 2

C 5K0 3215 2

Sketch Plan #2

Describe Circumstances of the Accident


driving along road, there was road work and slow traffic the car
of SKG 50852 could not brake in time and bang into my car before
and the impact drove me to hit the car in front of me (SKG 50852)
I have a mark on the side and did not hit the car in front of me
but it was a close call.

Declaration

I/We declare the foregoing particulars are in a true and correct manner.

Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Officer
Personnel

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD**Estimate : ES00353**

Date : 31/08/2017

Vehicle Num. : SLE 7285E (LCR)

Make/Model : HONDA SHUTTLE

Chassis/Eng# :

Accident Date : 31/08/2017

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

1.	1	REAR TAILGATE (SHUTTLE) ✓ DT		1,850.00 160
2.	1	REAR TAILGATE HONDA EMBLEM (SHUTTLE) ✓ NEC		81.30
3.	1	REAR TAILGATE HYBRID EMBLEM (SHUTTLE) ✓ NEC		88.40
4.	1	REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE) ✓ NEC		88.40
5.	1	REAR TAILGATE WEATHERSTRIP (SHUTTLE) X NN		380.00
6.	1	REAR WINDSCREEN MOULDING (SHUTTLE) ✓ NEC		195.00
7.	1	REAR END PANEL TOP GARNISH (SHUTTLE) ✓ Deform.		260.00
8.	1	REAR END PANEL (SHUTTLE) R		950.00
9.	1	REAR BUMPER (SHUTTLE) ✓ Deform.		1,350.00 120
10.	1	SMART BUZZER SENSOR (SHUTTLE) ? X NN		185.00
List Total S\$:				5,428.10
20.00% Discount S\$:				1,085.62
				4,342.48

SPECIAL NETT ITEMS :

1.	1	REVERSE SENSOR ✓ DMG		260.00 200
2.	1	REAR WINDSCREEN SEALANT ✓ NEC.		160.00 40
3.	8	REAR END PANEL TOP GARNISH CLIPS (SHUTTLE) ✓ NEC	9.80	78.40 30
4.	8	REAR BUMPER CLIP ✓ NEC.	9.80	78.40 30
Special Nett Total S\$:				576.80
LABOUR :				
TO REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)				160.00 120

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES00353

Attention : Motor Claim Department

Date : 31/08/2017
 Vehicle Num. : SLE 7285E (LCR)
 Make/Model : HONDA SHUTTLE
 Chassis/Eng# :
 Accident Date : 31/08/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO REMOVE AND INSTALL 1/4 GLASS (VEZEL)

To labour charge for removing rear tailgate, rear bumper, end panel out to facilitate repairs and replacement of damaged parts

To respray rear tailgate, rear bumper, end panel

To deactivate and activate high voltage hybrid battery as a requirement for safety precautions

Labour Total S\$:

repair
 To ~~remove~~ front bumper
 to respray front bumper

160.00

500 1,200.00

600

800.00

280

380.00

2,540.00

100

380

500

200

E. & O.E.

Total S\$:

8,419.28

=====

2499.28

for WORLD AUTO PTE LTD

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Haicyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES00353

Attention : Motor Claim Department

Date : 31/08/2017

Vehicle Num. : SLE 7285E (LCR)

Make/Model : HONDA SHUTTLE

Chassis/Eng# :

Accident Date : 31/08/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		To labour charge for removing rear tailgate, rear bumper, end panel out to facilitate repairs and replacement of damaged parts	500	1,200.00
		To respray rear tailgate, rear bumper, end panel	600	800.00
		To deactivate and activate high voltage hybrid battery as a requirement for safety precautions	280	380.00
		Labour Total S\$:		2,540.00

E. & O.E.

Total S\$: 7,459.28

=====

for WORLD AUTO PTE LTD



Sebastian. 5/9/2017.

- Part by part repair.

- Question Mark Item Photo.

- Photo before paint.

90036121

sebastianyeang@lkkauto.com

4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Estimate : ES00353

Attention : Motor Claim Department

Date : 31/08/2017
 Vehicle Num. : SLE 7285E (LCR)
 Make/Model : HONDA SHUTTLE
 Chassis/Eng# :
 Accident Date : 31/08/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR TAILGATE (SHUTTLE) ✓ DT		1,850.00 1600
2.	1	REAR TAILGATE HONDA EMBLEM (SHUTTLE) ✓ NEC		81.30
3.	1	REAR TAILGATE HYBRID EMBLEM (SHUTTLE) ✓ NEC		88.40
4.	1	REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE) ✓ NEC		88.40
5.	1	REAR TAILGATE WEATHERSTRIP (SHUTTLE) X		380.00
6.	1	REAR WINDSCREEN MOULDING (SHUTTLE) ✓ NEC		195.00
7.	1	REAR END PANEL TOP GARNISH (SHUTTLE) ✓ Deform.		260.00
8.	1	REAR END PANEL (SHUTTLE) R		950.00
9.	1	REAR BUMPER (SHUTTLE) ✓ Deform.		1,350.00 1200
10.	1	SMART BUZZER SENSOR (SHUTTLE) ? X		185.00
List TotalS\$:				5,428.10
20.00% Discount S\$:				1,085.62
				4,342.48

3513.10
 - 20%
 1) 2810.48

SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR ✓ DMG		260.00 200
2.	1	REAR WINDSCREEN SEALANT ✓ NEC		160.00 140
3.	8	REAR END PANEL TOP GARNISH CLIPS (SHUTTLE) ✓ NEC	9.80	78.40 30
4.	8	REAR BUMPER CLIP ✓ NEC	9.80	78.40 30
Special Nett Total S\$:				576.80

LABOUR :
 TO REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)

3) 1800 160.00 120

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD

Attention : Motor Claim Department

Estimate : ES00353

Date : 31/08/2017
 Vehicle Num. : SLE 7285E (LCR)
 Make/Model : HONDA SHUTTLE
 Chassis/Eng# :
 Accident Date : 31/08/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		To labour charge for removing rear tailgate, rear bumper, end panel out to facilitate repairs and replacement of damaged parts	500	1,200.00
		To respray rear tailgate, rear bumper, end panel	600	800.00
		To deactivate and activate high voltage hybrid battery as a requirement for safety precautions	280	380.00
		Labour Total S\$:		2,540.00

E. & O.E.

Total S\$: 7,459.28

=====

for WORLD AUTO PTE LTD

Sebastian. 5/9/2017.
 - Part by part repair.
 - Question Mark Item
 Photo.
 - Photo before paint.

90036121

sebastianyeang@lkkauto.com.

4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD**Estimate : ES00353**

Attention : Motor Claim Department

Date : 31/08/2017
 Vehicle Num. : SLE 7285E (LCR)
 Make/Model : HONDA SHUTTLE
 Chassis/Eng# :
 Accident Date : 31/08/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :				160.00
TO REMOVE AND INSTALL 1/4 GLASS (VEZEL)				1,200.00
To labour charge for removing rear tailgate, rear bumper, end panel out to facilitate repairs and replacement of damaged parts				800.00
To respray rear tailgate, rear bumper, end panel				380.00
To deactivate and activate high voltage hybrid battery as a requirement for safety precautions				

Labour Total S\$:

2,540.00

repair
 To ~~remove~~ ^{repair} front bumper

To respray front bumper

100

~~380~~~~500~~

200

E. & O.E.**Total S\$: 8,419.28**

for WORLD AUTO PTE LTD

1) Parts : \$ 2810.48

2) S/Nett: \$ 300.00

3) Labour: \$ 1800.00

\$ 4910.48 @ 4 days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17017062/SGBN2

Date: 20/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B27814254SMP
Claimant Vehicle No :	SLE7285E	Insured Vehicle No :	SKQ3885Z
Date of Loss:	31/08/2017	Nature of Claim:	TP
		Claim No:	528334

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE7285E	Engine No:	L15B3536077
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81005204
Reg. Date:	29/07/2016 (Man. Year: 2016)	Odometer:	107469 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,919.28	3,110.48	1,808.80	36.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	1,800.00	1,780.00	49.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,499.28	4,910.48	3,588.80	42.22
+ GST 7.00/7.00% (S\$)	594.95	343.73	251.22	42.23
Nett Amount (S\$)	9,094.23	5,254.21	3,840.02	42.22

INSPECTION

Date of Assignment:	04/09/2017	
Date Inspected:	05/09/2017	Inspected At:
		No 1 Kranji Loop
		Singapore 739535
		Repairer: World Auto Pte Ltd - Kranji
		(HQ)

Estimated Period of Repair: 4.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Dec 2017)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE7285E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE (SHUTTLE)	Dented	1,850.00 FL	*1,600.00 FL
2	1	*REAR TAILGATE HONDA EMBLEM (SHUTTLE)	Necessary	81.30 FL	*81.30 FL
3	1	*REAR TAILGATE HYBRID EMBLEM (SHUTTLE)	Necessary	88.40 FL	*88.40 FL
4	1	*REAR TAILGATE SHUTTLE EMBLEM (SHUTTLE)	Necessary	88.40 FL	*88.40 FL
5	1	*REAR TAILGATE WEATHERSTRIP (SHUTTLE)	Not Necessary	380.00 FL	*- FL
6	1	*REAR WINDSCREEN MOULDING (SHUTTLE)	Necessary	195.00 FL	*195.00 FL
7	1	*REAR END PANEL TOP GARNISH (SHUTTLE)	Deformed	260.00 FL	*260.00 FL
8	1	*REAR END PANEL (SHUTTLE)	Repair	950.00 FL	*- FL
9	1	*REAR BUMPER (SHUTTLE)	Deformed	1,350.00 FL	*1,200.00 FL
10	1	*SMART BUZZER SENSOR (SHUTTLE)	Not Necessary	185.00 FL	*- FL
11	1	*REVERSE SENSOR	Damaged	260.00 FS	*200.00 FS
12	1	*REAR WINDSCREEN SEALANT	Necessary	160.00 FS	*40.00 FS
13	8	*REAR END PANEL TOP GARNISH CLIPS (SHUTTLE)	Necessary	78.40 FS	*30.00 FS
14	8	*REAR BUMPER CLIPS	Necessary	78.40 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,004.90	3,813.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,085.62	702.62
Total Parts (\$\$)	4,919.28	3,110.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL REAR WINDSCREEN (SHUTTLE)	New	160.00	120.00
2	TO REMOVE AND INSTALL 1/4 GLASS (VEZEL)	New	160.00	-
3	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE, REAR BUMPER, END PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	500.00
4	TO RESPRAY REAR TAILGATE, REAR BUMPER, END PANEL	New	800.00	600.00
5	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS	New	380.00	280.00
6	TO REPAIR FRONT BONNET	New	380.00	100.00
7	TO RESPRAY FRONT BONNET	New	500.00	200.00
Gross Labour Cost (S\$)			3,580.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >