

ASS. REC. BY:

REF: CS/FC117017073 / Tirb02

Special Instruction:

Survivor:

Taufik

ASSIGNMENT (Office)From (Person): WS Sithara of JCI Date/Time: 04/02/07 3:34pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 3407J Insured: SHC 7253Eat Workshop m/s Shu Fatt Auto Tel: 6273 0119of Blk 1009 Bukit Merah Lane 3 # 01-90Policy No: _____ Claim No: D17008410MPSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29082007
(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

06/02/07 @ morning

H.O.D. Endorsement: _____

Date/Time: 04/02/07 4:14pm Person Contacted: Connie Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SJL 3407J - X</u>
	<u>SHC 7253E - X</u>
	<u>Sent pxi through email to Sithara</u>

(08/11/13)

REF: FQ1

Surveyor:

Tanjong

ASSIGNMENT

Let 2018 Nov

From:

Date:

06092017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJL 3407J

at Workshop m/s

Shu Fatt

of

Blk 1005 Bukit Melah Lane 3

Insured:

#01-90

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Morning

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$16K.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR. Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJL 3407J

Yr Regn:

2008, Nov

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit

c.c.

1339

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

6/765

T/Radio:

Insured / Std / NI / NA

Eng/No:

GE611 30920.

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55 R15

R:

2"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

6/4/17 E1120

Survey held at

Shu Fatt

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

check repair limit.

\$4636.72, 7 days e-mail to Pat

Confirm \$4636.72, 7 days

Red: \$2888.84, 38%

RECEIVED 10 DEC 2017

Date/Time, File Pass to?



Preli. Report



Final Report

1) typist

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

150

50

50

70

320

Report Format:

7p

Lump Sum / I.B.I. (\$

4636.72



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17017073/T1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 04-09-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHL 7253E	Veh. Inspected	SJL 3407J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17008410MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	04/09/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	29/08/2017	Inspection Date		
Survey held at	SHU FATT AUTO WORKS BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	31-08-2017	Our Ref No. D17008410MFSH
Accident Date	29-08-2017	Claim Type. Third Party
Insured Vehicle	SHC7253E	Third Party Vehicle. SJL3407J
Survey Location	BLK 1009 #01-90 BUKIT MERAH LANE 3	
Contact Person.	CONNIE WONG	
Contact No.	62730119/ 0	Fax No. 62707065
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SHU FATT AUTO WORKS	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/227564)



PRI Documents



Close



PRI Header Details

Claim No	D17008410MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & SH
Workshop Name	SHU FATT AUTO WORKS (Contact Person : CONNIE WONG)	Survey Location & Contact Details	BLK 1009 #01-90 BUKIT MERAH LANE 3 Mobile: 0 , Phone: 62730119 , Fax: 6270706 EmailId: SHUFATT@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY Q		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7253E	TP Vehicle No	SJL340
PRI Recieved Date	31-08-2017 07:00:17 PM	Surveyor Appointed Date	04-09-2017 03:35:05 PM	Surveyor Accept Date	04-09-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-09-2017	Upload Survey Report *:	
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17008410MFSH

Our Ref: CS/FCI17017073/T1rb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJL 3407J .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 06/09/2017 at the premises of M/s SHU FATT AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,525.56</u> .
Revised Estimate Amount	: S\$ <u>4,636.72</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

TAUFIKH
Automotive Assessor

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 8836E

Vehicle Details

Vehicle No.: SJL3407J
Vehicle to be Exported: No
Intended De-registration Date: 07 Sep 2017
Vehicle Make: HONDA
Vehicle Model: FIT 1.3G A
Primary Colour: White
Manufacturing Year: 2008
Engine No.: L13A4143151
Chassis No.: GE61130920
Maximum Power Output: 73.0 kW (97 bhp)
Open Market Value: \$14,045.00
Original Registration Date: 24 Nov 2008
First Registration Date: 24 Nov 2008
Transfer Count: 2
Actual ARF Paid: \$14,045.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Nov 2018
PARF Rebate Amount: \$7,724.00

Intended COE Rebate Details

COE Expiry Date: 23 Nov 2018
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$2.00
COE Rebate Amount: \$0.00

Total Rebate Amount: \$7,724.00

The information contained herein is correct as at 07 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 27 Aug 2017 at 01:09 AM



Honda Fit 1.3A G \$11,888 \$7,040 /yr 14-Jul-2008 1,339 cc -
 (Low Depreciation At \$597 Per Month Only!) Best For Short Term Usage, 10 Months To Be Driven. Drive And Get Back \$5925 COE. Value For Money, Cheaper Than Rental. (Viewing Available...

Sincere Motoring Pte Ltd

Posted: 05-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda



Honda Fit 1.3A (New 5-yr COE) \$39,800 \$7,960 /yr 28-Jul-2008 1,339 cc 108,501

New 5 Years Coe With New Tax And New Paint, One Owner With Low Mileage Done, 100% Accident Free, Trade In Welcome, Inhouse/Bank Loan Available. Call Now To View.

Posted: 04-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda



Honda Fit 1.3A G \$13,800 \$11,640 /yr 14-May-2008 1,339 cc -

Superb Well Kept And Maintained By Previous Owner! Accident Free! No Repair Or Touch Up Required! Low Depreciation! Low Great For Short Term Use! View To Believe. Please Call Us Fo...

Posted: 04-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda



Honda Fit 1.3A G \$16,800 \$10,170 /yr 02-Oct-2008 1,339 cc 120,001

1 Owner Only! Sporty Hatchback, Most Reliable And Economical, Comfort, Spacious And Fuel Efficiency, Superb Condition. Coe Gone.

Posted: 04-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda



Honda Fit 1.3A G \$12,988 \$8,410 /yr 15-Jul-2008 1,339 cc -

Well Maintained By Owner. Stock Condition. No Major Repairs Needed Till End Of COE. Lowest Depreciation, Best For Short Term Non-Obligating Test Drive And Discussion.

Posted: 03-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda



Honda Fit 1.3A G \$15,300 \$8,810 /yr 16-Oct-2008 1,339 cc -

Ideal For COE Extension Or Short Terms Users. \$3000 Down Payment, Monthly \$1050. Lady Owner. Very Well Maintain. New

Posted: 03-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda



Honda Fit 1.3A G \$15,999 \$8,360 /yr 12-Nov-2008 1,339 cc 129,231

Cheapest In Town. Owned By 1 Careful Owner, Car In Tip Top Condition, View To Believe. Come With Expensive DVD Player Now To View.

Posted: 03-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda



Honda Fit 1.3A G \$13,800 \$9,590 /yr 10-Jul-2008 1,339 cc -

\$0 Down Payment Available! sgCarMart Premium Dealer 2015-2017 Buy With Zero Worries! 100% No Hidden Cost! 100% Or Mileage! 100% Accident Free! In House Loan Or Bank Loan Available...

88 Motor Trading

Posted: 02-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda



Honda Fit 1.3A G \$12,500 \$7,640 /yr 25-Jul-2008 1,339 cc 159,001

Fire Sale! Nice Auspicious 3" Digits Bidded Reg No. Clean Interior And Well Maintained. CF Bonnet, Front Brake Rotor, DC Coil New Battery, Radiator, Radiator Fan And Motor, Thermo...

Posted: 02-Sep-2017 Tags: 2008 Honda Fit, Honda Fit, Honda, Fit, Used Honda

[Compare](#)



樹發汽車修理廠 SHU FATT AUTO WORKS

0-71

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
30th August 2017
TP

SLJ 3407 J HONDA FIT

Spare Parts			S\$
1	Rear boot.		833.65 <i>bt</i> ✓
1	Rear boot 'Fit' emblem.		42.05 <i>del</i> ✓
1	Rear boot centre garnish.		159.25 <i>Rx</i> ✓
1	Rear windscreen mouldings.		115.00 <i>del</i> ✓
1	Rear boot lock.		232.15 <i>del</i> ✓
1	Rear boot rubber.		98.35 <i>del</i> ✓
2	Rear tail lights. @\$296.25		592.50 <i>LH-out, RH-X nn</i> ✓
1	Rear bumper.		484.05 <i>del</i> ✓
1	Set rear bumper clips.		42.00 <i>del</i> ✓
2	Rear bumper side retainers. @\$32.55		65.10 <i>del</i> ✓
1	Rear bumper tow cover.		28.35 <i>mis</i> ✓
2	Set rear fender inner cowling clips. @\$35/-		70.00 <i>X nn</i> ✓
1	Rear support panel.		326.55 <i>bt</i> ✓
1	Rear panel inner garnish.		87.65 <i>del</i> ✓
1	Rear spare wheel base.		867.05 <i>Rx</i> ✓
1	Rear spare wheel base cover.		310.75 <i>X Rx</i> ✓
1	Rear number plate.		55.00 <i>Snet XSVc</i> ✓
1	Rear windscreen inner seal.		45.00 <i>Snet del</i> ✓
1	Rear windscreen sealant.		42.00 <i>Snet del</i> ✓

4496.45

Less 20% 870.89

3625.56

Labour

To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, left rear fender, rt rear fender, left rear wheel house, rt rear wheel house, renew rear boot, rear support panel, rear floor board, rear support panel, rear lights, rear bumper and assembly.

To respray damaged parts.

To remove rear garnishes, carpets, upholstery, seats, side covers to facilitate repairs and assembly.

To remove, replace rear windscreen and assembly.

To reseal joints, reinsulate, anti rust panels and assembly.

1650.00 *1000*

180.00 *60 100*

180.00 *120*

240.00 *60 100*

2320

7525.56

7647.96

Achilles

GE6- 1130920

161438

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- To display damaged part(s) subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749

'wp'

7 days.

Lumpsum 6/9/17 @ 1220.

Resurvey after repair

sur@lkkauto.com

17



樹發汽車修理廠 SHU FATT AUTO WORKS



BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
30th August 2017

TP

SL

SEI 3407 J HONDA FIT

Suppl^m

FFWLS headroom x2

Spare Parts	1	Rear boot.	SS
	1	Rear boot 'Fit' emblem.	833.65 <i>bt</i> ✓
	1	Rear boot centre garnish.	42.05 <i>del</i> ✓
	1	Rear windscreen mouldings.	159.25 <i>Ry</i> ✓
	1	Rear boot lock.	115.00 <i>del</i> ✓
	1	Rear boot rubber.	232.15 <i>del</i> ✓
	2	Rear tail lights. @\$296.25	98.35 <i>del</i> ✓
	1	Rear bumper.	<i>2 qt. 592.50 LH-del, RH-?</i>
	1	Set rear bumper clips.	484.05 <i>del</i> ✓
	2	Rear bumper side retainers. @\$32.55	42.00 <i>del</i> ✓
	1	Rear bumper tow cover.	65.10 <i>del</i> ✓
	2	Set rear fender inner cowling clips. @\$35/-	28.35 <i>mis</i> ✓
	1	Rear support panel.	70.00 <i>? X</i>
	1	Rear panel inner garnish.	326.55 <i>bt</i> ✓
	1	Rear spare wheel base.	87.65 <i>del</i> ✓
	1	Rear spare wheel base cover.	867.05 <i>Ry</i> ✓
	1	Rear number plate.	310.75 <i>XR</i>
	1	Rear windscreen inner seal.	55.00 <i>Snet XSVc</i>
	1	Rear windscreen sealant.	45.00 <i>Snet del</i> ✓
			42.00 <i>Snet del</i> ✓

Less 20%

Labour

To knock, straighten rear inner panel, rear lower panel, rear side panel, rear floor board, left rear fender, rt rear fender, left rear wheel house, rt rear wheel house, renew rear boot, rear support panel, rear floor board, rear support panel, rear lights, rear bumper and assembly.

To respray damaged parts.

To remove rear garnishes, carpets, upholstery, seats, side covers to facilitate repairs and assembly.

To remove, replace rear windscreen and assembly.

To reseal joints, reinsulate, anti rust panels and assembly.

3625.56
1650.00 *1000*

1650.00 *1000*
180.00 *60 → 100*

180.00 *120*
240.00 *60 → 100*

2320

7525.56

Achilles 195/55R15
GE6- 1130920
161438

Taufik 97495749
-wp-

7 days.

Lumpsum 6/9/17 @ 1220.

Resur very after repair

sur @ 1kkawd.wm



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
30th August 2017

Supplementary
First Capital - TP

SLJ 3407 J HONDA FIT

Spare parts 2 Rear windscreen moulding (top & bottom). @\$68/-

Less 10%
20

S\$

136.00

nett net ✓

(13.60)

122.40 108.80

Parts: 2782.15 ✓ (incl. SGP)

-10%: (552.43)

2229.72

Set: 87.00

2316.72

Labour: 2320.00

4636.72 *




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17017073/T1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7253E	Veh. Inspected	SJL 3407J	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17008410MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	04/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FIT	c.c	1339	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	GE61130920	Colour	WHITE	
Odometer	161765	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	ACHILLES	6 mm	
L/H Front Tyre	195/55 R15	ACHILLES	6 mm	
R/H Rear Tyre	195/55 R15	ACHILLES	6 mm	
L/H Rear Tyre	195/55 R15	ACHILLES	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2017	Inspection Date	06/09/2017	
Survey held at	SHU FATT AUTO WORKS BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 3407J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	BENT	833.65	833.65
1	REAR BOOT "FIT" EMBLEM	NECESSARY	42.05	42.05
1	REAR BOOT CENTRE GARNISH	TO REPAIR SEE LABOUR	159.25	-
1	REAR WINDSCREEN MOULDINGS	NECESSARY	115.00	115.00
1	REAR BOOT LOCK	DENTED	232.15	232.15
1	REAR BOOT RUBBER	TWISTED	98.35	98.35
2	REAR TAIL LIGHTS @\$296.25	N/S CUT / O/S NOT NECESSARY	592.50	296.25
1	REAR BUMPER	DEFORMED	484.05	484.05
1	SET REAR BUMPER CLIPS	NECESSARY	42.00	42.00
2	REAR BUMPER SIDE RETAINERS @\$32.55	NECESSARY	65.10	65.10
1	REAR BUMPER TOW COVER	MISSING	28.35	28.35
2	SET REAR FENDER INNER COWLING CLIPS @\$35.00	NOT NECESSARY	70.00	-
1	REAR SUPPORT PANEL	BENT	326.55	326.55
1	REAR PANEL INNER GARNISH	DEFORMED	87.65	87.65
1	REAR SPARE WHEEL BASE	TO REPAIR SEE LABOUR	867.05	-
1	REAR SPARE WHEEL BASE COVER	TO REPAIR SEE LABOUR	310.75	-
	LESS 20% DISCOUNT		-870.89	-530.23
			3,483.56	2,120.92
2	REAR WINDSCREEN MOULDING (TOP & BOTTOM) @\$68.00 (ADDITIONAL)	NECESSARY	136.00	136.00
	LESS 10% DISCOUNT		-13.60	-
	LESS 20% DISCOUNT		-	-27.20
			122.40	108.80
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	SERVICEABLE	55.00	-
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	45.00	45.00

Report Ref No. CS/FCI17017073/T1rbn2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	42.00	42.00
			142.00	87.00
	LABOUR			
	TO KNOCK,STRAIGHTEN REAR INNER PANEL,REAR LOWER PANEL,REAR SIDE PANEL,REAR FLOOR BOARD,LEFT REAR FENDER,RT REAR FENDER,LEFT REAR WHEEL HOUSE,RT REAR WHEEL HOUSE,RENEW REAR BOOT,REAR SUPPORT PANEL,REAR FLOOR BOARD,REAR SUPPORT PANEL,REAR LIGHTS,REAR BUMPER AND ASSEMBLY.INCLUSIVE OF THE REPAIR OF REAR BOOT CENTRE GARNISH,REAR SPARE WHEEL BASE AND REAR SPARE WHEEL BASE COVER.		1,650.00	1,000.00
	TO RESPRAY DAMAGED PARTS.		1,650.00	1,000.00
	TO REMOVE REAR GARNISHES,CARPETS,UPHOLSTERY, SEATS,SIDE COVERS TO FACILITATE REPAIRS AND ASSEMBLY.		180.00	100.00
	TO REMOVE,REPLACE REAR WINDSCREEN AND ASSEMBLY.		180.00	120.00
	TO RESEAL JOINTS,REINSULATE,ANTI RUST PANELS AND ASSEMBLY.		240.00	100.00
			3,900.00	2,320.00
GRAND TOTAL			7,647.96	4,636.72
RECOMMENDED COST OF REPAIRS				4,636.72

Report Ref No. CS/FCI17017073/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.