

ASS. REC. BY:

REF: CS/smo17017077/A162

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person):

Sheng Wong

of

SMO

Date/Time:

04/09/2017 4:18pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 4030U

Insured:

YN 4782E

at Workshop m/s

Hua Meng

Tel:

6746 5519

of

Blk 1 Kakt Bukit Ave 6 #01-61

Policy No:

Claim No:

CMTD1703051 / THE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

02/09/2017

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

04/09/2017

4:30pm

Person Contacted:

June

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKZ 4030U - X
	YN 4782E - X
	Lump Sum \$6200/- (Red: 6595.30 : 49%)

ASU REC BY: Adnan King

REF:

ASSIGNMENT

26/03/08

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SK24030U Yr Regn: 2008, MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 216843 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53ZEE106100594Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Crucero

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 04/04/17Survey held at Hua MengDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampa

RECEIVED 23 NOV 2017

MV: 16K

PV: 10K

Net: 6K

Date/Time, File Pass to?

1) 23/11 Typist

Date/Time, File Return to?

2) _____

Report From: TPLump Sum / I.B.I: (\$) 6800Days Of Repair: 7Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Trip Insp (\$ _____)☐ : Weekend (\$ _____)Survey Fee: 350

Transportation: _____

S + RS: \$ _____

Photos _____

Others _____

TOTAL

8489C

350

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO17017077/Atb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 04-09-2017



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 4782E	Veh. Inspected	SKZ 4030U
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1703051/THE	Excess (\$)	0.00
Assign From		Assign Date	04/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/09/2017	Inspection Date	04/09/2017
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

catherine

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Monday, 4 September, 2017 4:18 PM
To: assignments@lkkauto.com
Cc: admin-d@lkkauto.com; Choo, Thelma
Subject: RE: PRS-SOMPO INUSURED:YN 4782 E OUR REF:SKZ 4030 U D.O.A:02.09.2017

Our Reference: CMTD1703051/THE

Hi,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (SKZ4030U).

Please refer to the email correspondence below.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Hua Meng [mailto:huameng@live.com.sg]
Sent: Monday, September 04, 2017 3:57 PM
To: Wong, Shi Yi Shery
Subject: Re: PRS-SOMPO INUSURED:YN 4782 E OUR REF:SKZ 4030 U D.O.A:02.09.2017

Dear Sir

Thank you for your email.

We would like to choose LKK to conduct a survey.

Please take your immediate action.

Thanks & Regards

June

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Monday, September 4, 2017 3:02:21 PM
To: huameng@live.com.sg

Cc: Choo, Thelma

Subject: FW: PRS-SOMPO INUSURED:YN 4782 E OUR REF:SKZ 4030 U D.O.A:02.09.2017

Our Reference: CMTD1703051/THE

Your Reference: SKZ4030U

Date: 04TH September 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S HUA MENG SPRAY PAINTING WORKSHOP

Accident involving YN4782E and SKZ4030U on 02/09/2017

Dear Sir

We refer to your Notice of Accident via email dated 04/09/2017.

Please be informed that Thelma is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Ma Chin Fook (North area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Shery Wong

Claims Division

T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Hua Meng [<mailto:huameng@live.com.sg>]

Sent: Monday, September 04, 2017 1:55 PM

To: Motor Survey

Subject: PRS-SOMPO INUSURED:YN 4782 E OUR REF:SKZ 4030 U D.O.A:02.09.2017

Dear Sirs

Please refer the attachment for your necessary action and revert your surveyor name list to us urgently.

Your prompt reply will be appreciated by us.

Thanks & Regards

June

Hua Meng Spray Painting Workshop

1 Kaki Bukit Ave 6

#01-61

S 417883

Tel:67465519

Fax:67434896

**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 8489C

Vehicle Details

Vehicle No.: SKZ4030U

Vehicle to be Exported: Yes

Intended De-registration Date: 06 Sep 2017

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS 1.6 AUTO

Primary Colour: Silver

Manufacturing Year: 2008

Engine No.: 3ZZ4735466

Chassis No.: MR053ZEE106100594

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$16,994.00

Original Registration Date: 26 Mar 2008

First Registration Date: 26 Mar 2008

Transfer Count: 1

Actual ARF Paid: \$18,694.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 Mar 2018

PARF Rebate Amount: \$9,347.00

Intended COE Rebate Details

COE Expiry Date: 25 Mar 2018

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$12,856.00

COE Rebate Amount: \$708.00

Total Rebate Amount: \$10,055.00

The information contained herein is correct as at 06 Sep 2017



Username / Email Add

password



Connect

[Sign Up New Account](#)
[Forgot Password](#)

toyota altis

Price Range

Depreciation

2008

Vehicle Type

Advanced
Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Use search bar above to select
to compare.

CAR DETAILS

Price	\$16,800	\$16,800	\$17,899
Instalment	\$1,989	\$1,709	\$1,597
Registration Date	31-Mar-2008	18-Apr-2008	06-May-2008
Manufactured	2008	2008	2008
Mileage	-	-	167,000 km
Transmission	Auto	Auto	Auto
Engine Cap	1,598 cc	1,598 cc	1,598 cc
Road Tax	\$742 /yr	\$742 /yr	\$742 /yr
Power	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)
Curb Weight	1,195 kg	1,195 kg	1,195 kg
Features	1.6L DOHC VVT-i Engine, 4 Speed Automatic Transmission, SRS Airbags, Multi Function Steering Wheel, Reverse Sensors, Auto Climatic Aircon Control.	1.6L 4 Cylinders 16 Valves DOHC VVT-i Engine, ABS, Dual Airbags, Retractable Side Mirrors, Climatic Aircon Control, Multi Function Steering, Etc.	-
Accessories	Sport Rims, Factory Fitted Audio System, Blind Spot Mirrors, Door Visors, Solar Film, Electrical Retractable Side Mirrors With Indicator.	DVD Touchscreen, Leather Seats, Sports Rims.	-
Description	Only 1 Owner! Well Kept By Previous Owner! Ideal For Renewal Of COE! Extended Warranty Available! Be Delighted To Drive Away This Reliable Sedan Built To Give You Spacious Interior. Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Visit Us At Our Air-conditioned Showroom To Appreciate It In Pristine Condition Today!	1 Owner. Very Good Condition. Cheapest In Market.	Interested, Please Call For Viewing! Trade In All Available.
COE	\$12,856	\$16,930	\$15,600
OMV	\$16,994	\$16,994	\$16,994
ARF	\$18,694	\$16,994	\$16,994
Depreciation	\$13,270 /yr	\$13,590 /yr	\$14,240 /yr
No. of Owners	2	1	1
Type of Vehicle	Sedan	Sedan	Sedan
Category	PARF Car	PARF Car, Premium Ad Car	PARF Car
Availability	Available	Available	Available

MSME1716663 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 04/09/2017 12:28

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/09/2017 12:28
Date Of Accident	02/09/2017 17:00
Exact Location Of Accident	FILTER LANE OF TPE TWDS TAMPINES AVE 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ4030U
Insured/Policyholder	
Name Of Registered Owner	SH AUTO RENTAL AND LEASING PTE LTD
Co Reg No	201438489C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96388903
Vehicle Particulars	
Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5073363788-01
Cover Note Number	
Driver	
Name of Driver	SITI ZALEHA BINTE SELAMAT
NRIC No	S7713762I
Date Of Birth	24/05/1977
Occupation	INDOOR
Date Of Driving Pass	18/06/2007
Driving Experience	10 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81982558
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 406C FERNVALE ROAD #05-59
 Postcode 793406
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER --
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name HOGANG N.P.C
 Police Station Address ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT: T/20170904/2000.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN4782E
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver SAMY NADAN KANNAN
 NRIC/Passport Number G6867507W
 Contact Number 82515991
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

SITI ZALEHA BINTE SELAMAT

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SKZ4030U

Were seat belts worn?

Was injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident

Please refer the police report : T/20130904/2000

Declaration

We declare the foregoing particulars are true in every respect.



Employee's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers". The Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant governmental agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes, mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all insurers who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Tampines Ave 7

Vehicle SK 240306

Vehicle YN X182E



HIA MEXX

Sketch Plan #3 Pg. 1



SINGAPORE
POLICE FORCE



T/20170904/2000

1 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20170904/2000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/09/2017 00:12	Vide Report No.:	Station Diary No.: 5
--	------------------	-------------------------

Informant's Particulars

Name of Informant: SITI ZALEHA BINTE SELAMAT			Address: APT BLK 408C FERNVALE ROAD #05-59 SINGAPORE 793406		
ID Type / ID No.: NRIC NO / S7713762I			Contact No.: Home/Office: Mobile: 81982558		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 40	Date of Birth: 24/05/1977	Type of Informant: Driver		
Race: Malay			Language:		Institution / School Name:
Occupation: DRIVER			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/09/2017 17:00	Type of Location: Bend
Location: Along Road 1 TAMPINES AVENUE 7 TPE exit towards Tampines Ave 7, Filter lane.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKZ4030U	Car					0
YN4782E	Lorry					0

Sketch Plan #4 Pg. 1

SINGAPORE
POLICE FORCE

T/20170904/2000

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

2 of 3

Report No. T/20170904/2000

CONTINUATION OF REPORT

Brief Details.

On 02/09/2017 at about 1700hrs, I was travelling along TPE towards Tampines Ave 7. When I was approaching the filter lane, I stopped my vehicle as there were oncoming vehicle. While my vehicle come to a stop, I felt an impact from the rear. I exited my vehicle and discovered that there was a lorry collided onto the rear of my vehicle. No one was injured at the point of time therefore no ambulance was called in. We exchanged particulars and left the scene. I felt pain on my back therefore, I went to ProHealth Medical Group @ LRT Fernvale Pte Ltd located at Blk 437 Fernvale Road #01-04 S(790437) c/n: 64411672 and was given 3 days (02/09/2017 - 04/09/2017) Medical Certificate by Dr. Chee reference MC/80011. I wish to state that there isn't any government properties damaged prior to the incident. The reason for lodging the report after 24hrs is because after consulting doctor, I went to rest. I had installed a camera in my vehicle and it recorded the incident. There was a passenger in my vehicle at the point of time and she is willing to be the witness of the accident. Her particulars is : Zhi Hui, 97727979.

Sketch Plan #5 Pg. 1

SINGAPORE
POLICE FORCE

T/20170904/2000

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20170904/2000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 JANSEN KWOK SHU HAO	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 04/09/2017 00:12
Officer In Charge Of Case: TP / AEIT / SI ANG YITING, STEPHANIE Contact No.: 65476214	Classification Of Case:
Authentication Stamp: NP168 Signature: Singapore Police Force	SN 085

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

MROS32EE106100554

ESTIMATE

SH AUTO RENTAL AND LEASING PTE LTD
8 KAKI BUKIT AVE 4
#02-41
S 415875

TP Sampo
Dense

Date :16.09.2017
Vehicle no :SKZ 4030 U
Make/Model :TOYOTA ALTIS
Accident date :02.09.2017

No	Description	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear windscreen rubber <i>nr</i>	1	\$ 79.3
2	Rear boot lid <i>Disturbed</i>	1	\$ 754.7
3	Rear boot lid hinges @ \$56.40 <i>Best</i>	2	\$ 112.8
4	Rear boot lid upper lock <i>Disturbed</i>	1	\$ 105.6
5	Rear boot lid cable <i>nr</i>	1	\$ 58.1
6	Rear boot lid centre logo <i>nr</i>	1	\$ 58.3
7	Rear boot lid 1.6 emblem	1	\$ 32.5
8	Rear boot lid COROLLA emblem <i>nr</i>	1	\$ 46.6
9	Rear boot lid ALTIS emblem <i>nr</i>	1	\$ 46.6
10	Rear boot lid reflector @ \$80.60 <i>nr</i>	1	\$ 323.7
11	Rear boot lid insulation <i>torn</i>	2	\$ 174.1
12	Rear lamp @ \$299.60 <i>nr</i>	2	\$ 920
13	Rear lamp housing @ \$487.00 <i>nr</i>	1	\$ 168.2
14	Rear end panel <i>nr</i>	1	\$ 580.6
15	Rear end panel inner top garnish <i>nr</i>	1	\$ 202.7
16	Rear bumper <i>nr</i>	2	\$ 486.5
17	Rear bumper side holder @ \$17.40 <i>nr</i>	2	\$ 140.8
18	Rear bumper bracket @ \$51.00 <i>Best</i>	2	\$ 174.2
19	Rear bumper reflector @ \$37.20 <i>nr</i>	1	\$ 74.4
20	Rear bumper clips (1set) <i>nr</i>	1	\$ 46
21	Rear LH fender <i>Buckled</i>	2	\$ 927.2
22	Rear fender inner trim @ \$161.80 <i>torn</i>	1	\$ 703.4
23	Rear exhaust pipe <i>Best</i>	1	\$ 926.3
24	Rear exhaust pipe mounting <i>nr</i>	1	\$ 158
25	Rear bumper sponge <i>nr</i>	1	\$ 123.5
26	Rear spare tyre top board <i>torn</i>	1	\$ 276.6
27	Rear spare tyre well <i>nr</i>	1	\$ 780.9
28	Rear spae tyre well insulation @ \$279.60 <i>nr</i>	3	\$ 838.8
29	Rear boot lid handle <i>nr</i>	1	\$ 350.5
			9670.9

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

SH AUTO RENTAL AND LEASING PTE LTD
8 KAKI BUKIT AVE 4
#02-41
S 415875

Date :16.09.2017
Vehicle no :SKZ 4030 U
Make/Model :TOYOTA ALTIS
Accident date :02.09.2017

No	Description	Qty	Amount (\$\$)
30	Rear boot lid weather strip <i>wt</i>	1	\$ 148.1
31	Rear boot lid sensor <i>sgd</i>	1	\$ 106.8
32	Rear fender inner shield @ \$47.30 <i>mt</i>	2	\$ 94.6
			\$ 10020.4
		Less 25% Disc	\$ 2505.1
		Total	\$ 7515.3

Special Nett Items

1	Rear bumper reverse sensor (1set) <i>200</i>	1	\$ 380 <i>220</i>
		Total	\$ 380

Labour Cost

1	To supply rear windscreen sealant	\$ 50
2	To supply rear end panel inner sealant	\$ 200 <i>60</i>
3	Remove & reinstall rear windscreen	\$ 150 <i>120</i>
4	Remove & reinstall exhaust pipe	\$ 150 <i>80</i>
5	Remove & reinstall petrol tank	\$ 200 <i>80</i>
6	Remove & reinstall reverse sensor	\$ 150 <i>50</i>
7	Remove & reinstall boot lid inner garnish	\$ 150 <i>60</i>
8	Remove ,replace & repair consistent to the accident	\$ 2500 <i>1300</i>
9	Respray painting	\$ 1800 <i>1200</i>
10	Tuff kote	\$ 150 <i>60</i>
	Total	\$ 5500

Grand Total \$ 13395.3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 8491.75
4/s: 6.8K
07.2yr

6.8K
07.2yr




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO17017077/Atbe2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 05-12-2017		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 4782E	Veh. Inspected	SKZ 4030U	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1703051/THE	Excess (\$)	0.00	
Assign From		Assign Date	04/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053ZEE106100594	Colour	GREY	
Odometer	216843	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	CRUCERO	6 mm	
L/H Front Tyre	195/65 R15	CRUCERO	6 mm	
R/H Rear Tyre	195/65 R15	CRUCERO	6 mm	
L/H Rear Tyre	195/65 R15	CRUCERO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/09/2017	Inspection Date	04/09/2017	
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 4030U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR WINDSCREEN RUBBER	NECESSARY	79.30	79.30
1	REAR BOOT LID	DISTORTED	754.70	754.70
2	REAR BOOT LID HINGES @\$56.40	BENT	112.80	112.80
1	REAR BOOT LID UPPER LOCK	DAMAGED	105.60	105.60
1	REAR BOOT LID CABLE	NOT NECESSARY	58.10	-
1	REAR BOOT LID CENTRE LOGO	NECESSARY	58.30	58.30
1	REAR BOOT LID 1.6 EMBLEM	NECESSARY	32.50	32.50
1	REAR BOOT LID COROLLA EMBLEM	NECESSARY	46.60	46.60
1	REAR BOOT LID ALTIS EMBLEM	NECESSARY	46.60	46.60
2	REAR BOOT LID REFLECTOR	CRACKED	323.70	161.20
1	REAR BOOT LID INSULATION	TORN	174.10	174.10
2	REAR LAMP		920.00	599.20
2	REAR LAMP HOUSING	N/S DENTED	168.20	168.20
1	REAR END PANEL	DENTED	580.60	580.60
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	202.70	202.70
1	REAR BUMPER	DISTORTED	486.50	486.50
2	REAR BUMPER SIDE HOLDER @\$70.40	NECESSARY	140.80	140.80
2	REAR BUMPER BRACKET	BENT	174.20	102.00
2	REAR BUMPER REFLECTOR @\$37.20	N/S CRACKED	74.40	37.20
1	SET REAR BUMPER CLIPS	NECESSARY	46.00	30.00
1	REAR LH FENDER	BUCKLED	927.20	927.20
2	REAR FENDER INNER TRIM	TORN	703.40	323.60
1	REAR EXHAUST PIPE	BENT	926.30	926.30
1	REAR EXHAUST PIPE MOUNTING	NOT NECESSARY	158.00	-
1	REAR BUMPER SPONGE	CRACKED	123.50	123.50
1	REAR SPARE TYRE TOP BOARD	TORN	276.60	276.60
1	REAR SPARE TYRE WELL	TO REPAIR SEE LABOUR	780.90	-
3	REAR SPARE TYRE WELL INSULATION @\$279.60	NOT NECESSARY	838.80	-
1	REAR BOOT LID HANDLE	CRACKED	350.50	198.00
1	REAR BOOT LID WEATHER STRIP	CUT	148.10	148.10
1	REAR BOOT LID SENSOR	DAMAGED	106.80	106.80
2	REAR FENDER INNER SHIELD @\$47.30	NOT NECESSARY	94.60	-

Report Ref No. CS/SMO17017077/Atbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,505.10	-1,737.25
			7,515.30	5,211.75
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	380.00	220.00
			380.00	220.00
	<u>LABOUR</u>			
	TO SUPPLY REAR WINDSCREEN SEALANT.		50.00	50.00
	TO SUPPLY REAR END PANEL INNER SEALANT.		200.00	60.00
	REMOVE & REINSTALL REAR WINDSCREEN.		150.00	120.00
	REMOVE & REINSTALL EXHAUST PIPE.		150.00	80.00
	REMOVE & REINSTALL PETROL TANK.		200.00	80.00
	REMOVE & REINSTALL REVERSE SENSOR.		150.00	50.00
	REMOVE & REINSTALL BOOT LID INNER GARNISH.		150.00	60.00
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE WELL.		2,500.00	1,300.00
	RESPRAY PAINTING.		1,800.00	1,200.00
	TUFF KOTE.		150.00	60.00
			5,500.00	3,060.00
GRAND TOTAL			13,395.30	8,491.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,800.00

Report Ref No. CS/SMO17017077/Atbe2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.