

ASS. REC. BY:

REF: CS/QBE17017086/T1cbq

Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person):

Syuhada Ahman of QBE

Date/Time:

4/9/17 5:07p.m

Estimated Cost:

Bill to:

①

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCW 2235

Insured:

at Workshop m/s

Woon Meng

Tel:

63/6/131

of

50, Bukit Baruk st 23 # 01-06

Policy No:

Claim No:

VC010671

Sum Insured:

Excess:

\$3,500.00

Make of Veh:

(Client's Record)

D.O.A.

29/08/17

CA / (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

04/9/2017 5:15pm

Person Contacted:

Ms Heng

Vehicle

①

OUT

Date/Time

Action/Instruction

(✓) Estimate

SCW 2235 - CS / MSG 10013505 / Rbn - D.O.A 7/7/2010


BUTTERFIELD Taphan

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$200K.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Ms Heng Vehicle: IN / OUT

Veh No: SCW 2235 Yr Regn: 2014 April
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 730 LI C.C. 2996
 Colour: Bronze A/C: Insured / Std / NI / NA
 Sp. Reading: 52675 T/Radio: Insured / Std / NI / NA

Eng/No: _____
 C/No: WBAZE 220500 21097

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18
 R: 245/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 4/9/17 @ 1730

Survey held at Woon Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
5/9/17	email preli Rev to syaheeda.
5/9/17	syaheeda email approved CA.
5/9/17 @ 3.25 pm	spoked to Ms Heng, CA, Ex: 3500
13/12	2/5/6700, 4 days confirm with ms Heng for e-mail. (Red. 9030.85, 57%)

RECEIVED 14 DEC 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. \$ _____

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

Report Format : OD

Lump Sum / I.B.I. (\$ 6700)

TOTAL

300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CS/QBE17017086/T1gb		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 04-09-2017		
		Code : QBE		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SCW 223S
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		3,500.00
Assign From		Assign Date		04/09/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date 29/08/2017		Inspection Date 04/09/2017		
Survey held at		WOON MENG MOTOR PTE LTD		
		50 BUKIT BATOK ST 23		
		#01-06 MIDVIEW BUILDING		
		SINGAPORE 659578		
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE)				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Ai Phing (LKKAUTO)

From: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Sent: Tuesday, 5 September, 2017 3:15 PM
To: Ai Phing (LKKAUTO)
Cc: SUR
Subject: RE: NEW ASSIGNMENT OD : SCW223S ; QBE REF : VC010671

Please proceed to authorise and finalise.

Thank you.

Syaheeda Othman
Senior Executive, Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax : +6533 3270
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

-----Original Message-----

From: Ai Phing (LKKAUTO) [mailto:aipling@lkkauto.com]
Sent: Tuesday, 5 September, 2017 2:23 PM
To: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: NEW ASSIGNMENT OD : SCW223S ; QBE REF : VC010671

Dear Syaheeda,

Enclosed with preliminary advise of vehicle SCW 223S.
We have not authorise repair.

Best Regards,
Ai Phing | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25
| S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)
Sent: Monday, 4 September, 2017 5:20 PM
To: 'Syaheeda Nacah Binte Mohamed Othman' <syaheeda.othman@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: NEW ASSIGNMENT OD : SCW223S ; QBE REF : VC010671

Dear Syaheeda Othman,

Thank you for the assignment.

Ai Phing (LKKAUTO)

From: Ai Phing (LKKAUTO)
Sent: Tuesday, 5 September, 2017 2:23 PM
To: 'Syaheeda Nacah Binte Mohamed Othman'
Cc: SUR
Subject: RE: NEW ASSIGNMENT OD : SCW223S ; QBE REF : VC010671
Attachments: SCW 223S.pdf

Dear Syaheeda,

Enclosed with preliminary advise of vehicle SCW 223S.
We have not authorise repair.

Best Regards,
Ai Phing | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25
| S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO)
Sent: Monday, 4 September, 2017 5:20 PM
To: 'Syaheeda Nacah Binte Mohamed Othman' <syaheeda.othman@qbe.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: NEW ASSIGNMENT OD : SCW223S ; QBE REF : VC010671

Dear Syaheeda Othman,

Thank you for the assignment.

Best Regards,
Catherine Chong | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Syaheeda Nacah Binte Mohamed Othman [mailto:syaheeda.othman@qbe.com]
Sent: Monday, 4 September, 2017 5:07 PM
To: assignments <assignments@lkkauto.com>
Subject: NEW ASSIGNMENT OD : SCW223S ; QBE REF : VC010671

Dear Sir,

OD New Assignment.

OD XS - YEID \$3500.00

catherine

From: Syaheeda Nacah Binte Mohamed Othman <syaheeda.othman@qbe.com>
Sent: Monday, 4 September, 2017 5:07 PM
To: assignments
Subject: NEW ASSIGNMENT OD : SCW223S ; QBE REF : VC010671
Attachments: 20170904124943.pdf

Dear Sir,

OD New Assignment.

OD XS - YEID \$3500.00

Taufik - your surveyor is there to survey already.

Fyna.

Syaheeda Othman
Senior Executive, Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
DID: +6477 1130 Fax : +6533 3270
Email: syaheeda.othman@qbe.com
Visit us on the web at www.qbe.com.sg

-----Original Message-----

From: Heng Sew Sow [mailto:woonmeng@singnet.com.sg]
Sent: Monday, 4 September, 2017 1:33 PM
To: Angeline Koh <angeline.koh@qbe.com>
Subject: FW: SCW223S On 29.08.17

Dear Jenny

We refer to the above accident

Kindly arrange a surveyor to survey of vehicle SCW223S and attached GIA report for your reference.

Location : 50, Bukit Batok St 23 # 01- 06 Midview Building (S) 659578 (Vehicle in)

Thank you.

Woon Meng Motor Pte Ltd
Tel ; 63161131
Fax : 63167050

Your message is ready to be sent with the following file or link attachments:

20170904124943

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : VC010671

Date: 05-09-2016

Our Ref : CS/QBE17017086/T1gb

The Motor Claims Department
QBE Insurance International Ltd

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SCW 223S


We thank you for the instruction on 04-09-2017.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 04-09-2017 at the premises of M/s WOON MENG MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ 15,732.85
Revised Estimate Amount	: S\$ 8,187.65
"Check" Items Amount	: S\$ 6,425.20
Market Value	: S\$ 200,000.00
LTA Reimbursement Value	: S\$ 139,635.00
Nett Value	: S\$ 60,365.00

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages Consistent.
Repair Cost Economical.
We have not authorize repairs.

Yours faithfully

Mohamed Taufikh
Automotive Assessor

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 5839M

Vehicle Details

Vehicle No.: SCW223S

Vehicle to be Exported: No

Intended De-registration
Date: 05 Sep 2017

Vehicle Make: B.M.W.

Vehicle Model: 730LI AT D/AB 4DR SR LED DSC NAV HUD

Primary Colour: Brown

Manufacturing Year: 2013

Engine No.: 08518671N52B30AF

Chassis No.: WBAYE22050DZ21097

Maximum Power
Output: 190.0 kW (254 bhp)

Open Market Value: \$77,398.00

Original Registration
Date: 28 Apr 2014

First Registration Date: 28 Apr 2014

Transfer Count: 0

Actual ARF Paid: \$111,317.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 27 Apr 2024

PARF Rebate Amount: \$83,487.00

Intended COE Rebate Details

COE Expiry Date: 27 Apr 2024

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$84,504.00

COE Rebate Amount: \$56,148.00

Total Rebate Amount: \$139,635.00

The information contained herein is correct as at 05 Sep 2017



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 27 Aug 2017 at 01:09 AM

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	30/08/2017 11:48
Date Of Accident	29/08/2017 18:40
Exact Location Of Accident	MCE EXITING TOWARDS ECP
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SCW223S
Insured/Policyholder	
Name Of Registered Owner	LUBRITRADE TRADING PTE LTD
Co Reg No	199405839M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63237223
Vehicle Particulars	
Manufacturer	BMW
Model	730LI AT D/AB 4DR SR LED DSC NAV HUD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8-V0010324-MVA-R002
Cover Note Number	
Driver	
Name of Driver	KENNETH HO HONG WEI
NRIC No	S9713070A
Date Of Birth	11/04/1997
Occupation	INDOOR
Date Of Driving Pass	17/06/2016
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85111104
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	28, JALAN ULU SIGLAP
Postcode	457190
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

IT HAPPEN ALONG MCE, WHILE EXITING ECP CHANGI. THERE WAS A LONG CONGESTION WHILE EXITING ECP CHANGI. THE CARS WERE MOVING SLOWLY AND I WAS BEHIND CAR B. WHEN CAR B MOVED FORWARD, I SAW THAT I COULD MOVE FORWARD AS WELL. HOWEVER, I ACCIDENTALLY STEP ON THE ACCELERATOR AND MY VEHICLE COLLIDED INTO THE CAR INFRONT OF ME, WHICH INCIDENTALLY KNOCK ONTO CAR C. AFTER THE COLLISION, I IMMEDIATELY PRESS THE HAZARD LIGHT AND STEP OUT OF THE VEHICLE. OWNERS OF CAR B AND CAR C DID NOT SUSTAIN ANY DAMAGES. CAR B HAD A PAINT TRANSFER DAMAGE ON THE REAR, AND THE FRONT LICENSE PLATE WAS SLIGHTLY DENTED IN WITH A CHIP. CAR C SUFFERED FROM MINOR PAINT DAMAGES AT THE BOTTOM REAR. THESE WERE ALL VISUAL FROM THE SCENE OF THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH9742Z
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	WONG CHIN SING
NRIC/Passport Number	S1282762H
Contact Number	98190992
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
------	--

Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJG8368G

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

HIRANAND REWACHAND MIRPURI

NRIC/Passport Number

S1412291E

Contact Number

96375804

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

IMPORTANT NOTICE

- ### 8. Consent under the Personal Data Protection Act (PDPA)

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), w hich may be sited outside of Singapore, for one or more of the above Purposes.




Diagram illustrating the sequence of events and damage to the vehicles involved in the collision:

- Vehicle A (SCW 223S):** The first vehicle in the sequence, labeled "A".
- Vehicle B (SLH 9742Z):** The second vehicle, labeled "B".
- Vehicle C (BJG 2468C):** The third vehicle, labeled "C".
- Damage to Vehicle A:** "minc" (minor damage) is indicated on the front of vehicle A.
- Damage to Vehicle B:** "paint transfer damaged" is indicated on the front of vehicle B, and "damaged area" is indicated on the rear of vehicle B.
- Damage to Vehicle C:** "min. paint damaged" and "damaged area" are indicated on the front of vehicle C.
- Sequence of Events:** Arrows indicate the direction of travel from left to right. A note "at MCE Exiting ECP towards Changi" is written above the vehicles.
- Other Driver:** A note "other driver" is written above vehicle B.
- Licence Plate of B:** A note "from licence plate of B" is written below vehicle B.

(☒) Claim Own Damage (☐) Claim TP (☐) Reporting Only (☐) Claim OD/TP at other workshop

Describe Circumstances of the Accident

It happen along MCE, while exiting ECP Changi.

There was a long congestion while exiting ECP Changi.
The cars were moving slowly, and I was behind Car B.

When Car B moved forward, I saw that I could move forward as well.

However, I accidentally ~~hit~~ step on the accelerator and ~~my~~ my vehicle

collided into the car in front of me, which ~~or~~ incidentally ~~knock~~ knock over Car C.

After the ~~collide~~ collision, I immediately press the hazard light and step out of the vehicle. Car B and Car C did not.

Owners of Car B and Car C did not sustain any ~~damaged~~ damages. Car B had a paint transfer damage on the rear, and the front driver plate was slightly dented in with a chip.

Car C suffered from minor paint damage at the ~~bottom~~ bottom rear.

These were all visited from the scene of the accident.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Witnessed by Reporting Centre Personnel

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng@singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

OD Claim

To : QBE Insurance (Singapore) Pte Ltd
Motor Claims Dept

Date : 04 Sep 2017

Dear Sirs :

Fax : 65333270

RE : ESTIMATE COST FOR BMW 730L - SCW223S
ALONG MCE EXITING TOWARDS ECP ON 29/08/2017

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front bumper. <i>de✓</i>	1pc	\$ 1,000.00
2	Front bumper towing cover. <i>X nn.</i>	2pcs	\$ 38.00
3	Front bumper nozzle cover @\$40ea. <i>? de✓</i>	2pcs	\$ 80.00
4	Front bumper lower grille. <i>de✓</i>	1pc	\$ 50.00
5	Front bumper lower grille side outer @\$50ea. <i>not de✓</i>	2pcs	\$ 100.00
6	Front bumper lower grille inner (side) @\$50ea <i>ZH-de✓</i>	2pcs	\$ 100.00
7	Front fog lamp @\$180ea <i>cut✓</i>	2pcs	\$ 360.00
8	Front bumper lower grille outer chorme long@\$40ea <i>cut✓</i>	2pcs	\$ 80.00
9	Front bumper lower grille outer chorme short@\$55ea <i>cut✓</i>	2pcs	\$ 110.00
10	Front center grille @\$140ea <i>cut✓</i>	2pcs	\$ 280.00
11	Front center grille chorme @\$58ea <i>cut✓</i>	2pcs	\$ 116.00
12	Front headlamp @\$3000ea <i>ZH-cut✓, RH-Xnn.</i>	2pcs	\$ 6,000.00
13	Front bumper sponge. <i>de✓</i>	1pc	\$ 50.00
14	Front bumper reforcemet. <i>bt✓</i>	1pc	\$ 430.00
15	Front bumper sensor @\$195ea <i>? nn✓</i>	1 4 pcs	\$ 780.00 <i>195</i>
16	Front support top garnish (bumper). <i>cut✓</i>	1pc	\$ 150.00
17	Front support top beam. <i>bt✓</i>	1pc	\$ 135.00
18	Front support top side garnish @\$80ea. <i>Xnn.</i>	2pcs	\$ 160.00
Sum Carried Forward			\$ 10,019.00

Sum Carried Forward**\$ 10,019.00**

19	Front air con condenser. <i>X un</i>	1pc	\$ 660.00	
20	Front radiator. <i>X un</i>	1pc	\$ 680.00	6236.
			\$ 11,359.00	
			\$ 1,703.85	
	Add 15%		\$ 13,062.85	7171.40.
21	Coolant. <i>X un</i>		\$ 45.00	
22	Front number plate. <i>ht</i>	1pc	\$ 35.00	35
			\$ 13,142.85	

Labour Charge & Misc

To remove, replace, repair & install damaged parts.	}	\$ 1,000.00	600
To R & R air con condenser.		\$ 180.00	X
To R & R front radiator.		\$ 150.00	X
To R & R wiring.		\$ 80.00	30
To R & R air con system.	}	\$ 180.00	X
To refill & top up air con gas.	}		
To putty & spray painting.		\$ 1,000.00	1130.

Total**\$ 15,732.85**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

All prices quoted are subjected to 7% GST.

Acknowledged by Repairer
Signature:
Date:

This is a computer generated document. No signature is required.

\$8336.40

1/5 of 6700
4 days.

245/50R18

Dunlop.

sur@lkkauto.com

Taufik 97495749

Ex: ~~homestead~~

Revert.

4/9/17 @ 1730

Ex \$3500

4 days

Resurvey before paint



Woon Meng Motor Pte Ltd

Address: 50 Bukit Batok Street 23 #01-06 Midview Building, Singapore 659578
Tel: +6563161131 / +6563161151 FAX: +6563167050
Workshop 42, Sungei Kadut Ave Singapore 729666 Tel: +6563628523
Email: woonmeng@singnet.com.sg
Co Reg No.200603678M GST Reg No. 20-0603678M

TAX INVOICE NO: WM2018/C04201/dec/OD

Date : 12 Dec 2018

QBE Insurance (Singapore) Pte Ltd
1 Raffles Quay # 29-10
South Tower
Singapore 048583

Attn Motor Claims Department

Dear Sirs

RE : REPAIR COST FOR BMW 730L - SCW223S
ON 29/08/2017

<u>ITEM</u>	<u>DESCRIPTION</u>	<u>PRICE</u>
1	Cost of repair.	\$ 6,700.00
	Policy Excess	\$ (3,500.00)
		<hr/>
		\$ 3,200.00
	ADD GST 7%	\$ 224.00
	TOTAL AMOUNT S\$	<hr/>
		\$ 3,424.00

S/D : Three Thousand Four Hundred And Twenty Four Only.

This is a computer-generated document. No signature is required.

COMPANY: QBE Insurance (Singapore) Pte Ltd

MOTOR CLAIM NO.

SATISFACTION FORM

I/We hereby declare that the repairs to my/our BMW No. SCW2236

have been completed to my/our satisfaction and I/We agree that payment of the account
for such repairs is in full discharge of my/our claim under Policy No. RVN1324-ANAR002
respect of the damage caused in the accident which occurred on the 29 day
of Aug 2017

Date 11/9/2017

Signature [Signature]






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CS/QBE17017086/T1cbe2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 14-12-2018		
		Code : QBE		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SCW 223S	
Policy No.	8-V0010324-MVA-R002	Coverage (\$)	0.00	
Claim No.	VC010671	Excess (\$)	3,500.00	
Assign From		Assign Date	04/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 730LI	c.c	2996	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WBAYE22050DZ21097	Colour	BRONZE	
Odometer	52673	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	DUNLOP	6 mm	
L/H Front Tyre	245/50 R18	DUNLOP	6 mm	
R/H Rear Tyre	245/50 R18	DUNLOP	6 mm	
L/H Rear Tyre	245/50 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/08/2017	Inspection Date	04/09/2017	
Survey held at	WOON MENG MOTOR PTE LTD 50 BUKIT BATOK ST 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A)THE MARKET VALUE IS S\$200,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCW 223S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (WCP)	DEFORMED	1,000.00	1,000.00
2	FRONT BUMPER TOWING COVER (WCP)	NOT NECESSARY	38.00	-
2	FRONT BUMPER NOZZLE COVER @\$40.00 (WCP)	DEFORMED	80.00	80.00
1	FRONT BUMPER LOWER GRILLE (WCP)	DEFORMED	50.00	50.00
2	FRONT BUMPER LOWER GRILLE SIDE OUTER @\$50.00 (WCP)	DEFORMED	100.00	100.00
2	FRONT BUMPER LOWER GRILLE INNER (SIDE) @\$50.00 (WCP)	DEFORMED	100.00	100.00
2	FRONT FOG LAMP @\$180.00 (WCP)	CUT	360.00	360.00
2	FRONT BUMPER LOWER GRILLE OUTER CHROME LONG @\$40.00 (WCP)	CUT	80.00	80.00
2	FRONT BUMPER LOWER GRILLE OUTER CHROME SHORT @\$55.00 (WCP)	CUT	110.00	110.00
2	FRONT CENTER GRILLE @\$140.00 (WCP)	CUT	280.00	280.00
2	FRONT CENTER GRILLE CHROME @\$58.00 (WCP)	CUT	116.00	116.00
2	FRONT HEADLAMP @\$3000.00 (WCP)	N/S CUT / O/S NOT NECESSARY	6,000.00	3,000.00
1	FRONT BUMPER SPONGE (WCP)	DEFORMED	50.00	50.00
1	FRONT BUMPER REFORCEMENT (WCP)	BENT	430.00	430.00
4	FRONT BUMPER SENSOR @\$195.00 (WCP)	NOT WORKING - 1PC ONLY	780.00	195.00
1	FRONT SUPPORT TOP GARNISH (BUMPER) (WCP)	CRACKED	150.00	150.00
1	FRONT SUPPORT TOP BEAM (WCP)	BENT	135.00	135.00
2	FRONT SUPPORT TOP SIDE GARNISH @\$80.00 (WCP)	NOT NECESSARY	160.00	-
1	FRONT AIR CON CONDENSER (WCP)	NOT NECESSARY	660.00	-
1	FRONT RADIATOR (WCP)	NOT NECESSARY	680.00	-
	COST PLUS 15%		1,703.85	935.40
			13,062.85	7,171.40
<u>SPECIAL NETT ITEMS</u>				
1	COOLANT (SN)	NOT NECESSARY	45.00	-
1	FRONT NUMBER PLATE (SN)	BENT	35.00	35.00
			80.00	35.00

Report Ref No. CS/QBE17017086/T1cbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, REPLACE, REPAIR & INSTALL DAMAGED PARTS.		1,000.00	600.00
	TO R & R AIR CON CONDENSER.	NOT NECESSARY	180.00	-
	TO R & R FRONT RADIATOR.	NOT NECESSARY	150.00	-
	TO R & R WIRING.		80.00	30.00
	TO R & R AIR CON SYSTEM. TO REFILL & TOP UP AIR CON GAS.	NOT NECESSARY	180.00	-
	TO PUTTY & SPRAY PAINTING.		1,000.00	500.00
			2,590.00	1,130.00
	GRAND TOTAL		15,732.85	8,336.40

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,700.00
LESS EXCESS			-3,500.00
NETT LIABILITY			3,200.00

Report Ref No. CS/QBE17017086/T1cbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.