

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5137X -*Not Authored*
*11/12/2017***AAD1709-009**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5137X - CANDY

VF1ABL15AUC275895

RENAULT

LATITUDE

31.08.2017

*AKA***PART****LIST**

1	1	BUMPER COVER FRT	\$	Sn	1,259.42	
2	1	BUMPER RETAINER FRT RH	\$	Sn	151.41	
3	1	BUMPER BRACKET FRT RH	\$	N	181.75	
4	1	HEADLAMP RH	\$	Sn	1,184.43	
5	1	HEADLAMP PANEL FRT RH	\$	N	152.15	
6	1	FENDER PANEL FRT RH	\$	N	783.83	
7	1	WHEELARCH FRT RH	\$	Sn	278.84	
8	1	DOOR MIRROR RH	\$	Bo	1,483.40	
9	1	DOOR MIRROR GLASS RH	\$		148.20	X
10	1	DOOR MIRROR BACK COVER RH	\$		218.46	X
11	1	DOOR PANEL FRT RH	\$	N	2,844.66	
12	1	DOOR HINGE UPPER RH	\$	N	274.50	
13	1	DOOR HINGE LOWER RH	\$	N	300.55	
14	1	DOOR CHECK FRT RH	\$	Sn	194.77	
15	1	DOOR GRAB HANDLE FRT RH	\$	Sn	210.96	
16	1	DOOR HANDLE OUTER FRT RH	\$	Sn	258.12	
17	1	DOOR HANDLE CAP FRT RH	\$	Sn	26.44	
18	1	DOOR HANDLE SEAL FRT RH	\$	Sn	7.89	
19	1	DOOR HANDLE COVER FRT RH	\$	Sn	13.22	
20	1	DOOR HANDLE MODULE FRT RH	\$	Sn	133.60	
21	1	DOOR FINISHER FRT RH	\$	Sn	515.06	
22	1	DOOR MOULDING FRT RH	\$	Sn	176.82	
23	1	DOOR WHETHERSTRIP FRT RH	\$	Sn	474.21	
24	1	DOOR SEAL LOWER FRT RH	\$	Sn	105.18	
25	1	DOOR SEAL FRT RH	\$	Sn	68.67	
26	1	DOOR WAIST SEAL OUTER FRT RH	\$	Sn	291.27	
27	1	ROCKER PANEL OUTER RH	\$	N	987.49	
28	1	DOOR PANEL REAR RH	\$	N	2,844.66	
29	1	DOOR GUIDE REAR RH	\$	Sn	176.82	
30	1	DOOR HINGE UPPER RH	\$	N	315.74	
31	1	DOOR HINGE LOWER RH	\$	N	300.55	

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5137X -**AAD1709-009**

32	1	DOOR CHECK REAR RH	\$	Sin	203.06
33	1	DOOR GRAB HANDLE REAR RH	\$	Sin	210.96
34	1	DOOR HANDLE OUTER REAR RH	\$	Sin	126.49
35	1	DOOR HANDLE CAP REAR RH	\$	Sin	35.52
36	1	DOOR HANDLE SEAL REAR RH	\$	Sin	7.89
37	1	DOOR HANDLE COVER REAR RH	\$	Sin	13.22
38	1	DOOR HANDLE MODULE REAR RH	\$	Sin	133.60
39	1	DOOR FINISHER REAR RH	\$	Sin	423.10
40	1	DOOR MOULDING REAR RH	\$	Sin	176.82
41	1	DOOR WHEATHESTRIIP REAR RH	\$	Sin	474.60
42	1	DOOR SEAL REAR RH	\$	Sin	187.08
43	1	DOOR WAIST SEAL OUTER REAR RH	\$	Sin	334.69
44	1	TAILLAMP RH	\$	Sin	552.55
45	1	TAILLAMP PANEL RH	\$	N	986.70
46	1	FENDER PANEL REAR RH	\$	N	3,299.13
47	1	WHEELARCH REAR RH	\$	Sin	543.47
48	1	BUMPER COVER REAR	\$	Sin	1,108.46
49	1	BUMPER LOWER REAR	\$	Sin	768.84
50	1	BUMPER BRACKET CTR REAR	\$	Sin	113.47
51	1	BUMEPR BRACKET SIDE RH REAR	\$	Sin	135.97
52	1	BUMEPR BRACKET CTR RH REAR	\$	Sin	44.99
53	1	BUMPER REFLECTOR RH	\$	Sin	43.61

TOTAL	\$	26,287.32
10%	\$	2,628.73
	\$	23,658.59

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	nn	66.00
2	1SET	WHEELARCH CLIP FRT RH	\$	nn	66.00
3	1SET	WHEELARCH CLIP FRT RH	\$	nn	66.00
4	1SET	RADAITOR GRILLE FRAME CLIP	\$	nn	52.00
5	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00
6	1	CAP HUB RH FRT	\$	Sin	35.00
7	1	RIM RH FRT	\$	Sin	385.00
8	1	TYRE RH FRT	\$	Sin	330.00
9	1	CAP HUB RH FRT RR	\$	Sin	35.00
10	1	RIM RH FRT RR	\$	Sin	385.00

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5137X -**AAD1709-009**

11	1	TYRE RH FRT RR	\$	330.00
12	1	DOOR STICKER "Trans-cab"	\$	80.00
13	1	DOOR STICKER "Classic"	\$	30.00
14	1	DOOR STICKER "6555-3333"	\$	80.00
15	1SET	REAR BUMPER CLIP	\$	66.00
16	1SET	WHEELARCH CLIP RR RH	\$	66.00
17	1SET	WHEELARCH CLIP RR RH	\$	66.00

TOTAL	\$	2,208.00
TOTAL PARTS	\$	25,866.59

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 801

To Check Electrical Lighting Concerned.

\$ 170.00 151

Putty and spray painting of the affected portion.

\$ 4,500.00 601

To check steering geometry and computer wheel alignment

\$ 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ 170.00 X

Towing Fees

\$ 120.00 X

To transfer of door fittings, attachment and perform water seepage test.

\$ 170.00 X

To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.

\$ 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 X

To Transfer Of Fender Fittings, Attachments And

Perform Water Seepage Test.

\$ 170.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) to be made
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL \$ 10,060.00

Over All Total \$ 35,926.59

(PARTS BY PARTS) Repair Days

15Days

Acknowledged by Repairer

Signature:

Date:

1 day