

Date/Time: 6/9/17 2:24pm

Bill to:

Tel: 67488824

Excess:

D.O.A. 3/9/17

H.O.D. Endorsement

Vehicle **IN** OUT[illegible]



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17017257/Gtb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-09-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 8499A	Veh. Inspected	SKM 8211G
Policy No.		Coverage (\$)	0.00
Claim No.	D17008526MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	06/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/09/2017	Inspection Date	06/09/2017
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	05-09-2017	Our Ref No. D17008526MFSH
Accident Date	03-09-2017	Claim Type. Third Party
Insured Vehicle	SH8499A	Third Party Vehicle. SKM8211G
Survey Location	Blk 3007 Ubi Road 1 #01-450	
Contact Person.	MS S.THANALETCHUMI	
Contact No.	67488824/ 92206746	Fax No. 67488834
Survey Type	WITHOUT PREJUDICE: NO EST PROVIDED (LIABILITY CLEAR / QUANTUM TO BE AGREED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	JACK CARS ENTERPRISE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/227702)



PRI Documents



Close



PRI Header Details

Claim No	D17008526MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & JACK CAR
Workshop Name	JACK CARS ENTERPRISE PTE LTD (Contact Person : MS S.THANALETCHUMI)	Survey Location & Contact Details	Blk 3007 Ubi Road 1 #01-450 Mobile: 92206746 , Phone: 67488824 , Fax: 67488834 EmailId: THANA@JACKCARS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: NO EST PROVIDED (LIABILITY CL AGREED)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH8499A	TP Vehicle No	SKM8211G
PRI Recieved Date	05-09-2017 10:46:59 PM	Surveyor Appointed Date	06-09-2017 02:27:37 PM	Surveyor Accept Date	06-09-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			


Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



ESTIMATE

DATE OF ACCIDENT : 03/09/2017
VEHICLE : SKM8211G
MAKE & MODEL : TOYOTA ALTIS
INSURANCE : FIRST CAPITAL INSURANCE LIMITED
SURVEYOR : LKK -

PARTS		CONDITION	COST
1.	FRONT BUMPER / Re		\$ 500
2.	FRONT BUMPER BRACKET - LEFT X NN		\$ 86
3.	FRONT GRILLE EMBLEM / Mc		\$ 86
4.	FRONT LOWER GRILLE / ee		\$ 135
5.	FRONT CHROME GRILLE / Cut		\$ 380
6.	HEADLAMP - LEFT / CMA		\$ 1500
7.	HEADLAMP - RIGHT / CMA		\$ 1500
8.	HEADLAMP LOWER BRACKET - LEFT X NN		\$ 135
9.	FOG LAMP COVER - LEFT X NN		\$ 105
10.	NUMBER PLATE / m's		\$ 38
11.	NUMBER PLATE COVER / CMA		\$ 23
12.	CLIPS x 20 / Mc		\$ 150
LABOUR			
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	400	\$ 650
2.	TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	400	\$ 1140
3.	TO CHECK LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	NN X 20	\$ 250
4.	TO CHECK WIRING & REWIRING	30	\$ 180
			830

Total : 2888.25



	PART - 25% :	\$ 3,478.50
	LABOUR :	\$ 2,220
	TOTAL :	\$ 5,698.50
	7% GST :	\$ 398.90
	GRAND TOTAL :	\$ 6,097.40

4 Days.

part by part

before paint photos.

Gino Gicay - 81880282

06/9/17

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17017257/Gtbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 28-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 8499A	Veh. Inspected	SKM 8211G	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17008526MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	06/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	MR053REH104001935	Colour	BLUE	
Odometer	42187	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	6 mm	
L/H Front Tyre	205/55 R16	DUNLOP	6 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/09/2017	Inspection Date	06/09/2017	
Survey held at	JACK CARS ENTERPRISE PTE LTD BLK 3007 UBI ROAD 1 #01-450 SINGAPORE 408700			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 8211G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	500.00	500.00
1	FRONT BUMPER BRACKET-LEFT	NOT NECESSARY	86.00	-
1	FRONT GRILLE EMBLEM	NECESSARY	86.00	48.00
1	FRONT LOWER GRILLE	DEFORMED	135.00	135.00
1	FRONT CHROME GRILLE	CUT	380.00	380.00
1	HEADLAMP-LEFT	CRACKED	1,500.00	794.00
1	HEADLAMP-RIGHT	CRACKED	1,500.00	794.00
1	HEADLAMP LOWER BRACKET-LEFT	NOT NECESSARY	135.00	-
1	FOG LAMP COVER-LEFT	NOT NECESSARY	105.00	-
	LESS 25% DISCOUNT		-1,106.75	-662.75
			3,320.25	1,988.25
1	NUMBER PLATE (SN)	MISSING	38.00	20.00
1	NUMBER PLATE COVER (SN)	CRACKED	23.00	15.00
20	CLIPS (SN)	NECESSARY	150.00	35.00
	LESS 25% DISCOUNT		-52.75	-
			158.25	70.00
LABOUR				
	TO PUTTY & SPRAY PAINT OF AFFECTED AREA.		650.00	400.00
	TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS;KNOCK,JACK,WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.		1,140.00	400.00
	TO CHECK LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE.	NOT NECESSARY	250.00	-
	TO CHECK WIRING & REWIRING.		180.00	30.00
	-		-	-
	-		-	-
	-		-	-
			2,220.00	830.00
GRAND TOTAL			5,698.50	2,888.25



RECOMMENDED COST OF REPAIRS			2,888.25
-----------------------------	--	--	----------

Report Ref No. CS/FCI17017257/Gtbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.