

ASS. REC. BY

REF: CS/MSG17017276/T14602

Special Instruction

SURVIVOR

MELMEN

Tautah

ASSIGNMENT (Office)

From (Person)

Monica Chung

of MSIG

Date/Time: 6/9/17 11:23am

Estimated Cost

Bill to

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKE211B

Insured: ES1188B

at Workshop m/s

Performance Motors

Tel: 6319 0174

of

303 Alexandra Road

Policy No:

A80427631QMX

Claim No:

528771

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 3/18/17

CA / REV / REP. / REV 24 HRS

'wp'

22.05.2017 @ 2pm on

H.O.D. Endorsement:

Date/Time: 6/9/17 12:05pm

Person Contacted: caroline

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SKE211B-X

ES1188B-X

Part by Part \$2671.05 (Red: 3944.70; 59%)

Tan Jm

REF: MS1G

ASSIGNMENT

2015, June

From: _____ Date: 22/9/17
 Estimated Cost: _____
 OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SKE 211B
 at Workshop m/s: Performance Motors
 of: 303 Alexandra Road
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

2pm owner waiting

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs _____ days Res: Yes or No
 Lum Sum _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time: _____ Action / Instruction: SKP 6466 Han TP MS1G.

Veh No: SKE 211B Yr Regn: 2015, June
 Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BMW X4 CC: 1997
 Colour: White AC: Insured / Std / NI / NA
 Sp. Reading: 56185 T.Radio: Insured / Std / NI / NA
 Eng. No: _____
 C No: WBA XW 520000 F78644
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim
 Tyre Size: F: 275/40R19
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal: 6 mm R/Bal: 6 mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A: _____ D.O.I: 22/9/17 2pm
 Survey held at: PML
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

[Signature]
 12/2/2018

RECEIVED 12 FEB 2018

Date/Time File Pass to? ☐ : Prel. Report
☒ : Final Report
 Date/Time File Return to?

Days Of Repair: 3
 Resurvey No. of Trip: 1

Report Format: TP
 Lump Sum / I.B.I: (\$) 2671.00

Add Fee: ☐ Site Insp (\$) ☐ Interview (\$) ☐ Tech. Invs (\$) ☐ Weekend (\$)

Survey Fee	
Transportation	
S + RS	
Photos	
Others	
TOTAL	210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG17017276/T1tb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 06-09-2017



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	ES 1188B	Veh. Inspected	SKE 211B
Policy No.	A80427631QMX	Coverage (\$)	0.00
Claim No.	528771	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	06/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/08/2017	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Sep 2017		06 Sep 2017 17:55 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: LEONG HEE SUAN, ID: S0125254B, Tel: +6597559128, Email: NOEMAIL

Main Claimant: ANG TECK YONG, ID: S1627756H

Vehicle Reg. No.: SKE211B **Date of Loss:** 31/08/2017 12:00 - :59

Claim Type: TP / 528771 **Policy/Cover Note No.:** A80427631QMX (Comprehensive)
Coverage: 06/05/2017 - 05/05/2018

Vehicle Reg. No. (Insured): ES1188B **Policy No. (Claimant):**

Excess:

Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941
Alexandra - Tel: 63190172/63190174

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH] ... [Imm.Advice due 07/09/2017]

Driver/Custodian (Insured): LEONG HEE SUAN (63 / Male), NRIC: S0125254B, Tel: +6597559128

Adj Asg. Remarks: ON WP

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Sent: Wednesday, 6 September, 2017 11:23 AM
To: 'Ashley Chong (LKK Auto)'
Cc: 'PBSP'; Monica Chung
Subject: FW: REQ FOR DIRECT SETTLEMENT - SKE211B AND ES1188B ON 31/08/2017
Attachments: img-906094644-ApeosPort-IV 3070(122003)-9471-170906094654.tif; 20170905_153930.jpg; 20170905_153938.jpg; 20170905_153944.jpg; 20170905_153948.jpg; 20170905_153953.jpg

Dear LKK,





Fyna. We will grant rights to you in merimen by today.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

A member of **MS&AD** INSURANCE GROUP

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Wednesday, 6 September, 2017 11:20 AM
To: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>
Subject: Re: REQ FOR DIRECT SETTLEMENT - SKE211B AND ES1188B ON 31/08/2017

Dear Rashita,

We agree to use the surveyor below as the SJE

1) LKK Auto Consultants Pte Ltd

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Rashitha Binte Shahuthuman

Sent: Wednesday, 6 September, 2017 10:48 AM

To: 'PBSP' <pml-pbsp@simedarby.com.sg>

Cc: Monica Chung <Monica_Chung@sg.msig-asia.com>; Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>

Subject: FW: REQ FOR DIRECT SETTLEMENT - SKE211B AND ES1188B ON 31/08/2017

OUR REF – TBA

WITHOUT PREJUDICE

Dear Caroline,

We propose one of the motor surveyor name in the list below to conduct the joint pre-repair survey as the single joint expert.

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd

To facilitate an expeditious claim settlement, we hope you are agreeable for any of the above surveyor to be the SJE (Single Joint Expert) .

If not, you may wish to nominate any of the 9 surveyors listed below as the SJE, depending on their availability:

- 1) Adrian Ling
- 2) Kenneth Kong
- 3) Marcus Chua
- 4) Henry Ng
- 5) Lau Kwok Kwong
- 6) Frankie Pang
- 7) Ng You Han
- 8) Gary Soon
- 9) Chow Bo Xiong

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.


NB: If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.





Thank you.

Rashitha

Senior Admin Officer

Direct line +65 6594 2582 | Direct fax +65 6225 7402 | Rashitha_shahuthuman@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | www.msig.com.sg | Follow us on    

From: Monica Chung
Sent: Wednesday, 6 September, 2017 10:13 AM
To: PBSP <pml-pbsp@sime-darby.com.sg>
Cc: Rashitha Binte Shahuthuman <rashitha_shahuthuman@sg.msig-asia.com>
Subject: FW: REQ FOR DIRECT SETTLEMENT - SKE211B AND ES1188B ON 31/08/2017

WITHOUT PREJUDICE

Dear Caroline,

We are agreeable to direct settlement based on our surveyor's recommendation. The accident location is wrong in the accident report. Please amend and let us have a copy.

Thank you.

Regards,

Monica Chung
Assistant Executive, Claims Services (Motor)
Direct line +65 6594 2552 | Direct fax +65 6225 7402 | monica_chung@sg.msig-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on



From: PBSP [<mailto:pml-pbsp@sime-darby.com.sg>]
Sent: Wednesday, September 06, 2017 9:53 AM
To: Claims <claims@sg.msig-asia.com>
Subject: REQ FOR DIRECT SETTLEMENT - SKE211B AND ES1188B ON 31/08/2017

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

In compliance with "State Courts Practice Directions Amendment No.1 of 2016 ", please let us have your list of assessors.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/09/2017 10:07
Date Of Accident	31/08/2017 11:45
Exact Location Of Accident	DUNEARN RD TWD KALLANG (CITY)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKE211B
Insured/Policyholder	
Name Of Registered Owner	ANG TECK YONG
NRIC No	S1627756H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91882111
Alternative Phone No	OFFICE-91882111

Vehicle Particulars

Manufacturer	BMW
Model	X4-2.0 XDRIVE28I (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC16B00074000
Cover Note Number	

Driver

Name of Driver	ANG TECK YONG
NRIC No	S1627756H
Date Of Birth	15/10/1964
Occupation	INDOOR
Date Of Driving Pass	07/04/1982
Driving Experience	35 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91882111
Fax Number	
Contact Number	OFFICE-91882111
Email Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own
Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLANS

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ES1188B

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

10:20am
2/9/2017
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Sketch Plan

Denecon Road
B A

1A SKE011B
2A ES1188B

Sketch Plan Pg. 2

Describe Circumstances of the Accident

On the 31.08.2017 about 1145 at Dunearn Road.
My car SKED113 was hit from behind by ES1188R.
The Driver Mr. Leong advised me to claim insurance.

Declaration

We declare the foregoing particulars are true in every respect.

1420am
2/9/2017
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

06 SEP 2017

ESTIMATE

REC 05/09/17 @ 6pm

Estimate No. : b1 44040
Date Estimated : 05/09/2017
Prepared By : Wong Yit Loong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Ang Teck Yong
674 Choa Chu Kang Crescent
#04-417

Singapore 680674

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE211B	0F78644	26/06/2015	X4 xDrive 28i	0

DESCRIPTION

Replace rear bumper and remove attachment etc including knock
out accident dent

352

850

VALUE

1,700.00

Spray rear bumper

934

1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150

177.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150

177.00

Sundries.

new

40

80.00

Total Labour 1: 3,172.00

DESCRIPTION

RR BUMPER CARRIER ECE
FLAP TOWING EYE REAR
RR LH BUMPER MOUNTING MIDDLE
RR RH BUMPER MOUNTING MIDDLE
COVER MIDDLE BOTTOM
REAR BUMPER PANEL PRIMED (X LINE)
REAR BUMPER CLADDING (PDC/SCHWARZ)
UNDERSIDE GUARD PRIMED REAR (X LINE)
ULTRASONIC SENSOR BLACK CTR RR
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC
1	720.05
1	14.05
1	141.65
1	141.65
1	67.00
1	1,322.70
1	194.50
1	337.05
2	242.65
4	4.95

VALUE

720.05

14.05

141.65

141.65

67.00

Rx 1,322.70

de 194.50

de 337.05

? 485.30

new 19.80

Total Parts : 3,443.75

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 44040
Date Estimated : 05/09/2017
Prepared By : Wong Yit Loong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE211B	0F78644	26/06/2015	X4 xDrive 28i	0

Accident No. / 3rd Party / Uninsured / Road Side Assistance

Report No. _____ Claim No. _____

Date & Time 22/9/17 2:30pm

Surveyor's Name Tanjun

Surveyor's Tel 17445149

Approved Yes / No

Remarks Resurvey before paint 3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6629.25

Labour 1	:	3,172.00
Parts	:	3,443.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	463.10
Grand Total	:	7,078.85

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44040
Date Estimated : 05/09/2017
Prepared By : Wong Yit Loong

Page No. :

REPAIR FOR -
Ang Teck Yong
674 Choa Chu Kang Crescent
#04-417

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 680674

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SKE211B	0F78644	26/06/2015	X4 xDrive 28i	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To replace rear bumper and attachment include knocking out dents caused by the accident	852.00		852.00		
To spray paint rear bumper	934.00		934.00		
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00		
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00		
Sundries.	40.00		40.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CLADDING (PDC/SCHWARZ)	194.50	1.00		194.50
UNDERSIDE GUARD PRIMED REAR (X LINE	337.05	1.00		337.05
# EXPANDING RIVET *	1.35	10.00		13.50 (A) all ✓

SUPPLEMENTARY ITEMS

Total Labour :	2,126.00
Total Parts :	545.05
Total Labour & Parts :	2,671.05
Deduction for Excess :	0.00
Total Repair Costs less Excess:	2,671.05
GST @7%:	186.97
Grand Total :	2,858.02

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44040
Date Estimated : 05/09/2017
Prepared By : Wong Yit Loong

Page No. :

REPAIR FOR -
Ang Teck Yong
674 Choa Chu Kang Crescent
#04-417

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 680674

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SKE211B	0F78644	26/06/2015	X4 xDrive 28i	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET *	1.35	10.00		13.50

Total Labour :	0.00
Total Parts :	13.50
Total Labour & Parts :	13.50

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17017276/T1TBN2

Date: 13/02/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80427631QMX
Claimant Vehicle No :	SKE211B	Insured Vehicle No :	ES1188B
Date of Loss:	31/08/2017	Nature of Claim:	TP
		Claim No:	528771

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE211B	Engine No:	A7930808N20B20A
Make & Model:	BMW X4, 2.0 xDrive28i (A)	Chassis No:	WBAXW320000F78644
Reg. Date:	26/06/2015 (Man. Year: 2014)	Odometer:	56155 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40R19	Rear Tyre Size:	275/40R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,537.25	585.05	2,952.20	83.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,092.00	2,086.00	1,006.00	32.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,629.25	2,671.05	3,958.20	59.71
+ GST 7.00/7.00% (S\$)	464.05	186.97	277.08	59.71
Nett Amount (S\$)	7,093.30	2,858.02	4,235.28	59.71

INSPECTION

Date of Assignment:	06/09/2017	
Date Inspected:	22/09/2017 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2018)	
Parts: M1-SUV	BMW X4 2.0 xDrive28i (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SKE211B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*RR BUMPER CARRIER ECE	Not Necessary	720.05 FS	*- FS
2	1	*FLAP TOWING EYE REAR	Not Necessary	14.05 FS	*- FS
3	1	*RR LH BUMPER MOUNTING MIDDLE	Not Necessary	141.65 FS	*- FS
4	1	*RR RH BUMPER MOUNTING MIDDLE	Not Necessary	141.65 FS	*- FS
5	1	*COVER MIDDLE BOTTOM	Not Necessary	67.00 FS	*- FS
6	1	*REAR BUMPER PANEL PRIMED (X LINE)	Repair	1,322.70 FS	*- FS
7	1	*REAR BUMPER CLADDING (PDC/SCHWARZ)	Deformed	194.50 FS	*194.50 FS
8	1	*UNDERSIDE GUARD PRIMED REAR (X LINE)	Deformed	337.05 FS	*337.05 FS
9	2	*ULTRASONIC SENSOR BLACK CTR RR	Not Necessary	485.30 FS	*- FS
10	4	*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	19.80 FS	*- FS
11	10	*EXPANDING RIVET	Necessary	13.50 FS	*13.50 FS
12	1	*SUNDRIES	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	3,537.25	585.05
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDING KNOCK OUT ACCIDENT DENT	New	1,700.00	852.00
2	SPRAY REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			3,092.00	2,086.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >