

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44040
Date Estimated : 05/09/2017
Prepared By : Wong Yit Loong

Page No. :

REPAIR FOR -
Ang Teck Yong
674 Choa Chu Kang Crescent
#04-417

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 680674

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKE211B	0F78644	26/06/2015	X4 xDrive 28i	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachment include knocking out dents caused by the accident	852.00		852.00	
To spray paint rear bumper	934.00		934.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
Sundries.	40.00		40.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CLADDING (PDC/SCHWARZ)	194.50	1.00		194.50
UNDERSIDE GUARD PRIMED REAR (X LINE	337.05	1.00		337.05
# EXPANDING RIVET *	1.35	10.00		13.50 (A) all ✓

SUPPLEMENTARY ITEMS

Total Labour :	2,126.00
Total Parts :	545.05
Total Labour & Parts :	2,671.05
Deduction for Excess :	0.00
Total Repair Costs less Excess:	2,671.05
GST @7%:	186.97
Grand Total :	2,858.02