

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3790 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>deformed</i>	\$ 2,445.00	<i>1956</i>
2	FRONT BUMPER GRILLE <i>As per me</i>	\$ 106.00	<i>X</i>
3	LOCKING CLIP <i>2 new</i>	14 \$ 47.00	<i>X</i>
4	FOAM FILLER	\$ 193.00	<i>X</i>
5	REINFORCEMENT BEAM	\$ 674.00	<i>X</i>
6	FRONT PARKING SENSOR OUTER <i>2 new</i>	1 \$ 208.00	<i>X</i>
7	HEADLAMP MOUNTING RH <i>new</i>	\$ 100.00	<i>X</i>
8	LIFT CYLINDER RH <i>new</i>	\$ 204.00	<i>X</i>
9	LED HEADLAMP RH <i>cracked</i>	\$ 9,454.00	<i>7563 20</i>
10	SUNDRIES <i>As per me</i>	\$ 300.00	<i>X</i>
TOTAL SPARE PARTS		: \$ 13,731.00	
TOTAL LABOUR CHARGES		: \$ 3,572.00	
GRAND TOTAL		: <u>\$ 17,303.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 08/09/17
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08/09/17

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager



Allan Wu
Claims Consultant

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 1730F

Vehicle Details

Vehicle No.: SLN3790S

Vehicle to be Exported: No

Intended De-registration Date: 08 Sep 2017

Vehicle Make: AUDI

Vehicle Model: A6 1.8 TFSI ULTRA (PI) (NAV)

Primary Colour: White

Manufacturing Year: 2016

Engine No.: CYG016752

Chassis No.: WAUZZZ4G6HN043830

Maximum Power Output: 140.0 kW (187 bhp)

Open Market Value: \$40,434.00

Original Registration Date: 28 Apr 2017

First Registration Date: 28 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$43,608.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Apr 2027

PARF Rebate Amount: \$32,706.00

Intended COE Rebate Details

COE Expiry Date: 27 Apr 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$54,406.00

COE Rebate Amount: \$52,426.00

Total Rebate Amount: \$85,132.00

The information contained herein is correct as at 08 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 27 Aug 2017 at 01:09 AM

View Received Message

This mail is associated with :

***SLN3790S**
OD
Sep 4 2017 7:45PM
[LIEW FU TANG]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/09/2017 14:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$14527.00) - SLN3790S - Claim Handler: Loo, Tong Shing

Approved:14527.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 12 September, 2017 5:06 PM
To: Nora Khai; 'Claims Department'; SUR
Subject: RE: SLN 3790 S Own Damage Claim

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle ^{SLN 3790 S} **GBD 366A (Excess \$ 400.00 /-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)

Sent: Tuesday, 12 September, 2017 8:37 AM

To: Nora Khai <nora.khai@premiumauto.com.sg>; 'Claims Department' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SLN 3790 S Own Damage Claim

Dear Nora,

We are still pending approval from AIG, will give a chaser.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nora Khai [<mailto:nora.khai@premiumauto.com.sg>]

Sent: Monday, 11 September, 2017 5:57 PM

To: 'Claims Department' <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SLN 3790 S Own Damage Claim

Dear All,

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0871/2017/KS
Date	:	7-Sep-17

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

4 days - ok - jb - 9 dec

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Liew Fu Tang
Address	:	Blk 706 Pasir Ris Drive 10 #07-153 Singapore 510706
Telephone	:	HP +65 9635 8589
Type of Claim	:	Own Damage Claims
Policy No.	:	21000508922-00000
Vehicle No	:	SLN 3790 S
Model Code	:	Audi A61.8 TFSI S-Tronic
Model / Year	:	Apr-17
Engine No	:	CYG 016752
Chassis No	:	WAUZZZ4G6HN043830
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	4-Sep-17
Place of Accident	:	PASIR RIS CARPARK 700A

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 3790 S.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	480.00	\$ 480.00
2	To dismantle and renew front bumper and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$	1,400.00	\$ 750.00
3	To respray front bumper and front rh fender	\$	1,500.00	\$ 1,100.00
4	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 3,572.00	\$ 2,522.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3790 S.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,445.00	\$ 1,956.00
2	FRONT BUMPER GRILLE	\$ 106.00	
3	LOCKING CLIP	14 \$ 47.00	
4	FOAM FILLER	\$ 193.00	
5	REINFORCEMENT BEAM	\$ 674.00	
6	FRONT PARKING SENSOR OUTER	1 \$ 208.00	
7	HEADLAMP MOUNTING RH	\$ 100.00	
8	LIFT CYLINDER RH	\$ 204.00	
9	LED HEADLAMP RH	\$ 9,454.00	\$ 7,563.20
10	Added parts - see attached	\$ 102.00	\$ 81.60
11	SUNDRIES	\$ 300.00	
	TOTAL SPARE PARTS	\$ 13,833.00	\$ 9,600.80
	TOTAL LABOUR CHARGES	\$ 3,572.00	\$ 2,522.00
	GRAND TOTAL	\$ 17,405.00	\$ 12,122.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0871/2017/KS
1-Oct-17
Jeffery Tan
1
SLN 3790 S
Audi A61.8 TFSI S-Tronic

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Tone Chip Guard - RHS <i>See</i>	\$ 102.00	\$ 81.60
TOTAL		\$ 102.00	\$ 81.60

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLN 3790 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0871/2017/MAS

23 Feb 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLN 3790 S, Audi A6 1.8 TFSI S-Tronic

With reference to the above-mentioned vehicle, no **SLN 3790 S**, claimant,
Mr. Liew Fu Tang, please find the related document per attached.

1. A copy of the Original invoice no. 85012176 – S\$12,543.40
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLN 3790 S

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2323
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408559
Telephone 6388 2323

Customer Service
Service Appointment 6366 2323
24 hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

Page 1 14:44

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012176 Date : 22/02/2018 Order : SLN3790S Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLN3790S (V 31745)	Regn Date: 28/04/2017	Mileage: 14816	WIP No.: 37192
Model: A6 1.8 TFSI S tronic 4GC066 (N	Chassis: WAUZZZ466HN043830	Engine: CV6 016752	Dept: U
VS8 No.:			
You have been assisted by :- UB-Carrine	(33)		

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	480.00	1.00	480.00
Q	EXC	M: 8888 Insurance Excess/Liability	-400.00	1.00	-400.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	750.00	1.00	750.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
X	A460941774J	HEADLIGHT Less 020%	1.00	9454.00	7,563.20
X	A460807065ASGRU	COVER Less 020%	1.00	2445.00	1,956.00
X	A460890906	FOIL Less 020%	1.00	102.00	81.60
Sub-Total					11,722.80
7% GST					820.60
Grand Total					12,543.40

Parts 9,600.80
Labour 0.00
Sublet 2,522.00
Menus 0.00
Lubricant 0.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLN 3790 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0871/2017/TF
28 Sept 2017

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 1.8 TFSI S tronic
Vehicle Chassis No. : WAUZZZ4G6HN043830
Vehicle Regn No. : SLN 3790 S
Vehicle Mileage : 9998 KM
Vehicle Owner : Mr. Liew Fu Tang
Certificate No : 2100508922
Policy Excess : S\$428.00 (inclusive GST)
Accident Date : 4 September 2017
Place : Pasir Ris Carpark 700A
Repair Cost : \$ 12,543.40
WIP No. : 37192
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 16.30
Date : 28/09/17

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Pending for Survey Report
Main	08 Sep 2017 16:55		08 Sep 2017 13:36 Edit Adj Rpt	S\$12,041.20 Edit Estimates	S\$12,041.20 View Rpt		Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

[Created by insurer]

CLAIM SUBFOLDER DETAILS

Insured:	LIEW FU TANG, ID: S1491730F, Tel: +6596358589, Email: jeffreyift@gmail.com		
Vehicle Reg. No.:	SLN3790S	Date of Loss:	04/09/2017 19:00 - :59
Claim Type:	OD / 9834545525SG	Policy/Cover Note No.:	2100508922 (Comprehensive)
		Excess:	S\$400.00
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/09/2017]		
Driver/Custodian:	LIEW FU TANG (56 / Male), NRIC: S1491730F, Tel: +6596358589		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

- AIG_SG (14/09/2017): SLN3790S / OD / 04/09/2017 / Coverage & Excess update
- AIG_SG (13/09/2017): SLN3790S / OD / 04/09/2017 / Coverage & Excess update
- AIG_SG (12/09/2017): Alert - Adj Mandate Approved (S\$14527.00) - SLN3790S - Claim Handler: Loo, Tong ...
- AIG_SG (11/09/2017): SLN3790S / OD / 04/09/2017 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN3790S (9834545525SG)
OD

Sep 4 2017 7:45PM

[LIEW FU TANG]

Premium Automobiles Pte Ltd

View View in Browser

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/09/17 19:33	Video - Accident [Linked Accident Report Documents]	1 Load MP4	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/09/17 17:05	Adjuster Immediate Advice	1 Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/09/17 17:28	General View	1 Load JPG	☒
2	08/09/17 17:28	General View	1 Load JPG	☒
3	08/09/17 17:28	General View	1 Load JPG	☒
4	08/09/17 17:28	General View	1 Load JPG	☒
5	08/09/17 17:28	General View	1 Load JPG	☒
6	08/09/17 17:28	General View	1 Load JPG	☒
7	08/09/17 17:28	General View	1 Load JPG	☒
8	08/09/17 17:28	General View	1 Load JPG	☒
9	08/09/17 17:28	General View	1 Load JPG	☒
10	08/09/17 17:28	General View	1 Load JPG	☒
11	08/09/17 17:28	General View	1 Load JPG	☒
12	08/09/17 17:28	General View	1 Load JPG	☒
13	08/09/17 17:28	General View	1 Load JPG	☒

Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/09/17 17:31	Singapore Accident Statement	1 Load PDF	
2	08/09/17 17:35	Certificate of Insurance	1 Load PDF	
3	08/09/17 17:36	WORKSHOP ESTIMATE	1 Load PDF	
4	08/09/17 17:38	Drivers Driving License	1 Load PDF	
5	01/03/18 08:54	DISCHARGE VOUCHER	1 Load PDF	
6	01/03/18 08:54	WORKSHOP INVOICE	1 Load PDF	

Linked Accident Report Documents

View View in Browser

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/09/17 19:33	Video - Accident	1 Load MP4	

Assessment Reports

			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/09/17 19:34	Accident Statement	 Load HTM	☐
2	06/09/17 16:23	Addendum Sheet	 Load JPG	☒
3	06/09/17 16:29	Accident Statement Addm. #1	 Load HTM	☐

Photos/Images

			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/09/17 19:30	Accident Photo	 Load JPG	☒
2	05/09/17 19:30	Accident Photo	 Load JPG	☒
3	05/09/17 19:30	Accident Photo	 Load JPG	☒
4	05/09/17 19:30	Accident Photo	 Load JPG	☒
5	05/09/17 19:30	Accident Photo	 Load JPG	☒
6	05/09/17 19:30	Accident Photo	 Load JPG	☒
7	05/09/17 19:30	Accident Photo	 Load JPG	☒
8	05/09/17 19:30	Accident Photo	 Load JPG	☒

Documentation

			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/09/17 19:32	Sketch Plan	 Load JPG	☒
2	05/09/17 19:32	Sketch Plan #2	 Load JPG	☒
3	06/09/17 16:24	Accident Sketch Plan	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17017412/ATBS2
Date: 01/03/2018

REFERENCE

Insured/Claimant: LIEW FU TANG Policy No: 2100508922
Date of Loss: 04/09/2017 Nature of Claim: OD Claim No: 9834545525SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN3790S**
Make & Model: AUDI A6, 1.8 TFSI S-tronic (C7) (A)
Reg. Date: 28/04/2017 (Man. Year: 2016)
Colour: White
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$200,000.00
Sum Insured (S\$): **Market Value/New Car Price**
Engine No: CYG016752
Chassis No: WAUZZZ4G6HN043830
Odometer: 8656 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	13,731.00	9,519.20	4,211.80	30.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,572.00	2,522.00	1,050.00	29.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,303.00	12,041.20	5,261.80	30.41
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	16,903.00	11,641.20	5,261.80	31.13
+ GST 7.00/7.00% (S\$)	1,183.21	814.88	368.33	31.13
Nett Amount (S\$)	18,086.21	12,456.08	5,630.13	31.13

INSPECTION

Date of Assignment: 08/09/2017
Date Inspected: 08/09/2017 Inspected At: Premium Automobiles Pte Ltd (HQ)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,445.00 FS	*1,956.00 FS
2	1		*FRONT BUMPER GRILLE	Not Necessary	106.00 FS	*- FS
3	14		*LOCKING CLIP	Not Necessary	47.00 FS	*- FS
4	1		*FOAM FILLER	Not Necessary	193.00 FS	*- FS
5	1		*REINFORCEMENT BEAM	Not Necessary	674.00 FS	*- FS
6	1		*FRONT PARKING SENSOR OUTER	Not Necessary	208.00 FS	*- FS
7	1		*HEADLAMP MOUNTING RH	Not Necessary	100.00 FS	*- FS
8	1		*LIFT CYLINDER RH	Not Necessary	204.00 FS	*- FS
9	1		*LED HEADLAMP RH	Cracked	9,454.00 FS	*7,563.20 FS
10	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
Total Parts (\$\$)					13,731.00	9,519.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	1,400.00	750.00
3	TO RESPRAY FRONT BUMPER AND FRONT RH FENDER.	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour Cost (S\$)			3,572.00	2,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >