

ANS REC BY

REF: CS/FCI17017433/T1tbn2

Special Instruction:

w/s Taufik

ASSIGNMENT (Office)

From (Person): Aung Yin Min

of FCI

Date/Time: 8/9/17 238pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMB 3051 T

Insured: SHA 9985 Z

at Workshop m/s:

Tower Transit

Tel: 68171747/9848 2243

of 21 Bulim Drive

Policy No:

Claim No: D17008546 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A: 5/9/17

(Client's Record):

CA / REV / REP. / REV 24 HRS

'wp'

Date/Time: 8/9/17

25/pm

Person Contacted:

Sharifah

H.O.D. Endorsement:

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SMB 3051 T-X

SHA 9985 Z - NS/INC/1024304/H1gfn - D.O.A: 25/11/2011

Confirm COR @ \$7679.26, 7days

CRed: 1179.55, 130%

Survivor *Tangkh*

REF:

FCI

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

*Shari*Veh No: *SMR3051T* Yr Regn: *2013 May*Type: M.Car / M.Cycle *Bus* / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *MAN NL320F* c.c. *10518*Colour: *Green* A/C: Insured / Std / NI / NASp. Reading: *270474* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WMRA22720 D.7 001774*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Inorder* / Jammed / Leaked / Burnt orBrake: *Inorder* / Jammed / Leaked / Burnt orModi: *Nil* / S/Rim / STD A/Rim orTyre Size: F: *275/70R225*R: *i a . (D)*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. *8* mmL/Bal. *8* mm

D.O.A.

Survey held at

Tower Transit

Rear

R/Bal. *8/8* mmL/Bal. *8/8* mmD.O.I. *8/9/17*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S, Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

87679.26, 7 days - email to Shari.

RECEIVED 12 FEB 2018

12/2/2018

Date/Time, File Pass to?

1) *12/2 Typist*

Date/Time, File Return to?

2)

☐ Preli. Report☒ Final ReportDays Of Repair: *7*Resurvey No. of Trip: *-*

Survey Fee:

Transportation:

Add Fee:

☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

) \$ + RS \$

) Photos

) Others

TOTAL

*160**50**38**248*Report Format: *TP*Lump Sum / I.B.I. (\$ *7679.26*)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17017433/T1tb		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-09-2017		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9985Z	Veh. Inspected	SMB 3051T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17008546MFSH	Excess (\$)	0.00	
Assign From	CWS (AUNG YIN MIN)	Assign Date	08/09/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/09/2017	Inspection Date	08/09/2017	
Survey held at	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

MOTOR SURVEY ASSIGNMENT

Date	06-09-2017	Our Ref No. D17008546MFSH
Accident Date	05-09-2017	Claim Type. Third Party
Insured Vehicle	SHA9985Z	Third Party Vehicle. SMB3051T
Survey Location	21 Bulim Drive Bulim Bus Depot	
Contact Person.	SHARIFAH NUSAYBAH (MS)	
Contact No.	68171747/ 98482243	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TOWER TRANSIT SINGAPORE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/227721)



PRI Documents



Close



PRI Header Details

Claim No	D17008546MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & TOWER TR
Workshop Name	TOWER TRANSIT SINGAPORE PTE LTD (Contact Person : SHARIFAH NUSAYBAH (MS))	Survey Location & Contact Details	21 Bulim Drive Bulim Bus Depot Mobile: 98482243 , Phone: 68171747 , Fax: 0 EmailId: SHARIFAH@TOWERTRANSIT.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9985Z	TP Vehicle No	SMB3051T
PRI Recieved Date	06-09-2017 05:45:16 PM	Surveyor Appointed Date	08-09-2017 02:38:29 PM	Surveyor Accept Date	08-09-2017 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-09-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Denise Tay (LKKAUTO)

From: Sharifah Nusaybah Binte Syed Jamil Binshahab <sharifah@towertransit.sg>
Sent: Tuesday, 6 February 2018 10:08 AM
To: Denise Tay (LKKAUTO); Taufikh (LKKAUTO)
Cc: Subramanian Kasi; Wu Tzu Ying
Subject: RE: SURVEYOR APPOINTED; OUR REF : D17008546MFSH ; YOUR REF: SMB3051T

Hi Denise,

Yes, we confirm COR @ \$7,679.26 (before 7% gst) / 7 days.

Thank you.

Sharifah Nusaybah (Ms)
Senior Executive, Claims

Mobile +65 9848 2243
Office +65 6817 1747
Email sharifah@towertransit.sg



Tower Transit Singapore Pte Ltd
21 Bulim Drive, Bulim Bus Depot, Singapore 648170
Registration number 201419417K
www.towertransit.sg



Disclaimer: This email and any attached files may be coincidental, privileged and intended solely for the addressee. It may not be reviewed, acted upon, filed or communicated to or by any other person. If you have received this email by error, please delete it and notify the sender immediately. The views expressed in this email are not necessarily the views of Tower Transit.

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 5 February, 2018 3:54 PM
To: Sharifah Nusaybah Binte Syed Jamil Binshahab <sharifah@towertransit.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Subramanian Kasi <Subramanian.kasi@towertransit.sg>; Wu Tzu Ying <Wu.Zy@towertransit.sg>
Subject: RE: SURVEYOR APPOINTED; OUR REF : D17008546MFSH ; YOUR REF: SMB3051T

Dear Sharifah,

Is the amount confirm? \$7679.26, 7DAYS

ESTIMATED ACCIDENT REPAIR COST



SECTION 5: REPAIRS TO BUS ADVERTISEMENT VINYL/PANELS (ADVERTISEMENT COST)

TOTAL ADVERTISEMENT REPAIR COST	-
---------------------------------	---

SECTION 6: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 7: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

		Date In For Repairs	5/9/2017
		Date Out From Repairs	15/9/2017
		Number of Days Under Repair	10
BUS TYPE (SD / DD)	SD	LOSS OF USE COST	
			\$3,000.00

SUMMARY	
SECTION NO.	COST
1	\$4,578.81
2	\$4,280.00
3	-
4	-
5	\$3,000.00
ESTIMATED ACCIDENT REPAIR COST (1+2+3+4+5)	\$11,858.81

4279.26
3400

Toughen 77495749.
WP
7 days.
8/9/17

7679.26*

**TOWER TRANSIT
ENGINEERING**

BUS REGISTRATION NUMBER	SMB3051T
BUS TYPE (SD/DD)	SD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

Part No.	Part or Item Description	Quantity	Total Cost
77200066	FRONT WINDSCREEN	one ✓	1 \$2,012.50
77200044	COVER HEADLAMP - O/S/F	one ✓	1 \$389.85
77200045	COVER HEADLAMP - N/S/F	one ✓	1 \$389.85
77200677	LAMP HEAD - LH (81251016635)	one ✓	1 \$485.93
77200678	LAMP HEAD - RH (81251016636)	one ✓	1 \$485.93
77200679	LAMP HEAD - LH AUXILIARY FLASHER	one ✓	1 \$187.45
77200680	LAMP HEAD - RH AUXILIARY FLASHER	one ✓	1 \$217.35
77040670	SIKA TACK MOVE	new	6 \$110.40
			4279.26
		7% GST	\$299.55
		FINAL TOTAL COST	\$4,578.81

[illegible]

Date:

8279.26



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17017433/T1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 9985Z	Veh. Inspected	SMB 3051T	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17008546MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	08/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	MAN NL320F	c.c	10518	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WMAA22ZZ0D7001774	Colour	GREEN	
Odometer	270474	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	MICHELIN	8 mm	
L/H Front Tyre	275/70 R22.5	MICHELIN	8 mm	
R/H Rear Tyre	275/70 R22.5 (D)	MICHELIN	8/8 mm	
L/H Rear Tyre	275/70 R22.5 (D)	MICHELIN	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/09/2017	Inspection Date	08/09/2017	
Survey held at	TOWER TRANSIT SINGAPORE PTE. LTD. 21 BULIM DRIVE SINGAPORE 648170			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 3051T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT WINDSCREEN (SN)	CRACKED	2,012.50	2,012.50
1	COVER HEADLAMP-O/S/F (SN)	CRACKED	389.85	389.85
1	COVER HEADLAMP-N/S/F (SN)	CRACKED	389.85	389.85
1	LAMP HEAD-LH (SN)	CUT	485.93	485.93
1	LAMP HEAD-RH (SN)	CUT	485.93	485.93
1	LAMP HEAD-LH AUXILIARY FLASHER (SN)	CRACKED	187.45	187.45
1	LAMP HEAD-LH AUXILIARY FLASHER (SN)	CRACKED	217.35	217.35
6	SIKA TACK MOVE (SN)	NECESSARY	110.40	110.40
			4,279.26	4,279.26
LABOUR				
	TO REPLACE/REPAIR THE DAMAGED PARTS (INCLUDING SPRAY PAINTING).		4,000.00	3,400.00
			4,000.00	3,400.00
GRAND TOTAL			8,279.26	7,679.26
RECOMMENDED COST OF REPAIRS				7,679.26

Report Ref No. CS/FCI17017433/T1tbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.