

REF CS/AWA17017443 / A+b		Special Instruction	
ASSIGNMENT (Office)			
From (Person)	Tan Kah Leong	at	AWA
Date/Time	8/9/17 3:47pm		
Estimated cost	Value		
OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS			
To inspect Vehicle No.	SKX 1701 Y	Insured	SLN 9944 B
at Workshop no.	New Hock Teck	Tel	6747 9241
of	Blk 1 Kaki Bukit Ave 6 #01-43, 417883		
Policy No.	BV FPS B0007861712	Claim No.	
Sum Insured		Excess	
Make of Veh (Client's Record)		D.O.A.	4/9/17
CA / REV / REP / REV 24 HRS	'wp'	H.O.D. Endorsement	
Date/Time	8/9/17 4:08pm	Person Contacted	Rena
		Vehicle IN / OUT	OUT
Date/Time	Action/Instruction (✓) Estimate		
	SKX 1701 Y - CC3 / AIG 17017301 / T1k03 - D.O.A: 4/9/17		
	SLN 9944 B - CC3 / AIG 17017301 / T1k03 - D.O.A: 4/9/17		
	lump Sum \$3000/- (cred 955/11062.88%)		

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: **Yes** or No

GIA / PR Seen: _____ Consistent?: **Yes** or No

Est. Repairs: _____ days Res.: **Yes** or No

Lum Sum: _____ % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: SKX1701Y. Yr Regn: 2015 / Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 c.c. 1496

Colour: Grey. A/C: **Insured / Std / NI / NA**

Sp. Reading: 49796 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: JM6BM42A860324713.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16.

R: 205/60 R16.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 13/09/17.

Survey held at NHT

Des. of Damages: **Frnt / Rear / O/S / N/S / U/C / Rooftop** or

Front N/S.

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time _____ Action / Instruction

TP AWA.

RECEIVED 25 NOV 2017

Date/Time, File Pass to?

23/11/17 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$) 3000

☐ : Preli. Report

☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inv. (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

☐ S + RS ☐ SI

Photos

Others

TOTAL

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17017443/Atb

(SINGAPORE BRANCH)
60 ANSON ROAD, #08-01 (9th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 08-09-2017



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 9944B	Veh. Inspected	SKX 1701
Policy No.	BVFPB0007861712	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	08/09/2017

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Engine No.	HIDDEN	Accident Date	04/09/2017	Inspection Date	
Survey held at	NEW HOCK TECK MOTOR WORKSHOP BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883				

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Tan, KahLeong <KahLeong.Tan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Friday, 8 September, 2017 3:47 PM
To: LKK (assignments@lkkauto.com)
Cc: SUR (sur@lkkauto.com); 'admin@nhtmotor.com'
Subject: TP Survey assignment for SKX 1701Y DOA: 04.09.2017 Our ref: NSV1701034/KW

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of Mr Adrian Ling, as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SKX 1701 Y	Veh. Not In <i>claim</i> <i>Reena</i>
Insured Vehicle	:	SLN 9944 B	
Policy Number	:	BVFPSB0007861712	
Name of Workshop	:	New Hock Teck Motor Pte. Ltd.	
Contact Number	:	6747 9241	
Person to Contact	:	Sukyi / Reena	
Estimated Cost of repairs	:	\$ N.A	

Regards,
Claims Division

Copy to New Hock Teck Motor Pte Ltd via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2911Z

Vehicle Details

Vehicle No.: SKX1701Y

Vehicle to be Exported: No

Intended De-registration Date: 06 Sep 2017

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP6EAT

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: P520330770

Chassis No.: JM6BM42A8G0324713

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$15,030.00

Original Registration Date: 27 Nov 2015

First Registration Date: 27 Nov 2015

Transfer Count: 0

Actual ARF Paid: \$10,030.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 26 Nov 2025

PARF Rebate Amount: \$7,522.00

Intended COE Rebate Details

COE Expiry Date: 26 Nov 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$56,001.00

COE Rebate Amount: \$46,045.00

Total Rebate Amount: \$53,567.00

The information contained herein is correct as at 06 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 8.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 27 Aug 2017 at 01:09 AM

MSME17117856 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 05/09/2017 16:16

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/09/2017 16:16
Date Of Accident 04/09/2017 21:35
Exact Location Of Accident THE ROUNDABOUT NEAR NEWTON CIRCUS
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKX1701Y
Insured/Policyholder
Name Of Registered Owner BIZLINK RENT-A-CAR PTE LTD
Co Reg No 200402911Z
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-62856616

Vehicle Particulars

Manufacturer MAZDA
Model 3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 999995014/100780760
Cover Note Number

Driver

Name of Driver LIM POH HOON
NRIC No S7429733A
Date Of Birth 19/09/1974
Occupation INDOOR
Date Of Driving Pass 25/01/1996
Driving Experience 21 YEARS AND 7 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-92272117
Fax Number
Contact Number
EMail Address NOEMAIL

Address BLK 540 JELAPANG ROAD #02-32
 Postcode 670540
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name PASIR RIS NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 1 PASIR RIS DRIVE 4, POSTCODE: 519457, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-5852999 - FAX NO: 65855261
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLN9944B
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number

Email Address

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date

Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2 Pg. 1

Describe Circumstances of the Accident


Refer to police & reporting

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time



Driver's Signature (if driver is not the
policyholder) Date & Time

Witnessed by Reporting
Centre Personnel

Insurance Co. :
Vehicle NO. :

SEX POLY

Date of Accident:

06/09/2017

☐ Reporting Only☐ Own Damage☒ Third Party Claim

NEW HOF TOLL

Sketch Plan #3 Pg. 1

CONFIDENTIAL

ANNEX E

NOTICE OF REPORTING

This is to confirm that LIM POH HOON NRIC / FIN S7429733A reported to the Police a non injury traffic accident which occurred at the roundabout near Newton Circus on 04/09/2017 at 9.35pm involving the following vehicles;

SKX1701Y
SLN9944B

2 Complainant informed that she was driving on the outer lane at the roundabout. There was another vehicle SLN9944B who was also driving at the next lane on her left. Complainant wanted to turn left and exit Bukit Timah but the other driver drove straight. As a result, a collision occurred.

3 Complainant's car suffered some dents on her front left bumper and the vehicle had damages on the right rear side of the bumper. Both drivers managed to exchange particulars.

4 If this accident was reported to the Police within 24 hours of its occurrence then he/she has complied with Sec 84 (2) of the Road Traffic Act, Cap 276

Rank / Name of Issuing Officer: SI Norleen

Date: 06/09/2017 Time: 0950am

S/D Ref No: 13

Police Post / Unit: Pasir Ris NPC

Original to be issued to complainant
Duplicate to be submitted to Traffic Police



Text size + -

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 2911Z

Vehicle Details

Vehicle No.: SKX1701Y

Vehicle to be Exported: No

Intended De-registration
Date: 06 Sep 2017

Vehicle Make: MAZDA

Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: P520330770

Chassis No.: JM6BM42A8G0324713

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$15,030.00

Original Registration
Date: 27 Nov 2015

First Registration Date: 27 Nov 2015

Transfer Count: 0

Actual ARF Paid: \$10,030.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 26 Nov 2025

PARF Rebate Amount: \$7,522.00

Intended COE Rebate Details

COE Expiry Date: 26 Nov 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$56,001.00

COE Rebate Amount: \$46,045.00

Total Rebate Amount: \$53,567.00

The information contained herein is correct as at 06 Sep 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 27 Aug 2017 at 01:09 AM



新 福 德 車 廠

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883
Email: admin@nhtmotor.com Website: www.nhtmotor.com
Tel: 6747 9241 Fax: 6741 7276
UEN: 201718370K

Admin. LK

AWA

30/09/2017

BIZLINK RENT A CAR PTE LTD

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP AWA

Denise

JMBBM42A560314713

Accident date: 04/09/2017

Estimated repair cost for vehicle no: SKX1701Y MAZDA 3 SP 1.5 A '15

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>Defend</i>		\$925.10 ✓
2	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
3	1	Front Bumper Grille <i>new</i>		\$139.60 ✓
4	2	Front Bumper Grille Chrome Moulding <i>new</i>		\$196.70 ✓
5	1	Front Bumper Reinforcement <i>new</i>		\$561.10 ✓
6	1	Front L/H Bumper Side Retainer <i>new</i>		\$28.70 ✓
7	1	Front L/H Bumper Fog Lamp <i>new</i>		\$157.30 ✓
8	1	Front L/H Bumper Fog Lamp Cover <i>new</i>		\$42.70 ✓
9	1	Front Support Panel <i>new</i>		\$469.70 ✓
10	1	Front L/H Fender <i>Dented</i>		\$333.90 ✓
11	1	Front L/H Fender Cowling <i>Defend</i>		\$122.00 ✓
12	10	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$65.00 30
13	1	Front L/H Tyre <i>new</i>		\$350.00 ✓
14	1	Front L/H Rim <i>new</i>		\$680.00 500 (3N)
15	1	Front L/H Lower Arm		\$484.70 ✓
16	1	Front L/H Knuckle Arm		\$383.40 ✓
17	1	Front L/H Knuckle Arm Bearing <i>new</i>		\$343.60 ✓
18	1	Front L/H Shock Absorber		\$541.70 ✓
19	1	Front L/H Drive Shaft		\$915.40 ✓
20	1	Front Steering Rack		\$1,335.40 ✓
21	1	Headlamp L/H <i>new</i>	1511 ✓	
			Subtotal :-	\$8,141.00

3023.40

2418.72

S.N: 500

9652

Labour charges

To remove & refit front L/H undercarriage	\$380.00 +
To remove & refit steering rack	\$380.00 x
To remove & refit air-con condenser, radiator, fan motor & top up gas	\$450.00 x
To check wheel alignment	\$150.00 80
To check wiring	\$100.00 30
Tuff kote	\$150.00 + 30 840
Panel beating	\$1,400.00 300
Spray painting	\$1,400.00 400.

Subtotal :- \$4,410.00

Total:- \$12,551.00

14062

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

whl 378872
4/s: 31C
042yp.

31C
042yp



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17017443/Atbn2

(SINGAPORE BRANCH)
60 ANSON ROAD, #08-01 (9th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 24-11-2017



Code : AWA

Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	SLN 9944B	Veh. Inspected	SKX 1701Y
Policy No.	BVFPB0007861712	Coverage (\$)	0.00
Claim No.	NSV1701034/KW	Excess (\$)	0.00
Assign From	TAN KAH LEONG	Assign Date	08/09/2017

2.

Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0324713	Colour	GREY
Odometer	49796	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm

4.

Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5.

General Information

Accident Date	04/09/2017	Inspection Date	13/09/2017
Survey held at	NEW HOCK TECK MOTOR WORKSHOP BLOCK 1, KAKI BUKIT AVE 6 #01-43 SINGAPORE 417883		

5a.

Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.

Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 1701Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	925.10	925.10
10	FRONT BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	139.60	-
2	FRONT BUMPER GRILLE CHROME MOULDING	NOT NECESSARY	196.70	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	561.10	-
1	FRONT L/H BUMPER SIDE RETAINER	NECESSARY	28.70	28.70
1	FRONT L/H BUMPER FOG LAMP	NOT NECESSARY	157.30	-
1	FRONT L/H BUMPER FOG LAMP COVER	CUT	42.70	42.70
1	FRONT SUPPORT PANEL	NOT NECESSARY	469.70	-
1	FRONT L/H FENDER	DENTED	333.90	333.90
1	FRONT L/H FENDER COWLING	DEFORMED	122.00	122.00
10	FRONT L/H FENDER COWLING CLIP @\$6.50	NECESSARY	65.00	30.00
1	FRONT L/H TYRE	NOT NECESSARY	350.00	-
1	FRONT L/H LOWER ARM	NOT NECESSARY	484.70	-
1	FRONT L/H KNUCKLE ARM	NOT NECESSARY	383.40	-
1	FRONT L/H KNUCKLE ARM BEARING	NOT NECESSARY	343.60	-
1	FRONT L/H SHOCK ABSORBER	NOT NECESSARY	541.70	-
1	FRONT L/H DRIVE SHAFT	NOT NECESSARY	915.40	-
1	FRONT STEERING RACK	NOT NECESSARY	1,335.40	-
1	HEADLAMP L/H	CUT	1,511.00	1,511.00
	LESS 20% DISCOUNT		-	-604.68
			8,972.00	2,418.72
<u>SPECIAL NETT ITEMS</u>				
1	FRONT L/H RIM (SN)	CUT	680.00	500.00
			680.00	500.00
<u>LABOUR</u>				
	TO REMOVE & REFIT FRONT L/H UNDERCARRIAGE.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT STEERING RACK.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT AIR-CON CONDENSER,RADIATOR,FAN MOTOR & TOP UP GAS.	NOT NECESSARY	450.00	-
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	30.00

Report Ref No. CS/AWA17017443/Atbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.		1,400.00	300.00
	SPRAY PAINTING.		1,400.00	400.00
			4,410.00	840.00
GRAND TOTAL			14,062.00	3,758.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/AWA17017443/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.