

INS CASE OWNER

Aide | CC 4/11170 17515, G 2/3 9v

LKK IDAC

ASSIGNMENT
 Date/Time: 12-9-17
 Registered in Merimen: 11-09-17
 12-09-18

re-assign / CCU / FTE



Insured Vehicle No.: SHC 2931P
 Name of Insured: CTR
 Insured Tel No.:
 Excess Sec II :SS
 Is driver the owner? (YES /)
 If NO, Driver Name / Age: My left Gary (Gary Liang)
 Driver Tel No.:
 Nature of Accident: Kill
 (V/L: YES / NO)

Claim No.:
 Policy No.: M00001
 Make / Model: Honda
 Place of Accident: Nongwahn Rd
 OI GIA REPORT: / NO ; TP GIA REPORT: / NO
 Insured Liability: % Final ? Yes / No

SHR 5053L



INSRS: WSP: 46 motorsports
 Tel:
 Liability:
 RMKS:



INSRS: WSP:
 Tel:
 Liability:
 RMKS:



INSRS: WSP:
 Tel:
 Liability:
 RMKS:



INSRS: WSP:
 Tel:
 Liability:
 RMKS:

Date/Time	STAGE	DATE / PIC
2/19/18	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	
16/7/19	Documentation Check List: Handler Typist	
1/10	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
12/10	After call ltr to OI:	<input checked="" type="checkbox"/>
12/10	Authorisation To Act	<input checked="" type="checkbox"/>
22/10	Release Voucher	<input checked="" type="checkbox"/>
4/11	Final Repair Bill	<input checked="" type="checkbox"/>
08-11-19	Car Rental Invoice:	<input checked="" type="checkbox"/>
2/11	Towing Invoice	<input checked="" type="checkbox"/>
2/12/2020	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by: ENO Olang

Repair Cost: US \$2100.00 (4 days) Reduction: 85377.09% 72 Email Call

FINAL SETTLEMENT Date/Time: 2/11/2020 Confirm with: Koyuk Email Call

Final Liability: % 100% (Agreed / Assessed) BOLA S/N No.: NIL
 Repair Cost: (W/EST) \$2247.00
 Loss of Rental (LOR): \$5 (days)
 Loss of Use (LOU): \$300.00 (5 50 x 6 days)
 Loss of Income (LOI): \$5 (5 x days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search: \$5 -
 Medical: \$5 -
 Disbursement: \$5 - (e.g. Tow/Independent)
 Legal Cost: \$5 -
 Total: \$2547.00 Global Sum \$5: -

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$2547.00 Name 1: 46 Motorsports Pte Ltd
 Payee 2: \$ Name 2:
 Payee 3: \$ Name 3:

COPY SENT 2/11/2020

1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: \$350.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III17017515/Gua3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 11-09-2017	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2931P	Veh. Inspected	SGR 5053L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	11/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/09/2017	Inspection Date	12/09/2017
Survey held at	96 MOTORSPORTS PTE LTD 62/64 KAKI BUKIT AVENUE 6 SINGAPORE 417893 ARK @ KB		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

96 MOTORSPORTS PTE LTD

Company Registration: 201711783Z

Tel: 6702 6996
 Fax: 6384 6996
 Email: admin@96motorsports.com

ESTIMATE

Our Ref: SGR 5053 L
 Your Ref: SHC 2931 P

Date: 14 September 2017

Vehicle No: SGR 5053 L
 Make & Model: Toyota Ractis 1.3 (A)
 Chassis No: SCP1000007127

No	Qty	Particulars	Amount
1	1	Headlamp Assembly - RH <i>BR</i>	386.30 ✓
2	1	Front Support Panel Assembly <i>X Repair</i>	686.55
3	1	Front Fender Panel - RH <i>Buc</i>	395.3 - 562.65 ✓
4	1	Front Fender Inner Shield - RH <i>re</i>	162.75 ✓
5	8	Front Fender Inner Shield Clip - RH @\$4.00 each <i>McC.</i>	32.00 ✓
6	1	Front Bumper Fascia <i>re</i>	407.6 - 941.90 ✓
7	4	Front Bumper Clip @\$2.05 each <i>McC</i>	16.00 ✓
8	1	Front Bumper Lower Grille <i>X</i>	157.00
9	1	Front Bumper Reinforcement <i>X</i>	454.55
10	1	Front Bumper Side Retainer - RH <i>re</i>	36.20 ✓
11	1	Rear Bumper Fascia <i>X Repair.</i>	777.80
12	4	Rear Bumper Clip @\$2.05 each <i>X</i>	16.00
13	1	Rear Bumper Side Retainer - RH <i>X</i>	47.75
			<i>1436.15</i>
			4,277.45
			Less 25%
			1,069.36
			Sub-Total
			3,208.09
			<i>1077.11</i>
			60.00
			280.00
			150.00
			Total Part (S\$)
			3,698.09

Special Nett Items

14	1	Radiator Coolant <i>X</i>	60.00
15	1	Front 15" Alloy Wheel Rim - RH <i>X</i>	280.00
16	1	Front 195/60R15 Pirelli Tyre - RH <i>X</i>	150.00

No	Particulars	Amount
1	To cut/weld front support panel to renew; panel beat left rear fender and repair left rear door including replacement of the right front and left rear accident damaged parts.	<i>500</i> 1,200.00
2	To check front lightings and electrical wiring systems include focusing both headlights and adjust if necessary.	<i>30</i> 50.00

96 MOTORSPORTS PTE LTD

Company Registration: 201711783Z

Tel: 6702 6996

Fax: 6384 6996

Email: admin@96motorsports.com

3	To remove/install air-con condenser and fittings to facilitate the replacement of the front support panel assembly including vacuum/recharge air-con gas and check system for leaks.	X	150.00
4	To remove/install radiator assembly and fittings to facilitate the replacement of the front support panel assembly including pressure test cooling system for leaks.	X	180.00
5	To remove/install right front wheel to replace damaged alloy wheel rim and tyre include balancing the wheels.	X	45.00
6	To carry out computerized 4 wheels alignment and adjust if necessary.	X	120.00
7	To check rear lightings and electrical wiring system include performing water leakage test.	X	50.00
8	To putty and re-spray painting on front support panel, right front fender, front bumper fascia, left rear fender, left rear door and rear bumper fascia.	1000	1,800.00
9	Rust-proofing on the right front and left rear accident affected portions.	60.	120.00
Total Labour (S\$)			<u>3,715.00</u>

1590

GRAND TOTAL (S\$) 7,413.09

2667.11
20%: 2100
4 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 8 September, 2017 2:47 PM
To: admin1@96motorsports.com; Catherine Chong (LKK Auto); 'sur@lkkauto.com'
Cc: 'Alwyn Soh'; Zuhaidah Samsuri
Subject: RE: Notification of Accident and Require for Pre-Repair Inspection for SGR5053L

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SGR5053L and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Call on : 8/9/17 3:05 pm
Person Conf: Rachel Yen
Vehicle In
11/9/2017

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street #04/#05 IOB Building

Singapore 049711

Tel : 63476100, Ext-248, Fax : 62244174

e-mail: Gabriel@iii.com.sg

From: admin1@96motorsports.com [mailto:admin1@96motorsports.com]
Sent: Friday, 8 September, 2017 1:01 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'Alwyn Soh' <alwyn.soh@96motorsports.com>
Subject: RE: Notification of Accident and Require for Pre-Repair Inspection for SGR5053L

Dear Sir/Mdm,

- We would like to have LKK Auto Consultants Pte Ltd to do the survey.

Yours sincerely,

Rachel Yen
Admin Officer

96 Motorsports Pte Ltd
62/64 Kaki Bukit Avenue 6
Singapore 417893
Ark @ KB

Tel : 6702 6996
Fax : 6384 6996

 **MOTORSPORTS**
www.96Motorsports.com

CONFIDENTIALITY CAUTION: This email, together with any attachments, is intended only for use by the individual or entity to whom it is addressed, and may contain legally privileged, confidential information. If you are not the intended recipient of this e-mail or the person responsible for delivering this document to the intended recipient, please be informed that any dissemination, distribution, printing, copying or any other use of this e-mail, or any attachments, is strictly prohibited. If you have received this e-mail in error, please notify the sender by reply e-mail.

 Please consider the environment before printing this e-mail

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]
Sent: Friday, September 8, 2017 11:53 AM
To: admin1@96motorsports.com
Cc: 'Alwyn Soh' <alwyn.soh@96motorsports.com>; 'Gary Chang' <gary.chang@96motorsports.com>
Subject: RE: Notification of Accident and Require for Pre-Repair Inspection for SGR5053L

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street #04/#05 IOB Building

Singapore 049711

Tel : 63476100, Ext-248, Fax : 62244174

e-mail: Gabriel@iii.com.sg

From: admin1@96motorsports.com [<mailto:admin1@96motorsports.com>]
Sent: Friday, 8 September, 2017 10:09 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'Alwyn Soh' <alwyn.soh@96motorsports.com>; 'Gary Chang' <gary.chang@96motorsports.com>
Subject: Notification of Accident and Require for Pre-Repair Inspection for SGR5053L

WITHOUT PREJUDICE

ACCIDENT INVOLVING SGR5053L AND SHC2931P ON 07.09.2017 AT/ALONG MOULMAIN RD TO BALESTIER (BEFORE MANDALAY RD)

We act for HUANG XIU HUA, whose vehicle registration number **SGR5053L** was damaged in the above accident.

Please let us know within **2 working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

ALWYN SOH
96 MOTORSPORTS PTE LTD

Yours sincerely,

Rachel Yen
Admin Officer

96 Motorsports Pte Ltd
62/64 Kaki Bukit Avenue 6
Singapore 417893
Ark @ KB

Tel : 6702 6996
Fax : 6384 6996

 **MOTORSPORTS**
www.96Motorsports.com

CONFIDENTIALITY CAUTION: This e-mail, together with any attachments, is intended only for use by the individual or entity to which it is addressed, and may contain legally privileged and/or confidential information. If you are not the intended recipient of this e-mail (or the person responsible for delivering this document to the intended recipient), please be informed that any dissemination, distribution, printing or copying of this e-mail, or any attachment, is strictly prohibited. If you have received this e-mail in error, please respond to the sender by reply e-mail, and permanently delete the original and any copy of the e-mail, attachments and printouts. Kindly note that e-mail communications are not secured and therefore are susceptible to alteration. 96 Motorsports Pte Ltd will not accept legal responsibility for the contents of this message. Thank you for your cooperation.

 Please consider the environment before printing this e-mail

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 9B15H

Vehicle Details

Vehicle No.: SGR5053L

Vehicle to be Exported: No

Intended De-registration Date: 13 Sep 2017

Vehicle Make: TOYOTA

Vehicle Model: RACTIS 1.3 A

Primary Colour: Grey

Manufacturing Year: 2005

Engine No.: 2SZ1450432

Chassis No.: SCP1000007127

Maximum Power Output: 64.0 kW (85 bhp)

Open Market Value: \$15,023.00

Original Registration Date: 09 Feb 2007

First Registration Date: 09 Feb 2007

Transfer Count: 2

Actual ARF Paid: \$16,526.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 08 Feb 2027

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

PQP Paid: \$50,394.00

COE Rebate Amount: \$47,398.00

Total Rebate Amount: \$47,398.00

The information contained herein is correct as at 13 Sep 2017



Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 8.0 SP3 and above. 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)

Last updated on 27 Aug 2017 at 01:09 AM

(2 vehicles)

Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
41,800	15,360 /yr	10-Oct-2007	1,296 cc	-	88 Motor Trading	Available
56,800	15,180 /yr	24-Jan-2008	1,496 cc	13,000 km	Igua Motoring	Available

... We Are sgCarMart Premium Dealer! Buy With No Worries! No Hidden Cost! Car In Original Condition!

How - 82981851 | Ron - 82981859

... COE, High Headroom, Spacious, Original Paintwork, Renew COE Option Available. Low Mileage, Normal

... expert cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC
 ... you can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car
 ... dealers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches
 ... car news on the latest models. Visit our partner sites for job openings for Singapore jobs, massage
 ... car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.



GOLDEN CAR RENTAL PTE LTD
No.1 Soon Lee Street Pioneer Center #01-02 Singapore 627605
Company & GST Registration No: 201503574R

TAX INVOICE

Bill To :

Name : 96 Motorsports Pte Ltd
Address : 62/64 Kaki Bukit Avenue 6
Ark @ KB
Singapore 417893

Invoice No : YGC2017-SA00139
Reference No : GCRY2017-676
Date : 25.09.2017
Term : 30 Days
Page : 1

DESCRIPTION

	Rate	No of days	
Car Number Plate	SGY 4799 M		
Model	Toyota Vios		
Chassis Number			
Start Period	07.09.2017		
End Period	13.09.2017		
Deposit Kiv	\$ -		
Rental Amount	\$ 120.00	6	\$ 720.00

Sub Total	:	\$ 720.00
GST	:	\$ -
Grand Total	:	\$ 720.00

SGD :

Saki Loo

Golden Car Rental Pte Ltd

Customer Signature

Print Received Message

This mail is associated with :

***SGR5053L (MCT17090201)**
[SHC2931P]

TP

HUANG XIUHUA

Sep 7 2017 7:00AM

[COMFORT TRANSPORTATION PTE LTD]

96 Motorsports Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 30/10/2019 09:13 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2607.00) - SGR5053L - Claim Handler: Zuhaidah Bte Samsuri

Approved:2607.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2017 Edit Reg		11 Sep 2017 00:00 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Main Claimant:	HUANG XIUHUA, ID: S2699815H		
Vehicle Reg. No.:	SGR5053L	Date of Loss:	07/09/2017 07:00 - :59 [126 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT17090201	Policy/Cover Note No.:	MCOM0016
Vehicle Reg. No. (Insured):	SHC2931P	Policy No. (Claimant):	DMAP17S500266
		Excess:	
Repairer:	96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB, 417893 Kaki Bukit - Tel: 6702 6996		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	Etiga Insurance Pte Ltd (HQ) - Tel: 63360477		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/09/2017]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
<ul style="list-style-type: none"> III_SG (30/10/2019): Alert - Adj Mandate Approved (S\$2607.00) - SGR5053L - Claim Handler: Zuhaidah Bt... III_SG (23/10/2019): Alert - Adj Mandate Maintained - SGR5053L - Claim Handler: Zuhaidah Bte Samsuri III_SG (28/09/2017): Alert - Adj Mandate Approved (S\$0.00) - SGR5053L - Claim Handler: Zuhaidah Bte S... 			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Claim Documents

*SGR5053L (MCT17090201)
[SHC2931P]

TP

HUANG XIUHUA

Sep 7 2017 7:00AM

[COMFORT TRANSPORTATION PTE LTD]

96 Motorsports Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
2	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
3	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
4	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
5	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
6	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
7	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
8	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
9	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
10	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
11	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
12	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
13	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
14	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
15	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
16	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
17	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
18	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
19	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
20	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
21	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
22	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
23	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
24	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
25	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
26	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
27	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
28	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
29	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
30	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
31	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
32	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
33	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
34	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
35	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
36	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
37	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
38	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
39	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
40	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
41	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
42	16/07/19 11:51	General View		<input checked="" type="checkbox"/>
43	16/07/19 11:51	General View		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	16/07/19 11:51	General View	 Load JPG	<input checked="" type="checkbox"/>
45	16/07/19 11:51	General View	 Load JPG	<input checked="" type="checkbox"/>
46	29/10/19 17:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
47	29/10/19 17:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	29/10/19 17:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	29/10/19 17:01	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/09/17 15:41	ACKNOWLEDGEMENT EMAIL TO III DD 08.09.2017	 Load PDF	
2	13/09/17 10:57	TP GIA REPORT	 Load PDF	
3	09/10/19 18:06	LOD AND OTHER DOCUMENTS	 Load PDF	
4	21/10/19 14:18	WORKSHOP INVOICE	 Load PDF	
5	21/10/19 14:18	LOD	 Load PDF	
6	02/03/20 10:52	AUTHORISATION TO ACT FORM	 Load PDF	
7	02/03/20 10:52	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	11/09/17 17:15	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17017515/GGA3Q2

Date: 02/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0016
 Claimant SGR5053L Insured Vehicle No : SHC2931P
 Vehicle No : SGR5053L
 Date of Loss: 07/09/2017 Nature of Claim: TP Claim No: MCT17090201

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGR5053L
 Make & Model: TOYOTA RACTICS, 1.3 X (A) Engine No: 2SZ1450432
 Reg. Date: 09/02/2007 (Man. Year: 2005) Chassis No: SCP1000007127
 Colour: Grey Odometer: 136853 km
 Engine Capacity: 1296 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,698.09	1,077.11	2,620.98	70.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,715.00	1,590.00	2,125.00	57.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,413.09	2,667.11	4,745.98	64.02
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	7,413.09	2,100.00	5,313.09	71.67
+ GST 7.00/7.00% (S\$)	518.92	147.00	371.92	71.67
Nett Amount (S\$)	7,932.01	2,247.00	5,685.01	71.67
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
Nett Liability (S\$)		2,547.00		

INSPECTION

Date of Assignment: 11/09/2017
 Date Inspected: 12/09/2017 Inspected At: 96 Motorsports Pte Ltd (HQ)
 62/64 Kaki Bukit Avenue 6
 Singapore 417893
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2019)
Parts: 144	TOYOTA RACTICS 1.3 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGR5053L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSEMBLY -RH	Broken	386.30 FL	*386.30 FL
2	1		*FRONT SUPPORT PANEL ASSEMBLY	Repair	686.55 FL	*-FL
3	1		*FRONT FENDER PANEL -RH	Buckled	562.65 FL	*395.30 FL
4	1		*FRONT FENDER INNER SHIELD -RH	Deformed	162.75 FL	*162.75 FL
5	8		*FRONT FENDER INNER SHIELD CLIP-RH	Necessary	32.00 FL	*32.00 FL
6	1		*FRONT BUMPER FASCIA	Deformed	941.90 FL	*407.60 FL
7	4		*FRONT BUMPER CLIP	Necessary	16.00 FL	*16.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	157.00 FL	*-FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	454.55 FL	*-FL
10	1		*FRONT BUMPER SIDE RETAINER -RH	Deformed	36.20 FL	*36.20 FL
11	1		*REAR BUMPER FASCIA	Repair	777.80 FL	*-FL
12	4		*REAR BUMPER CLIP	Not Necessary	16.00 FL	*-FL
13	1		*REAR BUMPER SIDE RETAINER -RH	Not Necessary	47.75 FL	*-FL
14	1		*RADIATOR COOLANT	Not Necessary	60.00 FS	*-FS
15	1		*FRONT 15 ALLOY WHEEL RIM -RH	Not Necessary	280.00 FS	*-FS
16	1		*FRONT 195/60R15 PIRELLI TYRE -RH	Not Necessary	150.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,767.45	1,436.15
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,069.36	359.04
Total Parts (\$\$)	3,698.09	1,077.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT/WELD FRONT SUPPORT PANEL TO RENEW ,PANEL BEAT LEFT REAR FENDER AND REPAIR LEFT REAR DOOR INCLUDING REPLACEMENT OF THE RIGHT FRONT AND LEFT REAR ACCIDENT DAMAGED PARTS	New	1,200.00	500.00
2	TO CHECK FRONT LIGHTINGS AND ELECTRICAL WIRING SYSTEMS INCLUDE FOCUSING BOTH HEADLIGHTS AND ADJUST IF NECESSARY	New	50.00	30.00
3	TO REMOVE/INSTALL AIR-CON CONDENSER AND FITTINGS TO FACILITATE THE REPLACEMENT OF THE FRONT SUPPORT PANEL ASSEMBLY INCLUDING VACUUM ,RECHARGE AIR-CON GAS AND CHECK SYSTEM FOR LEAKAS	New	150.00	0.00
4	TO REMOVE/INSTALL RADIATOR ASSEMBLY AND FITTINGS TO FACILITATE THE REPLACEMENT OF THE FRONT SUPPORT PANEL ASSEMBLY INCLUDING PRESSURE TEST COOLING SYSTEM FOR LEAKS	New	180.00	0.00
5	TO REMOVE/INSTALL RIGHT FRONT WHEEL TO REPLACE DAMAGED ALLOY WHEEL RIM AND TYRE INCLUDE BALANCING THE WHEELS	New	45.00	0.00
6	TO CARRY OUT COMPUTERIZED 4 WHEELS ALIGNMENT AND ADJUST IF NECESSARY	New	120.00	0.00
7	TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRING SYSTEM INCLUDE PERFORMING WATER LEAKAGE TEST	New	50.00	0.00
8	TO PUTTY AND RESPRAY PAINTING ON FRONT SUPPORT PANEL,RIGHT FRONT FENDER ,FRONT BUMPER FASCIA ,LEFT REAR FENDER ,LEFT REAR DOOR AND REAR BUMPER FASCIA	New	1,800.00	1,000.00
9	RUST-PROOFING ON THE RIGHT FRONT AND LEFT REAR ACCIDENT AFFECTED PORTIONS	New	120.00	60.00
Gross Labour Cost (\$\$)			3,715.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >