

ESTIMATE FOR SKT5224C

SUPPLEMENTARY

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

引起要求的名词复数是作用服务。1. 可到底等等的 2.5 概则是 MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT 16 RAFFLES QUAY #24-01 HONG LEONG BUILDING SINGAPORE 048581 66431303

Vehicle & Document Information

16936

Reg No/Reg Date SKT5224C

/ 12/06/2015

Date In/Mileage Chassis No

24/10/2047/-44374

WDD2120362B145973

Engine No

WIP No

27492030371892

Make/Model

MB/E 250 2.0 CGI SEDAN (W212

Colour/Trim Operator

028 890 Cavansit BI/ 042 258 Basalt Grey

Account No

Terms

Date/Time Printed

CSE

WI000558

Credit

09/11/2017/ 13:35

YK

395 / Yik Chan Hoe

Description of Goods / Services

Unit Price Disc%

Amount

M BPNSUN POLICY POLIC NO ACC DATE: 2100416558 // 08/09/2017

DRIVE IN EXCESS: 08/09/2017 // TP VEH NO SET668H MSIG

DATE IN/DATE SURVEY: 24/10/2017 @ 1700 // RASUL LKK

BY/AUTHRIZED ON: DIRECT SETTLEMENT // MONICA MSIG

LEFT REAR BUMPER CHROME MOULDING

RIGHT REAR BUMPER CHROME MOULDING

124.67 00.00 124.67 00.00 124.67 ARC 124.67 NEC

Vik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett

249.34

7% GST on

249.34

17.45

Total Payable

266.79

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

Page 1 of 1