

ASS. BY

REF CS/MSG17017579/67602

Special Instruction

meiner

GB

ASSIGNMENT (Office)

From (Person): Winnie chua of MSG Date/Time: 12/9/17 10:34 am

Estimated Cost Bill to

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBF 3343K Insured:

At Workshop m/s: Kan Fook Sing Tel: 6747 9560

No. 61 Defu Lane 12, 539147

Policy No: A28840665 MKC Claim No: 529187

Sum Insured Excess: \$500.00

Make of Veh (Client's Record) D.G.A. 9/9/17

CA / (REV) / REP. / REV 24 HRS 13/9/17 @ 2pm owner waiting H.O.D. Endorsement

Date/Time: 12/9/17 11:15 am Person Contacted: Patricia / Yan Vehicle IN: OUT

Date/Time	Action/Instruction (✓) Estimate
	GBF 3343K - X

Surveilor Xhe  
Melimen

REF: MS11

10808

**ASSIGNMENT**

From: \_\_\_\_\_ Date: 13052017

Estimated Cost: \_\_\_\_\_

TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 3343K

at Workshop m/s: Kan Fook Sing

of: 61 Defu Lane #2

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \$ 500.00

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition) 2pm owner waiting



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 78K

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA /  REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GBF3343K Yr Regn: 22 Sep 2016

Type: M.Car / M.Cycle / Bus /  Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Fiat Doblo c.c. 1598

Colour: Green / white A/C: Insured / Std / NI / NA

Sp. Reading: 44898 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ZFA 26300006036802

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi:  Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 60 R 16  
R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 13-09-17

Survey held at w/s 2pm

Des. of Damages:  Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>14/9/17</u>	<u>REV in melimen.</u>
<u>14/9/17</u>	<u>mandate approved by Lui Siew Mei.</u>
<u>14/9/17</u>	<u>@ 2:55PM spoked to Yen, CA, Ex: 500</u>
<u>7/12/17</u>	<u>confirmed p/p \$ 4896.10 with Alice.</u>
	<u>(Red: 2205.92, 31%)</u>

RECEIVED 11 DEC 2017

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 7  
Resurvey No. of Trip: \_\_\_\_\_

1) Date/Time, File Return to?  
2) \_\_\_\_\_

Add Fee:  Site Insp (\$ )  
 Interview (\$ )  
 Tech. Invs (\$ )  
 Weekend (\$ )

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	

Report Format: 00  
Lump Sum /  B1: (\$ 4896.10 )



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17017579/Ggb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 12-09-2017	
		Code : MSG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	GBF 3343K
Policy No.	A28840665MKC	Coverage (\$)	0.00
Claim No.	529187	Excess (\$)	500.00
Assign From	MERIMEN (WINNIE CHUA)	Assign Date	12/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	09/09/2017	Inspection Date	
Survey held at	KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assignac	Adj Rpt	Adj Submitted	Ins Audited	Status
Main	11 Sep 2017 Sendback Est	11 Sep 2017 16:26 S\$6,823.90	12 Sep 2017 10:34 Assign				<b>New Assignment</b> Cancel Case

Main

Reference

Claim Details

Documents

Show All

### CLAIM SUBFOLDER DETAILS

Insured:	<b>NATURE LANSCAPES PTE LTD</b> , Co. Reg. No.: 198101080Z		
Vehicle Reg. No.:	<b>GBF3343K</b>	Date of Loss:	09/09/2017 10:00 - :59
Claim Type:	<b>OD / 529187</b>	Policy/Cover Note No.:	A28840665MKC (Comprehensive) Coverage: 23/09/2016 - 22/09/2017
		Excess:	S\$500.00
Repairer:	<b>Kan Fook Sing Motor Workshop (Defu)</b> No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Winnie Chua Ping Ping</b> - 6594 2556]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [ <b>Imm.Advice</b> due 13/09/2017]		
Driver/Custodian:	LEE KHONG TECK (50 / Male), NRIC: S1811852A, Tel: +6581330837		
Adj Asg. Remarks:	Please revert. tks.		

### ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

### ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	11 Sep 2017 14:02	<b>Clim Veh Model Changed</b>	(202652) FIAT DOBLO 1.6 D CARGO M) (M).	[R] Tan
2	11 Sep 2017 14:02	<b>Clim Created</b>	Reg No: GBF3343K. Policy No: A28840665MKC. Acct Date: 2017/09/09. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Kan Fook Sing Motor Workshop (Defu). Created from SAS:MKFS17119833	[R] Tan
3	11 Sep 2017 16:26	<b>Clim Submitted</b>	6823.90.	[R] Tan
4	11 Sep 2017 17:08	<b>Clim Registration Modified</b>	Excess: -> 500.00.	[I] Winnie Chua Ping Ping
5	11 Sep 2017 17:11	<b>Adj Co Assigned</b>	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert. tks.	[I] Winnie Chua Ping Ping
6	11 Sep 2017 17:11	<b>Adj Next Rpt Changed</b>	Next Rpt:Im. Advice.Due Date:2017/09/12	[I] Winnie Chua Ping Ping
7	11 Sep 2017 17:11	<b>Adj Mandate Set</b>	Approved:25000.00.Reinsp:Adj decides.	[I] Winnie Chua Ping Ping
8	12 Sep 2017 08:53	<b>Assignment 1st Accessed</b>		[A] Ho Pei Fang
9	12 Sep 2017 10:34	<b>Adj Assignment Cancelled</b>	LKK	[I] Winnie Chua Ping Ping
10	12 Sep 2017 10:34	<b>Adj Est Details Deleted</b>	Deleting Est Details For Cancelling Adjuster Assignment	[I] Winnie Chua Ping Ping
11	12 Sep 2017 10:34	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):Please revert. tks.	[I] Winnie Chua Ping Ping
12	12 Sep 2017 10:34	<b>Adj Next Rpt Changed</b>	Next Rpt:Im. Advice.Due Date:2017/09/13	[I] Winnie Chua Ping Ping
13	12 Sep 2017 10:34	<b>Adj Mandate Set</b>	Approved:25000.00.Reinsp:Adj decides.	[I] Winnie Chua Ping Ping
14	12 Sep 2017 10:39	<b>Assignment 1st Accessed</b>		[A] Nivitha Govindasamy
15	12 Sep 2017 13:30	<b>Adj Adjuster Assigned</b>	[None] -> MARCUS CHUA	[A] CATHERINE CHONG KAI LING
16	13 Sep 2017 09:41	<b>Adj Adjuster Assigned</b>	MARCUS CHUA -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
17	14 Sep 2017 12:15	<b>Adj Rpt Initiated</b>		[A] LOW AI PHING
18	14 Sep 2017 12:20	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2017/10/12	[A] LOW AI PHING
19	14 Sep 2017 12:20	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2017/10/12	[A] LOW AI PHING
20	14 Sep 2017 12:21	<b>Adj Mandate Request</b>	Cur.Reg:6203.90:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] LOW AI PHING
21	14 Sep 2017 14:38	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2017/10/12. Mandate Remarks: a if c; check items to be confirmed	[I] Lui Siew Wei
22	14 Sep 2017 14:38	<b>Adj Mandate Set</b>	Approved:4718.10:a if c; check items to be confirmed	[I] Lui Siew Wei
23	16 Oct 2017 12:07	<b>Clim Supp Created (S:647873)</b>		[R] Alice
24	16 Oct 2017 12:08	<b>Clim Submitted (S:647873)</b>	313.50.	[R] Alice
25	16 Oct 2017 12:08	<b>Adj Co Assigned (S:647873)</b>	LKK Auto Consultants Pte Ltd (HQ):	[R] Merimen Administrator
26	08 Dec 2017 09:58	<b>Supp Combined (S:647873)</b>		[A] LOW AI PHING
27	08 Dec 2017 10:08	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2017/10/12	[A] LOW AI PHING
28	08 Dec 2017 10:13	<b>Adj Mandate Request</b>	Cur.Reg:4896.10:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] LOW AI PHING
29	11 Dec 2017 11:32	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2017/10/12. Mandate Remarks: a if c; check items to be confirmed	[I] NG CHEN HOW
30	11 Dec 2017 11:32	<b>Adj Mandate Set</b>	Approved:4896.10:a if c; check items to be confirmed	[I] NG CHEN HOW

## ACTIVITY

[12/09/2017 09:45] Ho Pei Fang:  
Yen confirmed survey appt tnr at 2pm, owner waiting.

[12/09/2017 08:53] Ho Pei Fang:  
Pat confirmed car not in, will arrange and inform IHS.

**Merimen Billing for this case - Transaction History**

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1578358	11/09/2017 14:02	Motor	Kan Fook Sing Motor Workshop	Kan Fook Sing Motor Workshop (Defu)	GBF3343K		xx.xx
1582194	14/09/2017 12:15	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBF3343K		10.70

## Claim Audit

No.	On	Audit	Remarks	By
1	11 Sep 2017 14:02	<b>Cim Veh Model Changed</b>	(202652) FIAT DOBLO 1.6 D CARGO MJ (M).	[R] Tan
2	11 Sep 2017 14:02	<b>Cim Created</b>	Reg No: GBF3343K. Policy No: A28840665MKC. Acct Date: 2017/09/09. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Kan Fook Sing Motor Workshop (Defu). Created from SAS:MKFS17119833	[R] Tan
3	11 Sep 2017 16:26	<b>Cim Submitted</b>	6823.90.	[R] Tan
4	11 Sep 2017 17:08	<b>Cim Registration Modified</b>	Excess: -> 500.00.	[I] Winnie Chua Ping Ping
5	11 Sep 2017 17:11	<b>Adj Co Assigned</b>	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor):Please revert. tks.	[I] Winnie Chua Ping Ping
6	11 Sep 2017 17:11	<b>Adj Next Rpt Changed</b>	Next Rpt:Im. Advice.Due Date:2017/09/12	[I] Winnie Chua Ping Ping
7	11 Sep 2017 17:11	<b>Adj Mandate Set</b>	Approved:25000.00.Reinsp:Adj decides.	[I] Winnie Chua Ping Ping
8	12 Sep 2017 08:53	<b>Assignment 1st Accessed</b>		[A] Ho Pei Fang
9	12 Sep 2017 10:34	<b>Adj Assignment Cancelled</b>	LKK	[I] Winnie Chua Ping Ping
10	12 Sep 2017 10:34	<b>Adj Est Details Deleted</b>	Deleting Est Details For Cancelling Adjuster Assignment	[I] Winnie Chua Ping Ping
11	12 Sep 2017 10:34	<b>Adj Co Assigned</b>	LKK Auto Consultants Pte Ltd (HQ):Please revert. tks.	[I] Winnie Chua Ping Ping
12	12 Sep 2017 10:34	<b>Adj Next Rpt Changed</b>	Next Rpt:Im. Advice.Due Date:2017/09/13	[I] Winnie Chua Ping Ping
13	12 Sep 2017 10:34	<b>Adj Mandate Set</b>	Approved:25000.00.Reinsp:Adj decides.	[I] Winnie Chua Ping Ping
14	12 Sep 2017 10:39	<b>Assignment 1st Accessed</b>		[A] Nivitha Govindasamy
15	12 Sep 2017 13:30	<b>Adj Adjuster Assigned</b>	[None] -> MARCUS CHUA	[A] CATHERINE CHONG KAI LING
16	13 Sep 2017 09:41	<b>Adj Adjuster Assigned</b>	MARCUS CHUA -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
17	14 Sep 2017 12:15	<b>Adj Rpt Initiated</b>		[A] LOW AI PHING
18	14 Sep 2017 12:20	<b>Adj Im. Advice Submitted</b>	Next Rpt:Final Rpt.Due Date:2017/10/12	[A] LOW AI PHING
19	14 Sep 2017 12:20	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2017/10/12	[A] LOW AI PHING
20	14 Sep 2017 12:21	<b>Adj Mandate Request</b>	Cur.Req:6203.90:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] LOW AI PHING
21	14 Sep 2017 14:38	<b>Adj Next Rpt Changed</b>	Next Rpt:Final Rpt.Due Date:2017/10/12. Mandate Remarks: a if c; check items to be confirmed	[I] Lui Siew Wei
22	14 Sep 2017 14:38	<b>Adj Mandate Set</b>	Approved:4718.10:a if c; check items to be confirmed	[I] Lui Siew Wei

## ACTIVITY

[12/09/2017 09:45] Ho Pei Fang:  
Yen confirmed survey appt tmr at 2pm, owner waiting.

[12/09/2017 08:53] Ho Pei Fang:  
Pat confirmed car not in, will arrange and inform IHS.

## Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1578358	11/09/2017 14:02	Motor	Kan Fook Sing Motor Workshop	Kan Fook Sing Motor Workshop (Defu)	GBF3343K		xx.xx
1582194	14/09/2017 12:15	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBF3343K		10.70

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 08 Dec 2017

**Preliminary Advice**

Vehicle No	: GBF3343K	Accident Date	: 09/09/2017
Make	: FIAT DOBLO	Policy No.	: A28840665MKC
Assignment Date	: 12/09/2017	Excess	: S\$500.00
Date of Inspection	: 13/09/2017	Est. Duration of Repair	: 7.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,102.02	(with Supplementary \$313.50)
Revised Amount	:S\$	4,896.10	(with Supplementary \$313.50)
Check Items (Estimated)	:S\$	-	
Total	:S\$	4,896.10	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	4,472.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,528.00

**Remarks** ( X ) The vehicle is economical for repair.

Please assist supplementary approval.

 ( ) The above survey was conducted on a 'without prejudice' basis.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Winnie Chua Ping Ping

Date: 14 Sep 2017

**Preliminary Advice**

Vehicle No	: GBF3343K	Accident Date	: 09/09/2017
Make	: FIAT DOBLO	Policy No.	: A28840665MKC
Assignment Date	: 12/09/2017	Excess	: S\$500.00
Date of Inspection	: 13/09/2017	Est. Duration of Repair	: 7.00
Inspection At	: KAN FOOK SING MOTOR WORKSHOP (DEFU) NO. 61 DEFU LANE 12 SINGAPORE 539147		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,823.90
Revised Amount	:S\$	4,718.10
Check Items (Estimated)	:S\$	1,485.80
Total	:S\$	6,203.90
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	4,472.00
Salvage Value	:S\$	
Margin for Repair	:S\$	73,528.00

**Remarks**

( X ) The vehicle is economical for repair.

We have not authorise repair.

( ) The above survey was conducted on a 'without prejudice' basis.

Text size + -

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1080Z

### Vehicle Details

Vehicle No.: GBF3343K

Vehicle to be Exported: No

Intended De-registration Date: 13 Sep 2017

Vehicle Make: FIAT

Vehicle Model: DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 263A50007714579

Chassis No.: ZFA26300006D36802

Maximum Power Output: -

Open Market Value: \$18,516.00

Original Registration Date: 23 Sep 2016

First Registration Date: 23 Sep 2016

Transfer Count: 1

Actual ARF Paid: \$926.00

### Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 22 Sep 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$4,956.00

COE Rebate Amount: \$4,472.00

**Total Rebate Amount: \$4,472.00**

The information contained herein is correct as at 13 Sep 2017



Please read through the Privacy Statement, Terms of Use and Disclaimer.

Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution

Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)  
 Last updated on 27 Aug 2017 at 01:09 AM

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/09/2017 10:30
Date Of Accident	09/09/2017 10:30
Exact Location Of Accident	SLE (CTE)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF3343K
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NATURE LANSCAPES PTE LTD
Co Reg No	198101080Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62856802
<b>Vehicle Particulars</b>	
Manufacturer	FIAT
Model	DOBLO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 28840665 MKC
Cover Note Number	
<b>Driver</b>	
Name of Driver	LEE KHONG TECK
NRIC No	S1811852A
Date Of Birth	04/06/1967
Occupation	INDOOR
Date Of Driving Pass	18/03/1988
Driving Experience	29 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81330837
Fax Number	
Contact Number	
EMail Address	AHTECK.9541@GMAIL.COM

Phone Number NIL

Email Address NIL

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number ET9529T

Vehicle Make/Model/Colour TOYOTA

Details Of Properties NIL

Name of Driver CHANG CHOONG MENG

NRIC/Passport Number S7010480F

Contact Number NIL

Address NIL

Postcode NIL

Insurance Company Name

Nature Of Damage NIL

No. Of Passenger (Including Driver) 1

**Details of Witness**

Name NIL

Phone Number NIL

Email Address NIL



## Police report Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20170909/7004

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 4

Report No. T/20170909/7004

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	Chang Choong Meng	ID No.	S7010480F
Related Vehicle	ET9529T (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LEE KHONG TECK	ID No.	S1811852A
Related Vehicle	GBF3343K (Van)	Contact No.	81330837
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	09/09/2017	Date Discharge	09/09/2017
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver			
Name	Lau Yuan Dong	ID No.	G8510952R
Related Vehicle	WSK2579 (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 09/09/2017 @ 1029hrs, I was driving my van GBF3343K along Seletar Expressway (SLE) towards Central Expressway (CTE). Upon reaching the slip road into Woodlands Ave 12, a car in front of me came to a stop and I also stopped at the rear. Soon after, I felt an impact from the rear and caused my vehicle to surge forward to collide onto the car ahead. I then discovered that I was involved in a 3 vehicle chain collision and I was the 2nd vehicle.

The 1st vehicle is ET9529T and the last vehicle is a Malaysian car WSK2579. No police attended. I will be seeking my own medical treatment later as I felt pain on my body.



**SINGAPORE  
POLICE FORCE**



T/20170909/7004

4 of 4

Report No. T/20170909/7004

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / TPHQ / YEO GEAK ENG CECILIA Contact No.: 65476404

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 09/09/2017 12:59
Classification Of Case:

Authentication Stamp  
NP168



簡 福 星 啤 啤 工 廠  
KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147  
Tel : (65) 6747 9560, 6858 2126, 6858 4361  
Fax : (65) 6748 1006, 6281 8428  
E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 201408314  
GST Reg. No. S79-201408314

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A28840665MKC	Date of Loss:	09/09/2017
Vehicle Reg. No.:	GBF3343K	Driveable?	
Driver Age/Info:	50 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NATURE LANSCAPES PTE LTD		
Driver:	LEE KHONG TECK		
Make/Model:	FIAT DOBLO, 1.6 D CARGO MJ (M)	Vehicle Reg. Date:	23/09/2016
Vehicle Colour:	WHITE	Chassis No:	ZFA26300006D36802
Engine No:	263A50007714579		
Odometer:	0 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO THE SKETCH PLAN AND POLICE REPORT T/20170909/7004.		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	3,793.90
Miscellaneous Items	50.00
Labour	1,350.00
Paintwork Labour	1,630.00
Towing	0.00
<b>Calculated Gross Total (S\$)</b>	<b>6,823.90</b>
<b>- Excess (S\$)</b>	<b>500.00</b>
<b>(S\$)</b>	<b>6,323.90</b>
<b>+ GST 7.00% (S\$)</b>	<b>442.67</b>
<b>Nett Amount (S\$)</b>	<b>6,766.57</b>

This claim is handled by: TAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 11 Sep 2017)  
**Parts:** N/A FIAT DOBLO 1.6 D CARGO MJ (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** Kan Fook Sing Motor Workshop/GBF3343K/11/09/2017 16:26  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER / <i>ll</i>	0.00	0.00	*290.00 F ✓
2	1		*FRONT BONNET / <i>Buc</i>	0.00	0.00	*365.00 F ✓
3	1		*FRONT BONNET LOCK / <i>?x NN</i>	0.00	0.00	*135.00 F X
4	1		*FRONT GRILLE / <i>BR</i>	0.00	0.00	*200.00 F ✓
5	1		*FRONT GRILLE EMBLEM / <i>mc</i>	0.00	0.00	*70.00 F ✓
6	1		*FRONT HEADLAMP RH / <i>{ car }</i>	0.00	0.00	*350.00 F ✓
7	1		*FRONT HEADLAMP LH / <i>{ car }</i>	0.00	0.00	*350.00 F ✓
8	1		*FRONT BUMPER / <i>ll</i>	0.00	0.00	*345.00 F ✓
9	1		*FRONT BUMPER REINFORCEMENT / <i>?x NN</i>	0.00	0.00	*200.00 F X
10	1		*FRONT BUMPER SIDE RETAINER RH / <i>{ mc }</i>	0.00	0.00	*48.00 F ✓
11	1		*FRONT BUMPER SIDE RETAINER LH / <i>{ mc }</i>	0.00	0.00	*48.00 F ✓
12	10		*FRONT BUMPER CLIP / <i>x mc</i>	0.00	0.00	*20.00 F ✓
13	1		*AIR CON CONDENSER / <i>?x</i>	0.00	0.00	*310.00 F ✓
14	1		*RADIATOR ASSY / <i>?x</i>	0.00	0.00	*295.00 F ✓
15	1		*FRONT NUMBER PLATE GARNISH / <i>x ll</i>	0.00	0.00	*85.00 F ✓
16	1		*FRONT TOP PANEL / <i>? repair</i>	0.00	0.00	*192.00 F ✓
17	1		*FRONT HEADLAMP PANEL RH / <i>?x</i>	0.00	0.00	*73.00 F ✓
18	1		*FRONT HEADLAMP PANEL LH / <i>?x</i>	0.00	0.00	*73.00 F ✓
Sub Total (S\$)						<b>3,449.00</b>
+ Margin on L,N Items 10.00% (S\$)						344.90
Total Parts (S\$)						<b>3,793.90</b>

F=Franchise part.

Kan Fook Sing Motor Workshop/GBF3343K/11/09/2017 16:26. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	6PAX STICKER <del>X</del> <i>4 PAX NN</i>	10.00 <del>X</del>
2	1	70KM/H STICKER <del>X</del>	10.00 <del>X</del>
3	1	FRONT NUMBER PLATE <i>/ BT</i>	30.00 <del>/</del>
<b>Sub Total (S\$)</b>			<b>50.00</b>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>			
1	SPRAYPAINTING CHARGES(REAR)	New <i>/ 500</i>	550.00
2	SPRAYPAINTING CHARGES(FRONT)	New <i>/ 900</i>	1,080.00
<b>Labour Items</b>			
3	TO CHECK WIRING SYSTEM(FRONT & REAR)	New <i>/ 30</i>	50.00
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New <i>NNX</i>	80.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	New <i>/ 250</i>	400.00
6	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	New <i>/ 600</i>	820.00
<b>Gross Labour Cost (S\$)</b>			<b>2,980.00</b>

Kan Fook Sing Motor Workshop/GBF3343K/11/09/2017 16:26. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Not Authorized.  
Excess \$500.  
part by part  
before paint photos.  
7 Days.

*[Signature]*  
14/9/17

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**REPAIR DETAILS**

GBF 3343K Supplementary

**Reference**

Part Source: (Last Synchronised: 16 Oct 2017)  
 Parts: N/A FIAT DOBLO 1.6 D CARGO MJ (M) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Kan Fook Sing Motor Workshop/GBF3343K/16/10/2017 12:08  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER AIR GRILLE (A) / DE	0.00	0.00	*285.00 F
						Sub Total (S\$)
						285.00
						+ Margin on L,N Items 10.00% (S\$)
						28.50
						Total Parts (S\$)
						313.50

Kan Fook Sing Motor Workshop/GBF3343K/16/10/2017 12:08. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

**Estimates on Miscellaneous Items**

There are no new miscellaneous items selected.

**Estimates on Labour**

There are no labour items selected.

Kan Fook Sing Motor Workshop/GBF3343K/16/10/2017 12:08. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

簡福星嘍哆工廠  
 KAN FOOK SING MOTOR WORKSHOP  
 61 DEFU LANE 12  
 SINGAPORE 539147  
 TEL: 67479560, 68582126, 68584361  
 FAX: 67481006, 62818428

MSIG INSURANCE (SINGAPORE) PTE LTD  
 4 SHENTON WAY #21-01  
 SGX CENTRE 2  
 SINGAPORE 068807

INVOICE NO : TEST  
 DATE : 04-10-2017

VEHICLE NO. : GBF3343K  
 ACCIDENT DATE : 09-09-2017 10:30  
 THIRD PARTY REF. : WSK2579

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE GBF3343K FIAT DOBLO

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BUMPER	290.00
1	FRONT BONNET	365.00
1	FRONT GRILLE	200.00
1	FRONT GRILLE EMBLEM	70.00
2	FRONT HEADLAMP @\$350.00	700.00
1	FRONT BUMPER	345.00
2	FRONT BUMPER SIDE RETAINER @\$48.00	96.00
1	FRONT BUMPER AIR GRILLE	285.00
		<del>285.00</del>
		2,351.00
	ADD 10 %	235.10
	TOTAL ( A )	2,586.10
		<hr/>
		30.00
	TOTAL ( C )	30.00
		<hr/>
		30.00
		<hr/>
		80.00

SPECIAL NETT ITEMS

1 FRONT NUMBER PLATE

LABOUR CHARGES

1 TO CHECK WIRING SYSTEM ( FRONT & REAR )

1 TO REMOVE/REFIT/REFILL AIR CON GAS

簡福星嘍哆工廠  
 KAN FOOK SING MOTOR WORKSHOP  
 61 DEFU LANE 12  
 SINGAPORE 539147  
 TEL: 67479560, 68582126, 68584361  
 FAX: 67481006, 62818428

VEHICLE NO. : GBF3343K  
 ACCIDENT DATE : 09-09-2017 10:30  
 THIRD PARTY REF. : WSK2579

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS ( REAR )	250.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS ( FRONT )	600.00
1	SPRAYPAINTING CHARGES ( REAR )	900.00
1	SPRAYPAINTING CHARGES ( FRONT )	500.00
TOTAL ( D )		2,360.00
TOTAL REPAIR COST :		4,976.10
G S T % :		313.32
EXCESS AMOUNT :		500.00
INVOICE AMOUNT :		4,789.42

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*REAR BUMPER / <i>RL</i>	0.00	0.00	*290.00 F	
2	1		*FRONT BONNET / <i>RL</i>	0.00	0.00	*365.00 F	
3	1		*FRONT BONNET LOCK / <i>?</i>	0.00	0.00	*135.00 F	
4	1		*FRONT GRILLE / <i>BR</i>	0.00	0.00	*200.00 F	
5	1		*FRONT GRILLE EMBLEM / <i>RL</i>	0.00	0.00	*70.00 F	
6	1		*FRONT HEADLAMP RH / <i>{CPA}</i>	0.00	0.00	*350.00 F	
7	1		*FRONT HEADLAMP LH / <i>{CPA}</i>	0.00	0.00	*350.00 F	
8	1		*FRONT BUMPER / <i>RL</i>	0.00	0.00	*345.00 F	
9	1		*FRONT BUMPER REINFORCEMENT / <i>?</i>	0.00	0.00	*200.00 F	
10	1		*FRONT BUMPER SIDE RETAINER RH / <i>{CPA}</i>	0.00	0.00	*48.00 F	
11	1		*FRONT BUMPER SIDE RETAINER LH / <i>{CPA}</i>	0.00	0.00	*48.00 F	
12	10		*FRONT BUMPER GLIP / <i>RL</i>	0.00	0.00	*20.00 F	
13	1		*AIR CON CONDENSER / <i>?</i>	0.00	0.00	*310.00 F	
14	1		*RADIATOR ASSY / <i>?</i>	0.00	0.00	*295.00 F	
15	1		*FRONT NUMBER PLATE GARNISH / <i>RL</i>	0.00	0.00	*65.00 F	
16	1		*FRONT TOP PANEL / <i>?</i>	0.00	0.00	*192.00 F	
17	1		*FRONT HEADLAMP PANEL RH / <i>?</i>	0.00	0.00	*73.00 F	
18	1		*FRONT HEADLAMP PANEL LH / <i>?</i>	0.00	0.00	*73.00 F	
						<b>Sub Total (S\$)</b>	<b>3,449.00</b>
						<b>+ Margin on L,N Items 10.00% (S\$)</b>	<b>344.90</b>
						<b>Total Parts (S\$)</b>	<b>3,793.90</b>

F=Franchise part.

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	6PAX-STICKER / <i>RL</i>	10.00
2	1	70KM/H-STICKER / <i>RL</i>	10.00
3	1	FRONT NUMBER PLATE / <i>BT</i>	30.00
			<b>Sub Total (S\$)</b>
			<b>50.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES(REAR)	New	500 550.00
2	SPRAYPAINTING CHARGES(FRONT)	New	500 1,080.00
<u>Labour Items</u>			
3	TO CHECK WIRING SYSTEM(FRONT & REAR)	New	30 50.00
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New	? 80.00
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	New	250 400.00
6	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	New	600 820.00
			<b>Gross Labour Cost (S\$)</b>
			<b>2,980.00</b>

Kan Fook Sing Motor Workshop/GBF3343K/11/09/2017 16:26. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



# KIAN HUA

KIAN HUA MOTOR CO. PTE LTD  
 7 Jalan Lembah Kallang Singapore 339563  
 Tel: 62933850 Fax: 63551800  
 Email: Sales@Kianhuamotor.Com  
 Co. Reg No. / Gst Reg No: 200106569G

### Customer's Copy

Customer: KAN FOOK SING MOTOR WORKSHOP  
 Address: 61 DEFU LANE 12 FAX 67481006/62818428  
 SINGAPORE 539147

Tax Invoice No: SIN1542843  
 Date: 02/10/2017  
 Area Code: 2 DELIVER  
 Credit Terms: 30Days  
 Kian Hua Sales: KEVIN

GBF3343K - FIAT DOBLO

WWW.KIANHUAMOTOR.COM

No.	Description	Qty	Unit Price	Amount
1	BUMPER F/DOB REAR	1	290.00	290.00
2	BONNET F/DOB	1	365.00	365.00
3	GRILLE F/DOB FRT	1	200.00	200.00
4	GRILLE BADGE F/DOB FRT	1	70.00	70.00
5	H/LAMP F/DOB LH	1	350.00	350.00
6	H/LAMP F/DOB RH	1	350.00	350.00
7	BUMPER F/DOB FRT	1	345.00	345.00
8	BUMPER BKT F/DOB F/LH	1	48.00	48.00
9	BUMPER BKT F/DOB F/RH	1	48.00	48.00
10	BUMPER GRILLE F/DOB FRT	1	285.00	285.00

Products received and checked to be in good condition

Sub-Total: SGD 2,351.00  
 G.S.T(7%): 164.57  
 Total: SGD 2,515.57

Customer's Signature / Company Stamp  
 Products sold are not returnable.

#### FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

KEVIN - 02/10/2017 11:41:36 AM

Authorised Signature

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Sep 2017 <a href="#">Sendback Est</a>	11 Sep 2017 16:26 <b>S\$6,823.90</b>	12 Sep 2017 10:34 <a href="#">Edit Adj Rpt</a>	<b>S\$4,896.10</b> <a href="#">Edit Estimates</a>	<b>S\$4,896.10</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>
Supp #1	16 Oct 2017 12:07	16 Oct 2017 12:08 <b>S\$313.50</b>	16 Oct 2017 12:08			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

<b>Insured:</b>	NATURE LANSCAPES PTE LTD, Co. Reg. No.: 198101080Z		
<b>Vehicle Reg. No.:</b>	GBF3343K	<b>Date of Loss:</b>	09/09/2017 10:00 - :59
<b>Claim Type:</b>	OD / 529187	<b>Policy/Cover Note No.:</b>	A28840665MKC (Comprehensive) Coverage: 23/09/2016 - 22/09/2017
		<b>Excess:</b>	S\$500.00
<b>Repairer:</b>	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Winnie Chua Ping - 6594 2556]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 12/10/2017]		
<b>Driver/Custodian:</b>	LEE KHONG TECK (50 / Male), NRIC: S1811852A, Tel: +6581330837		
<b>Adj Asg. Remarks:</b>	Please revert. tks.		

**ASSOCIATED MAIL RECEIVED**

[View All](#) [Compose Case Mail](#)

- MSIG\_SG (11/12/2017): Alert - Adj Mandate Approved (S\$4896.10) - GBF3343K - Claim Handler: Winnie Chua...
- MSIG\_SG (14/09/2017): Alert - Adj Mandate Approved (S\$4718.10) - GBF3343K - Claim Handler: Winnie Chua...

**ALL ASSOCIATED TASKS**

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### Claim Documents

GBF3343K (529187)  
 OD  
 Sep 9 2017 10:00AM  
 [NATURE LANSCAPES PTE LTD]  
 Kan Fook Sing Motor Workshop

Upload Documents    Upload Photos    Compose New Letter

View Use Viewer

**Assessment Reports**

No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	1 per page	<input checked="" type="checkbox"/>
1	11/09/17 11:54	<b>Accident Statement</b>	Thumbnail	Print
2	11/09/17 16:26	<b>Repairer Estimates</b>	Load HTM	
3	16/10/17 12:08	<b>Repairer Estimates Suppl. #1</b>	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Load HTM	
1	14/09/17 12:20	<b>Adjuster Immediate Advice</b>	Thumbnail	Print
2	08/12/17 10:08	<b>Adjuster Immediate Advice</b>	Load HTM	
			Load HTM	

**Photos/Images**

No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	3 per page	<input checked="" type="checkbox"/>
1	11/09/17 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]	Thumbnail	Print
2	11/09/17 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	11/09/17 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	11/09/17 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	11/09/17 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	11/09/17 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	11/09/17 11:49	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	11/09/17 11:49	<b>Accident scene</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	11/09/17 11:49	<b>Accident scene</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	11/09/17 11:49	<b>Accident scene</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Load JPG	<input checked="" type="checkbox"/>
1	14/09/17 12:12	<b>General View</b>	Thumbnail	Print
2	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	14/09/17 12:12	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

20	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
21	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
22	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
23	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
24	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
25	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
26	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
27	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
28	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
29	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
30	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
31	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
32	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
33	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
34	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
35	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
36	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
37	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
38	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
39	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
40	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
41	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
42	14/09/17 12:12	General View		Load JPG	<input checked="" type="checkbox"/>
43	07/12/17 17:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	07/12/17 17:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
45	07/12/17 17:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
46	07/12/17 17:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
47	07/12/17 17:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
48	07/12/17 17:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	<b>Thumbnail</b>	<b>Print</b>
1	11/09/17 14:12	E-filed GIA report	Load PDF	
2	08/12/17 10:09	Repairers Bill	Load PDF	
3	08/12/17 10:09	Signed DV	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	<b>Thumbnail</b>	<b>Print</b>
1	11/09/17 16:51	tp gia report	Load PDF	
2	11/09/17 17:09	POLICY	Load PDF	
3	01/11/17 11:23	tp police report, pir-pending investigation, tp insurer name, maphilindo bill	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	<b>Thumbnail</b>	<b>Print</b>
1	14/09/17 14:24	ESTIMATE	Load PDF	
2	08/12/17 09:58	SUPPLEMENTARY	Load PDF	
3	11/12/17 11:08	ESTIMATE MARKING	Load PDF	
4	12/12/17 16:10	Parts Invoice	Load PDF	

### Linked Accident Report Documents

Assessment Reports			View	Use Viewer
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	1 per page	<input checked="" type="checkbox"/>
1	11/09/17 11:54	Accident Statement	Load HTM	<b>Thumbnail</b> <b>Print</b>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	<b>Thumbnail</b>	<b>Print</b>
1	11/09/17 11:49	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

2	11/09/17 11:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	11/09/17 11:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	11/09/17 11:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	11/09/17 11:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	11/09/17 11:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	11/09/17 11:49	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	11/09/17 11:49	Accident scene		Load JPG	<input checked="" type="checkbox"/>
9	11/09/17 11:49	Accident scene		Load JPG	<input checked="" type="checkbox"/>
10	11/09/17 11:49	Accident scene		Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	11/09/17 11:53	Accident Sketch Plan	Load TIF	
2	11/09/17 11:53	Accident Sketch Plan	Load TIF	
3	11/09/17 11:53	Police report	Load TIF	
4	11/09/17 11:53	Police report	Load TIF	
5	11/09/17 11:53	Police report	Load TIF	
6	11/09/17 11:53	Police report	Load TIF	
7	11/09/17 11:53	NRIC & DL	Load TIF	
8	11/09/17 11:53	CI	Load TIF	

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Repairer  Handling Insurer

Note: Remarks are private unless you show it to other parties.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

**Our File No:** CS/MSG17017579/GGBE2  
**Date:** 12/12/2017

**REFERENCE**

**Insured/Claimant:** NATURE LANSCAPES PTE LTD **Policy No:** A28840665MKC  
**Date of Loss:** 09/09/2017 **Nature of Claim:** OD **Claim No:** 529187

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

**Reg No:** GBF3343K **Engine No:** 263A50007714579  
**Make & Model:** FIAT DOBLO, 1.6 D CARGO MJ (M) **Chassis No:** ZFA26300006D36802  
**Reg. Date:** 23/09/2016 (Man. Year: 2016) **Odometer:** 44898 km  
**Colour:** White/Green  
**Engine Capacity:** 1598 cc  
**Market Value/New Car Price:** S\$78,000.00  
**Sum Insured (S\$):** Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

**General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

**CONDITION OF TYRES**

**Front Tyre Size:** 195/60R16 **Rear Tyre Size:** 195/60R16  
**Front Left Side:** Continental 6 mm **Rear Left Side:** Continental 6 mm  
**Front Right Side:** Continental 6 mm **Rear Right Side:** Continental 6 mm

*The above values represent the remaining tyre treads depth*

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,107.40	2,586.10	1,521.30	37.04
Miscellaneous Items	50.00	30.00	20.00	40.00
Labour	1,350.00	880.00	470.00	34.81
Paintwork Labour	1,630.00	1,400.00	230.00	14.11
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,137.40</b>	<b>4,896.10</b>	<b>2,241.30</b>	<b>31.40</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>6,637.40</b>	<b>4,396.10</b>	<b>2,241.30</b>	<b>33.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>464.62</b>	<b>307.73</b>	<b>156.89</b>	<b>33.77</b>
<b>Nett Amount (S\$)</b>	<b>7,102.02</b>	<b>4,703.83</b>	<b>2,398.19</b>	<b>33.77</b>

**INSPECTION**

**Date of Assignment:** 12/09/2017 **Present Location:** Kan Fook Sing Motor Workshop (Defu)  
**Date Inspected:** 13/09/2017 **Inspected At:** Kan Fook Sing Motor Workshop (Defu)  
No. 61 Defu Lane 12  
Singapore 539147

**Estimated Period of Repair:** 7.0 days

**Adjuster:** XING GUO QIANG

**Manager:** LOW AI PHING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b>	(Last Synchronised: 12 Dec 2017)
<b>Parts:</b>	N/A FIAT DOBLO 1.6 D CARGO MJ (M) (Model not available in database)
<b>Labour:</b>	Repairer's (Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBF3343K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (WCP)	Deformed	290.00 F	*290.00 F
2	1		*FRONT BONNET (WCP)	Buckled	365.00 F	*365.00 F
3	1		*FRONT BONNET LOCK (WCP)	Not Necessary	135.00 F	*- F
4	1		*FRONT GRILLE (WCP)	Broken	200.00 F	*200.00 F
5	1		*FRONT GRILLE EMBLEM (WCP)	Necessary	70.00 F	*70.00 F
6	1		*FRONT HEADLAMP RH (WCP)	Cracked	350.00 F	*350.00 F
7	1		*FRONT HEADLAMP LH (WCP)	Cracked	350.00 F	*350.00 F
8	1		*FRONT BUMPER (WCP)	Deformed	345.00 F	*345.00 F
9	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	200.00 F	*- F
10	1		*FRONT BUMPER SIDE RETAINER RH (WCP)	Necessary	48.00 F	*48.00 F
11	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Necessary	48.00 F	*48.00 F
12	10		*FRONT BUMPER CLIP (WCP)	Not Necessary	20.00 F	*- F
13	1		*AIR CON CONDENSER (WCP)	Not Necessary	310.00 F	*- F
14	1		*RADIATOR ASSY (WCP)	Not Necessary	295.00 F	*- F
15	1		*FRONT NUMBER PLATE GARNISH (WCP)	Not Necessary	85.00 F	*- F
16	1		*FRONT TOP PANEL (WCP)	Repair	192.00 F	*- F
17	1		*FRONT HEADLAMP PANEL RH (WCP)	Not Necessary	73.00 F	*- F
18	1		*FRONT HEADLAMP PANEL LH (WCP)	Not Necessary	73.00 F	*- F
<b>Supplementary #1</b>						
19	1		*FRONT BUMPER AIR GRILLE (WCP)	Deformed	285.00 F	*285.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>3,734.00</b>	<b>2,351.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	<b>373.40</b>	<b>235.10</b>
<b>Total Parts (\$\$)</b>	<b>4,107.40</b>	<b>2,586.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No Qty Particulars

			Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	6PAX STICKER Not Necessary	10.00	0.00
2	1	70KM/H STICKER Not Necessary	10.00	0.00
3	1	FRONT NUMBER PLATE Bent	30.00	30.00
Sub Total (S\$)			50.00	30.00

## Recommended Labour

No Particulars

		Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	SPRAYPAINTING CHARGES(REAR)	New	550.00	500.00
2	SPRAYPAINTING CHARGES(FRONT)	New	1,080.00	900.00
<b>Labour Items</b>				
3	TO CHECK WIRING SYSTEM(FRONT & REAR)	New	50.00	30.00
4	TO REMOVE/REFIT/REFILL AIR CON GAS	New	80.00	-
5	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	New	400.00	250.00
6	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	New	820.00	600.00
Gross Labour Cost (S\$)			2,980.00	2,280.00

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;