

ASS. REC. BY: Adrian King

REF:

CC3 / ALH17017663 / Atbn2**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2100488648Claims No. 218621988856

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 135K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 8 1/2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJL 3700L Yr Regn: 2016 10CTType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Audi A4 c.c. 1395Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 20188 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZF42HA 027053Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 12/09/17Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD A/G.SJL 3700L - CC3 / ALH17008458 / Atbn2DATE: 22041719/1 - Confirm repair cost \$3011.20 @ 3 days repair.
(Red: 2883.86 .43%)

RECEIVED 25 JAN 2019

Date/Time, File Pass to?

1/25/1 Typist

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 200Transportation: 10

S + RS, SI

Photos

Others

TOTAL

210Report Format: ODLump Sum / (B.): (\$ 3011.20)



LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG17017663/Atb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 12-09-2017	
		Code : AIG	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SJL 3700L
Policy No.	2100488648	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	12/09/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/09/2017	Inspection Date	12/09/2017
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699		
5a. Remarks			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6982167G



Name

VINCENT TAN KHAR KHENG



Race

CHINESE

Date of Birth

01-03-1969

Sex

M


Country of Birth

MALAYSIA

8392517



NRIC No. S6982167G



Nationality

MALAYSIAN

Blood Group

B+

Date of Issue

17-03-2001

7 PASIR RIS DRIVE 4 #07-05
SINGAPORE 519459

NRIC No. S6982167G

Date: 08-08-2006

No: 5487863



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1989
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

HOTLINE: 111-1951 8419 3000
FAX: (65) 6415-1721

M X 1

AUDI AUTO PROTECTOR

CERTIFICATE NO. 2100488648-00000

OWN DAMAGE EXCESS S\$600.00 (1)
WINDSCREEN EXCESS S\$100.00

(for policies with effect from 1st November 2002)

SUM INSURED Market Value
INSURING WITH COE/PARF Yes

SJL3700L

VINCENT TAN KHAR KHENG

1) VEHICLE REGISTRATION NO.

2) NAME OF INSURED

3) EFFECTIVE DATE OF THE COMMENCEMENT
OF INSURANCE FOR THE PURPOSES OF THE ACT

28 Oct 2016

4) DATE OF EXPIRY OF INSURANCE

27 Oct 2017

5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE *

SUBJECT TO AGE CONDITION: All Age Condition

a) The Insured.

b) Any other person who is driving on the Insured's order or with his permission.

This policy will indemnify the insured or any authorised driver only if he/she meets the age conditions.

A Young and/or Inexperienced Driver Excess ("YIDE") of S\$3,000.00, in addition to the

Policy Excess, applies to You and any Authorised Driver (named or unnamed) if You are or the said

Authorised Driver is below the age of 23 and/or has less than 2 years' driving experience.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6) LIMITATION AS TO USE *

Use only for social, domestic and pleasure purposes and for the Insured's business.

The Policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trial speed-testing

the carriage of goods other than samples in connection with any trade or business or use for any purpose in

connection with the Motor Trade.

APPROVED REPORTING CENTRES / AUDI AUTHORISED REPAIRERS

1. Audi Customer Service Center - 55 Ubi Road 1 (Tel: 63962323)

APPROVED REPORTING CENTRES / AIG AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

2. ComfortDelgro Engg - 205 Braddell Rd (Tel: 63837118) 3. UPS Body & Paint Workshop - 209 Pandan Gardens (Tel: 65684501)

4. Hbez - 30 Bukit Batok Crest (Tel: 66547777) 5. Glass-Fix - 52 Ubi Ave 3 (Tel: 62780887) - For windscreen only

6. Kai Fook Sing Motor - 61 Defu Lane 12 (Tel: 67479560) 7. Lat Huan (Meng Koe) Motor - 21 Sin Ming Ind (Tel: 64538110)

8. Mova Automotive - 1008 Bukit Merah Lane 3 (Tel: 62723892) 9. Progressive Automotive - 3022A Ubi Rd 1 (Tel: 67415336)

10. SME Motor - 1 Kaki Bukit Ave 5 Bld D (Tel: 67476106)

LOSS OF USE Loss Of Use 15 days Replacement Car only for repairs at Audi Customer Service Centre

NAMED DRIVER NA

HIRE PURCHASE COMPANY United Overseas Bank Limited
EMPLOYER'S LOAN

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Issued At Singapore 15 Dec 2016

AIG Asia Pacific Insurance Pte. Ltd.


94125-560
PREMIUM LEASING/CTIB
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE
CENTRE SINGAPORE 119938

AIG Asia Pacific Insurance Pte. Ltd.

To whom it may concern,

I, Vincent Tan Khar Kheng, NRIC No S6982167G, hereby authorise my wife, Tew Hwei Sin S7622343B to act on my behalf to report and make insurance claim for vehicle SJL3700L which is registered under my name. This is in relation to a car accident yesterday evening (11 Sep 2017) where my vehicle driven by my wife, was hit at the rear by a taxi. She will furnish details of the accident for the purpose of making the insurance claim.

Thank you.



Vincent Tan Khar Kheng
12 Sep 2017

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0886/2017/PH
Date	:	11-Sep-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Vincent Tan Khar Kheng
Address	:	7 Pasir Ris Drive 4 #07-05 Singapore 519459
Telephone	:	HP +65 83836868
Type of Claim	:	Own Damage Claims
Policy No.	:	2100488648-00000
Vehicle No	:	SJL 3700 L
Model Code	:	AUDI A4 SEDAN 1.4 TFSI
Model / Year	:	Oct-16
Engine No	:	CVN 017632
Chassis No	:	WAUZZZF42HA027053
Mileage	:	-
Date In	:	12-Sep-17
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-Sep-17
Place of Accident	:	PASIR RIS AVE 1 TO TPE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 12/09/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised repairs, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SJC 3700 L

Estimated Labour Charges for Accident Vehicle SLH 1495 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	\$ 280.00 ✓	✓
2	To dismantle & renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 500 ✓	✓
3	To respray rear bumper.	\$ 800.00 550 ✓	✓
4	To carry out diagnostic check.	\$ 192.00 ✓	✓
TOTAL SPARE PARTS		\$ 2,172.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 3700 L

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	REAR BUMPER <i>deformed</i>	\$ 1,844.00	✓ 1475.20
2	REAR BUMPER SPOILER <i>NE M</i>	\$ 203.00	x.
3	REAR BUMPER REINFORCEMENT <i>NE M</i>	\$ 756.00	x
4	REAR BUMPER GUIDE SECTION INNER LH / RH <i>2 NE M</i>	2 \$ 73.00	x
5	REAR BUMPER GUIDE SECTION OUTER LH / RH <i>2 NE M</i>	2 \$ 36.00	x 14
6	REAR BUMPER SECURING STRIP <i>2 NE M</i>	\$ 182.00	? x
7	Rear inner/outer reverse sensor <i>2 NE M</i>	2 \$ 415.00	207.50 x
8	Seal ring <i>NE M</i>	4 \$ 14.00	? x
9	Sundries <i>NE M</i>	\$ 200.00	? x
TOTAL SPARE PARTS		\$ 3,723.00	
TOTAL LABOUR CHARGES		\$ 2,172.00	
GRAND TOTAL		\$ 5,895.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0886/2017/PH
Date	:	11-Sep-17

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days - ok - jb - 11/11

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Vincent Tan Khar Kheng
Address	:	7 Pasir Ris Drive 4 #07-05 Singapore 519459
Telephone	:	HP +65 83836868
Type of Claim	:	Own Damage Claims
Policy No.	:	2100488648-00000
Vehicle No	:	SJL 3700 L
Model Code	:	AUDI A4 SEDAN 1.4 TFSI
Model / Year	:	Oct-16
Engine No	:	CVN 017632
Chassis No	:	WAUZZZF42HA027053
Mileage	:	-
Date In	:	12-Sep-17
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	11-Sep-17
Place of Accident	:	PASIR RIS AVE 1 TO TPE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLH 1495 P

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	\$ 280.00	\$ 280.00
2	To dismantle & renew rear bumper.Re-organise rear crash management components.Reinstall all parts removed.	\$ 900.00	\$ 500.00
3	To respray rear bumper.	\$ 800.00	\$ 550.00
4	To carry out diagnostic check.	\$ 192.00	\$ 192.00
TOTAL SPARE PARTS		\$ 2,172.00	\$ 1,522.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJL 3700 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,844.00	\$ 1,475.20
2	REAR BUMPER SPOILER	\$ 203.00	
3	REAR BUMPER REINFORCEMENT	\$ 756.00	
4	REAR BUMPER GUIDE SECTION INNER LH / RH	\$ 73.00	
5	REAR BUMPER GUIDE SECTION OUTER LH / RH	\$ 36.00	\$ 14.00
6	REAR BUMPER SECURING STRIP	\$ 182.00	
7	Rear inner/outer reverse sensor	\$ 415.00	
8	Seal ring	\$ 14.00	
9	Sundries	\$ 200.00	
TOTAL SPARE PARTS		\$ 3,723.00	\$ 1,489.20
TOTAL LABOUR CHARGES		\$ 2,172.00	\$ 1,522.00
GRAND TOTAL		\$ 5,895.00	\$ 3,011.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SJL 3700 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0886/2017/MAS

19 Jan 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SJL 3700 L, Audi A4 SEDAN 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SJL 3700 L**, claimant, **Mr. Vincent Tan Khar Kheng**, please find the related document per attached.

1. A copy of the Original invoice no. 85012031 – S\$3,221.98
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SJL 3700 L

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Sep 2017		12 Sep 2017 19:52 Edit Adj Rpt	S\$3,011.20 Edit Estimates	S\$3,011.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		VINCENT TAN KHAR KHENG, ID: S6982167G, Tel: +6598989898							
Vehicle Reg. No.:		SJL3700L		Date of Loss: 11/09/2017 17:00 - :59					
Claim Type:		OD / 2186219888SG		Policy/Cover Note No.: 2100488648 (Comprehensive)					
		Excess:		S\$0.00					
Repairer:		Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911							
Handling Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/09/2017]							
Driver/Custodian:		TEW HWEI SIN (41 / Female), NRIC: S7622343B, Tel: +6583836868							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (15/09/2017): SJL3700L / OD / 11/09/2017 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJL3700L (2186219888SG)

OD

Sep 11 2017 5:00PM

[VINCENT TAN KHAR KHENG]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View Use Viewer		
Video										1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	13/09/17 09:49	Video - Accident							Load MP4			
Photos/Images										3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	19/01/18 17:42	General View							Load JPG	☒		
2	19/01/18 17:42	General View							Load JPG	☒		
3	19/01/18 17:42	General View							Load JPG	☒		
4	19/01/18 17:42	General View							Load JPG	☒		
5	19/01/18 17:42	General View							Load JPG	☒		
6	19/01/18 17:42	General View							Load JPG	☒		
7	19/01/18 17:42	General View							Load JPG	☒		
8	19/01/18 17:42	General View							Load JPG	☒		
9	19/01/18 17:42	General View							Load JPG	☒		
10	19/01/18 17:42	General View							Load JPG	☒		
11	19/01/18 17:42	General View							Load JPG	☒		
12	19/01/18 17:42	General View							Load JPG	☒		
13	19/01/18 17:42	General View							Load JPG	☒		
14	19/01/18 17:42	General View							Load JPG	☒		
15	19/01/18 17:42	General View							Load JPG	☒		
16	19/01/18 17:42	General View							Load JPG	☒		
17	19/01/18 17:42	General View							Load JPG	☒		
18	19/01/18 17:43	Reinspection Photo							Load JPG	☒		
19	19/01/18 17:43	Reinspection Photo							Load JPG	☒		
20	19/01/18 17:43	Reinspection Photo							Load JPG	☒		
21	19/01/18 17:43	Reinspection Photo							Load JPG	☒		
Documentation										1 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail		Print		
1	13/09/17 09:51	Singapore Accident Statement							Load PDF			
2	13/09/17 09:51	Marked estimate							Load PDF			
3	13/09/17 09:51	Drivers Driving License							Load PDF			
4	13/09/17 09:51	Certificate of Insurance							Load PDF			
5	13/09/17 09:51	AUTHORISE LETTER							Load PDF			
6	26/01/18 12:20	WORKSHOP INVOICE							Load PDF			
7	26/01/18 12:20	DISCHARGE VOUCHER							Load PDF			

Linked Accident Report Documents

			View Use Viewer	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	12/09/17 10:00	Accident Statement	Load HTM	
Photos/Images			3 per page	☒

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	12/09/17 09:57	Accident Photo		Load JPG	☒
2	12/09/17 09:57	Accident Photo		Load JPG	☒
3	12/09/17 09:57	Accident Photo		Load JPG	☒
4	12/09/17 09:57	Accident Photo		Load JPG	☒
5	12/09/17 09:57	Accident Photo		Load JPG	☒
6	12/09/17 09:57	Accident Photo		Load JPG	☒
7	12/09/17 09:57	Accident Photo		Load JPG	☒
8	12/09/17 09:57	Accident Photo		Load JPG	☒
9	12/09/17 09:57	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	12/09/17 09:55	Sketch Plan		Load JPG	☒
2	12/09/17 09:55	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG17017663/ATBN2

Date: 26/01/2018

REFERENCE

Insured/Claimant: VINCENT TAN KHAR KHENG

Policy No: 2100488648

Date of Loss: 11/09/2017

Nature of Claim: OD

Claim No: 2186219888SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL3700L	Engine No:	CVN017632
Make & Model:	AUDI A4, 1.4 T (A)	Chassis No:	WAUZZZF42HA027053
Reg. Date:	28/10/2016 (Man. Year: 2016)	Odometer:	20188 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$135,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,723.00	1,489.20	2,233.80	60.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,172.00	1,522.00	650.00	29.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,895.00	3,011.20	2,883.80	48.92
+ GST 7.00/7.00% (S\$)	412.65	210.78	201.87	48.92
Nett Amount (S\$)	6,307.65	3,221.98	3,085.67	48.92

INSPECTION

Date of Assignment: 12/09/2017

Date Inspected: 12/09/2017 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,844.00 FS	*1,475.20 FS
2	1		*REAR BUMPER SPOILER	Not Necessary	203.00 FS	*- FS
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	756.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION INNER LH/RH	Not Necessary	73.00 FS	*- FS
5	2		*REAR BUMPER GUIDE SECTION OUTER LH/RH	Damaged	36.00 FS	*14.00 FS
6	1		*REAR BUMPER SECURING STRIP	Not Necessary	182.00 FS	*- FS
7	2		*REAR INNER/OUTER REVERSE SENSOR	Not Necessary	415.00 FS	*- FS
8	4		*SEAL RING	Not Necessary	14.00 FS	*- FS
9	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS
Total Parts (\$\$)					3,723.00	1,489.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE & RENEW REAR BUMPER.RE-ORGANISE REAR RASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	900.00	500.00
3	TO RESPRAY REAR BUMPER	New	800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			2,172.00	1,522.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >