

ASS. REC. BY:

REF CS/FC117017697/Tlrbn2

Special Instruction:

Surveyor:

CWS

Taufik

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

13/9/17 12.05pm

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 4054K

Insured:

SHA 2566X

at Workshop m/s

Charm's Customcraft

Tel:

62717054

of

Blk 1010 Bukit Merah Lane 3 # 01-105

Policy No

Claim No:

D17008591 MFSH

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A

6/9/17

CA / REV / REP. / REV 24 HRS

'Ds'

14/09/2017 @ 1pm-3pm

H.O.D. Endorsement

Date/Time: 13/9/17 1.50pm

Person Contacted:

Sharon Lee

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SLC 4054K -X

SHA 2566K -X

Taufik

REF: FCI

ASSIGNMENT

From: Date 14/9/17

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No SLC 4054K

at Workshop in's Chann's Customcraft

of BIK 1010 Bukit Merah Lane 3 #01-105

Insured

Policy No:

Claims No:

Sum Insured

Excess

(Client's Record)

Make of Veh:

* 1pm-3pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

DAC Accident Report:

Consistent? Yes or No

GIA PR Seen

Consistent? Yes or No

Est. Repairs:

3

days

Res.

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date

Person Contacted

Vehicle IN / OUT

Date Time

Action / Instruction

13/2 2.51pm Continued final sig B1840.48 with Sharon. (Red 344, 16%)

Veh No SLC4054K.

Yr Regn 2016 May

Type M.Cer / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make Hyundai Elantra

cc 1591

Colour Black

A/C Insured / Std / NI / NA

Sp Reading 35402.

T Radio: Insured / Std / NI / NA

Eng No:

KM 110841 CM 44143653

C No:

Gen Cond Good / Fair / Poor / Burnt

Steering Inorder / Jammed / Leaked / Burnt or

Brake Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S Rim / STD A/Rim or

Tyre Size F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal 6

mm

R/Bal 6

mm

L/Bal 6

mm

L/Bal 6

mm

D.O.A

D.O.I

14/9/17 @ 1420

Survey held at:

Chann's Custom

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision

RECEIVED 20 FEB 2018

Signature
19/1/2018

Date/Time File Pass to:

typist



Preli. Report



Final Report

Date/Time File Return to:

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee

Transportation

1. S + RS

2. Photos

3. Others

TOTAL

Add Fee:



Site Insp \$



Interview \$



Tech Invs \$



Weekend \$

Report Format: TP

Lump Sum / (B.I.): \$ 1,840.48

110
50
50
38
248

Survey Department Check List (Case Handler)

Reference No. : 2017017697/Tib.
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (*Catherine*): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code	✓			
N	Assign From	✓			
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (*Raufich*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: *Alvise* *14/7/18*
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17017697/T1rb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-09-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2566K	Veh. Inspected	SLC 4054K
Policy No.		Coverage (\$)	0.00
Claim No.	D17008591MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	13/09/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/09/2017	Inspection Date
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C

GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	07-09-2017	Our Ref No.	D17008591MFSH
Accident Date	06-09-2017	Claim Type.	Third Party
Insured Vehicle	SHA2566X	Third Party Vehicle.	SLC4054K
Survey Location	BLK 1010 BUKIT MERAH LANE 3 #01-105		
Contact Person.	SHARON LEE		
Contact No.	62717054/ 0	Fax No.	62736676
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHARN'S CUSTOMCRAFT	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	KARENT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/227779)



PRI Documents



Close



PRI Header Details

Claim No	D17008591MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CHARN'S
Workshop Name	CHARN'S CUSTOMCRAFT (Contact Person : SHARON LEE)	Survey Location & Contact Details	BLK 1010 BUKIT MERAH LANE 3 #01-105 Mobile: 0 , Phone: 62717054 , Fax: 62736676 EmailId: CHARN@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA2566X	TP Vehicle No	SLC4054K
PRI Recieved Date	12-09-2017 05:09:35 PM	Surveyor Appointed Date	13-09-2017 12:05:49 PM	Surveyor Accept Date	13-09-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	13-09-2017	Upload Survey Report *:	Choose File
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▾	Model	Please Select Model ▾	Year	Select Year ▾
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
----------------	----------------------	-------------------------------------

Celine Fong (LKKAUTO)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Monday, 12 February 2018 2:51 PM
To: Celine Fong (LKKAUTO); Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: Finalization - SLC 4054 K - Hyundai Elantra

Importance: High
Sensitivity: Confidential

Hi

Confirmed.

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L
Company Reg No: 25151300M

From: Celine Fong (LKKAUTO) [mailto:celinefong@lkkauto.com]
Sent: Monday, 29 January, 2018 12:41 PM
To: Charn's Customcraft; Taufikh (LKKAUTO)
Cc: SUR
Subject: RE: Finalization - SLC 4054 K - Hyundai Elantra
Sensitivity: Confidential

Hi Sharon,

Kindly confirm finalize amount \$1,840.48 (before GST).

No of days: 3 days

Best Regards,

Celine Fong

LKK Auto Consultants Pte Ltd

phone: 6256-3561 | email: celinefong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Celine Fong (LKKAUTO)
Sent: Monday, 15 January 2018 10:25 AM
To: Charn's Customcraft <charns@singnet.com.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: Finalization - SLC 4054 K - Hyundai Elantra
Sensitivity: Confidential

Hi Sharon,

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 5645F

Vehicle Details

Vehicle No.: SLC4054K

Vehicle to be Exported: Yes

Intended De-registration
Date: 30 Sep 2017

Vehicle Make: HYUNDAI

Vehicle Model: ELANTRA AD 1.6 GLS AT

Primary Colour: Black

Manufacturing Year: 2016

Engine No.: G4FGGU158554

Chassis No.: KMHD841CMHU143653

Maximum Power Output: 93.8 kW (125 bhp)

Open Market Value: \$17,132.00

Original Registration Date: 13 May 2016

First Registration Date: 13 May 2016

Transfer Count: 0

Actual ARF Paid: \$17,132.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 12 May 2026

PARF Rebate Amount: \$12,849.00

Intended COE Rebate Details

COE Expiry Date: 12 May 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$47,889.00

COE Rebate Amount: \$38,311.00

Total Rebate Amount: \$51,160.00

The information contained herein is correct as at 08 Sep 2017.

YOUR POLICY SCHEDULE

This document forms part of your contract with us and should be read together with your Certificate of Insurance and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Car Insurance

Policy number	: MT/00379649		
Period of cover	: Policy begins 13/05/2017 00:00 and runs until 12/05/2018 23:59		
Premium	: S\$ 987.11 (Inclusive of GST)		
Own Damage Excess	: S\$ 800.00 (before any applicable GST)		
Windscreen Excess	: S\$ 100.00 (before any applicable GST)		
Vehicle Details			
Vehicle Registration	: SLC4054K	Chassis number	: KMHD841CMHU143653
Make and model	: Hyundai Elantra 1.6	Car usage	: Private and Business Use
Year of registration	: 2016		
Finance company / Hire purchase	:	No. of accidents/claims in the last 36 months	: 0
Is your car modified? (Modifications are according to LTA guidelines)	: No		
Policyholder			
Policyholder	: SOH CHENG LOCK (SU QINGLE), DONNY		
Mailing Address	: 8 MARINE VISTA, 03-29 NEPTUNE COURT, Singapore 449032		
E-mail Address	: donnysoh@degrees9.com	Mobile Number	: 94561435
No Claims Discount (NCD)	: 20%		
Main Driver Details			
Main Driver	: SOH CHENG LOCK (SU QINGLE), DONNY		
Date of Birth	: 25/11/1978	Marital Status	: Married
Gender	: Male	Occupation	: Private sector : management
Certificate of Merit	: No	Number of accidents or claims in the last 36 months	: 1: Not at fault
Years of valid driving licence	: > 5		
Important Note: This policy does not cover drivers below the age of 30 and drivers who hold a valid driving licence of less than 2 years with the exception of the named drivers above.			
Young and/ or Inexperienced Driver (YIED): refers to any driver who is below the age of 30 or holds a driving licence for less than 2 years.			
Promotion Details			
Promotion Item : \$200 petrol voucher giveaway			

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7835645F



Name
SOH CHENG LOCK, DONNY
(SU QINGLE)
苏清乐

Race
CHINESE

Date of birth
25-11-1978

Sex
M

Country of birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

S7835645F



SOH CHENG LOCK, DONNY
(SU QINGLE, DONNY)

Birth Date: 25 Nov 1978

Issue Date: 18 Mar 2008

001562487J

4345591



NRIC No. S7835645F



Date of issue
05-02-2009

8 MARINE VISTA #03-29
SINGAPORE 449032

NRIC No: S7835645F Date: 20/01/2017 (R)

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver, and other motor vehicles < 2500kg

PASS DATE
18 Mar 2008

NP 428A

License No: S7835645F



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

AXA/FC(SHA2566X)

DOA: 06/09/2017@1020

FIRST CAPITAL INSURANCE PTE LTD

12/9/2017

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SLC 4054 K - HYUNDAI ELANTRA AD 1.6 GLS AT
CHASSIS NO: KMHD841CMHU143653 (2016)

1 pc	Rear boot logo	\$ 35.00	net ✓
1 pc	Rear boot emblem 'Elantra'	\$ 65.50	net ✓
1 pc	Rear bumper	\$ 559.40	de ✓
1 pc	Rear bumper reflector LH	\$ 55.00	crn ✓
1 pc	Rear bumper reflector RH	\$ 55.00	x
1 pc	Rear bumper lower garnish	\$ 275.20	ant ✓
1 pc	Rear bumper reinforcement	\$ 325.00	?
		\$ 1,370.10	
	LESS 20%	\$ 274.02	
		\$ 1,096.08	

Remove necessary parts; jacking, panel beating, repair
and straighten rear inner panel, rear end panel, rear,
boot, rear bumper and affected areas.

\$ 400.00

Putty and respray rear inner panel, rear end panel,
rear boot, rear bumper and affected areas.

\$ 600.00

\$ 2,096.08

\$ 146.73

\$ 2,242.81

ADD 7% GST

CHARN'S CUSTOMCRAFT

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfikh 97495749

DS'
14/9/17 @ 1420

3 days

Resurvey before paint

sur @ lkkauto.com

tanfikh @ lkkauto.com



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

AXA/FC(SHA2566X)

DOA: 06/09/2017@1020

FIRST CAPITAL INSURANCE PTE LTD

12/9/2017

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SLC 4054 K - HYUNDAI ELANTRA AD 1.6 GLS AT
CHASSIS NO: KMHD841CMHU143653 (2016)

1 pc	Rear boot logo	\$ 35.00	we
1 pc	Rear boot emblem 'Elantra'	\$ 65.50	we
1 pc	Rear bumper	\$ 559.40	de
1 pc	Rear bumper reflector LH	\$ 55.00	cm
1 pc	Rear bumper reflector RH	\$ 55.00	x nn
1 pc	Rear bumper lower garnish	\$ 275.20	art
1 pc	Rear bumper reinforcement	\$ 325.00	784
		\$ 1,370.10	1315.10
	LESS 20%	\$ 274.02	263.02
		\$ 1,096.08	1052.08

Remove necessary parts; jacking, panel beating, repair
and straighten rear inner panel, rear end panel, rear,
boot, rear bumper and affected areas.

\$ 400.00

Putty and respray rear inner panel, rear end panel,
rear boot, rear bumper and affected areas.

\$ 600.00

\$ 2,096.08

ADD 7% GST

\$ 146.73

\$ 2,242.81

2184.48

CHARN'S CUSTOMCRAFT

Parts -

Tanjik 97495749

DS'
14/9/17 @ 1420

3 days

Resurvey before paint

sur@kkanto.com

tanjik@kkanto.com



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62738676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

AXA/FC(SHA2566X)

DOA: 06/09/2017@1020

FIRST CAPITAL INSURANCE PTE LTD

12/9/2017

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SLC 4054 K - HYUNDAI ELANTRA AD 1.6 GLS AT
CHASSIS NO: KMHD841CMHU143653 (2016)

Supplementary

3 pcs Rear bumper clips @ \$3.50
1 pc Smart key antenna

\$ 10.50

\$ 100.00

\$ 110.50

LESS 20%

\$ 22.10

\$ 88.40

ADD 7% GST

\$ 6.19

\$ 94.59

CHARN'S CUSTOMCRAFT

Parts - 1052.08
Lab - 700.00
1752.08

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17017697/T1rbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-02-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2566X	Veh. Inspected	SLC 4054K	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17008591MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	13/09/2017	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHD841CMHU143653	Colour	BLACK	
Odometer	35402	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KUMHO	6 mm	
L/H Front Tyre	205/55 R16	KUMHO	6 mm	
R/H Rear Tyre	205/55 R16	KUMHO	6 mm	
L/H Rear Tyre	205/55 R16	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/09/2017	Inspection Date	14/09/2017	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 4054K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LOGO	NECESSARY	35.00	35.00
1	REAR BOOT EMBLEM "ELANTRA"	NECESSARY	65.50	65.50
1	REAR BUMPER	DEFORMED	559.40	559.40
1	REAR BUMPER REFLECTOR LH	CRACKED	55.00	55.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	55.00	-
1	REAR BUMPER LOWER GARNISH	CUT	275.20	275.20
1	REAR BUMPER REINFORCEMENT	BENT	325.00	325.00
1	SMART KEY ANTENNA (ADDITIONAL)	BROKEN	100.00	100.00
3	REAR BUMPER CLIPS @\$3.50 (ADDITIONAL)	NECESSARY	10.50	10.50
	LESS 20% DISCOUNT		-296.12	-285.12
			1,184.48	1,140.48
LABOUR				
	REMOVE NECESSARY PARTS, JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN REAR INNER PANEL, REAR END PANEL, REAR BOOT, REAR BUMPER AND AFFECTED AREAS.		400.00	300.00
	PUTTY AND RESPRAY REAR INNER PANEL, REAR END PANEL, REAR BOOT, REAR BUMPER AND AFFECTED AREAS.		600.00	400.00
			1,000.00	700.00
GRAND TOTAL			2,184.48	1,840.48
RECOMMENDED COST OF REPAIRS				1,840.48

Report Ref No. CS/FC117017697/T1rbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.