

	REAR WHEEL HUB <i>He n</i>	1	\$ 450.00	15.00%	\$ X 382.50	Not given (x)	Not given (x)
	REAR BRAKE DRUM <i>He n</i>	1	\$ 450.00	15.00%	\$ X 382.50	Not given (x)	Not given (x)
	BRAKE CALIPHER <i>He n</i>	1	\$ 650.00	15.00%	\$ X 552.50	Not given (x)	Not given (x)
	REAR EXHAUST ASSY <i>He n</i>	1	\$ 650.00	15.00%	\$ X 552.50	Replace (/)	
NETT ITEMS	REVERSE SENSOR (1 SET) <i>Paged</i>	2	\$ 250.00	NETT	\$ 220 250.00	Replace (/)	
NETT ITEMS	NO PLATE (METAL) <i>He n</i>	1	\$ 25.00	NETT	\$ X 25.00	Replace (/)	
NETT ITEMS	NO PLATE GARNISH <i>He n</i>	1	\$ 25.00	NETT	\$ X 25.00	Replace (/)	
	PANEL BODY LWER BACK <i>He n</i>	1	\$ 488.00	NETT	\$ X 488.00	Replace (/)	
	PLATE 1.3 <i>He n</i>	1	\$ 38.00	15.00%	\$ X 32.30	Replace (/)	
	PANEL , WH HOUSING RH <i>Ryur</i>	1	\$ 532.50	15.00%	\$ X 532.20	Replace (/)	
	PANEL , QTR INNER RH <i>Ryur</i>	1	\$ 380.00	15.00%	\$ X 323.00	Replace (/)	
TOTAL MATERIALS			\$ 13,649.50		\$ 11,799.85		

3672

SIG 9804

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim 96893735
L/S 13/09/17

09 Days.

total: 6042
L/S: 4.8K