

ASS. REC. BY:

REF: CS/FC117017883/R1rbn2

Special Instruction:

SURVAYOR
CWS

RCSU

ASSIGNMENT (Office)

From (Person): Aung Yin Ming

of FC1

Date/Time: 15/9/17 4:32pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 9577L

Insured: SHC 0666T

at Workshop m/s

Wearnes Automotive

Tel: 81261237

of

249 Alexandra Road

Policy No:

Claim No: D17008723 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/9/17

CA / REV / REP. / REV 24 HRS

'DS'

13.10.2017 @ after 4pm at 28 Leng Kee Road

H.O.D. Endorsement

Date/Time: 15/9/17 4:53pm

Person Contacted:

Paul Ong

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLQ 9577L - X

SHC 0666T - X

Confirm P/P \$7308.39 6 days

Red: \$3.063.51, 291.

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

D.O.A.

10/09/17

D.O.I.

13/10/17

Survey held at

WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 08 JAN 2018

Date/Time, File Pass to?



: Preli. Report



: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

1)

typist

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

170

50

50

31

301

Report Format:

TP

Lump Sum / I.B.I: (\$ 7308.39)